

22/03/2018

ASS. REC. BY:

REF: CS3/MSG18002360/T1d3e2

Special Instruction:

Surveyor:

Maimen

From (Person):

jasmine lok

ASSIGNMENT (Office)

of MSG

Date/Time:

6/2/18 @ 11am

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJD 7079M

Insured:

SKV 2034T

at Workshop m/s

V-Tech Auto

Tel:

6264 6211

of

No. 1800 n lee str #06-04

Policy No:

29065794 QMX

Claim No:

518701

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/02/2018

CA / REV / REP. / REV 24 HRS

wup

H.O.D. Endorsement:

Date/Time:

11:32am @ 6/2/18

Person Contacted:

Ms. Choney

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SJD 7079M-X
	SKV 2034T-X
	Dismantle: 8/2/2018

Tanphm

RCP:

MSLG

ASSIGNMENT

CoE 2018 March.
2008 March

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop no: _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The Veh had commenced its
repair at the time of inspection.



Val. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR / Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS "WP"

Date: _____ Person Contacted: _____ Vehicle IN / OUT

Van No: **SJD7079M**
Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **Toyota Rush 1.5A** : **1445**
Colour: **Green** A/C Insured / Std / NI / NA
Ser. Reading: **142465** T. Radio: Insured / Std / NI / NA
Eng No: _____
C No: **3200E0018931**
Gen. Cond: **Good** / Fair / Poor / Burnt
Steering: **Good** / Jammed / Leaked / Burnt or
Brake: **Good** / Jammed / Leaked / Burnt or
Mod: **Nil** / Rim / STD A/Rim or
Tyre Size: **215/65 R16**
R: _____

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /
☒ TOYO / YOKO or

Front: _____ Rear: _____
R. Bal: **6** mm R. Bal: **6** mm
L. Bal: **6** mm L. Bal: **6** mm
D.O.A: _____ D.O.I: **6/2/18**
Survey held at: **Y-Tech Sun Lee**
Des. of Damages: **Front** / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 3500 - 4500

* 3 days

20/4. Submit PRE report

RECEIVED 20 APR 2018

Date/Time File Pass No: ☐ : Prell. Report

Days Of Repair: **3**

☐ : Final Report

Resurvey No. of Trip: **1**

Date/Time File Return No:

Survey Fee

120

Transaction

50

3

Add Fee:

☐ Site Insp \$
☐ Inter. Insp \$
☐ Tech. Insp \$
☐ Lab. Insp \$

Lab. Insp \$

Photo

Video

10

Report Format: **PRE**

Lump Sum / LB 1:13

180

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	05 Feb 2018		06 Feb 2018 11:00 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LAI KON SEE, ID: S6874886J		
Main Claimant:	CAR IMPRESSION PTE LTD, Co. Reg. No.: 20170321G		
Vehicle Reg. No.:	SJD7079M	Date of Loss:	05/02/2018 00:00 - :59
Claim Type:	TP / 548701	Policy/Cover Note No.:	29065794QMX (Comprehensive) Coverage: 05/01/2018 - 04/01/2019
Vehicle Reg. No. (Insured):	SKV2034T	Policy No. (Claimant):	
		Excess:	
Repairer:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/02/2018]		
Adj. Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0321G
Vehicle Details	
Vehicle No.:	SJD7079M
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	RUSH 1.5X A
Primary Colour:	Green
Manufacturing Year:	2007
Engine No.:	3SZ2000854
Chassis No.:	J200E0018931
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,885.00
Original Registration Date:	31 Mar 2008
First Registration Date:	31 Mar 2008
Transfer Count:	0
Actual ARF Paid:	\$14,885.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2018
PARF Rebate Amount:	\$7,442.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10

QP Paid:	\$15,389.00
COE Rebate Amount:	\$223.00
Total Rebate Amount:	\$7,665.00

The information contained herein is correct as at 07 Feb 2018

OK

SGCARMART.COM[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Articles](#)

ANNOUNCING Cosmo Automobiles
as sgCarMart Premium Dealer for the 3rd Consecutive Year

**Post an Advertisement**

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**May 16 Infiniti Q50 2.0A. Warranty From Wearnes May 19.**

Smooth & Refined Performance.
Mint Condition. Well Kept By 1
Owner. Must View!
Shine Connect [StarAd](#)

ABWIN[Browse by Category](#)[Sort by Date](#)**14 vehicles**

Toyota Rush

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage
Search Selection	Toyota Rush		Any	Any	2008	Any	Any
	Toyota Rush	Toyota Rush 1.5A X (New 5-yr COE)	\$37,800	\$7,560 /yr	16-Apr-2008	1,495 cc	125,380
Shining Silver, Very Well Maintained, MINI SUV, Very Low Fuel Consumption, Low Deprecation, Can Cover Warranty, 90% Loan Viewing And Test Drive Welcome.							
Posted: 06-Feb-2018 Tags: 2008 Toyota Rush, Toyota Rush, Toyota, Rush, Used Toyota							
	Toyota Rush	Toyota Rush 1.5A X (New 5-yr COE)	\$37,800	\$7,560 /yr	14-Feb-2008	1,495 cc	-
Well Maintained By Previous Owner, One Of The Most Fuel Efficient And Economical Mini SUV. Original Condition.High Loan/Trade In Are Welcome. Call Us Now For A Test Drive.							
Posted: 04-Feb-2018 Tags: 2008 Toyota Rush, Toyota Rush, Toyota, Rush, Used Toyota							
	Toyota Rush	Toyota Rush 1.5A X (New 5-yr COE)	\$35,800	\$7,160 /yr	26-Jun-2008	1,495 cc	118,020
Beautiful White. Well Kept. Accident Free. Best Seller Mini Toyota SUV.							
Posted: 02-Feb-2018 Tags: 2008 Toyota Rush, Toyota Rush, Toyota, Rush, Used Toyota							
	Toyota Rush	Toyota Rush 1.5A X	\$12,800	N.A	10-Jul-2008	1,495 cc	108,000
Beautiful Metallic Grey, Very Careful Owner, Well Maintained. Very Spacious And Big Boot Space SUV. Ideal For Those Who F Comfort Interior Yet Powerful Drive! Loans And In House Loan ...							
Posted: 01-Feb-2018 Tags: 2008 Toyota Rush, Toyota Rush, Toyota, Rush, Used Toyota							

[Car Buying](#)[Car Selling](#)[Car Aftermarket](#)[Car Ownership](#)[On The Move](#)[Lifestyle](#)[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 08:04
Date Of Accident	05/02/2018 10:30
Exact Location Of Accident	JURONG WEST AVE - 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJD7079M
Insured/Policyholder	
Name Of Registered Owner	CAR IMPRESSION PTE LTD
Co Reg No	NA 2017/032169
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98460955
Alternative Phone No	OFFICE-94522234

Vehicle Particulars

Manufacturer	TOYOTA
Model	RUSH-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5090754498
Cover Note Number	

Driver

Name of Driver	TAN ENG JOO (CHEN YONGYU)
NRIC No	S7830633E
Date Of Birth	14/10/1978
Occupation	OUTDOOR
Date Of Driving Pass	27/11/1997
Driving Experience	20 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98460955
Fax Number	
Contact Number	OFFICE-94522234
EMail Address	ALFREDHENG27@GMAIL.COM

Address	BLK 671A JURONG WEST STREET 65 #08-96
Postcode	641671
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV2034T
Vehicle Make/Model/Colour	NA
Details Of Properties	REAR AND FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKK5189T
Vehicle Make/Model/Colour	NA
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

I am the driver of SJ07079M Toyota Rush when I was making a right turn from Turning West St 64 to Turning West Ave 4. I stopped when I spotted a bicycle using the road crossing when I stopped at the junction. A mercedes benz SK 120571 hit my car from the back. After the impact, I realized there it was a chain collision between 3 cars. The 3rd car is a mercedes Benz SK-K 51897.

DATE: 12/1/16



Signature



收稿日期: 2003-03-10

[Handwritten signature]






































...CLAIM SUBFOLDER...(Pending for Survey Report)

















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		06 Feb 2018 11:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<div> <div>CLAIM SUBFOLDER DETAILS</div> <div>[Created by insurer]</div> <div> Insured: LAI KON SEE, ID: S6874886J Main Claimant: CAR IMPRESSION PTE LTD, Co. Reg. No.: 20170321G Vehicle Reg. No.: SJD7079M Claim Type: TP / 548701 Vehicle Reg. No. (Insured): SKV2034T Date of Loss: 05/02/2018 00:00 - :59 [118 Months and 5 Days From LTA Reg Date (Man Yr)] Policy/Cover Note No.: 29065794QMX (Comprehensive) Coverage: 05/01/2018 - 04/01/2019 Policy No. (Claimant): Excess: Repairer: V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211 Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550] Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 07/02/2018] Adj Asg. Remarks: Third Party Pre-Repair Survey </div> </div>																								
<div> <div>ASSOCIATED MAIL RECEIVED</div> <div>View All Compose Case Mail</div> <div>There are no mail for this case.</div> </div>																								
<div> <div>ALL ASSOCIATED TASKS</div> <div> View All Search Tasks Create New Task Complete </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SJD7079M (548701)
[SKV2034T]
TP
CAR IMPRESSION PTE LTD
Feb 5 2018 12:00AM
[LAI KON SEE]
V-Tech Auto Service

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser		
Photos/Images							3 per page		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
2	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
3	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
4	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
5	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
6	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
7	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
8	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
9	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
10	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
11	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
12	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
13	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
14	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
15	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
16	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
17	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
18	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
19	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
20	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
21	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
22	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
23	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
24	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
25	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
26	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
27	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
28	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
29	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
30	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
31	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
32	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
33	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
34	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
35	20/04/18 15:49	General View		Load JPG	<input checked="" type="checkbox"/>						
36	20/04/18 15:54	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						
37	20/04/18 15:54	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/04/18 15:54	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/02/18 10:12	TP PRI	 Load PDF	
2	06/02/18 10:59	REJECTION REPLY TO TP & NOMINATED LKK TO BE OUR SJE	 Load PDF	
3	06/02/18 11:03	TP CIRCUMSTANCE OF THE ACCDT REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18002350/T1D3E2

Date: 23/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29065794QMX

Claimant Vehicle No : SJD7079M

Insured Vehicle No : SKV2034T

Date of Loss: 05/02/2018

Nature of Claim: TP

Claim No: 548701

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD7079M

Make & Model: TOYOTA RUSH, 1.5 X (A)

Engine No: 3SZ2000854

Reg. Date: 31/03/2008 (Man. Year: 2007)

Chassis No: J200E0018931

Colour: Green

Odometer: 142465 km

Engine Capacity: 1495 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/02/2018

Date Inspected: 06/02/2018 Inspected At:

V-Tech Auto Service (HQ)
No.1 Soon Lee Street, #06-04 Pioneer
Center
Singapore 627605

Estimated Period of Repair: 0.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 -\$4,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2018)
Parts:	M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJD7079M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >