

22/03/2002

ASS. REC. BY:

REF: CC/SMU1800 2359 /Uqbm/ Special Instruction:

Surveyor: Marius.

ASSIGNMENT (Office)

From (Person): Grace Teo of Smo Date/Time: 06022018 432pm

Estimated Cost: Bill to:

OD / ~~IP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLK 8586Z Insured: FBL 4041Tat Workshop m/s LBA Automotive Tel: 6509 5521of Blk 1 Kaki Bukit Ave 6 #02-47Policy No: Claim No: CMTD 1800407 / GPL

Sum Insured: Excess:

Make of Veh: D.O.A. 30-11-2017

(Client's Record)

07-07-2018

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 06022018 440pm Person Contacted: Karen Vehicle: OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SLK 8586Z - X
	FBL 4041T - X
08/2/18 @ 5.17pm	revised to Groh Pan loong by email.

(08/11/13) \*wef

ASS. REC. BY: Marcus

REF:

Sami**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLK 85867at Workshop m/s L3A

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

DAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: 2

Consistent? : Yes or No

Est. Repairs: 4

days

Res.: Yes or No

Lum Sum: 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLK 85867 Yr Regn: 4111Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or NAMake: Mercedes c.c. 1799Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 89565 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMF01630A S2000SLGen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16

R: \_\_\_\_\_

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/1/17D.O.I. 7/2/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/2/18 Confirmed L/S @ 1530 with Karen. (Red B 191676, 55%)

RECEIVED 09 FEB 2018

Date/Time, File Pass to? \*

☐

Preli. Report

1) 09/2 typist☐

Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

Site Insp (\$

) \_\_\_\_ S + RS \_\_\_\_ S

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: TPLump Sum / L.B.I.: (\$ 1530 )

TOTAL

250

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18002359/Uqb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 06-02-2018



Code : SMO

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	FBL 4041T	Veh. Inspected	SLK 8586Z
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800407/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/02/2018

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	30/11/2017	Inspection Date	07/02/2018
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

Reference No.: CG/SMO18002359/UGP  
Policy Type: OD / TP / TP RES / TL / EVA

### Case Handler

Typist

Admin ( *Cathy* ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

Y-Date	N-Date
✓	
✓	
✓	
✓	
✓	
✓	
✓	
✓	

Surveyor ( *Martin* ): Case handler to make sure the surveyor completed all required information.

C	Vehicle No		
C	Regn Month/Year		
N	Vehicle Type		
N	Make & Model		
C	Engine Capacity. (C.C)		
N	Colour		
C	Odometer. (Sp.Reading)		
C	Chassis No		
N	General Condition		
N	Steering		
N	Brake		
N	Modification (Modi)		
C	Tyre Size		
N	Tyre Make		
C	Tyre Balance		
C	Date of Inspection		
N	Survey held		
N	Des.of Damages		

C	Damaged Vehicle Photographs Uploaded	<input checked="" type="checkbox"/>	<input type="checkbox"/>
---	--------------------------------------	-------------------------------------	--------------------------

N	ALL Parts condition			
C	Market Value for OD cases			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
C	Days of repair			
C	Finalised Amount			
C	Re-inspection Cases to Finalize within 5 Days			

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: 

--

--

  
Case Handler                      Date

\*C: Critical \*N: Non-Critical

## Catherine Chong (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Tuesday, 6 February, 2018 4:32 PM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** LBA Automotive Pte. Ltd.; Gnoh, Pau Loong; Henry, Irene James  
**Subject:** CMTD1800407/GPL - ACCIDENT INVOLVING FBL4041T & SLK8586Z ON 30.11.2017

Our Reference: CMTD1800407/GPL  
Your Reference: SLK8586Z

Dear LKK AUTO CONSULTANTS/ Marcus,

Please make arrangement to conduct the survey for SLK8586Z.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** LBA Automotive Pte. Ltd. [mailto:lbaautomotive@hotmail.com]  
**Sent:** Tuesday, February 06, 2018 4:22 PM  
**To:** Teo, Grace  
**Cc:** Gnoh, Pau Loong; Henry, Irene James  
**Subject:** RE: CMTD1800407/GPL - ACCIDENT INVOLVING FBL4041T & SLK8586Z ON 30.11.2017  
**Importance:** High

Dear Grace,

Please arrange Marcus Chua from LKK Auto Consultants

Thanks & Best Regards

Ms Karen  
LBA Automotive Pte Ltd  
1 Kaki Bukit Ave 6  
#02-47 Autobay  
Singapore 417883  
Tel: 6509 5521  
Fax: 6509 5523

---

**From:** Teo, Grace [mailto:grace.teo@sompo.com.sg]  
**Sent:** Tuesday, 6 February, 2018 4:15 PM  
**To:** LBA Automotive Pte. Ltd.  
**Cc:** Gnoh, Pau Loong; Henry, Irene James  
**Subject:** CMTD1800407/GPL - ACCIDENT INVOLVING FBL4041T & SLK8586Z ON 30.11.2017

Our Reference: CMTD1800407/GPL  
Your Reference: SLK8586Z

**Without Prejudice**

Date: 6<sup>th</sup> February 2018

**Attention:**  
**M/S LBA AUTOMOTIVE PTE LTD**

Dear Karen,

**ACCIDENT INVOLVING FBL4041T & SLK8586Z ON 30.11.17**

We refer to your Notice of Accident dated 06/02/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	

		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** LBA Automotive Pte. Ltd. [<mailto:lbaautomotive@hotmail.com>]

**Sent:** Tuesday, February 06, 2018 4:06 PM

**To:** Claims - Motor Survey

**Subject:** ACCIDENT INVOLVING SLK8586Z AND FBL4041T ALONG QUEENSWAY ON 30.11.2017

**Importance:** High

Dear Sirs,

We refer to the above matter.

Please arrange pre-repair inspection for our client vehicle no. SLK8586Z soon.

Thanks & Best Regards

Ms Karen

LBA Automotive Pte Ltd

1 Kaki Bukit Ave 6

#02-47 Autobay

Singapore 417883

Tel: 6509 5521

Fax: 6509 5523





## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Thursday, 8 February 2018 5:17 PM  
**To:** 'Teo, Grace'; assignments; 'Gnoh, Pau Loong'  
**Cc:** 'Henry, Irene James'; SUR  
**Subject:** RE: CMTD1800407/GPL - ACCIDENT INVOLVING FBL4041T & SLK8586Z ON 30.11.2017  
**Attachments:** CSSMO18002359Uqb.pdf

Dear Mr Gnoh,

Enclosed herewith preliminary advice of SLK 8586Z.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 6 February 2018 4:41 PM  
**To:** 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Gnoh, Pau Loong' <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: CMTD1800407/GPL - ACCIDENT INVOLVING FBL4041T & SLK8586Z ON 30.11.2017

Dear Grace,

Thank you for your email.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Teo, Grace [<mailto:grace.teo@sompo.com.sg>]  
**Sent:** Tuesday, 6 February, 2018 4:32 PM  
**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** LBA Automotive Pte. Ltd. <[lbaautomotive@hotmail.com](mailto:lbaautomotive@hotmail.com)>; Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>; Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** CMTD1800407/GPL - ACCIDENT INVOLVING FBL4041T & SLK8586Z ON 30.11.2017

Our Reference: CMTD1800407/GPL

Your Reference: SLK8586Z

Dear LKK AUTO CONSULTANTS/ Marcus,

Please make arrangement to conduct the survey for SLK8586Z.



Auto  
Consultants  
Pte Ltd

51 UBI AVE I, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1800407/GPL

Date: 08<sup>th</sup> February 2018

Our Ref: CS/SMO18002359/Uqb

Without Prejudice

The Motor Claims Department  
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SLK 8586Z.**


We thank you for the instruction on 06/02/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/02/2018 at the premises of M/s LBA AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,466.76</u>
Revised Estimate Amount	: S\$ <u>1,550.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 4 days.

We have NOT authorize repair.

Yours faithfully

Marcus Chua  
Licensed Appraiser

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8077J
Vehicle Details	
Vehicle No.:	SLK8586Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L 5AT
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	R18A15000254
Chassis No.:	JHMF1630AS200082
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,843.00
Original Registration Date:	26 Apr 2011
First Registration Date:	26 Apr 2011
Transfer Count:	1
Actual ARF Paid:	\$25,843.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2021
PARF Rebate Amount:	\$16,797.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$55,001.00
COE Rebate Amount:	\$17,707.00
<b>Total Rebate Amount:</b>	<b>\$34,504.00</b>

The information contained herein is correct as at 06 Feb 2018

OK

**SINGAPORE ACCIDENT STATEMENT**

## IMPORTANT NOTICE

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	02/12/2017 12:31
Date Of Accident	30/11/2017 17:55
Exact Location Of Accident	QUEENSWAY
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SLK8586Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG HAN WEE ALVIN
NRIC No	S8128077J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93278001
Alternative Phone No	OFFICE-93278001

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company **SOMPO INSURANCE SINGAPORE PTE. LTD.**

Type Of Coverage	COMPREHENSIVE
------------------	---------------

Fleet Policy	NO
--------------	----

Policy Number D17MTPV01003233

Cover Note Number

## Driver

Name of Driver	CHEN YISHAN
NRIC No	S8124897D
Date Of Birth	11/08/1981
Occupation	INDOOR
Date Of Driving Pass	27/12/2002
Driving Experience	14 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-85333851
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 144 BISHAN STREET 12 #05-544  
 Postcode 570144  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER --  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2

### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name EUNOS NPP  
 Police Station Address ROAD: 629 BEDOK RESERVOIR ROAD #01-1620 , POSTCODE: 470629 ,  
 COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

REFER TO POLICE REPORT: T/20171130/2167.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBL4041T  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Name of Driver CHEN HAN WEI  
 NRIC/Passport Number S8327865Z  
 Contact Number 97622079  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

### Details of Witness

Name  
 Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name

CHEN HAN WEI

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBL4041T

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### SKETCH PLAN



A - SLK 8586 Z  
B - FBL 4041 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

LEE BROTHERS



## Sketch Plan #3 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171130/2167

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

1 of 4

Report No. T/20171130/2167

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 30/11/2017 21:10	Vide Report No.:	Station Diary No.: 35
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: CHEN YISHAN			Address: APT BLK 144 BISHAN STREET 12 #05-554 SINGAPORE 570144		
ID Type / ID No.: NRIC NO / S8124897D			Contact No.: Home/Office: Mobile: 85333851		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 36	Date of Birth: 11/08/1981	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: DESIGNER			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 30/11/2017 17:55	Type of Location: Straight Road
Location: Along Road 1 QUEENSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL4041T	Motorcycle					0
SLK8586Z	Car	HONDA	CIVIC	Grey	Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Sketch Plan #4 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171130/2167

2 of 4

Report No. T/20171130/2167

Police Station Of Origin:

Eunos NPP

629 Bedok Reservoir Road #01-1620

SINGAPORE 470629

Tel No: 1800-4439999

## CONTINUATION OF REPORT

<b>Rider</b>			
Name	CHEN HANWEI	ID No.	S8327865Z
Related Vehicle	FBL4041T (Motorcycle)	Contact No.	97622079
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	CHEN YISHAN	ID No.	S8124897D
Related Vehicle	SLK8586Z (Car)	Contact No.	85333851
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 30/11/2017 at about 5.57pm, I was driving along Queensway. At that point of time I was on the 3rd lane and the traffic was moderate. On the left there is a filter lane and at that point of time there is a van at the filter lane. As I was approaching the filter lane, the said van on the left was moving in to my lane. As the vehicle did not slowed down, I immediately apply brake to avoid the collision and stopped. Two seconds later, I felt an impact from behind.

I then realized that there is a bike (FBL4041T) behind me had hit the left rear bumper of my car. I went down to check the condition of the rider and the rider sustain bruises on the right knee. According to the rider, when he saw my vehicle applying the brake, he also did the same however he skidded and lose control and hit my car. I suggested to call for Ambulance however he refused to seek immediate medical attention. Subsequently, 2 man came in and claimed that they are from VICOM. One of them assisted the rider whereas the other attended to me. A man namely 'Jason Chua' told me that he will bring my car and assist me lodging the report and both of us left the scene.

As for my car, there are some scratches on the left rear bumper, a crack and a hole in a left tail light, the rear left rear bumper was dislodge and as for the motorcycle there are some scratches on the right side of the bike and also the right mirror was dent.

I wished to state that I did not sustain any injuries.

## Sketch Plan #5 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20171130/2167

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

3 of 4

Report No. T/20171130/2167

CONTINUATION OF REPORT



SINGAPORE  
POLICE FORCE



T/20171130/2167

Police Station Of Origin:  
Eunos NPP  
629 Bedok Reservoir Road #01-1620  
SINGAPORE 470629  
Tel No: 1800-4439999

4 of 4

Report No. T/20171130/2167

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
G/  
Sr Staff Sgt ABDUL RAHMAN BIN ABDUL  
RAHIM

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
✓ Sgt 2 YEO KIA HUAT  
✓ Contact No.: 65476325

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
30/11/2017 21:10

Classification Of Case:

# LBA AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

**M/S SOMPO INSURANCE SINGAPORE PTE LTD**

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

**FBL4041T**

## ESTIMATE

DATE : 06/02/2018

VEHICLE NO : SLK8586Z

MAKE/MODEL : HONDA CIVIC

ACC DATE : 30/11/2017

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<b>LIST PRICE</b>			
1	1 REAR BUMPER <i>Deep cut 638</i>	698.00	698.00 ✓
2	1 REAR BUMPER BRACKET LH <i>11</i>	15.60	15.60 ✓
3	1 REAR BUMPER RETAINER LH <i>3rd</i>	21.50	21.50 ✓
4	1 REAR TAIL LAMP LH <i>CR</i>	380.30	380.30 ✓
5	1 REAR TAIL LAMP PANEL <i>R</i>	107.70	107.70 ✓
6	1 REAR FENDER LH <i>R</i>	876.30	876.30 ✓
7	1 REAR FENDER COWLING <i>11</i>	27.80	27.80 ✓
			2,127.20
<i>1039.8</i> <i>831.84</i> Less 20%			425.44
			1,701.76

## SPECIAL NETT ITEMS

1	1 (SET) REAR BUMPER CLIP <i>rec</i>	45.00	45.00 ✓
2	1 (SET) REAR FENDER COWLING CLIP <i>11</i>	30.00	30.00 ✓
			75.00

## LABOUR CHARGES :

1	TO KNOCK, CUT/WELD REAR FENDER AND REPLACE ACCIDENT PARTS	<i>520</i>	800.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	<i>500</i>	600.00
3	TO CHECK WIRING	<i>20</i>	30.00
4	TO REMOVE AND REFIT CUSHION	<i>60</i>	180.00
5	TO TUFF KOTE	<i>11x</i>	80.00
			1,690.00

*not Admit*

*2/5 \$1550/-*

*4 day*

*1/2/18*

*the photo after repair*

*1976.84*

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ **3,466.76**

hence notify  
of the following:  
before after spray painting  
damaged part(s) during resurvey  
subject to confirmation  
survey is on a "Without Prejudice" basis  
modification(s) is allowed  
item(s) must be resurveyed and  
subject to final approval from Insurance Company  
Acknowledged by Repairer  
Signature:  
Date:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18002359/Uqbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 12-02-2018



Code : SMO

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 4041T	Veh. Inspected	SLK 8586Z
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800407/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/02/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	JHMF1630AS200082	Colour	GREY
Odometer	89565	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	30/11/2017	Inspection Date	07/02/2018
Survey held at	LBA AUTOMOTIVE PTE. LTD. 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 8586Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEEP CUT	698.00	638.00
1	REAR BUMPER BRACKET LH	NOT NECESSARY	15.60	-
1	REAR BUMPER RETAINER LH	BENT	21.50	21.50
1	REAR TAIL LAMP LH	CRACKED	380.30	380.30
1	REAR TAIL LAMP PANEL	TO REPAIR SEE LABOUR	107.70	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	876.30	-
1	REAR FENDER COWLING	NOT NECESSARY	27.80	-
	LESS 20% DISCOUNT		-425.44	-207.96
			1,701.76	831.84
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR FENDER COWLING CLIP (SN)	NOT NECESSARY	30.00	-
			75.00	45.00
<b><u>LABOUR</u></b>				
	TO KNOCK,CUT/WELD REAR FENDER AND REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL AND REAR FENDER LH.		800.00	520.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		600.00	500.00
	TO CHECK WIRING.		30.00	20.00
	TO REMOVE AND REFIT CUSHION.		180.00	60.00
	TO TUFF KOTE.	NOT NECESSARY	80.00	-
			1,690.00	1,100.00
<b>GRAND TOTAL</b>			<b>3,466.76</b>	<b>1,976.84</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,550.00</b>

Report Ref No. CS/SMO18002359/Uqbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.