NEC, BY:	Rasyl Assig	18002363 R1 rd; NMENT (Office) CTI	Dete/Time 5 2 18 03	-02pm
Inspect Vehic	RESTOD RESTEVATING SLS 2 Volksu	MV / CS 227 In	PA 76972 Tel: 93867833	
Workshop m/s f Policy No. Dt Sum Insured.	1 Kampong Ampa 1815N15559317	of Macpherson	D.O.A. 2/2/2018 2/18/00/2019 DUNER 18/00/2019 DUNER	neitire
Make of Veh. (Client's Record) CA / REV / Date/Time.	REP. / REV 24 HRS wp/	7 Shushi shata	Venicle Diff	
Date/Time	Action/Instruction () 6 S1S 2227 - X PA 76472 - NJA INC	Stimate	D-0-A: 15/1	1000
	Confirm \$9966.31			

...CLAIM SUBFOLDER...(New Assignment)

Coste	Notified	Est Submitted	Adi Assigned	Adj Ept	Adj Submitted	Ins Auth's	10 3	status	
Main	05 Feb 2018		05 Feb 2018 15:02 Assign				1	New Assi Cancel Ca	gnment
	Main	Refere	ence	Claim De	tails	Documen	ts	s	how All
CLAIM S	UBFOLDER DETA	ILS		The state of the s		[Creat	ed by ins	urer]	
Insured:		LIM CHIN Y	ONG TRANSPOR	RT PTE LTD, C	o. Reg. No.: 20111	15637H			
Main Clain	nant:	LIM SHU JU							
Vehicle Re		SLS2227		Date o	f Loss:		2018 20:00		
Claim Typ	÷.	TP / SNM1	P / SNM18D00653C02 Policy/Cover Note No.:		DMB1S Only)	DMB1SN1555931702 (Third Party Only)			
Vahicle Re	eg. No. (Insured):	PA7697Z	PA76977 Policy No. (Claimant):						
venicle re	g, No. (msorca).	11.33.000	Excess:		5\$0.00				
Repairer:		Vamoona Am	nat 368314 Tua	s - Tel:	on) (HQ) Volkswa				
Handling	Insurer:	China Taipi	ng Insurance (S	Singapore) Pte	Ltd. (HQ) - Tel:				ay Hui
Adjuster:		LKK Auto C	onsultants Pte	Ltd (HQ) - Tel:	5256-3561 [Fi r	nal Rpt due	14/02/20	18]	
Adj Asg. F	Remarks:	EST \$9873.7	1, ASSIGN LKK A	AS SJE.					
ASSOCIA	ATED MAIL RECE	IVED					View All	Compose	Case Mai
There are	no mail for this ca	se.							
ALL ASS	SOCIATED TASKS	s=			View All	Search Tasks	Create N	ew Task	Complet
Due Da			oup Subject	Handler	Assigned By	Completed C	n Cre	eated On	Done
No result		NUMBER OF STREET	owner something						
No result	5.								



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	TANGE (O) PIE LID	Ref : CS/CTI1800236	3/R1rd3
CHINA TAIPING INSU	RANCE (S) PTE LTD	Rei , Colo III coczoc	
3 ANSON ROAD #16-0 SPRINGLEAF TOWER	00 RSINGAPORE 079909	Date: 06-02-2018	
	Policy Particula	rs :- THIRD PARTY CLAI	M
Insured Veh.	PA 7697Z	Veh. Inspected	SLS 2227
Policy No.	DMB1SN1555931702	Coverage (\$)	0.00
Claim No.	SNM18D00653C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	06/02/2018
2.	Vehicle Pa	articulars & Condition	
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4.	Descr	iption of Damages	Mary interest of the second
5. wildinika kalenda	C ALBERTANCE - CONTRACTOR	neral Information	图
Accident Date	- Extend to the Control of the Contr	Inspection Date	
Survey held at			
	1 KAMPONG AMPAT OFF I SINGAPORE 368314	MACPHERSON ROAD	
5a.		Remarks	Mary State of the

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

	ACCIDENT CTATEMENT
Date Of Report	03/02/2018 10:02
Date Of Accident	02/02/2018 20:30
Exact Location Of Accident	SLE B4 WOODLAND AVE 12 EXIT
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLS2227H
Insured/Policyholder	
Name Of Registered Owner	LIM SHU JUN
NRIC No	S8721741H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96446449
Alternative Phone No	OFFICE-96446449
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA-1.4 TSI (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29009676AVW
Cover Note Number	
Driver	
Name of Driver	POR SIANG POH
NIBIO NE	\$25375491

S8537549J

NRIC No 17/12/1985 Date Of Birth INDOOR Occupation 18/04/2005 Date Of Driving Pass

12 YEARS AND 9 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-96496499 Mobile Number

Fax Number Contact Number

NOEMAIL EMail Address

BLK 637 PASIR RIS DR 1 Address

#10-572 510637

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Postcode

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD ON COLLISION Type Of Accident

RAINING Weather Conditions

WET Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

YES Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

YES

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 02/02/2018 AT ABOUT 2030, I WAS TRAVELLING ON SLE EXPRESSWAY TOWARD THE DIRECTION OF WOODLAND, VEHICLE NUMBER PA7697Z CAME FROM BEHIND AND HIT MY CAR FROM THE REAR

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

PA7697Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

POR SIANG MOH

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address Postcode 33

BACK

SLS2227H

YES

NO

Page 3 of 12

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes"
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Nam

NRICHEN NO.:

VOLKSWAGEN GROUP

8103000

3000

Sketch Plan #2 Pg. 1

KETCH PLAN	SLE towards	Woodlands	, before	mooplant	uque 12	Exit	
	A 5182225	414					
	PAT	6972					
ESCRIBE CIRC	UMSTANCES OF THE	ACCIDENT				ivit	
04. 3	nd Feb 2018	, at about	2030 h	rı , I	was t	rave lins	on
SLE F	Expressway +	owards the	Direction	of was	dlands	Bus	number
PA 7697	Z Came from	n behind	and hit i	my car	from +	ne rea	r .
41-11-11-11							
						G	
DECLARATION /Weydenlare the	foregoing particulars a	re true in every resp	ect.		₩\/	1	GROUP GROUP SINGAPORE
Policyholder's Sig Date & Time:	nature	Driver's Signature (If driver is not the pi	olicyholder)	Nan	orting Centre F	Personna 8 s	g 0:3:0002



MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807 Tel +65 6827 7888, Fax +65 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA) THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form M.X.1 Individual Ownership VW DRIVEEASY Comprehensive

Certificate No. A 29009676 AVW

Excess: SGD500

Windscreen Excess: SGD100

1. Index Mark and Registration Number of Vehicle

2. Name of Policyholder

Lim Shu Jun

3. Effective Date of the Commencement of Insurance for the purposes of the Act

16/08/2017

4. Date of Expiry of Insurance

15/08/2018

Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

for Chief Executive Officer

REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8537549J



POR SIANG MOH


茂

CHINESE 17-12-1985

SINGAPORE

\$8537549.

REPUBLIC OF SINGAPORE





LIM SHU JUN

淑 君

CHINESE Date of birth

23-07-1987 intru/Place of birth SINGAPORE


S8721741H


















1 of 3

Report No. T/20180203/2117

Police Station Of Origin: Tampines North NPP 461 Tampines Street 44 #01-56 SINGAPORE

Tel No: 1800-7818999

REPORT OF	A TE	AFFIC	ACCIDENT
KEPUKI UT	4 11	MILIO	MODIDLINI

	ate/Time Report Made: 3/02/2018 15:25		Vide Report No.:	Station Diary No. 26	
Informa	nt's Partic	ulars .			
	Informant: ANG MOH		Address: APT BLK 637 PASIR F 510637	RIS DRIVE 1 #10-572 SINGAPORE	
ID Type / ID No.: NRIC NO / \$8537549J			Contact No.: Home/Office:	Mobile: 96496499	
National SINGAP	ity: ORE CITIZ	EN EN	Email:		
Sex: Male	Age:	Date of Birth: 17/12/1985	Type of Informant: Driver		
Race: Chinese		Language: Institution / School N			
Occupation: LOGISTIC EXECUTIVE		Driving Licence Inform Class:	ation: Date of Expiry:		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/02/2018 20:30	Type of Location Straight Road
Location: Along Road 1 SELETAR EX SLE TOWAR Weather:		BEFORE WOODLANDS		toad Speed Limit:
		Wet		
Drizzling	The second secon			
Drizzling Traffic Flow: One Way		Traffic Control: Not Controlled	1.00	raffic Volume: leavy

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
PA7697Z	Bus/Coach/Mi nibus					0
SLS2227H	Car	Marie E Rise				0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20180203/2117

Police Station Of Origin: Tampines North NPP 461 Tampines Street 44 #01-56 SINGAPORE 520461

Tel No: 1800-7818999

CONTINUATION OF REPORT

Driver Name	POR SIANG MOH		ID No		S8537549J	
Ivanic	1 OIL OF THE WOLL					
Related Vehicle	SLS2227H (Car)			Conta	ct No.	96496499
Trelated verifice	OLOZZZIII (Odi)			0.000		
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of		Class: NIL	
1 Toopitali olii ilo				Drivin	g	Date of Expiry: NIL
			Licence &		Sel 59	
				Expin	Date	
Date Treatment	03/02/2018	12-20-00-00-00-00-00-00-00-00-00-00-00-00	Date Disc	charge	NIL	
	ted Medical Leave	06	Degree o	f Injury	NIL	

Brief Details.

On 02/02/18, at about 2030hrs, I was travelling on the most left lane along SLE towards Woodlands, before Woodlands Ave 12 exit. As the traffic volume was heavy, the front vehicle started to brake and came to a gradual stop. As such, I followed suit as well. While stationary, all of a sudden, I felt an impact from the back. I realized that the bus behind me and collided with my vehicle. After the accident, we alighted from our vehicles to assess the damage on our vehicles. I wanted to take the particulars of the bus driver but he refuses. As such, I only have his bus plate number.

I would like to state that there were no traffic police or ambulance at scene. I have a front inbuilt vehicle camera and it was recording at the point of accident. The next day after the accident, I felt discomfort around my back and neck area. As such, I consulted a medical practitioner and was given 6 days medical certificate.





Police Station Of Origin: Tampines North NPP 461 Tampines Street 44 #01-56 SINGAPORE 520461 co Tel No: 1800-7818999

3 of 3 Report No. T/20180203/2117

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording 3 G / Sgt 2 JONATHAN LIM XIONG H	1000	Signature Of Informant			
Signature Of Interpreter: Not applicable		Date/Time: 03/02/2018 15	5:25		
Officer In Charge Of Case: TP / AEIT / SI DZUL HAIRIE BIN RAMLI Contact No.: 65476904	SINGAPORE POLICE FORCE	Classification	Of Case:		
Authentication Stamp NP168	SI	GNATURE			



PDI TUAS

LIM SHU JUN 637 PASIR RIS DRIVE 1 #10-572 Singapore, 510637 Singapore

PDI TUAS

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. M20098505-2 199101494Z

Service Quote

Customer No.

CV025691

Quote No.

SER/QUO/1800199

QuoteDate

03/02/18

Salesperson

Nicholas Chua

Page

1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make Volkswagen Passeng

License No.

SLS2227H Engine Code Model Description

JETTA TSI (DSG) HIGHLINE HIDC

VIN

WVWZZZ16ZGM007023

Labor Type M4 Mileage 14,199

Initial Registration

16/08/17

Engine No. CAX F81579 Service Advisor Ong Germaine

Sales Advisor Nicholas Chua

Model Code 1634G7

			04.	HeM	Unit Price		Amount
	No.	Description	Qty.	UoM	Unit Price		Amount
D	B&P MACP LABOUR	LABOUR	3	UNIT	72	0 /680	2.520.00
P	B&P MACP PAINT	SPRAY PAINT	3	UNIT	15 3	200 /600	2.400.00
P	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs			80.00
P	B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480	480.00
P	B&P MECH	ELECT WIRING & MECH COMPO Nett	1	Time Un		580	280.00
		Sum Labor					5,760.00
						xsu.	7
P	5C6807251E	BUMPER FOAM	1	Pieces		you.	142.24
P		REAR REINFORCEMENT	1	Pieces	(0)2	2/	445.64
P	5C6807417J GRU	REAR BUMPER	1	Pieces			1,020.21
P	5C6807433J	SPOILER	1	Pieces	414		412.75
P	5C6827025E	REAR BOOT LID Predecessor 5C6827025D	1	Pieces		1,4,072	1,222.87
P	5C6853630F ULM	VW SIGN	1	Pieces			108.42
, D	5C6853675APGQF	NAME PLATE - TSI	Ť	Pieces			49.68
D	5C6853687 739	NAME PLATE - JETTA	1	Pieces		1	65.96
E-1	300033007 700	Sum Item					3,467.77

PDI TUAS

PDITUAS

LIM SHU JUN 637 PASIR RIS DRIVE 1 #10-572 Singapore, 510637 Singapore

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. 199101494Z

Service Quote

Customer No.

CV025691

Quote No.

SER/QUO/1800199

QuoteDate

03/02/18

Salesperson

Nicholas Chua

Page

2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

Volkswagen Passeng

License No.

SLS2227H **Engine Code** Model Description

JETTA TSI (DSG) HIGHLINE HIDC

WVWZZZ16ZGM007023

Labor Type

M4

Mileage

14,199

Initial Registration

16/08/17 Engine No.

CAX F81579

Service Advisor

Ong Germaine

Sales Advisor

Nicholas Chua

Model Code

1634G7

10029 77

Sum Labor Sum Item

12 192.19

5,760.00 3,467.77

Total 7% GST SGD

9,227.77

9,227.77 645.94

Total SGD Incl. GST

9.873.71

Explanations

P = Proportionately Charged

Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paral 4p 200 10068 5 days 07/02/18 e 16 45 Rens 64 paint

Payments to:

- BBN: - Acc.-No ..:


Supplementary or Omitted List

VEHICLE NUMBER: SLS2227H

MODEL

JETTA TSI (DSG) TRENDLINE

CLAIMS DETAILS



No.	Item No.	Description	Qty	Unit Pricing	Discount	Amount
1	5C6807863B	BUMPER CENTRE BRACKET	1	\$96.99	7	\$96.99
2	WHT007341	NUT	2	\$2.18		\$4.36
3	8D0853419D	RR NUMBER PLATE PACKING	1	\$12.66		\$12.66
	5C6919491E	SENSOR BRACKET	2	\$23.79	(A)	\$47.58
	5C6919492D	SENSOR BRACKET	1	\$23.79	/	\$23.79
	5C6919491D	SENSOR BRACKET	1	\$23.79		\$23.79
	D 180KU2A1	2KADHESIVE	1	\$89.84		\$89.84
	D 822150A1	BONDAGENT	1	\$64.27		\$64.27
	5CU971104	SENSOR WIRE HARNESS	1	\$161.14		\$161.14
	30		TOTAL:			\$524.42

Total Labour & Parts

\$2,964.42

Survey By

per-M Ne

Service Order Confirmation

SA: Ong Germaine

SERVICE ORDER NO: 18/P0501

CUSTOMER NO .:

CV025691

CUSTOMER NAME: LIM SHU JUN

TELEPHONE NO .:

ADDRESS:

637 PASIR RIS DRIVE 1 #10-572

Singapore

WVWZZZ16ZGM007023

VEH No.: SLS2227H

Order Date:

21/02/18

Reg Date:

16/08/17

KM:

ENGINE NO:

21,232

VIN NO.: MODEL:

JETTA TSI (DSG) HIGHLINE HIDCMODEL NO.: 1634G7

	No.	DESCRIPTION	QTY	MOU	UNIT PRICE	DISC %	AMOUNT
	Labor				2020		280
03	B&P MECH	ELECT WIRING & MECH COMPONENT CHECK NETT	3	TU	280		
2	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
3	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	ST	80		80
4	B&P MACP LABOUR	LABOUR +1 Day repair end panel	3	UNIT	840		2,520
5	B&P MACP PAINT	SPRAY PAINT+ 2 panel	4	UNIT	800		3,200
6	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0		0
7	EXT00037	Tow SVC- Quality Recovery Services	1	UNIT	0		0
	item			0.00	4 000 04		1,022.21
8	5C6807421H GRU	REAR BUMPER	1	PCS	1,022.21		
9	505807433J	SPOILER	1	PCS	412.75		412.75
10	5C6827025E	REAR BOOT LID	1	PCS	1,222.87		1,222.87
11	5C6853687 739	NAME PLATE - JETTA	1	PCS	65.96		65.96
12	5C6853675APGQF	NAME PLATE - TSI	1	PCS	49.68		49.68
13	5C6853630F ULM	vw sign	10	PCS	108.42		108.42
14	5C6807863B	BUMPER CENTRE BRACKET	1	PCS	96.99		96.99
	1 Acres and the second	NUT	2	PCS	2.18		4.36
15	WHT007341	BR NUMBER PLATE PACKING	1	PCS	12.66		12,66
16	8D0853419D	SENSOR BRACKET	2	PCS	23.79		47.58
17	5C6919491E	ARTHORN (1997)	1	PCS	23.79		23.79
18	5C6919492D	SENSOR BRACKET	1	PCS	23.79		23.79
19	506919491D	SENSOR BRACKET			89.84		89.84
20	D 180KU2A1	2KADHESIVE	1	PCS	VIII VIII VIII VIII VIII VIII VIII VII		64.27
21	D 822150A1	BONDAGENT	1	PCS	64.27		161.14
22	5CU971104	SENSOR WIRE HARNESS		PCS	161.14		101.14

Remarks : CHINA TAIPING DIRECT SETTLEMENT

DOA: 03/02/2018

TP VEHICLE: PA7697Z

SURVEY BY: RASUL (LKK)

SPRAY REAR BUMPER, REAR BOOTLID, REAR PANEL & RHR FENDER

CHINA TAIPING CLAIMS REFERENCE : SNM18D00653

Service Order Confirmation

SERVICE ORDER NO: 18IP0501

CUSTOMER NAME: LIM SHU JUN

CV025691

Singapore

637 PASIR RIS DRIVE 1 #10-572

CUSTOMER NO.:

TELEPHONE NO.:

ADDRESS:

		-	Authorized Signatur	re .		i e	Custom	er
		On B	ehalf Of "COMPANY"			Certified Goods/	Service received	
						TAL AMOUNT		10,663.95
						T AMOUNT		697.64
					Yo	TAL.		9,966.31
OF REPAI	R WORKING DAYS IS 6 DAYS							
No.	DESCRIPT	TION		QTY	UOM	UNIT PRICE	DISC %	AMOUNT
EL	JETTA TSI (DSG) HIGHLINE	HIDOMODEL NO	D.: 1634G7					
10.:	WVWZZZ16ZGM007023	ENGINE N					67201.	
Date:	16/08/17	KM:	21,232				ea.	Ong Germaine
r Date:								

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	05 Feb 2018		05 Feb 2018 15:02 Edit Adj Rpt	S\$9,966.31 Edit Estimates	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	9,966.31 ew Rpt		Pending fo Report Cancel Cas	
1	Main	R	eference	Claim I	etails		Documents		Show All
CLAIM SU	BFOLDER DE	TAILS	C. Selvenson	SECTION AND PROPERTY AND POSSESSES.		[Created	by insurer]	A CONTRACTOR IN COLUMN	A CONTRACTOR OF THE PARTY OF TH
Insured:	LIM CHIN	YONG TRANSP	ORT PTE LTD, Co.	Reg. No.: 20111	637H				
Main Claimant:	LIM SHU	JUN, ID: S8721	741H						
Vehicle Reg No.:	SLS222	7		Date	of Loss:		3 20:00 - :59 and 17 Days From LT	A Reg Date (Man Yr)]
Claim Type:	TP / SNI	418D00653C02		Policy Note	/Cover No.:	DMB1SN1555931702 (Third Party Only)			
Vehicle Reg No. (Insured):	PA7697Z			Policy (Clair	No. nant):				
				Exce	ss:	S\$0.00			
Repairer:	Volkswag Tuas - Tel		pore (macpherso	n) (HQ) Volkswag	en Cent	re Singapore	(Macpherson), 1 Kar	npong Ampat	, 368314
Handling Insurer:	China Tai	ping Insurance	(Singapore) Pte. I	Ltd. (HQ) - Tel: 6	389 611	1 [Handled	d by Irene Tay Hui l	Ping - 63898	6192]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	256-3561 [Hand	lled by X	ING GUO Q	IANG] [Final R	pt due 14/	02/2018]
Adj Asg. Remarks:	EST \$987	3.71, ASSIGN LKK	AS SJE.		75				- AN - 1 150
ASSOCIAT	ED MAIL RE	CEIVED					View /	All Compo	se Case Mai
There are n	o mail for this	case.							
ALL ASSO	CIATED TAS	sks [⊟]			13	View All 5	Search Tasks Crea	te New Task	Complete
hwares earson	en merenamen		Group Subject	ct Handler		ned By	Completed On	Created 0	
Due Date	Priority	type task	Group Subject	ct nanoier	Assign	ied by	Completed on	created 0	n Done

Claim Documents

*SLS2227 (SNM18D00653C02)

[PA7697Z]

TP

LIM SHU JUN

Feb 2 2018 8:00PM

[LIM CHIN YONG TRANSPORT PTE LTD]

Volkswagen Centre Singapore (macpherson)

Asse	essment Reports		1 per p	age 🔻	~
Vo	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	Print
1	05/02/18 10:28	Accident Statement	0	Load HTM	
	t/Y		3 per p	age V	V
	tos/Images	UCB Engineering Pte Ltd (HQ)	- Louis and Control of the Control o	Thumbnail	-
No	Finalized On	Accident Photo	O	Load JPG	V
1	05/02/18 10:24	[Linked Accident Report Documents]		1 100	-
2	05/02/18 10:24	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
3	05/02/18 10:24	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
4	05/02/18 10:24	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
5	05/02/18 10:24	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
6	05/02/18 10:24	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
7	05/02/18 10:24	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
8	05/02/18 10:24	Police Report [Linked Accident Report Documents]	0	Load JPG	✓
9	05/02/18 10:24	Police Report [Linked Accident Report Documents]	0	Load JPG	V
10	05/02/18 10:24	Police Report [Linked Accident Report Documents]	0	Load JPG	✓
11	05/02/18 10:24	Driving License [Linked Accident Report Documents]	0	Load JPG	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnai	Print
1	16/04/18 16:02	General View	0	Load JPG	V
2	16/04/18 16:02	General View	0	Load JPG	V
3	16/04/18 16:02	General View	0	Load JPG	V
4	16/04/18 16:02	General View	0	Load JPG	V
5	16/04/18 16:02	General View	0	Load JPG	V
6	16/04/18 16:02	General View	0	Load JPG	V
7	16/04/18 16:02	General View	0	Load JPG	V
8	16/04/18 16:02	General View	0	Load JPG	V
9	16/04/18 16:02	General View	0	Load JPG	✓
10	16/04/18 16:02	General View	0	Load JPG	V
1000	16/04/18 16:02	General View	0	Load JPG	V
11	16/04/18 16:02	General View	0	Load JPG	V
12		General View	0	Load JPG	V
13	16/04/18 16:02	General View	0	Load JPG	V
14	16/04/18 16:02	General View	0	Load JPG	-
15	16/04/18 16:02		0		-
16	16/04/18 16:02	General View	0	_	-
17	16/04/18 16:02	General View General View	0		-

	sessment Reports		1 per	page 🔻	V
No 19	Finalized On 16/04/18 16:02	UCB Engineering Pte Ltd (HQ) General View		Thumbnail	-
3.0		2500000 C 650000	0	Load JPG	V
20	16/04/18 16:02	General View	0	Load JPG	V
21	16/04/18 16:02	General View	6	Load JPG	V
22	16/04/18 16:02	General View	0	Load JPG	V
23	16/04/18 16:02	General View	0	Load JPG	V
24	16/04/18 16:02	General View	0	Load JPG	V
25	16/04/18 16:02	General View	0	Load JPG	V
26	16/04/18 16:02	General View	0	Load JPG	V
27	16/04/18 16:02	General View	0	Load JPG	V
28	16/04/18 16:02	General View	0	Load JPG	V
29	16/04/18 16:03	General View	0	Load JPG	V
30	16/04/18 16:03	General View	0	Load JPG	V
31	16/04/18 16:03	General View	0	Load JPG	V
32	16/04/18 16:03	General View	0	Load JPG	V
33	16/04/18 16:03	General View	0	Load JPG	V
4	16/04/18 16:03	General View	0	Load JPG	₹ X
5	16/04/18 16:03	General View	0	Load JPG	₹
6	16/04/18 16:03	General View	0	Load JPG	₹ V
7	16/04/18 16:03	General View	0		-
8	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
9	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
0	16/04/18 16:04	Reinspection Photo		Load JPG	V
1	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
2	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
3	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
4	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
5	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
6	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
7	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
8	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
9	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
0	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
1	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
2	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
3	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
,	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
5	16/04/18 16:04		0	Load JPG	V
	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
,	16/04/18 16:04	Reinspection Photo	0	Load JPG	¥
	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
		Reinspection Photo	0	Load JPG	✓
-	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
8	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
	16/04/18 16:04	Reinspection Photo	0	Load JPG	☑
	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
	16/04/18 16:04	Reinspection Photo	0	Load JPG	\mathbf{V}
	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
	16/04/18 16:04	Reinspection Photo	0		✓
	16/04/18 16:04	Reinspection Photo	0		V

Ass	essment Reports		1 per p	oage 🔻	V
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	Print
69	16/04/18 16:04	Reinspection Photo	0	Load JPG	~
70	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
71	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
72	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
73	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
74	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
75	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
76	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
77	16/04/18 16:04	Reinspection Photo	0	Load JPG	V
78	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
79	16/04/18 16:04	Reinspection Photo	0	Load JPG	✓
Doc	cumentation		1 per	page 🔻	V
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	05/02/18 15:00	REPAIR EST	0	Load PDF	
2	05/02/18 15:00	OI GIA REPORT	0	Load PDF	
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	Print
1	05/02/18 10:25	Sketch Plan [Linked Accident Report Documents]	0	Load JPG	✓
2	05/02/18 10:25	Sketch Plan #2 [Linked Accident Report Documents]	0	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/04/18 08:23	Supplementary	0	Load PDF	

Linked Accident Report Documents

			View	View in Brows	ser 🗸
Ass	essment Reports		1 per p	age 🔻	V
No:	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	Print
1	05/02/18 10:28	Accident Statement	0	Load HTM	
Pho	otos/Images		3 per p	age 🔻	V
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	-
1	05/02/18 10:24	Accident Photo	0	Load JPG	V
2	05/02/18 10:24	Accident Photo	0	Load JPG	V
3	05/02/18 10:24	Accident Photo	0	Load JPG	☑
4	05/02/18 10:24	Accident Photo	0	Load JPG	✓
5	05/02/18 10:24	Accident Photo	0	Load JPG	V
6	05/02/18 10:24	Accident Photo	0	Load JPG	✓
7	05/02/18 10:24	Accident Photo	0	Load JPG	V
8	05/02/18 10:24	Police Report	0	Load JPG	V
9	05/02/18 10:24	Police Report	0	Load JPG	V
10	05/02/18 10:24	Police Report	0	Load JPG	V
11	05/02/18 10:24	Driving License	0	Load JPG	✓
Doc	cumentation		1 per (age 🔻	V
No	Finalized On	UCB Engineering Pte Ltd (HQ)		Thumbnail	-
1	05/02/18 10:25	Sketch Plan	0	Load JPG	☑
2	05/02/18 10:25	Sketch Plan #2	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
			10123

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	V

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18002363/R1RD3E2

Date:

17/04/2018

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Policy No: Pte. Ltd.

DMB1SN1555931702

Claimant Vehicle

Date of Loss:

SLS2227

Insured Vehicle

Nature of Claim: TP

PA7697Z

No:

No:

Claim No: SNM18D00653C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

02/02/2018

Reg No:

SLS2227

Make & Model:

VOLKSWAGEN JETTA, 1.4 TSI (A)

Engine No:

CAXF81579

19060 km

Reg. Date:

16/08/2017 (Man. Year: 2015)

Chassis No: Odometer: WVWZZZ16ZGM007023

Colour:

Red 1390 cc

Engine Capacity: Market Value/New Car

N/A

Price:

W/O

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): CONDITION OF TYRES Yes Engine Modification:

Pre-accident Condition:

Front Tyre Size: Front Left Side: 225/45 R17

Rear Tyre Size:

225/45 R17 Goodyear 6 mm

Front Right Side:

Goodyear 6 mm Goodyear 6 mm Rear Left Side: Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,074.19	3,486.31	587.88	14.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,480.00	6,480.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,554.19	9,966.31	587.88	5.57
+ GST 7.00/7.00% (S\$)	738.79	697.64	41.15	5.57
Nett Amount (S\$)	11,292.98	10,663.95	629.03	5.57

INSPECTION

Date of Assignment:

05/02/2018

Date Inspected:

07/02/2018 Inspected At:

Volkswagen Centre Singapore

(macpherson) (HQ)

Volkswagen Centre Singapore (Macpherson), 1 Kampong Ampat

Singapore 368314

Estimated Period of Repair:

6.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 17/4/2018

Adjuster: XING GUO QIANG Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2018)

VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLS2227)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE	Scratched	80.00 FS	*80.00FS
2	1		*BUMPER FOAM	Serviceable	142.24 FS	*- FS
3	1		*REAR REINFORCEMENT	Serviceable	445.64 FS	*-FS
4	1		*REAR BUMPER	Deformed	1,022.21 FS	*1,022.21 FS
5	1		*SPOILER	Scratched	412.75FS	*412.75FS
6	1		*REAR BOOT LID	Bent	1,222.87FS	*1,222.87 FS
7	1		*VW SIGN	Necessary	108.42 FS	*108.42 FS
8	1		*NAME PLATE - TSI	Necessary	49.68 FS	*49.68 FS
9	1		*NAME PLATE - JETTA	Necessary	65.96 FS	*65.96 FS
10	1		*BUMPER CENTRE BRACKET	Cracked	96.99 FS	*96.99 FS
11	2		*NUT	Necessary	4.36 FS	*4.36 FS
12	1		*RR NUMBER PLATE PACKING	Necessary	12.66 FS	*12.66 FS
13	2		*SENSOR BRACKET	Necessary	47.58 FS	*47.58 FS
14	1		*SENSOR BRACKET	Necessary	23.79FS	*23.79FS
15	1		*SENSOR BRACKET	Necessary	23.79 FS	*23.79FS
16	1		*2KADHESIVE	Necessary	89.84 FS	*89.84 FS
17	1		*BONDAGENT	Necessary	64.27 FS	*64.27 FS
18	1		*SENSOR WIRE HARNESS	Cut	161.14 FS	*161.14FS
F=Fra	nchise	part. S=SpcNe	tt.	_		101.141.0
				Total Parts (S\$)	4,074.19	3,486.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Lab.Type	Repairer's	Amoun
	2 2 3 10 10 10 10 10 10 10 10 10 10 10 10 10	
		Amoun
New	2.520.00	2 520 04
New		2,520.00 3,200.00
New	480.00	480.00
New	280.00	280.00
Gross Labour Cost (S\$)		6,480.00
	New New	New 3,200.00 New 480.00 New 280.00 ur Cost (S\$) 6,480.00

< END OF ESTIMATES >