

ASS. REC. BY:

REF: CS/LCR 18002367 / Svd3 n2 Special Instruction

Survivor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Naor Maniessa

of LCR

Date/Time: 6/2/18 @ 11:51am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 5705S

Insured:

SLF 992M

at Workshop m/s

Seah Motor

Tel:

62694284 9627 5090

of

Blk 2 Kranji Loop

Policy No:

09999503

Claim No:

2911348870 SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/2/2018

11:30am @ 7/2/18

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

1:52pm @ 6/2/18

Person Consisted:

Mr. Samuel

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJY 5705S-X

SLF 992M-X

25/6/18

LS \$1850 confirmed by email (Ref 3710.50, 6610)

REF: LCR

ASSIGNMENT

From: _____ Date: **7/2/18**

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **SJY 5705S**

at Workshop mis: **Seah Motor**

of **Blk 2 Kranji Loop**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

after 11:30am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bel. or Market Value: _____

ICAD Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS' up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJY 5705S** Reg: **14/4/2007**

Type: ☒ Car / M/Cycle / Bus/Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: **Mercedes Benz** C/SOK Reg: **1796**

Colour: **Black** A/C Insured: Std / Nil / NA

So Reading: **116427** T Radio Insured: Std / Nil / NA

Eng No: _____

C No: **WDD2040462J1244103**

Gen Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/40 ZR18**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

| Front | | Rear | |
|--------|---------------|--------|-----------------|
| R.Bal. | 6 mm | R.Bal. | 6 mm |
| L.Bal. | 6 mm | L.Bal. | 6 mm |
| D.O.A | 3/2/18 | D.O.A | 7/2/2018 |

Survey held at: **Seah Motor**

Des. of Damages: Fnt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time Action / Instruction

RECEIVED 25 JUN 2018

Date/Time File Pass to: ☐ : Prel. ReportDate/Time File Return to: ☐ : Final ReportDays Of Repair: **3**Resurvey No. of Trips: **1**

Survey Fee

Transportation

Labour

Other

Total

Report Format: _____

Lump Sum / I.B.R: _____

Add Fee: ☐

Site Insp: \$

Intercept: \$

Tech: \$

Access: \$

250

00

250

Survey Department Check List (Case Handler)

Reference No.: CS | LCR 18003367 | Svdb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

| | | Y-Date | N-Date | Y-Date | N-Date |
|---|---------------------------------------|--------|--------|--------|--------|
| C | Reference No. | ✓ | | | |
| C | Customer Code | | | | |
| N | Assign From | | | | |
| C | Assign Date | ✓ | | | |
| C | Veh No (Inspected) | ✓ | | | |
| C | Veh No (Insured) | ✓ | | | |
| C | D.O.A | ✓ | | | |
| C | Policy No | ✓ | | | |
| C | Claim No | ✓ | | | |
| C | Insurance Authorisation (CA /REV/REP) | | | | |
| C | Report Type | ✓ | | | |
| C | Weekend Charges | | | | |
| N | Survey held at/Repairer | ✓ | | | |
| C | Excess | | | | |

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

| | | | | | |
|---|------------------------|---|--|--|--|
| C | Vehicle No | ✓ | | | |
| C | Regn Month/Year | ✓ | | | |
| N | Vehicle Type | ✓ | | | |
| N | Make & Model | ✓ | | | |
| C | Engine Capacity. (C.C) | ✓ | | | |
| N | Colour | ✓ | | | |
| C | Odometer. (Sp.Reading) | ✓ | | | |
| C | Chassis No | ✓ | | | |
| N | General Condition | ✓ | | | |
| N | Steering | ✓ | | | |
| N | Brake | ✓ | | | |
| N | Modification (Modi) | ✓ | | | |
| C | Tyre Size | ✓ | | | |
| N | Tyre Make | ✓ | | | |
| C | Tyre Balance | ✓ | | | |
| C | Date of Inspection | ✓ | | | |
| N | Survey held | ✓ | | | |
| N | Des.of Damages | ✓ | | | |

(2) System - (Views/Merimen)

| | | | | | |
|---|--------------------------------------|---|--|--|--|
| C | Damaged Vehicle Photographs Uploaded | ✓ | | | |
|---|--------------------------------------|---|--|--|--|

(3) Workshop Estimate/Assignment Form

| | | | | | |
|---|---|---|--|--|--|
| N | ALL Parts condition | ✓ | | | |
| C | Market Value for OD cases | | | | |
| C | Estimate Repair Cost for PRI (RSI, TMI, MSIG) | | | | |
| C | Days of repair | ✓ | | | |
| C | Finalised Amount | ✓ | | | |
| C | Re-inspection Cases to Finalize within 5 Days | | | | |

(4) System - (Views/Merimen)

| | | | | | |
|---|-------------------------|---|--|--|--|
| C | Resurvey photo Uploaded | ✓ | | | |
|---|-------------------------|---|--|--|--|

Check By: VERON 25/6/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|-----------------|---------------------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD | | | Ref : CS/LCR18002367/Svd3 | |
| 78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120 | | | Date : 06-02-2018 |  |
| | | | Code : LCR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLF 992M | Veh. Inspected | SJY 5705S | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | | Excess (\$) | 0.00 | |
| Assign From | NOOR MARISSA | Assign Date | 06/02/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 03/02/2018 | Inspection Date | | |
| Survey held at | SEAH MOTOR TRADING CO. BLK 2 KRANJI LOOP #01-06 . SINGAPORE 739538 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 June 2018 12:22 PM
To: 'Seah Motor - Samuel'
Cc: SUR
Subject: RE: SJY 5705S-DOA: 3/2/2018

Dear Samuel,

Noted with thanks.

Final invoice and all supporting documents sent over to AIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Seah Motor - Samuel [mailto:seahmotor@gmail.com]
Sent: Friday, 22 June 2018 7:28 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: SJY 5705S-DOA: 3/2/2018

Attn :: Veron Chen,

We accepted the offer lump sum \$1850.00 @ 3 days. Thanks.

Sorry for the late reply.

Best Regards,

Samuel Seah

Seah Motor Trading Co.

Blk 2 Kranji Loop #01-06

Singapore 739538

Email: seahmotor@gmail.com

Tel: 63650428

HP: 96275090

On Wed, Jun 20, 2018 at 1:57 PM, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Sir,

WITHOUT PREJUDICE

Re-offer Lump Sum \$1850 @ 3 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 13 June 2018 4:24 PM

To: 'seahmotor@gmail.com' <seahmotor@gmail.com>

Cc: SUR <sur@lkkauto.com>

Subject: SJY 5705S-DOA: 3/2/2018

Dear Sir,

WITHOUT PREJUDICE

Offer Lump Sum \$650/- @ 3 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Tuesday, 6 February 2018 11:51 AM
To: 'assignments@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene
Subject: aigencrypt - Pre repair inspection request - SJY5705S VS SLF992M (OI) DOA: 3/2/2018
Attachments: FaxCBBA.TIF; FaxDDB8.tif

Hi,

Please refer to the enclosed request from **VISION LAW LLC**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SIU-HSIEN
PAUL YAP TAI SAN
ANJALLI DYO MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓ HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓ (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SJY 5705 S (PM)
Your Ref: SLF 992 M

6 February 2018

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

BY FAX (68357416) & EMAIL

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SJY 5705 S & SLF 992 M ON 03 FEBRUARY 2018
AT/ALONG JALAN TODAK AT ABOUT 0055 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : M/s Seah Motor Trading Co.
Block 2 Kranji Loop
#01-06
Singapore 739538
Contact : Mr. Samuel @ 62694284 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M
(HEAD OFFICE)

cc: SJY 5705 S – By fax: 63678421 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|--------------------------------|--------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 5860Z |
| Vehicle Details | |
| Vehicle No.: | SJY5705S |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 08 Feb 2018 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | C180K |
| Primary Colour: | Black |
| Manufacturing Year: | 2008 |
| Engine No.: | 27195231168007 |
| Chassis No.: | WDD2040462A244103 |
| Maximum Power Output: | 115.0 kW (154 bhp) |
| Open Market Value: | \$37,090.00 |
| Original Registration Date: | 14 Apr 2009 |
| First Registration Date: | 14 Apr 2009 |
| Transfer Count: | 3 |
| Actual ARF Paid: | \$37,090.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 13 Apr 2019 |
| PARF Rebate Amount: | \$20,399.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 13 Apr 2019 |
| COE Category: | B - Car (1601cc & above) |

| | |
|-----------------------------|--------------------|
| COE Period(Years): | 10 |
| QP Paid: | \$7,501.00 |
| COE Rebate Amount: | \$885.00 |
| Total Rebate Amount: | \$21,284.00 |

The information contained herein is correct as at 08 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/02/2018 12:48
Date Of Accident 03/02/2018 00:55
Exact Location Of Accident JLN TODAK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJY5705S
Insured/Policyholder
Name Of Registered Owner CARSZONE LEASING PTE LTD
Co Reg No 201725860Z
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-92237799

Vehicle Particulars

Manufacturer MERCEDES-BENZ
Model C180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
PRIVATE HIRE

Vehicle Category

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5094681218(CLASSIC)

Cover Note Number

Driver

Name of Driver BOO LIJUN
NRIC No S8848953E
Date Of Birth 05/12/1988
Occupation INDOOR
Date Of Driving Pass 29/09/2008
Driving Experience 9 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-92237799
Fax Number
Contact Number
Email Address NOEMAIL

Address BLK 442B FAJAR RD #11-20
 Postcode 672442
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - RENTAL
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF992M
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 03 FEB 2018
1303 MRS

IDAAC BUKIT RATOK (VAO)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON DATED 3 FEB 2018, 12:56 AM

I WAS TURNING IN FROM A INTERSECTION FROM UPPER THOMSON ROAD TOWARDS SALAN TODAK SLOWLY WHEN THE TRAFFIC LIGHT TURN GREEN ~~AND~~ AT MY FAVOUR. JUST AS I'M ENTERING SALAN TODAK A VEHICLE KIA CERATO (SLF992M) DRIVEN BY NG GUAN HAO (NRIC 69006094E) WHICH WAS STOPPING AT MINOR ROAD (UPPER THOMSON RD) ~~BE~~ BEHIND A GIVE WAY LINE IN FRONT OF A KTV PUB "TALK CORK SING SONG" SUDDENLY DROOF OUT ~~AND~~ HIT MY REAR PASSENGER DOOR. NOBODY IS INSURE DURING THE ACCIDENT - THAT'S ALL.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 3 FEB 2018
13:03 PM

IDAC BUKIT BATOK (VAC)
511 7111

Reporting Centre Personnel's Signature
Name:
NRIC/RIN No.:

CONFIDENTIAL



NOTICE OF COMPLIANCE

1. This is to inform that Boo Li Jun NRIC S8848953E, HP 92237799 residing at Blk 442B Fajar Road #11-20 has report to the Police a non-injury traffic accident which occurred at Jalan Todak Road on 03/02/2018 at 0056hrs involving the following vehicles:

I SJY5705S (Black, Mercedes, C180)

II SLF992M (Black, Kia Cerato)

2. If the accident was reported to Police within 24 hours of its accident occurrence, He/she therefore has complied with Sec 84(2) of the Road Traffic Act, 276

Rank/Name of Issuing Officer: SGT Kaize Chua

Date : 03/02/2018

S/D Ref : 25

Police Post/ Unit : Bukit Panjang NPC

| | | |
|-----------|---|--------------------------------------|
| Original | - | To issue to informant |
| Duplicate | - | To be retained at NPC or Police Post |

CONFIDENTIAL

SEAH MOTOR TRADING CO.

BLK 2 KRANJI LOOP #01-06

SINGAPORE 739538

Tel No. : 63650428 Fax No. : 63678421

E-Mail : seahmotor@gmail.com

Buss. Reg. No. : 288020/00J

AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 SHENTON WAY #07-16 SINGAPORE 079120

Attention : Motor Claim Department
Contact : 64193000 Fax No. : 64153723

Estimate : ES000261

Date : 05/02/2018

Vehicle Num. : SJY5705S

Make/Model : MERC C180-2008

Chassis/Eng# : WDD2040462A244103/2719523116

Accident Date : 03/02/2018

Claim No. :

Reference : Y18JAN/SJY5705STP

Policy No. : 5094681218(CLASSIC)

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|---------------------------------------|------------|------------|
| | | LIST ITEMS : | | |
| 1. | 1 | REAR DOOR - LH <i>170/341 1645.32</i> | | 1,980.00 |
| 2. | 1 | REAR DOOR PROTECTOR LH <i>✓ NEC</i> | | 120.00 |
| 3. | 1 | FRONT DOOR - LH <i>R</i> | | 1,950.00 |
| 4. | 1 | FRONT DOOR PROTECTOR LH <i>✓ NEC</i> | | 120.00 |
| 5. | 1 | SIDE SKIRT LH <i>R</i> | | 580.00 |
| | | List Total S\$: <i>next 10%</i> | | 4,750.00 |
| | | 5.00% Discount S\$: | | 237.50 |
| | | | | 4,512.50 |

LABOUR :

| | | |
|--|-----|----------|
| TO DISMANTLE/REPLACE DOOR AND TRIMBOARD AND SKIRTING | 200 | 400.00 |
| TO FACILITATE THE REPAIR AND THE PANEL BEATING | | |
| TO KNOCKOUT AND STRAIGHTEN AND THE DOORS | 400 | 500.00 |
| TO PUTTY AND SPRAY PAINTING REAR DOOR X 2 AND SIDE SKIRTING AND PROTECTORS | 40 | 150.00 |
| TO APPLY TURF COATING TO THE WELDED AND REPAIR PARTS | | |
| Labour Total S\$: | | 1,050.00 |

SingDollars : Five Thousand Five Hundred Sixty-Two & Cents Fifty Only

E. & O.E.

Total S\$: 5,562.50

=====


for SEAH MOTOR TRADING CO.

Sebastian
7/2/2018

- Lump Sum Repair
- Photo After Paint
90036121

Sebastian@lkkauto.com


12/2/18

3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR18002367/SVD3N2

Date: 28/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995053
 Claimant Vehicle No: SJY5705S Insured Vehicle No: SLF992M
 Date of Loss: 03/02/2018 Nature of Claim: TP Claim No: 2911348870SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJY5705S Engine No: 27195231168007
 Make & Model: MERCEDES-BENZ C180, 1.6 (A) Chassis No: WDD2040462A244103
 Reg. Date: 14/04/2009 (Man. Year: 2008) Odometer: 116427 km
 Colour: Black
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 4,512.50 | 1,696.79 | 2,815.71 | 62.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,050.00 | 640.00 | 410.00 | 39.05 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,562.50 | 2,336.79 | 3,225.71 | 57.99 |
| Approved Total (Overridden) (S\$) | | 1,850.00 | | |
| Nett Amount (S\$) | 5,562.50 | 1,850.00 | 3,712.50 | 66.74 |

INSPECTION

Date of Assignment: 06/02/2018
 Date Inspected: 07/02/2018 Inspected At: Seah Motor Trading Co (Kranji)
 Blk 2 Kranji Loop #01-06
 Singapore 739538

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------|-------------|--|-----------------|
| 1 | 1 | | *REAR DOOR-LH | Dented/Bent | 1,980.00 FN | *1,645.32 FN |
| 2 | 1 | | *REAR DOOR PROTECTOR LH | Necessary | 120.00 FN | *120.00 FN |
| 3 | 1 | | *FRONT DOOR-LH | Repair | 1,950.00 FN | *- FN |
| 4 | 1 | | *FRONT DOOR PROTECTOR LH | Necessary | 120.00 FN | *120.00 FN |
| 5 | 1 | | *SIDE SKIRT LH | Repair | 580.00 FN | *- FN |
| | | | | | Sub Total (S\$) | 4,750.00 |
| | | | | | - Nett Item Discount on N Items 5.00/10.00% (S\$) | 237.50 |
| | | | | | Total Parts (S\$) | 4,512.50 |
| | | | | | | 1,885.32 |
| | | | | | | 188.53 |
| | | | | | | 1,696.79 |

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|---|----------|------------|--------|
| Labour Items | | | | |
| 1 | TO DISMANTLE/REPLACE DOOR AND TRIMBOARD AND SKIRTING TO FACILITATE THE REPAIR AND THE PANEL BEATING TO KNOCK OUT AND STRAIGHTEN AND THE DOORS | New | 400.00 | 200.00 |
| 2 | TO PUTTY AND SPRAY PAINTING REAR DOOR X2 AND SIDE SKIRTING AND PROTECTORS | New | 500.00 | 400.00 |
| 3 | TO APPLY TURF COATING TO THE WELDED AND REPAIRS PARTS | New | 150.00 | 40.00 |
| Gross Labour Cost (S\$) | | | 1,050.00 | 640.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >