

DAR & days.

23/03/2018

ASS. REC. BY:

REF: CS3/ALG18002378/ W d342

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

6/2/18 @ 10:11am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBJ 8938R

Insured:

SLV 197H

at Workshop m/s

SS Motorring

Tel:

6298 9596

of

Blk 1084 Serangoon Rd

Policy No:

Claim No:

045558338586

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/1/18

CA / REV / REP. / REV 24 HRS

wp/

7/2/18

H.O.D. Endorsement:

Date/Time:

10:11am @ 6/2/18

Person Contacted:

Samuel

Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	FBJ 8938R - X
	SLV 197H - X

REF: AIG

ASSIGNMENT

From: Date: 7/2/18

Estimated Cost:

OO (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBJ 8938R
at Workshop/mis: SS Motoring
of: Blk 1084 Serangoon Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
NS	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP: / 24 HRS w/p

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBJ 8938R Reg: 114

Type: M/Car / ~~M/Cycle~~ / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: SYM. 171

Colour: Black / Silver / A.D. Insured: Std / Nil / NA

Sp. Reading: 41576 T-Ratio: Insured: Std / Nil / NA

Eng No:

C.No: RFG L1F18WYTES01555 3

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / ~~3 Rim~~ STD A/Rim or

Tyre Size: F: 110/90-13

R: 130/70-12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Michelin

Front

Rear

F.Bal: 3 mm R.Bal: 4 mm

L.Bal: mm R.Bal: mm

D.O.A: 3.1.18 DOI: 7/2/2018

Survey held at: As Above

Des. of Damages: Frt / Rear / O/S / N/S / U/O / Rooftop or

The U/O / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

11/4

Submit DAR report.

RECEIVED 11 APR 2018

Date/Time: File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time: File Return to?

2:

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Photographer

8 x 10

Excess

Other

TOTAL

Add Fee:

☐

Site Insp

\$

☐

Interview

\$

☐

Tech. File

\$

☐

Weekend

\$

Report Format: DAR

Lump Sum / I.B.I: \$


180

20

200

Your password will expire in 5 days. [Click here to change it.](#)

- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLV197H AND FBJ8938R ON 31/01/2018 ; Our Ref: 18-A32-8996-
VL.ts.ec

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 6/2/2018 10:11:48 AM
Attachments:  FaxD342.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Elaine Chong [<mailto:elaine@legaloptions.biz>]
Sent: Monday, February 05, 2018 3:37 PM
To: Abu Kassim, Noor Mariesa
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLV197H AND FBJ8938R ON 31/01/2018 ; Our Ref: 18-A32-8996-VL.ts.ec

Dear Mariesa,

Our client has rejected your list of surveyors.

We provide you herewith our client's list of surveyors: -

	Surveyor	Contact Person
1.	OH APPRAISAL SERVICES	OH HAN CHEONG
2.	PAR AUTOMOTIVE CONSULTANCY	B J LOI
3.	UNITED APPRASAL AND MANAGEMENT PTE LTD	MARC
4.	AUTO PERFORMANCE APPRAISAL	LEK BOON HWEE
5.	SINCERE APPRAISAL SERVICES	DAVE CHANG

6.	L H TEO	MR TEO
7.	PRO-OPTION SERVICES	LIAW CHEONG SAN

If we do not hear from you within 2 days of this email, our clients shall deem that you have agree that the surveyor appointed by our clients shall be our single joint expert for this matter.

Please find the the venue for inspection as follows:-

M/s SS Motoring

Blk 1084 Serangoon Road, Singapore 328186

Person to contact : Sam - 6298 9596 (Please call to make appointment before going down)

Regards,

Elaine

Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513 2800 DID (65) 6513 2806 Fax (65) 6438 8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

LEGAL OPTIONS LLC

ADVOCATES & SOLICITORS

Mediators - Commissioners for Oaths - Notary Public

法商律師事務所

Motor Accident & Personal Injuries

Tel: (65) 6513 2800 Fax: (65) 6438 8275

Commercial, Litigation, Property, Trust & Estate, Family

Tel: (65) 6438 8039 Fax: (65) 6734 5230

We do not accept service of Court Documents by fax

Your Ref : SLV 197H

Our Ref : 18-A32-8996-VL.ts.ec

5th February 2018

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

78 Shenton Way #07-16

AIG Building

Singapore 079120

(Attn: Motor Claims Department)

Dear Sirs,

CLAIMANT : TAY CHEE WAH

ACCIDENT INVOLVING FBJ 8938R & SLV 197H ALONG PAYA LEBAR ROAD
TOWARDS KATONG ROAD ON 31.01.2018

We are instructed by Tay Chee Wah to notify you of a road traffic accident on 31st January 2018 at about 18:15 hours along Paya Lebar Road towards Katong Road involving our client's vehicle registration number FBJ 8938R and vehicle registration number SLV 197H driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully



Encl

Cc: Clients (FBJ 8938R)

Directors

Joan Lim Pheek Heon LL.B (Hons)

Victor Leong Wai Meng LL.B (Hons)

Teo Lip Hua Benedict LL.B (Hons) LL.M

Secretary's DID: 6513 2806

Direct Fax: 6438 8275

(Email: clntur@legaloptions.biz)

Mailing Address for Accident Claims

Documents Support:

23 Kaki Bukit Avenue 4 #01-01 South Wing,

Singapore 415933

BY FAX: 6835 7416/POST

Enquire Transfer Fee

Vehicle Details

Vehicle No.: FBJ893BR
 Vehicle Type: P01 - Passenger Scooter
 Vehicle Attachment 1: No Attachment
 Vehicle Scheme: Normal
 Vehicle Make: SYM
 Vehicle Model: JOYRIDE 200I EVO CVT
 Chassis No.: RFGLF18WYES015553
 Propellant: Petrol
 Engine No.: KB220246
 Engine Capacity: 171 cc
 Maximum Power Output: -
 Maximum Laden Weight: 315 kg
 Unladen Weight: 155 kg
 Year Of Manufacture: 2014
 Original Registration Date: 06 Dec 2014
 Lifespan Expiry Date: -
 COE Category: D - Motorcycle
 Quota Premium: \$4,089.00
 COE Expiry Date: 05 Dec 2024
 Road Tax Expiry Date: 05 Dec 2018
 Inspection Due Date: 05 Dec 2018
 Intended Transfer Date: 11 Apr 2018
 CO2 Emission: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			

You may print this page for reference.

OK

Print

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2276G

Vehicle Details

Vehicle No.: FBJ8938R
Vehicle to be Exported: No
Intended De-registration Date: 11 Apr 2018
Vehicle Make: SYM
Vehicle Model: JOYRIDE 200i EVO CVT
Primary Colour: Silver
Manufacturing Year: 2014
Engine No.: KB220246
Chassis No.: RFGLF18WYES015553
Maximum Power Output: -
Open Market Value: \$2,602.00
Original Registration Date: 06 Dec 2014
First Registration Date: 06 Dec 2014
Transfer Count: 1
Actual ARF Paid: \$391.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 05 Dec 2024
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$4,089.00
COE Rebate Amount: \$2,719.00
Total Rebate Amount: \$2,719.00

The information contained herein is correct as at 11 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/02/2018 10:24
Date Of Accident	31/01/2018 18:15
Exact Location Of Accident	PAYA LEBAR ROAD TOWARDS KATONG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBJ8938R
Insured/Policyholder	
Name Of Registered Owner	TAY CHEE WAH
NRIC No	S1402276G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96150658
Alternative Phone No	OTHERS-96150658

Vehicle Particulars

Manufacturer	SYM
Model	JOYRIDE 200I EVO CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	MSCN: 60774720 (TPFT)
Cover Note Number	

Driver

Name of Driver	TAY CHEE WAH
NRIC No	S1402276G
Date Of Birth	16/06/1959
Occupation	INDOOR
Date Of Driving Pass	04/05/1990
Driving Experience	27 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96150658
Fax Number	
Contact Number	OTHERS-96150658
Email Address	NOEMAIL

Address	BLK 4 JOO CHIAT ROAD #10-1175
Postcode	420004
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JOO CHIAT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: 267 ONAN ROAD , POSTCODE: 424773 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3459999 - FAX NO: 64474181
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV197H
Vehicle Make/Model/Colour	NISSAN QASHQAI 1.2 DIG-T CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAY CHEE WAH
Approximate Age	
Injuries Sustain	RIGHT KNEE, RIGHT TOE, RIGHT INDEX FINGER
Injured person in which vehicle?	FBJ8938R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

- 2 FEB 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305


Email: feedback@singnet.com.sg

Name:

NRIC/FIN No:

SKETCH PLAN

00 - FBJS938R
 [X] - SLV197H



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Ref:

Q1

Police Report

DECLARATION

✓We decide the grouping patterns are true in every respect

- 2 FEB 2018

Email: yackb@singnet.com.sg

Tel: 67416697 Fax: 67492305

Singapore 415933

23 Kaki Bukit Ave 4

IDAC KAKI BUKIT (VAC)

May 2002

01)Identified 02)Disturbed 03)Cracked 04)Cm 05)Cracked
 06)Churned 07)Shaded 08)Structural 09)Broken 10)Necessary
 11)Missing 12)Torn 13)Unconfirmed 14)Not Working

4. Not Consistent (NC)

Vehicle No:

FBI 8938 R

Motorcycle			CON	AC	Qty
NAC	INC	Item			
1001	991886	Front Number Plate	NFC	✓	
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	DD	SCR	✓
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube			
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing	CRA	WP	✓
3017	992130	Front Windshield		SCR	✓
3018	992134	Front Wing Mirror			
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp		SCR	✓
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH		SCR	✓
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever		SCR	✓
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower (RHF)		SCR	✓
		RH centre lower		SCR	✓
		- Fairing			
		RHS Wing Mirror		SCR	✓

[illegible]

Assessor: _____

3 Days Report

Devin Corp

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Feb 2018 Edit Reg		06 Feb 2018 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Chi Keat Sung, ID: S26203891		
Main Claimant:	TAY CHEE WAH, ID: S1402276G		
Vehicle Reg. No.:	FBJ8938R	Date of Loss:	31/01/2018 18:00 - :59 [37 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0455583385SG	Policy/Cover Note No.:	1700090984 (Comprehensive)
Vehicle Reg. No. (Insured):	SLV197H	Policy No. (Claimant):	
		Excess:	
Repairer:	Ss Motoring (HQ) 1084 SERANGOON ROAD, 328186 Serangoon - Tel: 62989546		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 21/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (13/03/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBJ8938R (0455583385SG)

[SLV197H]

TP

TAY CHEE WAH

Jan 31 2018 6:00PM

[Chi Keat Sung]

Ss Motoring

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
------------------	--	---------------	--------------------	--------------	--------------	--	--

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/03/18 15:03	Accident Statement <small>From: SC - Reg. No: SLV197H, Claimant: CHI KEAT SUNG</small>		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
2	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
3	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
4	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
5	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
6	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
7	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
8	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
9	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
10	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
11	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
12	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
13	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
14	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
15	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
16	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
17	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>
18	11/04/18 09:01	General View		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18002378/WD3E2
Date: 12/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700090984
Claimant Vehicle No: FBJ8938R Insured Vehicle No: SLV197H
Date of Loss: 31/01/2018 Nature of Claim: TP Claim No: 0455583385SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBJ8938R
Make & Model: SYM JOYRIDE 200 A, 171cc (A) Engine No: KB220246
Reg. Date: 06/12/2014 (Man. Year: 2014) Chassis No: RFGLF18WYES015553
Colour: Black/Silver Odometer: 41576 km
Engine Capacity: 171 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-13 Rear Tyre Size: 130/70-12
Front Left Side: Michelin 3 mm Rear Left Side: Michelin 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/02/2018
Date Inspected: 07/02/2018 Inspected At: Ss Motoring (HQ)
1084 SERANGOON ROAD
Singapore 328186
Estimated Period of Repair: 3.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Dented / Scratched	0.00 F	*- F
3	1		*FRONT HEADLAMP FAIRING	Cracked / Warped	0.00 F	*- F
4	1		*FRONT WINDSHIELD	Scratched	0.00 F	*- F
5	1		*FRONT RH SIGNAL LAMP	Scratched	0.00 F	*- F
6	1		*HAND BRAKE LEVER	Scratched	0.00 F	*- F
7	1		*FAIRING LOWER (RHF)	Scratched	0.00 F	*- F
8	1		*RH CENTRE LOWER FAIRING	Scratched	0.00 F	*- F
9	1		*RHS WING MIRROR	Scratched	0.00 F	*- F
10	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
11	1		*REAR BOX	Scratched	0.00 F	*- F
12	1		*HANDLE BAR BALANCER RH	Scratched	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >