

INS. CASE OWNER:

Unsettling | CC 4 / AIG1800 2402, K y639

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

06/02/18

Date / Time:

6/1/18

Registered in Merimen:

6/2/18

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SJF 7962C

Name of Insured:

ZABAR BIN DSHAN

Insured Tel No.:

HP: 9242180

Excess Sec II :SS

D.O.A: 2/2/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

067518319254

Policy No.:

210008026

Make / Model:

F14

Place of Accident:

TELOR BLANMAN FOLLOVE
INDS RYE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES

NO

TP GIA REPORT: YES

NO

Insured Liability:

Final ? Yes / No

SJD 2408E



INSRS:
WSP:
Tel:
Liability:
RMKS:

WEL
UL



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
8/1/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
9/2/18 @ 11:35	Call Of:	2/09/02/18
	After call ltr to Of:	
	Documentation Check List:	Handler Typist
9/04/18 @ 2:30	Notification ltr (if non-pickup):	
	After call ltr to Of:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

RECEIVED 0 / MAR 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS 1,350	(3 days)	Reduction: 64
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No.: 27
Repair Cost:	SS 1,350		
Loss of Rental (LOR):	SS	(days)	
Loss of Use (LOU):	SS 18000	(560 x 3 days)	
Loss of Income (LOI):	SS	(S x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search:	SS 2.45		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	
Legal Cost:	SS		
Total:	SS 1,537.45	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 1,537.45	Name 1:	Wei Lee Motor Works
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

077561

BY:

REF: AIG

ASSIGNMENT

Jm:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

7/12 File pass to Catherine
L.B. & BSC

Veh No:

Type:

M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng No:

C.No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal:

L/Bal:

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Survey Fee:

Transportation:

S - RS - SI

Phone:

Other:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Date/Time File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Phone:

Other:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format:

ump Sum / L.B.I. (\$)

Merimen

950/2

23/2/2018




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18002402/Kyb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-02-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJF 7962C	Veh. Inspected	SJD 2408E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/02/2018	Inspection Date		
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

威利摩多 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 8986

Business Regn No: 269436/00J

Not Authorized
USing B1350t
Recovery After Paving
3 days

05, Feb 2018

AIG Asia Pacific Insurance PL
78 Shenton Way
#07-16 S 079120

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SJF7962C
Accident involving vehicle No: SJD2408E/SJF7962C
DOA: 02022018 AT West Coast highway

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SJD2408E

To supply—

Description	Qty	Amount	
Rear bumper	1 <i>SVL AT CR</i>	862.00	X <i>X2.0.0</i>
Bumper retainer @32.00	2 <i>SVL</i>	64.00	X
Bumper reflector @96.00	2 <i>AT CR</i>	192.00	X
Bumper clip		42.00	X
Tail lamp @320.00N	2 <i>SVL</i>	640.00	N
End panel	1 <i>SVL</i>	506.00	N
End panel top garnish	1 <i>SVL</i>	149.00	N
Boot weather strip	1 <i>SVL</i>	166.00	N X
Lid	1 <i>SVL</i>	693.00	N X
Lid-Mit logo	1 <i>SVL</i>	47.00	N
Lid-EX emblem	1 <i>SVL</i>	39.00	N
Lid-lancer emblem	1 <i>SVL</i>	52.00	N
Lid lock	1 <i>SVL</i>	67.00	N X

Rear number plate w bracket

Reverse sensor

To remove damaged parts n attachments.

Cut n weld damaged panels. Repair/reshape dented/damaged areas.

Replace/align all parts into position.

To spray paint.

Per 50.00 455N
Shor 220.00 2005N

300.00
500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

威利摩多
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~456 3988~~ 6458 0128
Business Regn No: 269436/00J

Supplementary parts for vehicle no: SJD2408E

To supply—


1 pc Rear bumper enforcement
Parts less 10%

Ry \$ 210.00 N ✓
\$ 21.00

\$ 189.00
=====

Your password will expire in 5 days. [Click here to change it.](#)

- FW: TP survey for vehicle no: SJD2408E

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 6/2/2018 12:32:48 PM
Attachments:  doc02302620180206111758.pdf

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

12.52pm @ 6/2/2018
Vehicle In
Person @ Karen
sur @ Kenneth

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: karen Seah [mailto:weileemotorworks@gmail.com]
Sent: Tuesday, February 06, 2018 11:23 AM
To: AIG SGP, Claims-Survey
Subject: TP survey for vehicle no: SJD2408E

Your insured vehicle no: SJF7962C
Accident involving vehicle no: SJD2408E/SJF7962C
DOA: 02022018 AT West Coast Highway

Dear officer incharge
I Refer to the above case, please arrange to survey the vehicle no: SJD2408E ASAP.
Attached with the accident report n estimate of repair.
Thank you.

--

Best Regards,

Karen Seah

Wei Lee Motor Works
Block 9 Sin Ming Industrial Estate
#01-32 Singapore 575644
Tel: 6456 9830
Fax: 6458 0128
Company registration: 269436/00J

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~456 9886~~ 6458 0128
Business Regn No : 269436/00J

05, Feb 2018

AIG Asia Pacific Insurance PL
78 Shenton Way
#07-16 S 079120

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SJF7962C
Accident involving vehicle No: SJD2408E/SJF7962C
DOA: 02022018 AT West Coast highway

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SJD2408E

To supply—

Description	Qty	Amount
Rear bumper	1	862.00
Bumper retainer @32.00	2	64.00
Bumper reflector @96.00	2	192.00
Bumper clip		42.00
Taillamp @320.00N	2	640.00 N
End panel	1	506.00 N
End panel top garnish	1	149.00 N
Boot weather strip	1	166.00 N
Lid	1	693.00 N
Lid-Mit logo	1	47.00 N
Lid-EX emblem	1	39.00 N
Lid-lancer emblem	1	52.00 N
Lid lock	1	67.00 N

Rear number plate w bracket	50.00
Reverse sensor	220.00
To remove damaged parts n attachments.	
Cut n weld damaged panels. Repair/reshape dented/damaged areas.	
Replace/align all parts into position.	900.00
To spray paint.	800.00

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986

Business Regn No : 269436/00J

02,Mar 2018

AIG Asia Pacific Insurance PL

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SJF7962C

Accident involving vehicle no:SJD2408E/SJF7962C

ON 02/02/2018 AT West Coast highway

Dear officer incharge

We are the workshop for the owner of vehicle no: SJD2408E

Regarding the claim for the case above, this is a liability clear case considering that your client's vehicle collided into the rear portion of our client's vehicle.

The claim for vehicle No: SJD2408E as follow:-

Cost of repair to SJD2408E \$ 1,350.00 finalised with your surveyor

Loss of use \$ 240.00 \$80x03d

LTA search fee \$ 7.45

\$ 1,597.45

Enclosed with all the necessary document for your reference.

Kindly let us have your reply soonest possible.

Thank you.





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG18002402/Kyb3

09 FEBRUARY 2018

ZAIBAL BIN OSMAN
BLK 43 CHAI CHEE ST
#07-70
SINGAPORE 461043

Dear Sir/Madam,

**ACCIDENT INVOLVING SJF 7962C & SJD 2408E ALONG/AT TELOK
BLANGAH FLYOVER TOWARDS AYE ON 02/02/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Jas Khine
Case Handler
DID: 6841 2928
FAX: 6741 4108
Email: jaskhine@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

I, KH Leasing PL ("the third party claimant") of
261A UPP Thomson Rd. (address), owner of
SD2408E (vehicle no.) hereby authorize Wei Lee Motor Works
the (workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of
use ("claim") for my vehicle no. SD2408E that was damaged pursuant to the accident
which occurred 24/2/18 (date) at West Coast Highway (location)
involving vehicle no/s. 88F7962C This ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 5 (day) of Feb (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **WEI LEE MOTOR WORKS** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,350.00** (Repair Cost), **S\$180.00** (Loss of Rental/Use) **S\$7.45** (Disbursement), for vehicle no. **SJD 2408E** that was damaged pursuant to the accident which occurred on **02/02/2018** (date) along **TELOK BLANGAH FLYOVER TWDS AYE** (location) involving vehicle no/s **SJF 7962C**.

This is pursuant to the inspection conducted on **06/02/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **KH LEASING PTE LTD** ("the third party claimant") of vehicle no. **SJD 2408E** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJD 2408E** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 06 (day) of 03 (month) 2018 (year)

Signed by appointed surveyor

A circular stamp with the letters "LKK" inside, followed by a handwritten signature.

Signed by "the workshop" (with chop)

A circular stamp with the text "WEI LEE MOTOR WORKS" around the perimeter, followed by a handwritten signature.

威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,

SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128

Business Regn No: 269435/00J

AIG Asia Pacific Insurance PL
78 Shenton Way #07-16
S 079120

INVOICE No:12528

DATE:02,Mar 2018

PARTICULARS	AMOUNT (S\$)
Vehicle No: SJD2408E	
Cost of repair for vehicle No: SJD2408E	1,350.00
Lump sum repaired as recommended by your surveyor-LKK	-----
Auto Consultants.	1,350.00
	=====



Payments to be made by crossed cheque in favour of WEI LEE MOTOR WORKS



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 05 Feb 2018 / 15:34:06

Receipt Date/Time : 05 Feb 2018 / 15:34:06

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180205-001438

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SJF7962C				
As at 02 Feb 2018/20:00:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SJF7962C Enquiry Fee 20180205153202523279	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180205153214580	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018 Edit Reg		06 Feb 2018 00:00 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Zainal Bin Osman , ID: S1583945G		
Main Claimant:	KH LEASING PTE LTD , Co. Reg. No.: 201611813C		
Vehicle Reg. No.:	SJD2408E	Date of Loss:	02/02/2018 20:00 - :59
Claim Type:	TP / 0675183192SG	Policy/Cover Note No.:	2100081046 (Comprehensive) Coverage: 12/06/2017 - 11/06/2018
Vehicle Reg. No. (Insured):	SJF7962C	Policy No. (Claimant):	5090891147
	Excess:		
Repairer:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, 575644 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/02/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJD2408E (0675183192SG)
[SJF7962C]
TP
KH LEASING PTE LTD
Feb 2 2018 8:00PM
[Zainal Bin Osman]
Wei Lee Motor Works

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
------------------	--	---------------	--	--------------------	--	--------------	--	--------------	--	--	--

Letters/Correspondences										1 per page v		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown						1		Edit		

Assessment Reports										1 per page v		<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)								Thumbnail	Print	
1	07/02/18 14:28	Accident Statement <small>From: OD - Reg. No: SJF7962C, Claimant: ZAINAL BIN OSMAN</small>						1		Load HTM		

Photos/Images										3 per page v		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
2	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
3	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
4	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
5	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
6	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
7	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
8	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
9	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
10	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
11	07/03/18 11:57	Odometer Reading						1		Load JPG	<input checked="" type="checkbox"/>	
12	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
13	07/03/18 11:57	General View						1		Load JPG	<input checked="" type="checkbox"/>	
14	07/03/18 11:59	Reinspection Photo						1		Load JPG	<input checked="" type="checkbox"/>	
15	07/03/18 11:59	Reinspection Photo						1		Load JPG	<input checked="" type="checkbox"/>	

Documentation										1 per page v		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	06/02/18 18:31	EMAIL FROM AIG DD 06022018						1		Load PDF		
2	06/02/18 18:31	TP EST & GIA REPORT						1		Load PDF		
3	08/03/18 08:31	WORKSHOP INVOICE						1		Load PDF		
4	08/03/18 08:31	AUTHORISATION TO ACT FORM						1		Load PDF		
5	08/03/18 08:31	Release Voucher						1		Load PDF		
6	08/03/18 08:31	LTA SEARCH						1		Load PDF		
7	08/03/18 08:31	LETTER TO OI						1		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJF7962C (Insd veh)	Model:	MITSUBISHI LANCER 1.3 (A)
	SJD2408E (TP veh)		
Date of Accident:	02/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,699.00
Final Repair Cost	:	\$	1,350.00
Loss of Use	:	\$	180.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,537.45

3.00 days at \$60.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Wei Lee Motor Works	:	\$ 1,537.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

08 Mar
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18002402/KYB3Q2

Date: 08/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100081046
 Claimant Vehicle No: SJD2408E Insured Vehicle No: SJF7962C
 Date of Loss: 02/02/2018 Nature of Claim: TP Claim No: 0675183192SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD2408E
 Make & Model: MITSUBISHI LANCER, 1.3 (A) Engine No: 4A910084197
 Reg. Date: 17/04/2008 (Man. Year: 2008) Chassis No: JMYSRCY2A8U006775
 Colour: Metallic Red Odometer: 203306 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Falken 3 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Falken 3 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,999.00	1,090.40	2,908.60	72.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	800.00	900.00	52.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,699.00	1,890.40	3,808.60	66.83
Approved Total (Overridden) (S\$)		1,350.00		
Nett Amount (S\$)	5,699.00	1,350.00	4,349.00	76.31
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,537.45		

INSPECTION

Date of Assignment: 06/02/2018
 Date Inspected: 06/02/2018 Inspected At: Wei Lee Motor Works (HQ)
 BLOCK 9 SIN MING INDUSTRIAL
 ESTATE #01-32
 Singapore 575644
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Jasmine Khine Phoo Wai

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Serviceable	862.00 F	*- FL
2	2		*BUMPER RETAINER	Serviceable	64.00 F	*- FL
3	1		*BUMPER REFLECTOR	N/S Cracked	192.00 F	*96.00 FL
4	1		*BUMPER CLIP	Not Necessary	42.00 F	*- FL
5	2		*TAILLAMP	Serviceable	640.00 F	*- FN
6	1		*END PANEL	Bent	506.00 F	*506.00 FN
7	1		*END PANEL TOP GARNISH	Serviceable	149.00 F	*- FN
8	1		*BOOT WEATHERSTRIP	Serviceable	166.00 F	*- FN
9	1		*LID	Repair	693.00 F	*- FN
10	1		*LID -MIT LOGO	Necessary	47.00 F	*47.00 FN
11	1		*LID -EX EMBLEM	Necessary	39.00 F	*39.00 FN
12	1		*LID -LANCER EMBLEM	Necessary	52.00 F	*52.00 FN
13	1		*LID LOCK	Repair	67.00 F	*- FN
14	1		*REAR NUMBER PLATE W BRACKET	Dented	50.00 FS	*45.00 FS
15	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
16	1		*REAR BUMPER ENFORCEMENT	Bent	210.00 F	*210.00 FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	3,999.00	1,195.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	19.20
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	85.40
Total Parts (\$\$)	3,999.00	1,090.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS N ATTACHMENTS.CUT N WELD DAAGED PANELS .REPAIR /RESHAPE DENTED /DAMAGED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION	New	900.00	300.00
2	TO SPRAY PAINT	New	800.00	500.00
Gross Labour Cost (\$\$)			1,700.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >