

(INSUR)

INS. CASE OWNER

Ming YAO

CC 6 / AIG18002404

U u 33

LCK

IDAC

Surveyor:

marcus

DOI:

ASSIGNMENT

06/02/18

Date / Time:

06/02/18

Registered in Merit:

06/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGR 239B

Claim No.:

332109168956

Name of Insured:

LEONG WAI KUEN

Policy No.:

Insured Tel No.:

HP: 9737 6144

Make / Model:

HYUNDAI AVANTE

Excess Sec II :\$5

D.O.A: 04/02/18

Place of Accident:

KOWAN MARKET OPEN C/P

Is driver the owner?

(YES / ☒)

Nature of Accident:

If NO, Driver Name / Age: LEONG TUCK SUNG

OI GIA REPORT ☒ YES / NO: TP GIA REPORT ☒ YES / NO

Driver Tel No.: 9730 4181

(VA ☒ YES / NO)

Insured Liability:

Final ? Yes / No

SGT 605K



INSRS:

WSP: Jin Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

06/02/18 (THURSDAY) # NO estimate

16/3/18

Spoke to OJD he confirmed the accident details. Informed TP claim. OJD reversing into parking lot.

RECEIVED 02 MAY 2018

STAGE

DATE / PIC

Non-Reporting 1st (1st)

Non-Reporting 1st (2nd)

Non-Reporting 1st (Final)

Notification 1st (if non-pickup)

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

/

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: 24

If NO or B 28, Ass. Lia:

Repair Cost:

\$5

1423.10

Loss of Rental (LOR):

\$5

/

(days)

Loss of Use (LOU):

\$5

120.00 (\$60 x 2 days)

Loss of Income (LOI):

\$5

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search:

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Towel Independent)

Legal Cost:

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5

1543.10

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

1543.10

Name 1:

JIN AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

(08/11/13) wef  
ASS. REC. BY: MORIS

REF:

A16/

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / (TP) WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No SLJ605K  
at Workshop m/s J.n. Arth  
of \_\_\_\_\_  
Insured: SHR 2393  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its  
repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GI/A / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 2 days Res.: Yes or No  
Lum Sum: plp % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

DISSE  
Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLJ605K Yr Regn: 10/16  
Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or SA/  
Make: Mazda 2 c.c. 1496  
Colour: (grey) A/C: Insured / Std / NI / NA  
Sp. Reading: 32401 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
Ci/No: MM6DL2SAAGW196278  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 185/60R16  
R: \_\_\_\_\_  
BS: (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front Rear  
R/Bal. 2 mm R/Bal. 2 mm  
L/Bal. 2 mm L/Bal. 2 mm  
D.O.A. 4/4/18 D.O.I. 6/2/18  
Survey held at: \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
frt.  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 54775

\$ 1330.00 (red: \$ 868.00/39%)

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

☐ S + RS ☐ S

☐ Photos

☐ Others

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18002404/Uus3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-02-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
	Insured Veh. SGR 239B	Veh. Inspected	SLJ 605K
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	06/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
	R/H Front Tyre		mm
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
	Accident Date 04/02/2018	Inspection Date	06/02/2018
	Survey held at JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8155F
Vehicle Details	
Vehicle No.:	SLJ605K
Vehicle to be Exported:	No
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5L SP.6EAT (LED)
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	P520348349
Chassis No.:	MM6DL2SAAGW196278
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,727.00
Original Registration Date:	28 Oct 2016
First Registration Date:	28 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$13,727.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2026
PARF Rebate Amount:	\$10,295.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$44,480.00
<b>Total Rebate Amount:</b>	<b>\$54,775.00</b>

The information contained herein is correct as at 06 Feb 2018

# Jin Auto Services Pte Ltd

Bik 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Date : 9/2/2018

M/S AIG

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLJ605K

## LIST PRICE

### List Items

1	1 PC	FRONT BUMPER	2/10.1
2	1 PC	FRONT CORNER RH SIDE	chrome moulding
3	1 PC	FRONT CORNER LH SIDE	chrome moulding
4	1 PC	FRONT GRILLE	AA

## LESE 20%

5		
6		LABOUR CHARGE ( FRONT )
7		SPRAY PAINTING (FRONT)
8		WIRING

\$	833.00	✓
\$	343.00	x
\$	142.00	✓
\$	142.00	x
\$	1,460.00	975
\$	(292.00)	
\$	1,168.00	
\$	600.00	250
\$	400.00	280
\$	30.00	20
\$	2,198.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# ***Jin Auto Services Pte Ltd***

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Business Registration No:200704370C

Date : 17/04/2018

Your ref :SGR239B(AIG Insured)

Our Ref SLJ605K

C/O LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1  
#01-25 Paya Ubi Industrial Park  
(S) 408933

Dear Sir/Madam

Accident involving vehicle SLJ605K & SGR239B E ON 4/2//2018

We are instructed by the owner SLJ605K to write ,negotiate and settle claim on her behalf for the above mentioned accident. we are now seeking the total amount of claim as follow:

Repair cost	S\$1423.10( with gst)
LOSS OF USE	200.00

-----  
**TOTAL SS 1623.10**  
-----

We shall appreciate if you could kindly consider our claim at your earliest convenience and kindly let us have your acknowledgement of receipt of this letter within 14days of your receipt of this letter.

Yours faithfully



Jouis Seow (Email: jouis@jinauto.com.sg)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18002404/Uus3

21 MARCH 2018

**LEONG WAI KUEN**  
BLK 279B SENGKANG EAST AVE  
#05-551  
SINGAPORE 542279

Dear Sir/Madam,

**ACCIDENT INVOLVING SGR 239B & SLJ 605K ON 04/02/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## LETTER OF AUTHORISATION

To: Jin Auto Services Pte Ltd

Dear Sir

ACCIDENT INVOLVING SLJ 605K & SHR239B ON 4/2/18

I/We, the owner of Vehicle Registration Number SLJ 605 K hereby authorise you to repair my/our vehicle repair, submit, correspond, negotiate and settle my/our claim for cost of repair and/or uninsured losses arising from the above accident.

I/We further authorise you M/S Jin Auto Services Pte Ltd, to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me/us in respect of my/our claim above.

I/We hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my /our behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me/us in person.

I/We further confirm that the acceptance by M/s Jin Auto Services Pte Ltd of the settlement amount in respect of such claim shall constitute the full discharge of my/our claim in respect of such loss and damage.

Signed by :



Name: Yau Chu So

NRIC NO: S075815 F

Date: 6/2/18



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, JIN AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for SS 1,423.10 (Repair Cost), SS 120.00 (Loss of ~~Rental~~/Use), SS --- (Disbursement) for vehicle no. SLJ 605K that was damaged pursuant to the accident which occurred on 04/02/2018 (date) along 209 HOUGANG STREET 21 (location) involving vehicle no/s SGR 239B. This is pursuant to the inspection conducted on 06/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner YAU CHU SOON ("the third party claimant") of vehicle no. SLJ 605K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLJ 605K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 3 (day) of May (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

**JIN AUTO SERVICES PTE LTD**

Blk 14 #01- 410/412 Defu Lane 10 Singapore 539195

Tel: 6289 8126 (24 hrs) Fax: 6287 0590

Email: jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg. No: 200704370C

**TAX INVOICE**

M/s

AIH ASIA PACIFIC INSURANCE PTE LTD

Invoice No: 15788

Vehicle No: SLJ 6051K

Date: 5/3/18

[illegible]

N.B No responsibility will be accepted for any loss or damage to any Vehicles or parts left in this workshop for any reason whatsoever.

*E. & O. E.*

**ADD GST**

TOTAL

Q 93-10  
\$ 1423-10

**JIN AUTO SERVICES PTE LTD**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Feb 2018 <a href="#">Edit Reg</a>		06 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,330.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,330.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	Leong Wai Kuen, ID: S0152039C		
Main Claimant:	YAU CHU SOON, ID: S0758155F		
Vehicle Reg. No.:	SLJ605K	Date of Loss:	04/02/2018 12:00 - :59 [15 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3321091689SG	Policy/Cover Note No.:	2100000942
Vehicle Reg. No. (Insured):	SGR239B	Policy No. (Claimant):	5094867889
		Excess:	
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/02/2018]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLJ605K (3321091689SG)  
[SGR239B]  
TP  
YAU CHU SOON  
Feb 4 2018 12:00PM  
[Leong Wai Kuen]  
Jin Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

**View** View in Browser

**Letters/Correspondences**

1 per page v

☒












No	Finalized On		Thumbnail	Print
1	(Draft)	LKK Auto Consultants Pte Ltd (HQ)		
		Third Party Express Settlement – Payment Breakdown		Edit

**Photos/Images**

3 per page v

☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/03/18 08:49	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	02/03/18 08:49	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
4	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
5	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
6	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
7	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
8	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
9	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
10	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
11	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
12	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
13	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
14	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
15	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
16	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
17	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
18	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
19	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
20	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
21	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
22	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
23	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
24	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
25	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
26	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
27	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
28	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
29	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
30	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
31	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
32	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
33	02/03/18 08:49	General View	Load JPG	<input checked="" type="checkbox"/>
34	02/03/18 08:49	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	02/03/18 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	02/03/18 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	02/03/18 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	02/03/18 08:49	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/18 18:39	TP GIA REPORT	 Load PDF	
2	28/03/18 09:38	TP ESTIMATE	 Load PDF	
3	08/05/18 08:37	WORKSHOP INVOICE	 Load PDF	
4	08/05/18 08:37	AUTHORISATION TO ACT FORM	 Load PDF	
5	08/05/18 08:37	Release Voucher	 Load PDF	
6	08/05/18 08:37	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/02/18 14:26	OI GIA	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGR239B (Insd veh)	Model:	MAZDA 3 1.5 SEDAN L
	SLJ605K (TP veh)		SP.6EAT (A)
Date of Accident:	04/02/2018		

Global Sum Settlement	: [ ] Yes	: [ X ] No	
Repair Estimate	: \$		2,351.86
Final Repair Cost	: \$		1,423.10
Loss of Use	: \$		120.00
Rental (if any)	: \$		0.00
LTA / GIA Search Fee	: \$		0.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		1,543.10

2.00 days at \$60.00 per day  
days

Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ 100 _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Jin Auto Services Pte Ltd	: \$	1,543.10
2)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

08 May  
2018

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18002404/UUA3Q2

Date: 08/05/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100000942  
**Claimant Vehicle No :** SLJ605K **Insured Vehicle No :** SGR239B  
 Date of Loss: 04/02/2018 Nature of Claim: TP Claim No: 3321091689SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ605K**  
 Make & Model: MAZDA 3, 1.5 SEDAN L SP.6EAT (A) Engine No: P520348349  
 Reg. Date: 28/10/2016 (Man. Year: 2016) Chassis No: MM6DL2SAAGW196278  
 Colour: Grey Odometer: 32401 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60 R16 Rear Tyre Size: 185/60 R16  
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm  
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,168.00	780.00	388.00	33.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	550.00	480.00	46.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,198.00</b>	<b>1,330.00</b>	<b>868.00</b>	<b>39.49</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>153.86</b>	<b>93.10</b>	<b>60.76</b>	<b>39.49</b>
<b>Nett Amount (S\$)</b>	<b>2,351.86</b>	<b>1,423.10</b>	<b>928.76</b>	<b>39.49</b>
<b>+ Loss of Use (2.0 x S\$60.00/day) (S\$)</b>		<b>120.00</b>		
<b>Nett Liability (S\$)</b>		<b>1,543.10</b>		

### INSPECTION

Date of Assignment: 06/02/2018  
 Date Inspected: 06/02/2018 Inspected At: Jin Auto Services Pte Ltd (Defu)  
 Blk 14 Defu Lane 10, #01-410/412  
 Singapore 539195  
 Estimated Period of Repair: 2.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Torn	833.00 FL	*833.00 FL
2	1		*FRONT CHROME MOULDING RH SIDE	Serviceable	343.00 FL	*- FL
3	1		*FRONT CHROME MOULDING LH SIDE	Scratched	142.00 FL	*142.00 FL
4	1		*FRONT GRILLE	Not Necessary	142.00 FL	*- FL
				Sub Total (S\$)	1,460.00	975.00
				- List Item Discount on L Items 20.00/20.00% (S\$)	292.00	195.00
				Total Parts (S\$)	1,168.00	780.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGE (FRONT)	New	600.00	250.00
2	SPRAY PAINTING (FRONT)	New	400.00	280.00
3	WIRING	New	30.00	20.00
Gross Labour Cost (\$\$)			<b>1,030.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >