



PDI TUAS

HERWAN BIN SAMAT
8 BOON KENG ROAD
#03-146
Singapore, 330008
Singapore

PDI TUAS

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV021777
Quote No. SER/QUO/1800205
Quote Date 05/02/18
Salesperson Shawn Lim
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model	Description	Mileage	Service Advisor
Volkswagen Passeng	Touran	6 CL 1.4 TSI (DSG)	142,494	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor	
SGN1937J	WVGZZZ1TZDW044958	05/03/13	Shawn Lim	
Engine Code	Labor Type	Engine No.	Model Code	
1N		CTH 022680	1T33B4	

Spray Bumper, bot Lid, spoiler.				
No.	Description	Qty.	UoM	Unit Price Amount
P B&P MACP LABOUR	R&R REAR WSCREEN	1	UNIT	X 840.00
P B&P MACP LABOUR	TFR BOOT LID MECH	1	UNIT	X 840.00
P B&P MACP LABOUR	LABOUR	5	UNIT	1260 4,200.00
P B&P MACP PAINT	SPRAY PAINT	6	UNIT	2000 12,000.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un	480.00
P B&P MECH	COMPULSORY TO DO AFTER AC			
	ELECT WIRING & MECH COMPO	1	Time Un	280.00
	Nett			
	Sum Labor			11,440.00
P 1K0867388A	CLIP	2	Pieces	? 6.27
P 1T0807305D	REINFORCEMENT	1	Pieces	? 560.31
P 1T0807393D	LHR BUMPER BRACKET	1	Pieces	? 30.81
P 1T0807394D	RHR BUMPER BRACKET	1	Pieces	? 30.81
P 1T0807421K GRU	REAR BUMPER	1	Pieces	DE 1,329.72
P 1T0807453	LHR TAILLIGHT BRACKET	1	Pieces	? 38.09
P 1T0807454	RHR TAILLIGHT BRACKET	1	Pieces	? 83.75
P 1T0807521H GRU	SPOILER	1	Pieces	? 520.07
P 1T0807863D	CENTRE BRACKET	1	Pieces	? 63.27
P 1T0827025Q	BOOT LID	1	Pieces	R 1,957.01
	Use Predecessor 1T0827025P			
P 1T0827705K	BOOT LID SEAL	1	Pieces	X 320.63
	Use Predecessor 1T0827705H			
P 1T0853630D ULM	VW SIGN	1	Pieces	ne 99.72
	Use Predecessor 1T0853630C UL			
P 1T0853675AAGQF	TSI EMBLEM	1	Pieces	ne 52.23
	Sum carried forward			16,532.67

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

HERWAN BIN SAMAT
8 BOON KENG ROAD
#03-146
Singapore, 330008
Singapore

PDI TUAS

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV021777
Quote No. SER/QUO/1800205
QuoteDate 05/02/18
Salesperson Shawn Lim
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Touran 6 CL 1.4 TSI (DSG)	142,494	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SGN1937J	WVGZZZ1TZDW044958	05/03/13	Shawn Lim
Engine Code	Labor Type	Engine No.	Model Code
	1N	CTH 022680	1T33B4

Continued			16,532.67
P 1T0853687C 739	TOURAN EMBLEM	1 Pieces	79.89
P D 002000A2	CLEANER	1 Pieces	147.86
P D 004660M2	2K GLUE	1 Pieces	183.87
P D 00920002	PRIMER	1 Pieces	32.19
P D 00950025	APPLICATOR	2 Pieces	22.38
P D 181802M1	ACTIVATOR	1 Pieces	29.46
P N 90825901	BOLT	4 Pieces	6.36
Sum Item			5,594.67

Explanations

P = Proportionately Charged

Payment Terms

No Credit

Payments to:

- BBN: - Acc.-No...

Sum Labor		11,440.00
Sum Item		5,594.67
Total	SGD	17,034.67
7% GST		1,192.46
Total SGD Incl. GST		18,227.13

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: