

CASE OWNER:

CC<sup>3</sup> / AIG1800 2412 / R. 2039

LKK:  
IDAC:

Survey: RAGUL DOI: 15/2/18 Date / Time: 6/2/18  
Registered in Merimen: 6/2/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SKJ 27 J  
Name of Insured : SIOW TENA SONG  
Insured Tel No. : 92390530 HP: 91883024  
Excess Sec II :SS : \_\_\_\_\_ D.O.A: 02/02/18  
Is driver the owner? (  YES / NO ) Nature of Accident : \_\_\_\_\_  
If NO, Driver Name / Age : \_\_\_\_\_  
Driver Tel No. : \_\_\_\_\_ (V/L:  YES / NO )

Claim No. : \_\_\_\_\_  
Policy No. : 2100326925  
Make / Model : Lexus LS460  
Place of Accident : PURANA RIVERFRONT HOTEL  
OI GIA REPORT:  YES / NO ; TP GIA REPORT:  YES / NO  
Insured Liability : % Final ? Yes / No



INRS: \_\_\_\_\_  
WSP: PML  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_



INRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel : \_\_\_\_\_  
Liability : \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date / Time

DATE / TIME	STAGE	DATE / PIC
9/2/18 Rzh	SAHP - 014 / ASK / 0372741 / 91883024, D.O.A 20/02/18 SKJ 27 J - X	
	# LIBRARY WAGON TO REQUEST EVIDENCE.	
11/02/18	WSP ROOM CLAIMANT CONTACT CD. BRNA RM TO REPORT TP REQUEST BR CD.	
	RECEIVED 11 APR 2018	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to CI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorization To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_  
Repair Cost: \$S ( \_\_\_\_\_ days) Reduction: % Email  Call

FINAL SETTLEMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call   
Final Liability: % (Agreed / Assessed) BOLA S/N No. : \_\_\_\_\_ If NO or B 28, Ass. Lia : \_\_\_\_\_

Repair Cost: \$S  
Loss of Rental (LOR): \$S ( \_\_\_\_\_ days)  
Loss of Use (LOU): \$S ( \$ x \_\_\_\_\_ days)  
Loss of Income (LOI): \$S ( \$ x \_\_\_\_\_ days)  
LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]  
GIA/LTA Search: \$S  
Medical: \$S  
Disbursement: \$S (e.g. Tow/ Independent)  
Legal Cost: \$S  
Total: \$S Global Sum \$S:  
1) Claim status: Normal/Reject/Private Settle  
2) Report Format: TP  
3) Survey fee: +320 +420

COPY SENT

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$S Name 1: \_\_\_\_\_  
Payee 2: (Strike if N.A.) \$S Name 2: \_\_\_\_\_  
Payee 3: (Strike if N.A.) \$S Name 3: \_\_\_\_\_

AXA

AXA

NW 1870 NW 11 MEAS / 248A

Date: 15/02/18

Policy No: SQ110

Year: 2016 Oct

Estimated Cost:

TO WS TP RES / OO RES / EVA / NW / M

To inspect/area No: SQ110  
at Workstation: Performance  
303 Alexandra Rd

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:


Client Record:

11 am @ owner waiting

Make of Van:

Policy Condition:

Remark: The van had commenced its repair at the time of inspection.



Est. of Market Value:

CAO Accident Form: Consistent? Yes or No

CA PR Seen: Consistent? Yes or No

Est. Repair: 5-6 days Yes Yes or No

Lim Sum: Yes Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: Person Contacted:

Vehicle IN / OUT

Date / Time: Action / Instruction:

PP: +4.691 (Red: +3,524.90 45%)

Year: 2016 Oct

Make: B.M.W 523I A 2.5 2497

Color: Grey

Chassis No: 175454

Engine:

Chassis: WBAFP32050C546258

Gen Cond: Good  Fair  Burnt

Steering:  Jammed / Leaked / Burnt

Brake:  Jammed / Leaked / Burnt

Mod: Nil  STD AIR

Tyre Size: F 245/45R18

R

BS / DUN / EXNOVA / GY / FB / LIZA / MID / CHTEL /  SUM / TOYO / YOKO

Front:

FRS: 6 --- RRS: 6 ---

LRS: 6 --- LRS: 6 ---

DOC: 03/02/18 DOC: 15/02/18

Surveyed at: PERFORMANCE

Des of Damage: Fr. Rear OS  UC Roof/door

The UC Chassis/frame Body Structure affected due to repair

See The File Pass of:

Prel. Report  
 Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

See The File Reason of:

Add Fee:

5th Trip  
 1st Trip  
 2nd Trip  
 3rd Trip

Report Format:

Sum Insured:

Large empty box for notes or signature.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18002412/ea3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-02-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKJ 217J	Veh. Inspected	SQ 11D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/02/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Present  
 Boney only  
 15/02/18 @ Attam



MS Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
 Co. Reg. No. 197401599W GST Reg. No M2-0020081-X

303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Tel. 43190100 (Sales & Admin)  
 43190111 (AfterSales)  
 Fax. 44747770

380, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Tel. 43190888 (AfterSales)  
 Fax. 43449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Tel. 43190528 (AfterSales)  
 43190533/530 (Motorrad)  
 Fax. 44796601 (AfterSales)  
 44796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

06 FEB 2018

Estimate No. : b1 45803	Page No. : 1 of 1
Date Estimated : 06/02/2018	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Lee Lay Ting Jane 45 Sunrise Close  Singapore 806650	- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SQ11D	C546258	06/10/2010	523iA	0

DESCRIPTION	VALUE
To replace front left door, repair rear left door and side sill left.	2125 <del>3,400.00</del>
Painting front left door, rear left door and side sill left.	2336 <del>2,586.00</del>
To check electrical wiring systems for proper function	150 <del>177.00</del>
To carry out body cavity preservation. (Per panel).	X 118.00
Sundries. <i>New</i>	80.00
<b>Total Labour 1:</b>	<b>6,371.00</b>

DESCRIPTION	QTY	PRIC	VALUE
FRT LH DOOR	1	1,731.25	R 1,731.25
FRT LH DOOR WINDOW GUIDE	1	113.55	X 113.55

Claims OD / 3rd Party / Uninsured Losses / Road Side Assistance

Rep No. 15/02/18 @ 1150 Claim No. \_\_\_\_\_

Date of Claim 15/02/18 Excess \$1 \_\_\_\_\_

Insured Name Rahul Sign \_\_\_\_\_

Insured No. 90010068 Insured Val. \$1 \_\_\_\_\_

**Total Parts : 1,844.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Labour 1	:	6,371.00
Parts	:	1,844.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ <i>5-6 days</i>	:	575.11
<b>Grand Total</b>	:	<b>8,790.91</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
 \*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 27 February 2018 11:17 AM  
**To:** 'PBSP'; Mei Kwan (LKKAuto)  
**Cc:** Admin A; Vic (LKKAuto); assignments  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SQ11D & SKJ217J ON 3.02.2018 \*\*\* LKK REF: CC3/AIG18002412/ea3  
**Attachments:** OI SKETCH PLAN.pdf

Without Prejudice

Hi Caroline,

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client cut into his lane to make a right turn collided into our insured vehicle. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 13 February 2018 12:31 PM  
**To:** 'PBSP' <pml-pbsp@simedarby.com.sg>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; assignments <assignments@lkkauto.com>  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SQ11D & SKJ217J ON 3.02.2018 \*\*\* LKK REF: CC3/AIG18002412/ea3

Dear Caroline,

Thank you for your email.

Please be informed that we are currently pending for our insured's report.

## Asher Sng (LKKAuto)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Wednesday, 11 April 2018 4:29 PM  
**To:** Asher Sng (LKKAuto)  
**Subject:** Re: REQ FOR DIRECT SETTLEMENT - SQ11D & SKJ217J ON 3.02.2018 \*\*\* LKK REF: CC3/AIG18002412/ea3

Dear Asher

Please be advised that our customer had reverted the claim from TP to OD with recovery.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** PBSP  
**Sent:** Tuesday, 27 February 2018 11:49:35 AM  
**To:** Inthiran Thurasamy  
**Subject:** Fw: REQ FOR DIRECT SETTLEMENT - SQ11D & SKJ217J ON 3.02.2018 \*\*\* LKK REF: CC3/AIG18002412/ea3

---

**From:** Asher Sng (LKKAuto) <AsherSng@lkkauto.com>  
**Sent:** Tuesday, 27 February 2018 11:16 AM  
**To:** PBSP; Mei Kwan (LKKAuto)  
**Cc:** 甯珺 ©; Vic (LKKAuto); assignments  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SQ11D & SKJ217J ON 3.02.2018 \*\*\* LKK REF: CC3/AIG18002412/ea3

Without Prejudice

Hi Caroline,

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client cut into his lane to make a right turn collided into our insured vehicle. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Wednesday, 11 April 2018 4:57 PM  
**To:** Md Noor, Norsiah  
**Cc:** Vic (LKKAuto)  
**Subject:** Your ref : 7813586395SG, ACCIDENT INVOLVING SQ 11D & SKJ 217J ON 03/02/2018

Your ref : 7813586395SG  
Our ref : CC3/AIG18002412/R1ea3

Dear Norsiah,

ACCIDENT INVOLVING SQ 11D & SKJ 217J ON 03/02/2018

We refer to the above matter.

Please be informed that TP claimant have converted to OD claim, as liability unclear for this case.

In view of above, we will submit W/P report to your office.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Feb 2018 <a href="#">Edit Reg</a>		15 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,691.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,691.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Siow Teng Soong</b> , ID: S2587826D								
Main Claimant:	<b>LEE LAY TING JANE</b> , ID: S1777248A								
Vehicle Reg. No.:	<b>SQ11D</b>	Date of Loss:	03/02/2018 22:00 - :59 [87 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 7813586395SG</b>	Policy/Cover Note No.:	2100326925 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKJ217J</b>	Policy No. (Claimant):	B8026340BSMP						
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 15/02/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SQ11D (7813586395SG)**  
**[SKJ217J]**  
**TP**  
**LEE LAY TING JANE**  
**Feb 3 2018 10:00PM**  
**[Siow Teng Soong]**  
**Performance Motors Limited**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <input type="button" value="View in Browser"/>
<b>Assessment Reports</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	<b>Thumbnail</b> <b>Print</b>
1	07/02/18 16:09	<b>Accident Statement</b> <small>From: SC - Reg. No: SKJ217J, Claimant: SIOW TENG SOONG</small>	<input checked="" type="checkbox"/> Load HTM
<b>Photos/Images</b>			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
17	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
18	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
19	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
20	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
21	11/04/18 17:06	<b>General View</b>	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b> <b>Print</b>
1	06/02/18 19:12	<b>TP ESTIMATE</b>	<input checked="" type="checkbox"/> Load PDF
2	06/02/18 19:12	<b>TP GIA REPORT</b>	<input checked="" type="checkbox"/> Load PDF
3	20/02/18 19:26	<b>TP ESTIMATE - MARKED</b>	<input checked="" type="checkbox"/> Load PDF
4	11/04/18 16:58	<b>EMAIL FROM WSP DD 110418</b>	<input checked="" type="checkbox"/> Load PDF
5	11/04/18 16:58	<b>EMAIL TO AIG DD 110418</b>	<input checked="" type="checkbox"/> Load PDF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/>   <input type="button" value="Save"/>   <input type="button" value="Print"/>

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG18002412/R1EA3Q2  
**Date:** 12/04/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100326925
<b>Claimant Vehicle No :</b> SQ11D	<b>Insured Vehicle No :</b>	SKJ217J
Date of Loss: 03/02/2018	Nature of Claim: TP	Claim No: 7813586395SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SQ11D</b>	
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Engine No: 08267555N52B25AF
Reg. Date:	06/10/2010 (Man. Year: 2010)	Chassis No: WBAFP32050C546258
Colour:	Grey	Odometer: 175454 km
Engine Capacity:	2497 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,924.80	80.00	1,844.80	95.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,291.00	4,611.00	1,680.00	26.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,215.80</b>	<b>4,691.00</b>	<b>3,524.80</b>	<b>42.90</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>575.11</b>	<b>328.37</b>	<b>246.74</b>	<b>42.90</b>
<b>Nett Amount (S\$)</b>	<b>8,790.91</b>	<b>5,019.37</b>	<b>3,771.54</b>	<b>42.90</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

#### INSPECTION

Date of Assignment:	15/02/2018	
Date Inspected:	15/02/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	6.0 days	

---

**Adjuster:** MOHD RASUL

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT LH DOOR	Repair	1,731.25 FS	*- FS
3	1		*FRT LH DOOR WINDOW GUIDE	Not Necessary	113.55 FS	*- FS
<b>Total Parts (S\$)</b>					<b>1,924.80</b>	<b>80.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT LEFT DOOR ,REPAIR REAR LEFT DOOR AND SIDE SILL LEFT	New	3,400.00	2,125.00
2	PAINTING FRONT LEFT DOOR ,REAR LEFT DOOR AND SIDE SILL LEFT	New	2,596.00	2,336.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>6,291.00</b>	<b>4,611.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >