

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

*Present.  
Survey only  
15/02/18 @ Han*



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

06 FEB 2018

Estimate No. : <b>b1 45803</b>	Page No. : <b>1 of 1</b>
Date Estimated : <b>06/02/2018</b>	
Prepared By : <b>Inthiran A/L Thurasamy</b>	

<p><b>- ESTIMATE REPAIR FOR -</b> <b>Lee Lay Ting Jane</b> <b>45 Sunrise Close</b>  <b>Singapore 806650</b></p>	<p><b>- ACCOUNT - 121</b> <b>AIG Asia Pacific Insurance Pte. Ltd.</b> <b>78 Shenton Way</b> <b>#08-16 Chartis Building</b> <b>Singapore 079120</b></p>
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SQ11D	C546258	06/10/2010	523iA	0

DESCRIPTION	VALUE
To replace front left door, repair rear left door and side sill left.	2125 <del>3,400.00</del>
Painting front left door, rear left door and side sill left.	2336 <del>2,596.00</del>
To check electrical wiring systems for proper function	150 <del>177.00</del>
To carry out body cavity preservation. (Per panel).	X 118.00
Sundries.	80.00
<b>Total Labour 1:</b>	<b>6,371.00</b>

DESCRIPTION	QTY	PRIC	VALUE
FRT LH DOOR	1	1,731.25	R 1,731.25
FRT LH DOOR WINDOW GUIDE	1	113.55	X 113.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	1,844.80
Regn No. _____ Claim No. _____	
Date & Time <b>15/02/18 @ 1150</b>	Excess S\$ _____
Surveyor's Name <b>Rahul</b>	Sign _____
<b>9006068</b>	Authorised Yes / No _____

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Labour 1 Time	6,371.00
Parts	1,844.80
Labour 2	0.00
Excess	0.00
Total GST @ <b>7% 5-6 days</b>	575.11
<b>Grand Total</b>	<b>8,790.91</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***