

INS. CASE OWNER:

CC 6 / CTI1800 2430, R1E 2430

LKK:
IDAC:

Surveyor: Rasul

DOI: 05/12/18

Date / Time: 5/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: SJD 5298K

Name of Insured: MA GEOK FEE

Insured Tel No.: _____ HP: _____

Excess Sec II : \$5 _____ D.O.A: 05/01/18

Is driver the owner? (YES / ☒ NO) Nature of Accident: _____

If NO, Driver Name / Age: KEERNANE TAN YU LING

Driver Tel No.: _____ (V/L: ☒ YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

SNM 1800060002

0MPCSW3014 6710Y

HONDA

OLD TMS 104.

OI GIA REPORT ☒ YES / NO : TP GIA REPORT ☒ YES / NO

Insured Liability: % Final ? Yes / No

PZ 1688H



INSRS:
WSP: SL
Tel: Am 70.
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
<u>12/1/18</u>	Non-Reporting ltr (1st):	
<u>15/5/18</u>	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OE:	<u>14.05.18</u>
	After call ltr to OE:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	☐ ☐
	After call ltr to OE:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD:	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE Date/Time: 2/1/18 Sent By: DM

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: <u>PP</u> <u>\$53,040</u>	(3 days)	Reduction: <u>48</u> %	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: <u>16.12.19</u>	Confirm with: <u>M&L</u>	Email ☒ Call ☐
Final Liability: % <u>100</u>	(Agreed / Assessed)	BOLA S/N No.: <u>2430</u>	If NO or B 28, Ass. Lia:
Repair Cost: <u>0/18</u> <u>\$52,182.80</u>		<u>OLD LOST CONTROL AND TWT TP.</u>	
Loss of Rental (LOR): \$5 -	(days)		
Loss of Use (LOU): \$5 1,000.00	(\$ 250 x 4 days)		
Loss of Income (LOI): \$5 -	(\$ x days)		
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐	(Tick only one)		
GIA/LTA Search: \$5 2.00			
Medical: \$5 -			
Disbursement: \$5 -	(e.g. Tow/ Independent)		
Legal Cost: \$5 -			
Total: \$5 2,184.80		Global Sum \$5:	
FINAL PAYMENT	Date/Time: <u>16.12.19</u>	Confirm with: <u>M&L</u>	Email ☒ Call ☐
Payee 1: <u>\$53,184.80</u>	Name 1: <u>SL AUTO INDUSTRIES (S) PTE LTD</u>		
Payee 2: (Strike if N.A.) \$5	Name 2:		
Payee 3: (Strike if N.A.) \$5	Name 3:		

COPY SENT

Signature: *[Signature]*

REF: CTZ

43546

ASSIGNMENT

From: _____ Date: 05-02-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: PZ 1688H

at Workshop no: SC Auto

of: 51 Senoko Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: Mei Ling

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Ball. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 72 1688H

Vr Regn: 2011 July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SCANIA K1B 4x2 M 8867

Colour: MULTI A/C Insured / Std / NI / NA

Sp. Reading: 216972 T. Radio: Insured / Std / NI / NA

Eng No: _____

C No: 4S2K4X20001874465

Gen. Cond: Good / Fair / Poor / Burnt

Steering: / Jammed / Leaked / Burnt or

Brake: / Jammed / Leaked / Burnt or

Mod: Nil / Si/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: A -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front

Rear

R/Bal: 8 mm R/Bal: 8/8 mm

L/Bal: 8 mm L/Bal: 8/8 mm

O/OA: 02/01/18 O/OA: 05/02/18

Survey held at: SC AUTO

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Fnt

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

05/02/18 @ 12:00 Finalized amount at \$2040 / 3 days p/p with neither amount confirmed

(RED: +1.920 48%)

Date/Time File Pass to:

☐

: Preli. Report

Date/Time File Return to:

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time File Return to:

Date/Time File Return to:

Add Fee:

☐

Site Insp: \$

☐

Inter. Insp: \$

☐

Tech. Insp: \$

☐

Final Insp: \$

Report Format: _____

Lump Sum / I.B. / \$

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18002430/R1yb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 06-02-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJD 5298K	Veh. Inspected	PZ 1688H
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	06/02/2018
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	02/01/2018	Inspection Date	05/02/2018
	Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD #03-01 SINGAPORE 758133		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE. 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI18002430/R1yb3

Date: 06.02.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

PZ1688H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 05.02.2018 at the premises of M/s SC Auto Industries (S) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,960.00
Revised Estimate Amount	: S\$	2,040.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S TOUR ROYALE SERVICES PTE LTD

42 Craig Road

SINGAPORE 089680

Insured TOUR ROYALE SERVICES PTE LTD

Policy VBX/P1090834/00008

ESTIMATE Bill

GST Reg. No: 19-9800107D

Date: 24/1/2018

Our Case Ref. SC18/01/011/4TR-TP

Accident Date 2/1/2018

Damaged Vehicle No: PZ1688H

S/no	Description	QTY	Price	Disc	Amount
------	-------------	-----	-------	------	--------

Replaced Parts

1	DOOR RUBBER	400 1	PC	\$160.00	- cut / \$160.00
2	ALUMINIUM PROFILE	1	PC	\$240.00	- cut / \$240.00

Labour Charges

1	SPRAY PAINTING	1640 1		\$1,600.00	- 1000 / \$1,600.00
2	LABOUR FOR LHS FRONT PORTION	1		\$1,960.00	- 640 / \$1,960.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rate
HP 90010068
3 days
7/p
05/02/18 @ 1240
Rem after repair

1640
400
2040
3 days

Sub Total

\$ 3,960.00

Authorised Signature

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 9 February 2018 11:25 AM
To: Shu Pei (LKKAUTO)
Cc: Joel Goh
Subject: RE: Direct Settlement - Accident Involving SJD5298K (OI : CTI - SNM18D00060C02) and PZ1688H (TP : LKK REF -CC6/CTI18002430/R1yb3) on 02.01.2018
Attachments: leeSZ_SNM18D00060C02-SJD5298K-LKKDirectSettlementAccidentLtr_CLCR95.746.pdf; MLHM18001364-SJD5298K.pdf

Dear Shu Pei,

Kindly refer to the above attachment.

Case Handler: Joel Goh

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 7 February, 2018 4:57 PM
To: Claims Dept of CTI
Cc: Joel Goh; Jowyn Tay; Jas Khine (LKKAUTO); Thin Thin (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJD5298K (OI : CAI - TBA) and PZ1688H (TP : LKK REF - CC6/CTI18002430/R1yb3) on 02.01.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle PA 1688H at M/s SC Auto Industries (S) Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Jas and she can be contacted at DID: 6841 2928.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Arden Road #16-00 Springvale Tower Singapore 078008
Tel: 6389 6111 Fax: 6222 1033
Website: www.cti.taiping.com
Co. Reg. No. 200206946E

Our Reference: **SNM18D00060/C02/8**

Date : **09 FEBRUARY 2018**

via Ordinary & Registered Mail

**LUA GEOK KEE
BLK 78 LENTOR GREEN
PRESIDENT GARDENS
SINGAPORE 789309**

Dear Sir / Madam

**ACCIDENT INVOLVING SJD5298K AND PZ1688H ON 02 JANUARY 2018
ALONG ECP TOWARDS CITY(ROCHOR ROAD EXIT)**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **PZ1688H** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : JAS
Ref : CC6/CTI18002430/R1YB3
Contact No : 68412928
via Email : JAS@LKKAUTO.COM

CC : Agent - (AN0450A) - INXPIRE N SOLUTIONS

F01/LKKDS-2013



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CT118002430/R1ea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 09-01-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJD 5298K	Veh. Inspected	PZ 1688H
	Policy No.	DMPCSN3014691702	Coverage (\$)	0.00
	Claim No.	SNM18D00060C02	Excess (\$)	0.00
	Assign From		Assign Date	05/02/2018
2. Vehicle Particulars & Condition				
	Make & Model	SCANIA KIB4X2 M	c.c	8867
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	YS2K4X20001874405	Colour	MULTI
	Odometer	216972	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	295/80 R22.5	TRIANGLE	8 mm
	L/H Front Tyre	295/80 R22.5	TRIANGLE	8 mm
	R/H Rear Tyre	295/80 R22.5 (D)	TRIANGLE	8/8 mm
	L/H Rear Tyre	295/80 R22.5 (D)	TRIANGLE	8/8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	02/01/2018	Inspection Date	05/02/2018
	Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD #03-01 SINGAPORE 758133		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PZ 1688H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR RUBBER (SN)	CUT	160.00	160.00
1	ALUMINIUM PROFILE (SN)	CRACKED	240.00	240.00
			400.00	400.00
LABOUR				
	SPRAY PAINTING.		1,600.00	1,000.00
	LABOUR FOR LHS FRONT PORTION.		1,960.00	640.00
			3,560.00	1,640.00
GRAND TOTAL			3,960.00	2,040.00
RECOMMENDED COST OF REPAIRS				2,040.00

Report Ref No. CC6/CTI18002430/R1ea3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.