

22/03/2008

ASS. REC. BY:

REF: CS3/CTI18002452/TID302

Special Instruction:

Surveyor:

Taw Kieh

ASSIGNMENT (Office)

Menmen

From (Person): Chong Boon Sen

of CTI

Date/Time: 7/2/18 @ 9.31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 5281X

Insured:

SLD 7691X

at Workshop m/s

AMA Autocare

Tel:

8778 3636

of 36 Toh Guan Rd East #01-36

Policy No: DMPCS N3069971801

Claim No:

SNM18D00650C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 03/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 10.47am @ 7/2/18

Person Contacted:

kelvin

Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLP 5281X - X
	SLD 7691X - X
	Dismantle: 7/2/2018

Taylor

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP) WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop/mis: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No
CA / REV / REP. / 24 HRS ^{up}
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLP 5281 X 2010 Apr 21
Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota A/Tis 1.6A cc 1528
Colour: Black A.C Insured / Std / NI / NA
Sp Reading: 234205 T Radio Insured / Std / NI / NA
Eng No: _____
C No: MR053ZEE 106175371
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal: 6 mm R/Bal: 6 mm
L/Bal: 6 mm L/Bal: 6 mm
D.O.A: _____ D.O.I: 7/2/18
Survey held at: AMIA Automotive
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis/frame / Body Structure affected due to collision

Date: Time Action / Instruction

ups will meet G114

* Repair Estimate : S\$ 3500 - 4500

* 3 days

Date/Time File Pass to:

☐
☐

Prel. Report

Final Report

Days Of Repair: 3

Resurvey No. of Trips: 1

Survey Fee

Transporter

Tools - Pliers

Phone

Others

150

150

Report Format:

PRE

Lump Sum / L.B. / 3

Add Fee:

☐
☐
☐
☐

Site Insp: \$

Attention: \$

Techn. Insp: \$

Rep. End: \$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		07 Feb 2018 09:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN CHYE KENG, ID: S7019844D		
Main Claimant:	YANG RENPING, ID: S7263857C		
Vehicle Reg. No.:	SLP5281X	Date of Loss:	03/02/2018 12:00 - :59
Claim Type:	TP / SNM18D00650C02	Policy/Cover Note No.:	DMPCSN3069971801 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD7691X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE. CONTACT MR. MELVIN AT 8778 3636 FOR PRS.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLP5281X		
Vehicle Type :	N18 - Passenger (Co) Company Car (Single Rate)		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	COROLLA ALTIS 1.6 AUTO		
Chassis No. :	MR053ZEE106175371		
Propellant :	Petrol		
Engine No. :	3ZZ4998025		
Engine Capacity :	1598 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1630 kg		
Unladen Weight :	1195 kg		
Year Of Manufacture :	2010		
Original Registration Date :	29 Apr 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$30,000.00		
COE Expiry Date :	28 Apr 2020		
Road Tax Expiry Date :	28 Apr 2019		
PARF Eligibility Expiry Date :	28 Apr 2020		
Inspection Due Date :	28 Apr 2019		
Intended Transfer Date :	16 May 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0267E
Vehicle Details	
Vehicle No.:	SLP5281X
Vehicle to be Exported:	No
Intended De-registration Date:	16 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	3ZZ4998025
Chassis No.:	MR053ZEE106175371
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	29 Apr 2010
First Registration Date:	29 Apr 2010
Transfer Count:	1
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2020
PARF Rebate Amount:	\$9,193.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$30,000.00
COE Rebate Amount:	\$5,850.00
Total Rebate Amount:	\$15,043.00

The information contained herein is correct as at 16 May 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

License No. **S7263857C**

YANG RENPING

Age: 25 Nov 1972

Valid Until: 29 Sep 2014

0023509928

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7263857C**

Name: **YANG RENPING**

楊仁平

Race: **CHINESE**

Date of Birth: **25-11-1972**

Country of Birth: **CHINA**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg

NP 428A

License No: **S7263857C**

APL BLK 204 BOON LAY DRIVE #02-05
SINGAPORE 640204

APC No. **S7263857C** Date: **14-07-2007** No. **6769914**

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5091812397

Cover : drivo CLASSIC

1. Index mark and Registration Number of Vehicle : SLP5281X
Chassis Number : MR053ZEE106175371
2. Name of Policyholder : YANG MARINE AUTOMATION PTE. LTD.
3. Effective Date of Insurance : 16 Jun 2017
4. Expiry Date of Insurance : 15 Jun 2018
5. Persons or Classes of Persons entitled to drive#
(a) The Policyholder.
(b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

- (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
(b) Use for racing, pace-making, reliability trial or speed-testing.
(c) Use for the carriage of goods (other than samples) in connection with any trade or business.
(d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: LAI WAN JIAUN
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: HONG LEONG FINANCE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)


Agency : SININS AGENCY PTE. LTD. (00000615123)
Date of Issue : 15 Jun 2017 19:10 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/02/2018 14:54
Date Of Accident	03/02/2018 12:00
Exact Location Of Accident	JURONG WEST ST 93
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP5281X
Insured/Policyholder	
Name Of Registered Owner	YANG MARINE AUTOMATION PTE. LTD.
Co Reg No	201000267E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96991329

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091812337(CLASSIC)
Cover Note Number	

Driver

Name of Driver	YANG RENPING
NRIC No	S7263857C
Date Of Birth	25/11/1972
Occupation	INDOOR
Date Of Driving Pass	02/03/2010
Driving Experience	7 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96991329
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 204 BOON LAY DR #02-35
Postcode	640204
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHEN MY VEHICLE WAS STATIONARY AT JURONG WEST ST 93 TO BOON LAY WAY TO GIVE WAY. SUDDENLY A VEHICLE CAME FROM BEHIND HIT ONTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD7691X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN CHYE KENG
NRIC/Passport Number	S7019844D
Contact Number	90291787
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time:

3/1/18 7:49pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

3/1/18 7:49pm

WAC BUKIT BATOK (VAC)

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

© 2006 The Authors
Journal compilation © 2006 Blackwell Publishing Ltd

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

I/We declare the foregoing particulars are true in every respect.



~~Date & time:~~

3/2/18 2:47 pm

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: 3/2/08

Date & Time: 3/2/18 2:49 PM

IDAC BUKIT BATOK (VAC)
511 Bukit Batok

Reporting Centre Personnel's Signature

Name: _____
NRIC/FIN No.: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		07 Feb 2018 09:31 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
<div>CLAIM SUBFOLDER DETAILS [Created by insurer]</div> <div> <div>Insured: TAN CHYE KENG, ID: S7019844D</div> <div>Main Claimant: YANG RENPING, ID: S7263857C</div> <div> <div>Vehicle Reg. No.: SLP5281X</div> <div>Date of Loss: 03/02/2018 12:00 - :59 [93 Months and 5 Days From LTA Reg Date (Man Yr)]</div> </div> <div> <div>Claim Type: TP / SNM18D00650C02</div> <div>Policy/Cover Note No.: DMPCSN3069971801 (Comprehensive)</div> </div> <div> <div>Vehicle Reg. No. (Insured): SLD7691X</div> <div>Policy No. (Claimant):</div> </div> <div> <div>Excess: S\$0.00</div> </div> <div> <div>Repairer: Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:</div> <div>Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]</div> <div>Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/02/2018]</div> <div>Adj Asg. Remarks: NO EST, CASE W/O SJE. CONTACT MR. MELVIN AT 8778 3636 FOR PRS.</div> </div> <div> View All Compose Case Mail </div> </div>				

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP5281X (SNM18D00650C02)
[SLD7691X]
TP
YANG RENPING
Feb 3 2018 12:00PM
[TAN CHYE KENG]
Ama Autocare Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	05/02/18 16:24	Video - Accident [Linked Accident Report Documents]	1	Load MP4	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	05/02/18 16:28	Accident Statement	1	Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
2	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
3	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
4	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
5	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
6	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
7	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
8	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
9	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
10	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
11	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
12	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
13	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
14	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
15	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
16	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
17	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
18	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
19	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
20	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
21	05/02/18 16:26	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/04/18 13:54	General View	1	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
2	30/04/18 13:55	Photographs of Damaged Parts		Load PDF
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/18 09:30	OI GIA REPORT		Load PDF
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	05/02/18 16:24	Sketch Plan [Linked Accident Report Documents]		Load TIF
2	05/02/18 16:26	IC,CI,DL [Linked Accident Report Documents]		Load TIF

Linked Accident Report Documents

Video			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	05/02/18 16:24	Video - Accident		Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	05/02/18 16:28	Accident Statement		Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
14	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
15	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
16	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
17	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
18	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
19	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
20	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
21	05/02/18 16:26	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	05/02/18 16:24	Sketch Plan		Load TIF	
2	05/02/18 16:26	IC,CI,DL		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18002452/T1D3E2
Date: 16/05/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3069971801
 Claimant Vehicle No: SLP5281X Insured Vehicle No: SLD7691X
 Date of Loss: 03/02/2018 Nature of Claim: TP Claim No: SNM18D00650C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP5281X Engine No: 3ZZ4998025
 Make & Model: TOYOTA COROLLA ALTIS, 1.8 (A) Chassis No: MR053ZEE106175371
 Reg. Date: 29/04/2010 (Man. Year: 2010) Odometer: 234205 km
 Colour: Black
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/02/2018
 Date Inspected: 07/02/2018 Inspected At: Ama Autocare Pte Ltd (HQ)
 36 Toh Guan Road East, #01-36
 Singapore 608580
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP5281X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >