

27/06/2002

ASS. REC. BY:

REF: CS / ASM18002468 / Agbe2

Special Instruction:

Surveyor:

Admin.

ASSIGNMENT (Office)

From (Person):

Know Saw Theng

of

ASM

Date/Time:

06/02/2018 10:39am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 1342S

Insured:

SJW 2110M

at Workshop m/s

M7 Solution

Tel:

6243 1373

of

23 Kaki Bukit Ave 4 #02-03B

Policy No:

Claim No:

SSMV008FP

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/02/2018

CA / REV / REP. / REV 24 HRS Wp1

H.O.D. Endorsement:

Date/Time:

07/02/2018 12pm

Person Contacted:

Ms. Wing

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJW 1342S - NS/INC1002468 / RWR
	SJW 2110M - X
07/2/18 @ 242pm	Informed Ms Khor, we are pending estimate from repairer.
27/4/18 @ 3.10pm	revised to Khor Saw Theng via Smart Claim.
	US \$ 4800, 6 days Used \$1149.71, 70%.

ASM (AXA)

ADDITIONAL

Weekend Car

STW1342S.

2010 March.

From Date 07/02/2018

Estimated Cost

OD / P / WS / TP RES / CD RES / EVA / INV / MV

To inspect vehicle No. STW 1342S
at Worked on M6 Solution

of insured.

Policy No.

Claims No.

Sum Insured Excess

Client's Record

Make of veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball or Market value

SAC Accident Report Consistent? : Yes or No

G.A. / P. Seen Consistent? : Yes or No

Est. Repairs: 6 days Fee: Yes or No

Lum Sum: % 3 Val: Yes or No

OA / REV / REP. / 24 HRS

Date Person Contacted

Vehicle IN / OUT

Type M Car M Cycle Bus Van Comp Taxi Prime Mover

Truck Trailer

Make Kia Cerato Forte 1591

Colour Grey A.C. Insured / Std / Nil / NA

Se Reading 80574 T.Paid Insured / Std / Nil / NA

Eng No

C No KNAFU411LA5171103

Gen. Cond. Good Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod. Nil / S/Rim / STD A/Rim or

Tyre Size F. 205/55R16

R. 205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MINI / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R.Bal. 06 mm R.Bal. 06 mm

L.Bal. 06 mm L.Bal. 06 mm

D.O.A. D.O. 07/02/18

Survey held at M6 Solution.

Des. of Damages: Frt / Yes / O/S / N/S / U/O / Roof top or

The U/O Chassis frame Body Structure affected due to collision

Date Time Action Instruction

TPAXA.

MV: 22K
RV: 6.8K.
Nett: 15.2K

RECEIVED 27 MAR 2018

Date Time Fee Passes? ☐ : Preli. Report

27/4 14:00 ☐ : Final Report

Date Time Fee Return?

Days Of Repair 6

Resurvey No. of Trip: 1

Survey Fee

Insurance

Add Fee: ☐ Estimated \$

☐ Agent \$

☐ Tax \$

☐ Ad \$

Report Form: Smart Claim 20

Lump Sum: 4800

250
250

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18002468/Aqb	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 07-02-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJW 2110M	Veh. Inspected	SJW 1342S
Policy No.		Coverage (\$)	0.00
Claim No.	S8M008FP	Excess (\$)	0.00
Assign From	SMART CLAIM (KHOR SAW THENG)	Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/02/2018	Inspection Date	07/02/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			




Service Request Details

Claim

S8M008FP

Reference

None 

Loss Date

February 3, 2018

Request Date

February 6, 2018

Due Date

February 13, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Standard workshop survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJW1342S

Make

TPVD KIA

Service Address

...

Primary Contact/Insured

MARICAN KADER HASNA
31 WESTWOOD AVENUE, 648711, Singapore
97850786

Claim Handler

KHOR Saw Theng
6568804754
sawtheng.khor@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message



PENDING FOR ESTIMATE FROM REPAIRER

Type

🔔 Question

Message

Dear Ms Khor, Please be informed that we have inspected the vehicle SJW 1342S on 07/02/2018. We are pending for estimate from repairer. - Shiau Chan

Reply



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 27/4/2018

To : AXA Insurance Pte Ltd

Survey details

Date of loss	3-Feb-18
Date of appointment	6-Feb-18
Date of survey	7-Feb-18
Location of survey	MG Solution Pte Ltd

Vehicle Details:

Claim Type:	Third party / Own Damage
Vehicle number	SJW 1342S
Make and Model	KIA CERATO FORTE
Date of registration	4/3/2010
Excess	
Market Value	\$
Parf Rebate	\$
Nett Loss	#VALUE!

Repair details

Initial Estimate	15,949.21
------------------	-----------

Proposed/Revised repair cost:

Parts	\$	4,081.76
Labour	\$	1,920.00
Total	\$	6,001.76
Lump Sum(if applicable)	\$	4,800.00

Number of days of repair	
--------------------------	--

Remarks:[illegible]

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3674A

Vehicle Details

Vehicle No.: SJW1342S

Vehicle to be Exported: Yes

Intended De-registration Date: 08 Feb 2018

Vehicle Make: KIA

Vehicle Model: CERATO EX FORTE 1.6L M/T ABS AB 2WD 4DR

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: G4FC9H336708

Chassis No.: KNAFU411LA5171103

Maximum Power Output: 92.7 kW (124 bhp)

Open Market Value: \$10,288.00

Original Registration Date: 04 Mar 2010

First Registration Date: 04 Mar 2010

Transfer Count: 0

Actual ARF Paid: \$10,288.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No

OPC Cash Rebate Eligibility Expiry Date: -

OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Mar 2020

PARF Rebate Amount: \$6,172.00

Intended COE Rebate Details

COE Expiry Date: 03 Mar 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$3,340.00

COE Rebate Amount: \$690.00

Total Rebate Amount: \$6,862.00

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3674A

Vehicle Details

Vehicle No.: SJW1342S
Vehicle to be Exported: No
Intended De-registration Date: 09 Feb 2018
Vehicle Make: KIA
Vehicle Model: CERATO EX FORTE 1.6L M/T ABS AB 2WD 4DR
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: G4FC9H336708
Chassis No.: KNAFU411LA5171103
Maximum Power Output: 92.7 kW (124 bhp)
Open Market Value: \$10,288.00
Original Registration Date: 04 Mar 2010
First Registration Date: 04 Mar 2010
Transfer Count: 0
Actual ARF Paid: \$10,288.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No
OPC Cash Rebate Eligibility Expiry Date: -
OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 Mar 2020
PARF Rebate Amount: \$6,172.00

Intended COE Rebate Details

COE Expiry Date: 03 Mar 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$3,340.00
COE Rebate Amount: \$689.00
Total Rebate Amount: \$6,861.00

The information contained herein is correct as at 09 Feb 2018

OK



Powerful And Sporty Rare Lime Green Color 2 Doors Coupe With Sunroof! Car Is Extremely Well Maintained With Excellent Engine Condition. Nice Lime Green Original Color From Kia. Car Parked In Car Park ...

2010 Kia Cerato

Prem Roy Motoring

Posted: 01-Jan-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte 1.6A SX

\$24,000

\$8,690 /yr

27-Jan-2010

1,591 cc

181,268 km

Sedan

Available

Cool Blue Exterior With Lush Black Interior Maintained By Meticulous Owner. Road Tax And Insurance Till July 2018. Servicing Done Recently. You Can Bring Her Home With A Peace Of Mind. Call/SMS Now To...

PREMIUM AD

Posted: 05-Feb-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte 1.6A SX

\$25,000

\$9,070 /yr

28-Jan-2010

1,591 cc


-

Sedan

Available

Just 1 Owner! Excellent Condition! Maintained By C&C. Fuel Efficient Sedan.

Posted: 31-Jan-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 1.6A SX

\$26,800

\$9,330 /yr

19-Feb-2010

1,591 cc

93,776 km

Sports

Available

Viewed To Believe! Nice Bidded Car Plate(1668). Stylish And Well Designed Car With Sporty Exterior Looks. Sexy Red In Colour! Extremely Well Kept By Previous Owner! Car Purchase Will Come With 6 Month...

Posted: 05-Feb-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 1.6A SX

\$25,800

\$8,790 /yr

23-Feb-2010

1,591 cc

160,000 km

Sports

Available

Full C&C Serviced, Well Maintained, Low Down Payment, 80% To 90% Loan Available, Viewing By Appointment Only.

CONSIGNMENT

Posted: 29-Dec-2017 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 2.0A SX

\$27,800

\$9,520 /yr

24-Feb-2010

1,998 cc

107,000 km

Sports

Available

1 Owner, Excellent Condition. Well Maintained And Regularly Serviced By The Previous Owner. Trendy Sporty Look Car With Low Depreciation. Call To View Now Before It Is Too Late! In House Loan Availabl...

Hui Hua Credit Pte Ltd

Posted: 11-Jan-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 1.6A SX

\$29,300

\$10,500 /yr

24-Feb-2010

1,591 cc

-

Sports

Available

New Road Tax, Serviced Regularly. No Repair Required. Viewings And Test Drives Are Strictly By Appointment Only. Up To 80% Loan And Trade In Available. Call/Whatsapp Us Now! (Christmas Promotion! Fre...

PREMIUM AD

Monster Motors Pte Ltd

Posted: 10-Jan-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 1.6A SX

\$24,000

\$7,900 /yr

24-Feb-2010

1,591 cc

125,000 km

Sports

Available

Exciting And Sporty Outlook, Immaculate Condition, Sports Rims, Tyres And Solar Films Are Fixed This Year (Have Receipt To Show).

DIRECT OWNER

Posted: 07-Dec-2017 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 2.0A SX

\$26,000

\$8,610 /yr

26-Feb-2010

1,998 cc

-

Sports

Available

New Arrival Beautiful White Paintwork! Original Condition And Lowest Depreciation! Car Is In Good Working Condition. Wait No More And Call Us To Make An Appointment Now!

Posted: 06-Feb-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte 1.6A SX

\$31,800

\$12,000 /yr

26-Feb-2010

1,591 cc

-

Sedan

Available

Do Not Miss Out The Best Selling Sedan In The Market! Spacious And Comfort. Best Handling. Low Maintenance, Low Depreciation! Trade In Welcome. 1.99% Loan / In House Available! Call Us Today For More ...

Posted: 02-Feb-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 1.6A SX (OPC)

\$23,800

\$7,800 /yr

01-Mar-2010

1,591 cc

-

Sports

Available

Loan Interest 1.99%. Welcome Trade-in Vehicle. Good Condition. Accident Free. Buy With Assurance. Owner Consignment Vehicle. OPC Conversion Fees Additional \$3500. Need To Arrange For Viewing.

Posted: 04-Feb-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia



Kia Cerato Forte Koup 2.0A SX

\$30,000

\$10,480 /yr

03-Mar-2010

1,998 cc

100,000 km

Sports

Available

Selling On Behalf Of Private Owner, Please Call To Arrange Before Viewing!

CONSIGNMENT

Posted: 30-Jan-2018 Tags: 2010 Kia Cerato, Kia Cerato, Kia, Cerato, Used Kia

Kia Cerato Forte Koup 1.6A SX (OPC)

\$24,800

\$8,220 /yr

04-Mar-2010

1,591 cc

110,000 km

Sports

Available

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/02/2018 17:28
Date Of Accident	03/02/2018 20:25
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE BEDOK RESERVOIR RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW1342S
Insured/Policyholder	
Name Of Registered Owner	TEO MENG FOOK WILLIAM
NRIC No	S8203674A
Email Address	BUZAIJIA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83832629
Alternative Phone No	OFFICE-88888888
Vehicle Particulars	
Manufacturer	KIA
Model	CERATO FORTE-1.6 A/T ABS AB 2WD 4DR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5049009104-06
Cover Note Number	
Driver	
Name of Driver	TEO MENG FOOK WILLIAM
NRIC No	S8203674A
Date Of Birth	28/01/1982
Occupation	INDOOR
Date Of Driving Pass	26/03/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83832629
Fax Number	
Contact Number	OFFICE-88888888
EMail Address	BUZAIJIA@GMAIL.COM

Address	BLK 366 CORPORATION DRIVE #08-425
Postcode	610366
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 03/02/2018 AT ABOUT 2027HRS AT ALONG PIE TOWARDS CHANGI BEFORE BEDOK RESERVOIR ROAD EXIT. I WAS TRAVELLING ON THE EXTREME RIGHT LANE AND WHEN MY FRONT VEHICLE SLOW DOWN HENCE I FOLLOW SUIT. SUDDENLY I HEARD A LOUD BANG FROM BEHIND AND WHEN I ALIGHTED, I REALISED THAT IT WAS VEHICLE (B) WHO HIT ONTO MY REAR PORTION OF MY VEHICLE (A) CAUSING DAMAGES TO MY VEHICLE. I HAVE ONE PASSENGER INSIDE MY VEHICLE. (A) SJW1342S (B) SJW2110M

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW2110M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 03/02/2018 at about 2027 hrs at along PTE towards Changi before Bedok Reservoir Road Exit. I was travelling on the extreme Right lane and when my front vehicle slow down hence I follow suit. Suddenly I heard a loud bang from behind and when I alighted, I realised that it was Vehicle (B) who hit onto my Rear Portion of my Vehicle (A) causing damages to my vehicle. I have one passenger inside my vehicle.

(A) SJW 1342 S

(B) SJW 2110 M

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NIC/FIN No:

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA INSURANCE	DATE	: 05/02/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJW1342S		
MODEL	: KIA CERATO FORTE 1.6A	KNAFU41LAS171103	
CHASSIS NO		xiao chen	
<u>ACCIDENT DETAILS</u>		DATE	: 3-Feb-18
		TIME	: 20:27HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Buckled</i>	1	\$ 867.00	\$ 867.00
2	BOOT LID LOGO <i>Neu</i>	1	\$ 92.00	\$ 92.00
3	BOOT LID EMBLEM 'CERATO' <i>Neu</i>	1	\$ 58.00	\$ 58.00
4	BOOT LID EMBLEM 'FORTE' <i>Neu</i>	1	\$ 64.00	\$ 64.00
5	BOOT LID EMBLEM 'CYCLE & CARRIAGE' <i>Neu</i>	1	\$ 68.00	\$ 68.00
6	BOOT LID LOCK <i>Damaged</i>	1	\$ 174.00	\$ 174.00
7	BOOT LID HINGE <i>Not m</i>	2	\$ 168.00	\$ 336.00
8	BOOT LID REFLECTOR <i>2H at</i>	2	\$ 222.30	\$ 444.60
9	BOOT LID WEATHER STRIP <i>lt</i>	1	\$ 184.00	\$ 72.20
10	REAR BUMPER <i>replaced</i>	1	\$ 688.90	\$ 688.90
11	REAR BUMPER LOWER LIP <i>replaced</i>	1	\$ 360.00	\$ 360.00
12	REAR BUMPER SIDE RETAINER <i>m</i>	2	\$ 89.60	\$ 179.20
13	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 498.00	\$ 498.00
14	REAR BUMPER REINFORCEMENT BRACKET <i>Best</i>	2	\$ 89.00	\$ 178.00
15	REAR BUMPER SPONGE <i>compressed</i>	1	\$ 211.00	\$ 211.00
16	TAIL LAMP <i>2H at</i>	2	\$ 422.00	\$ 844.00
17	TAIL LAMP PANEL <i>Repair</i>	2	\$ 265.00	\$ 530.00
18	REAR FENDER <i>Not Neu</i>	2	\$ 927.00	\$ 1,854.00

19	REAR FENDER INNER TRIM <i>new</i>	2	\$ 223.00	\$ 446.00	+
20	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 142.00	\$ 142.00	+
21	REAR END PANEL <i>Detd-</i>	1	\$ 412.00	\$ 412.00	✓
22	REAR END PANEL TOP GARNISH <i>2nd</i>	1	\$ 169.00	\$ 169.00	✓
23	REAR FLOOR PANEL <i>Rgs</i>	1	\$ 794.00	\$ 794.00	+
24	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 219.00	\$ 219.00	+
25	REAR TOOLS SPONGE <i>new</i>	1	\$ 167.00	\$ 167.00	+
26	REAR EXHAUST INSULATOR <i>green</i>	1	\$ 189.00	\$ 189.00	+
27	REAR EXHAUST MOUNTING	4	\$ 30.00	\$ 120.00	+

4046.4
364.76

TOTAL PRICE \$ 10,176.90
LESS 10% \$ 1,017.69
SUB TOTAL PRICE \$ 9,159.21

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new new</i>	1	\$ 50.00	\$ 50.00	30
2	BOOT LID SEALANT(SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
3	BOOT LID OUTER RUBBER <i>new</i>	1	\$ 180.00	\$ 180.00	100
4	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
5	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
6	TAIL LAMP PANEL SEALANT <i>new</i>	2	\$ 80.00	\$ 160.00	+
7	REAR FENDER INNER TRIM CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
8	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 200.00	\$ 200.00	60
9	REAR END PANEL TOP GARNISH CLIP <i>new</i>	1	\$ 20.00	\$ 20.00	10
10	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 250.00	\$ 250.00	+
11	REAR EXHAUST PIPE <i>new</i>	1	\$ 1,100.00	\$ 1,100.00	+
12	REVERSE SENSOR <i>Revised</i>	1	\$ 220.00	\$ 220.00	200

440 TOTAL \$ 2,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 1,800.00	900	
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,600.00	800	
3	TUFF COAT	\$ 250.00	40	
4	WIRING CHECK	\$ 120.00	30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	50	

6	TRANSFER BOOTLID MECHANISM	\$ 80.00 40	
6	TRANSFER BOOTLID WINDSCREEN	\$ 100.00	X
7	TO REMOVE AND REFIX EXHAUST PIPE	\$ 320.00	X
8	BREAK SEAL	\$ 80.00 60	

TOTAL

\$4,470.00

1920

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,479.21

TOTAL LABOUR COST : \$ 4,470.00

TOTAL REPAIR COST : \$ 15,949.21

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lj
H/S 07/02/18.
06 days.

total: 6001.76
H/S A.812

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: