

30/05/2001

ASS. REC. BY:

REF: CS/FCI18002469/T1903 n2

Head Instruction:

Surveyor:

Tauhidh

ASSIGNMENT (Office)

CWS

From (Person):

Joanne Yong

of

FCI

Date/Time:

6/2/18 @ 5:24pm

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKV7742A

Insured:

SHA7297P

at Workshop m/s

Volkswagen Centre
247 Alexandra Rd

Tel:

63057176

Policy No:

Claim No:

D18001047MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 02/02/2018

CA / REV / REP. / REV 24 HRS

'Ds'

8/2/18 @ 2pm

H.O.D. Endorsement:

Date/Time:

9:34am @ 7/2/18

Person Contacted:

Chermaine

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKV7742A-X

SHA7297P-CS/FCI17022950/Yrb

D.O.A. 29/11/2017

12/2/18 @ 3pm revised to Joanne Yong by email.

27/5/18 @ 2:04pm confirmed with Pearlyn final fig \$5198.54, 3 days.

CPed \$7314.12, 312)

FCI

150
50
50
39
289



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002469/T1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7297P	Veh. Inspected	SKV 7742A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001047MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/02/2018	Inspection Date		
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001047MFSH

Date: 12 February 2018

Our Ref: CS/FCI18002469/T1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKV 7742A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/02/2018 at the premises of M/s VOLKSWAGEN, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,512.71</u> .
Revised Estimate Amount	: S\$ <u>4,178.63</u> .
"Check" Items Amount	: S\$ <u>894.08</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	05-02-2018	Our Ref No. D18001047MFSH
Accident Date	02-02-2018	Claim Type. Third Party
Insured Vehicle	SHA7297P	Third Party Vehicle. SKV7742A
Survey Location	247 ALEXANDRA ROAD	
Contact Person.	CHARMAINE KONG	
Contact No.	63057176/ 63057299	Fax No. 64743643
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	VOLKSWAGEN CENTRE SINGAPORE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234641)



PRI Documents



Close



PRI Header Details

Claim No	D18001047MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & VOLKSWA PTE LTD
Workshop Name	VOLKSWAGEN CENTRE SINGAPORE (Contact Person : CHARMAINE KONG)	Survey Location & Contact Details	247 ALEXANDRA ROAD Mobile: 63057299 , Phone: 63057176 , Fax: 6474364: EmailId: EDMUND.GOH@VW.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7297P	TP Vehicle No	SKV7742A
PRI Recieved Date	05-02-2018 04:09:41 PM	Surveyor Appointed Date	06-02-2018 05:23:15 PM	Surveyor Accept Date	07-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-02-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 May 2018 2:04 PM
To: 'Cheong, Pearlyn (VWG Singapore)'; Taufikh (LKKAUTO); SUR; Admin A; Admin-D (LKKAUTO)
Cc: Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Foo, John (VWG Singapore)
Subject: RE: SKV7742A - FINALISE

Dear Pearlyn,

Confirm final fig \$5198.59 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]
Sent: Friday, 23 March 2018 3:48 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>
Subject: SKV7742A - FINALISE

Dear Taufikh,

Please confirmed

COR \$5198.59 before GST

Total 3 working days repairs

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
Main line: +65 6305 7299
Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 12 February 2018 3:00 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001047MFSH/1
Attachments: CSFCI18002469T1qd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SKV 7742A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 7 February 2018 9:51 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001047MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 February 2018 5:24 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001047MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System



MSIG Insurance (Singapore) Pte. Ltd.
 4 Selegie Way #21-01 SGX Centre 2 Singapore 068971
 Tel: (65) 6827 7888 Fax: (65) 6827 7500
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form M.X.1
 Individual Ownership

VW DRIVEEASY
 Comprehensive

Certificate No. A 2862...250 AVW

Excess : SGD500

Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
 SKV7742A

2. Name of Policyholder
 Esteem Packaging Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
 30/09/2017

4. Date of Expiry of Insurance
 29/09/2018

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace making reliability trial speed testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT VOLKSWAGEN CENTRE SINGAPORE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189)

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.



Signature / Date

Counter-Signatory:

Winner Consultancy Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers

Amy Ler
 Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company, and Counter Signed by a duly authorised representative of the Counter-Signatory

XWCP1 RASK20170909060402774

SKU7742A
 CONTACT : 94502726
 EMAIL : sgtan@

REPUBLIC OF SINGAPORE
 IDENTITY CARD NO. S1667143F



TAN SENG GUAN

Race
 CHINESE

Date of Birth
 23-05-1964

Country of Birth
 SINGAPORE

Sex
 M

REPUBLIC OF SINGAPORE — DRIVING LICENCE



License Number: S1667143F

TAN SENG GUAN

Birth Date: 23 May 1964

Issue Date: 25 Jun 2004



Taxi driver SHA7297P
 Low Kuan Liang
 S0166586C
 HP: 9798 3322



2451195

NRIC No: S1667143F



Board Grade: A+
 Date of Issue: 05-10-1994

SO CHOA CHU KANG NORTH S #06-07
 SINGAPORE 689574

NRIC No: S1667143F Date: 02-10-2000 No: 3876321

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 3	Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg	10 Jul 1987



LKK... hence notify
the Repair... following:
• To resurvey damaged parts spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party... is on a "Without Prejudice" basis
PDI TUAS
• No illegal modification(s) is allowed
ESTEEM PACKAGING PTE LTD
TAN SENG GUAN
31 WOODLANDS CLOSE
#01-14 WOODLANDS HORIZON
Singapore, 737855
Singapore

Taylor 9749249 PDI TUAS
WP
8/2/18 @ 2:15pm
3 days
Resurvey before paint
sur CLK auto...

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV031291
Quote No. SER/QUO/1800198
Quote Date 03/02/18
Salesperson Jimmy Lee
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	60,074	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKV7742A	WVWZZZ16ZFM048893	30/09/15	Jimmy Lee
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F72067	1634G5

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	2	UNIT		840 1,680.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		280.00
	Nett				
	Sum Labor				4,840.00
P 5C6807251E	FOAM INSERT	1	Pieces		142.24
P 5C6807305	BUMPER INFORCEMENT	1	Pieces		445.64
P 5C6807375	BUMPER BRACKET LH	1	Pieces		83.31
P 5C6807376	BUMPER BRACKET RH	1	Pieces		83.31
P 5C6807393D	BUMPER GUIDE LH	1	Pieces		69.79
P 5C6807394D	BUMPER GUIDE RH	1	Pieces		69.79
P 5C6807417J GRU	REAR BUMPER COVER	1	Pieces		1,020.21
P 5C6807433J	SPOILER	1	Pieces		412.75
P 5C6807863B	STRIP	1	Pieces		96.40
P 5C6919491D	SENSOR BRACKET	1	Pieces		23.79
P 5C6919491E	SENSOR BRACKET	1	Pieces		23.79
P 5C6919491E	SENSOR BRACKET	1	Pieces		23.79
P 5C6919492D	SENSOR BRACKET	1	Pieces		23.79
P D 180KU2A1	2KADHESIVE	1	Pieces		89.84
P D 822150A1	BONDAGENT	1	Pieces		64.27
Sum carried forward					7,512.71

PDI TUAS

PDI TUAS

ESTEEM PACKAGING PTE LTD
TAN SENG GUAN
31 WOODLANDS CLOSE
#01-14 WOODLANDS HORIZON
Singapore, 737855
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV031291
Quote No. SER/QUO/1800198
QuoteDate 03/02/18
Salesperson Jimmy Lee
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	60,074	Kong Charmaine
License No.	VIN	Initial Registration	Sales Advisor
SKV7742A	WVWZZZ16ZFM048893	30/09/15	Jimmy Lee
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F72067	1634G5
Continued			7,512.71
Sum Item			2,672.71
Sum Labor			4,840.00
Sum Item			2,672.71
Total SGD			7,512.71
7% GST			525.89
Total SGD Incl. GST			8,038.60

Explanations

P = Proportionately Charged

Payment Terms No Credit

7944.79

Payments to: - BBN: - Acc.-No.:

Service Order Confirmation

SERVICE ORDER NO: 18IP0403

CUSTOMER NO.: CV031291

CUSTOMER NAME: ESTEEM PACKAGING PTE LTD

TELEPHONE NO.: TAN SENG GUAN

ADDRESS: 31 WOODLANDS CLOSE #01-14 WOODLANDS HORIZON
Singapore

VEH No.: SKV7742A

Order Date: 08/02/18

Reg Date: 30/09/15

KM: 64,285

SA: Kong Charmaine

VIN NO.: WVVZZZ16ZFM048893

ENGINE NO:

MODEL: JETTA TSI (DSG) HIGHLINE H1DCMODEL NO.: 1634G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	480		480
2	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	280		280
3	B&P ALEX LABOUR LABOUR	1	UNIT	840		840
4	B&P ALEX PAINT SPRAY PAINT	1	UNIT	800		800
5	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
6	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Item						
7	5C6807421H GRU REAR BUMPER - IMPROVED VERSION	1	PCS	1,452.29		1,452.29
8	5C6807433J SPOILER	1	PCS	412.75		412.75
9	5C6807863B STRIP	1	PCS	96.40		96.40
10	5C6919491D SENSOR BRACKET	1	PCS	23.79		23.79
11	5C6919491E SENSOR BRACKET	1	PCS	23.79		23.79
12	5C6919491E SENSOR BRACKET	1	PCS	23.79		23.79
13	5C6919492D SENSOR BRACKET	1	PCS	23.79		23.79
14	D 180KU2A1 2KADHESIVE	1	PCS	89.84		89.84
15	D B22150A1 BONDAGENT	1	PCS	64.27		64.27
16	5C6807305 REINFORCEMENT	1	PCS	445.64		445.64
17	5C6807251F FOAM INSERT	1	PCS	142.24		142.24

Remarks : MS FIRST CAPITAL DIRECT SETTLEMENT

DOA 2/2/2018

SURVEYOR LKK TAUFIKH

TP VEHICLE SHA7297P

Service Order Confirmation

SERVICE ORDER NO: 18IP0403

CUSTOMER NO.: CV031291

CUSTOMER NAME: ESTEEM PACKAGING PTE LTD

TELEPHONE NO.: TAN SENG GUAN

ADDRESS: 31 WOODLANDS CLOSE #01-14 WOODLANDS HORIZON
Singapore

VEH No.: SKV7742A

Order Date: 08/02/18

Reg Date: 30/09/15

KM: 64,285

SA: Kong Charmaine

VIN NO.: WVVZZZ16ZFM048893

ENGINE NO:

MODEL: JETTA TSI (DSG) HIGHLINE HIDC MODEL NO.: 1634G5

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	5,198.59
GST AMOUNT	363.90
TOTAL AMOUNT	5,562.49

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

PDI TUAS

wood purpose.

PDI TUAS

ESTEEM PACKAGING PTE LTD
TAN SENG GUAN
31 WOODLANDS CLOSE
#01-14 WOODLANDS HORIZON
Singapore, 737855
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV031291
Quote No. SER/QUO/1800501
QuoteDate 23/03/18
Salesperson Jimmy Lee
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	JETTA TSI (DSG) HIGHLINE HIDC	64,285	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SKV7742A	WVWZZZ16ZFM048893	30/09/15	Jimmy Lee
Engine Code	Labor Type	Engine No.	Model Code
	M4	CAX F72067	1634G5

SUPPLEMENTARY

No.	Description	Qty.	UoM	Unit Price	Amount
5C6807251F	FOAM INSERT	1	Pieces	142.24	142.24
5C6807305	REINFORCEMENT	1	Pieces	445.64	445.64
	Sum Item				587.88

Sum Item 587.88

Total	SGD	587.88
7% GST		41.15
Total SGD Incl. GST		629.03

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002469/T1qd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7297P	Veh. Inspected	SKV 7742A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001047MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN JETTA	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WWWZZZ16ZFM048893	Colour	BRONZE	
Odometer	61621	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2018	Inspection Date	08/02/2018	
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 7742A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FOAM INSERT (SN)	DEFORMED	142.24	142.24
1	BUMPER INFORCEMENT (SN)	BENT	445.64	445.64
1	BUMPER BRACKET LH (SN)	NOT NECESSARY	83.31	-
1	BUMPER BRACKET RH (SN)	NOT NECESSARY	83.31	-
1	BUMPER GUIDE LH (SN)	NOT NECESSARY	69.79	-
1	BUMPER GUIDE RH (SN)	NOT NECESSARY	69.79	-
1	REAR BUMPER COVER (SN)	DEFORMED	1,452.29	1,452.29
1	SPOILER (SN)	CUT	412.75	412.75
1	STRIP (SN)	NECESSARY	96.40	96.40
1	SENSOR BRACKET (SN)	NECESSARY	23.79	23.79
1	SENSOR BRACKET (SN)	NECESSARY	23.79	23.79
1	SENSOR BRACKET (SN)	NECESSARY	23.79	23.79
1	SENSOR BRACKET (SN)	NECESSARY	23.79	23.79
1	2KADHESIVE (SN)	NECESSARY	89.84	89.84
1	BONDAGENT (SN)	NECESSARY	64.27	64.27
			3,104.79	2,798.59
LABOUR				
LABOUR.			1,680.00	840.00
SPRAY PAINT.			2,400.00	800.00
PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.			480.00	480.00
ELECT WIRING & MECH COMPO.			280.00	280.00
			4,840.00	2,400.00
GRAND TOTAL			7,944.79	5,198.59
RECOMMENDED COST OF REPAIRS				5,198.59

Report Ref No. CS/FCI18002469/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.