

ASS. REC. BY:

REF:

CS/ASM18002472/G16³²

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Kitty Tao

of

ASM

Date/Time: 06022018 5:56pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 8261J

Insured:

at Workshop m/s

Trans Eurokars

Tel: 9777928 / 63957875

of

5 Ubi Close

Policy No:

Claim No:

S8M00866

Sum Insured:

Excess:

NIL

Make of Veh:

(Client's Record)

D.O.A. 03.02.2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

07.02.2018

9:35am

Person Contacted:

Ronald

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 8261J - X
3/2-	Revert via ASM.
	Confirm \$4237.49. 4days (Red. 197930, 31%)
	Attached DV & Final Bill.

(08/11/13)

A.S.G. REC. BY:

REF:

AXA

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Trans Eurocars

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

Nil

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value:

\$73K.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKW 8261J

Yr Regn:

18 Nov 2015

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2

C.C.

1496

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

31641

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM60J2HAA 01100260

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYOTA YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

07-02-18

Survey held at

W/S

11:40AM

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 01 AUG 2018

Date/Time, File Pass to?



Preli. Report

1) 1/3 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

OD

Lump Sum / I.B.I. (\$ 4287.49)

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18002472/Gtb	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 07-02-2018	
		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKW 8261J
Policy No.		Coverage (\$)	0.00
Claim No.	S8M008GG	Excess (\$)	0.00
Assign From	SMART CLAIM (KITTY TEO)	Assign Date	06/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/02/2018	Inspection Date	07/02/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			



Service Request Details

Claim

S8M008GG

Reference

None 

Loss Date

February 3, 2018

Request Date

February 6, 2018

Due Date

February 13, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKW8261J

Make

MAZDA

Service Address

5 Ubi Close, , 408605

Primary Contact/Insured

LIM MEI LING

BLK 527, HOUGANG AVE 6, 530527, Singapore

NLEMKNG@SINGNET.COM.SG

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

EXCESS NIL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/02/2018 11:37
Date Of Accident	03/02/2018 09:15
Exact Location Of Accident	HOUGANG AVENUE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW8261J
Insured/Policyholder	
Name Of Registered Owner	LIM MEI LING
NRIC No	S8027918C
Email Address	TRIALMAX80@YAHOO.COM
Mobile Phone No	(LOCAL) +65-93669981
Alternative Phone No	OTHERS-93669981

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 2
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA129822/1
Cover Note Number	

Driver

Name of Driver	LIM MEI LING
NRIC No	S8027918C
Date Of Birth	06/09/1980
Occupation	INDOOR
Date Of Driving Pass	26/01/2000
Driving Experience	18 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93669981
Fax Number	
Contact Number	OTHERS-93669981
Email Address	TRIALMAX80@YAHOO.COM

Address	BLK 527 HOUGANG AVENUE 6 #11-209
Postcode	530527
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 3/2/18
11:00am

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

NO AVAILABLE SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Car was parked stationary at the car park. When I wanted to drive off, I realised that the rear windscreen was smashed. Seem to be from a foreign object.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKW8261J		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MAZDA		
Vehicle Model :	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT		
Chassis No. :	JM6DJ2HAA01100260		
Propellant :	Petrol		
Engine No. :	P520275128		
Engine Capacity :	1496 cc		
Maximum Power Output :	85.0 kW (113 bhp)		
Maximum Laden Weight :	1509 kg		
Unladen Weight :	1036 kg		
Year Of Manufacture :	2015		
Original Registration Date :	18 Nov 2015		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$56,001.00		
COE Expiry Date :	17 Nov 2025		
Road Tax Expiry Date :	17 May 2018		
PARF Eligibility Expiry Date :	17 Nov 2025		
Inspection Due Date :	17 Nov 2018		
Intended Transfer Date :	08 Feb 2018		
CO2 Emission :	119.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$10,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)



**SINGAPORE POLICE FORCE
CASE CARD**

Report Number: F/20180203/0104

Classification: Littering

Actions Taken

- | | |
|---|---|
| ☐ Police Advisory Issued | ☐ Community Mediation |
| ☐ Magistrate's Complaint | ☐ Investigation Branch |
| ☐ Others: | |

Officer's Name:

Contact Number:
6489 0999



redefining / insurance

AXA Insurance Pte Ltd
☎ 1800 880 4888 (Within Singapore)
(65) 6880 4888 (International)
☎ (65) 6880 4740
✉ customer.care@axa.com.sg
🌐 www.axa.com.sg

Certificate of Insurance

account number
03830

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960-Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	LIM MEI LING	Certificate number	GA129822 / 1
Cover	Comprehensive	Chassis number	JM6DJ2HAA01100260
Plan name	Flexi	Engine number	P520275128
NCD applicable	50%		
Vehicle registration number	SKW8261J		
Period of Insurance	from 18/11/2017 to 17/11/2018 (both dates inclusive)		
Finance loan company	HONG LEONG FINANCE LIMITED		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Windscreen Excess	Not Applicable
---------------	-------------------	----------------

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).
The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8027918C**

Name: **LIM MEI LING (LIN MEILING)**

Birth Date: **06 Sep 1980**

Issue Date: **06 Dec 2008**

001040213J




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8027918C**

Name: **LIM MEI LING (LIN MEILING)**
林美玲

Race: **CHINESE**

Date of birth: **06-09-1980** Sex: **F**

Country of birth: **SINGAPORE**






YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **26 Jan 2000**

Licence No: **S8027918C**

NP 428A



4697048

NRIC No: **S8027918C**

Date of issue: **22-03-2011**

Address: **APT BLK 527 HOUGANG AVENUE 6 #11-209 SINGAPORE 530527**






TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Lim Mei Ling ADDRESS : Blk 527 Hougang Avenue 6 #11-209 Singapore 530527 TEL : 93669981	WIP : 61173 EXCESS : DATE: 5-Feb-18
VEH NO :	SKW8261J	DATE IN :	CONTACT PERSON : RONALD 6395 7875
CHASSIS NO :	JM6DJ2HAA01100260	MILEAGE :	TYPE OF CLAIM : OWN DAMAGE CLAIM
MODEL :	MAZDA2 HB DELUXE	DATE REG.: 18-Nov-15	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	TAILGATE / Bnc	1	MD0Y0-62-02XB \$ 911.10
2	VALVE ONEWAY, TAILGATE / Bnc	2	MGHP9-58-867 \$ 22.80
3	TAPE PROTECTOR, TAILGATE / Bnc	2	MG043-62-864A \$ 6.60
4	REAR WINDSCREEN / Bnc	1	MDA6R-63-930A \$ 878.80
5	FASTENER, REAR WINDSCREEN / Bnc	2	MD204-50-896A \$ 5.20
6	MAZDA, EMBLEM /	1	MD82M-51-721 \$ 55.50
7	MASCOT, REAR /	1	MD09W-51-730 \$ 58.20
8	SKYACTIV, EMBLEM /	1	MD09W-51-771 \$ 64.70
9	TAPE, REAR SIDE SPOILER /	1	MD10V-50-898 \$ 17.50
10	TAPE, REAR SIDE SPOILER /	1	MD09V-50-898 \$ 17.50
11	TAPE, REAR SIDE SPOILER /	1	MD10T-50-898 \$ 12.60
12	TAPE, REAR SIDE SPOILER /	1	MD09T-50-898 \$ 12.60
13	CLIP, REAR SIDE SPOILER /	4	MD09W-50-M38A \$ 19.60
14	GASKET(LHS), TAILGATE LAMP /	1	MDA6A-51-3J8 \$ 51.70
15	GASKET(RHS), TAILGATE LAMP /	1	MDA6A-51-3H8 \$ 51.70
16	TRAY, REAR PACKAGE 7 x nn	1	MD09W-68-310A02 \$ 377.00
TOTAL PARTS			\$ 2,563.10
LESS 10%			\$ 256.31
TOTAL PARTS COST			\$ 2,306.79

Labour Description

1	TO REPLACE TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,320.00
2	TO RESPRAY TAILGATE.	630	\$ 1,260.00
3	MZ-BR-WIND02 TO REPLACE REAR WINDSCREEN GLASS. ✓	NETT	\$ 560.00

4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS. <i>rec ✓</i>	NETT	\$ 120.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES. <i>rec 20.</i>	NETT	\$ 100.00
TOTAL LABOUR			\$ -	\$ 3,960.00
TOTAL PARTS			\$ -	\$ 2,306.79
TOTAL			\$ -	\$ 6,266.79
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -
GRAND TOTAL			\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

*4D ang.
part by part.
refine paint photos.
Gino Qiang - 82880282.
Excess : Nil
Authorized -
07/2/18.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



AXA INSURANCE PTE LTD		NAME : Ms Lim Mei Ling		WIP : 61173	
8 SHENTON WAY		ADDRESS : Blk 527 Hougang Avenue 6		EXCESS : \$	
#24-01 AXA TOWER		#11-209		DATE: 5-Feb-18	
SINGAPORE 068811		Singapore 530527			
ATTN. : MOTOR CLAIMS		TEL : 93669981			
FAX :					
VEH NO :	SKW8261J	DATE IN :		CONTACT PERSON :	RONALD 6395 7875
CHASSIS NO :	JM6DJ2HAA01100260	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGE CLAIM
MODEL :	MAZDA2 HB DELUXE	DATE REG.:	18-Nov-15	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	MD0Y0-62-02XB	\$ 911.10	\$ 911.10	
2	2	MGHP9-58-867	\$ 22.80	\$ 22.80	
3	2	MG043-62-864A	\$ 6.60	\$ 6.60	
4	1	MDA6R-63-930A	\$ 878.80	\$ 878.80	
5	2	MD204-50-896A	\$ 5.20	\$ 5.20	
6	1	MD82M-51-721	\$ 55.50	\$ 55.50	
7	1	MD09W-51-730	\$ 58.20	\$ 58.20	
8	1	MD09W-51-771	\$ 64.70	\$ 64.70	
9	1	MD10V-50-898	\$ 17.50	\$ 17.50	
10	1	MD09V-50-898	\$ 17.50	\$ 17.50	
11	1	MD10T-50-898	\$ 12.60	\$ 12.60	
12	1	MD09T-50-898	\$ 12.60	\$ 12.60	
13	4	MD09W-50-M38A	\$ 19.60	\$ 19.60	
14	1	MDA6A-51-3J8	\$ 51.70	\$ 51.70	
15	1	MDA6A-51-3H8	\$ 51.70	\$ 51.70	
16	1	MD09W-68-310A02		\$ 377.00	
TOTAL PARTS			\$ 2,186.10	\$ 2,563.10	
LESS 10%			\$ 218.61	\$ 256.31	
TOTAL PARTS COST			\$ 1,967.49	\$ 2,306.79	
Labour Description					
1		TO REPLACE TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,320.00	
2		TO RESPRAY TAILGATE.	\$ 630.00	\$ 1,260.00	
3	MZ-BR-WIND02	TO REPLACE REAR WINDSCREEN GLASS.	\$ 560.00	\$ 560.00	
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$ 120.00	\$ 120.00	

5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
7	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 2,320.00 \$ 3,960.00
			TOTAL PARTS	\$ 1,967.49 \$ 2,306.79
			TOTAL	\$ 4,287.49 \$ 6,266.79
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 4,287.49
			GST 7%	\$ 300.12 \$ -
			GRAND TOTAL	\$ 4,587.61 \$ -

REMARKS: SKW8261J

4 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Attn : Motor Claims Department

DATE : 23/07/2018

Car Regn No : **SKW8261J**

Accident involving SKW8261J on 03/02/2018

Own Damage Claim

Dear Sirs

The repair has been completed for **SKW8261J**. We submit the following documents for your perusal:

- | | |
|---------------------------------------|--------------------|
| 1) Invoice No : 30000883 | \$ 4,587.61 |
| 2) Discharge Voucher signed by client | |

TOTAL	<u>\$ 4,587.61</u>
--------------	---------------------------

Please pay **Trans Eurokars Pte Ltd** the sum of **\$4,587.61** as soon as possible and mail your cheque to **12 Sungei Kadut Avenue Singapore 729648**.

Yours faithfully,

Stanley Ngu
Manager - Body & Paint Division
DID : 63602845
FAX : 63602899
e-mail : stanley@eurokars.com.sg



Corporate Head Office

: Trans Eurokars Pte Ltd, Eurokars Centre, 12 Sungei Kadut Ave Singapore 729648
Tel : 6363 3003 Fax : 6369 3003 BRN.199103859N

Showroom & Service Centres : 5 Ubi Close Singapore 408605

Sales Tel : 6395 8888 Service Tel : 6395 8899
Sales Fax : 6846 1700 Service Fax : 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel : 6603 6118 Service Tel : 6603 6128
Sales Fax : 6476 7073 Service Fax : 6476 7417

zoom-zoom

ID:t05

TAX INVOICE
GST Reg No:M90364005A

A0002 INS-AXA

CUSTOMER: AXA INSURANCE SINGAPORE PTE LTD
ADDRESS: 8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

PAGE NO : 1
INVOICE NO: 30000883
DEPT/POS ID: I / 12
DATE IN 03/02/2018
DATE PRINTED: 20/07/2018
JOB NO: 61173
CSO/OP CODE: Catherine Chua

TEL NO:

MODEL: MAZDA2 HB HIGH GRADE INT OFF W
CHASSIS NO: JM6DJ2HAA01100260
ENGINE NO: P520275128
DESCRIPTION: Body repair

REGN NO: SKW8261J
REGN DATE: 18/11/2015
MILEAGE: 31641
REQUISITION NO: RONALD

CODE	DESCRIPTION	AMOUNT
NOTES	INSURANCE CLAIM: OWN DAMAGE	0.00
	DATE OF ACCIDENT: 03/02/2018	
MZ-BR-RE	TO REPLACE TAILGATE. TO REPAIR ALL AREAS AFFECTE BY THE ACCIDENT.	660.00
MZ-SP-SR	TO RESPRAY REAR BUMPER.	630.00
MZ-BR-WI	TO REPLACE REAR WINDSCREEN GLASS.	560.00
MZ-BR-GL	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	120.00
MZ-BR-EL	TO CHECK ELECTRICAL SYSTEM	150.00
MZ-BR-RE	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.00
MZ-BR-SU	SUNDRIES	20.00
DOYO-62-02XB	BODY,LIFT GATE HB DJ 1.0 911.10	819.99
GHP9-58-867	VALVE,ONEWAY 2.0 11.40	20.52
GO43-62-864A	TAPE,PROTECTOR-STOPP 2.0 3.30	5.94
DA6R-63-930A	REAR WINDSCREEN DJ 1.0 878.80	790.92
D204-50-896A	FASTENER 2.0 2.60	4.68
DB2M-51-721	ORNAMENT,CAR NAME-RE 1.0 55.50	49.95
D09W-51-730	MASCOT,REAR DJ 1.0 58.20	52.38
D09W-51-771	ORNAMENT DJ 1.0 64.70	58.23
ORIGINAL COPY		

All major repaired parts stated above are covered under a 6 months or 10,000 km warranty, whichever comes first. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling.

Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

TRANS EUROKARS PTE LTD

CASH / NETS / AMEX / VISA / MASTER
NO:

Customer Signature

Authorised Signature



ZOOM-ZOOM

Corporate Head Office : Trans Eurokars Pte Ltd, Eurokars Centre 12 Sungai Kadut Ave Singapore 729648
Tel: 6363 3003 Fax: 6369 3003 BRN:199103859N

Showroom & Service Centre: 5 Ubi Close Singapore 408605
Sales Tel : 6395 8888 Service Tel : 6395 8899
Sales Fax : 6846 1700 Service Fax : 6744 9402

23 Leng Kee Road Singapore 159085
Sales Tel : 6603 6118 Service Tel : 6603 6126
Sales Fax : 6476 7073 Service Fax : 6476 7417

ID: t05

TAX INVOICE
GST Reg No: M90364005A

A0002 INS-AXA

 PAGE NO: 2
 INVOICE NO: 30000883
 DEPT/POS ID: I / 12
 DATE: 03/02/2018
 DATE PRINTED: 20/07/2018
 JOB NO: 61173
 CSO/OP CODE: Catherine Chua

 CUSTOMER: AXA INSURANCE SINGAPORE PTE LTD
 ADDRESS: 8 SHENTON WAY
 #24-01 AXA TOWER
 SINGAPORE 068811
 SINGAPORE

TEL NO:

 MODEL: MAZDA2 HB HIGH GRADE INT OFF W
 CHASSIS NO: JM6DJ2HAA01100260
 ENGINE NO: P520275128
 DESCRIPTION: Body repair

 REGN NO: SKW8261J
 REGN DATE: 18/11/2015
 MILEAGE: 31641
 REQUISITION NO: RONALD

CODE	DESCRIPTION	AMOUNT
D10V-50-898	TAPE 1.0 17.50	15.75
D09V-50-898	TAPE 1.0 17.50	15.75
D10T-50-898	TAPE 1.0 12.60	11.34
D09T-50-898	TAPE 1.0 12.60	11.34
D09W-50-M38A	CLIP, GARNISH 4.0 4.90	17.64
DA6A-51-3J8	GASKET(L), LAMP-TRUNK 1.0 51.70	46.53
DA6A-51-3H8	GASKET(R), LAMP-TRUNK 1.0 51.70	46.53
Parts 1,967.49		Net 4287.49
Surcharge 0.00		G.S.T. 7% 300.12
Labour 2,320.00		Total 4587.61
Menus 0.00		Paid 0.00
		Amount Due 4587.61

ORIGINAL COPY

All major repaired parts stated above are covered under a 6 months or 10,000 km warranty, whichever comes first. The above excludes expendable maintenance items, natural wear & tear components and parts damaged due to negligence or improper handling.

Proof of Payment is only valid if this invoice is stamped "PAID" & signed by us. Any dispute to this invoice must be made within 5 calendar days.

TRANS EUROKARS PTE LTD

 CASH / NETS / AMEX / VISA / MASTER
 NO:

Customer Signature

Authorised Signature



ZOOM-ZOOM

Corporate Head Office

Showroom & Service Centre

Trans Eurokars Pte Ltd, Eurokars Centre 12 Sungei Kadut Ave Singapore 729648

Tel: 6363 3003 Fax: 6369 3003 BRN.199103859N

5 Ubi Close Singapore 408605

Sales Tel : 6395 8888 Service Tel : 6395 8899
Sales Fax : 6846 1700 Service Fax : 6744 9402

23 Leng Kee Road Singapore 159085

Sales Tel : 6603 6118 Service Tel : 6603 6128
Sales Fax : 6478 7073 Service Fax : 6478 7417

18



DISCHARGE VOUCHER

I/ We hereby acknowledge having received from the under-mentioned
repairers my/our vehicle No: SKW8261J which has been
repaired to my satisfaction and I/we admit that the payment for such
repairs by Trans Eurokars Pte Ltd is in full and final discharge of my claim
under policy number: GA129822/1 in respect of damage
caused to the said vehicle as a result of an accident that occurred on
02/02/2018 at HONGKONG AVENUE 6.


Witnessed by Repairers



13/02/18
Date


Signature by Insured

13/02/18
Date



Corporate Head Office

: Trans Eurokars Pte Ltd, Eurokars Centre, 12 Sungai Kadut Ave Singapore 729648
Tel: 6363 3003 Fax: 6369 3003 BRN.199103859N

Showroom & Service Centre :

23 Leng Kee Road Singapore 159095

Sales Hotline : 6603 6118 Service Hotline : 6603 6128
Sales Fax : 6476 7073 Service Fax : 6476 7417

5 Ubi Close Singapore 408605

Sales Hotline : 6395 6888 Service Hotline : 6395 6899
Sales Fax : 6646 1700 Service Fax : 6744 9402

<< Service Request Details

Claim	S8M008GG	Vehicle Information	
Reference		Incident Vehicle	SKW8261J
CS/ASM18002472/Gtbs Date		Registration #	MAZDA
February 3, 2018	Request Date	Model	2 1.5
February 6, 2018	Due Date		Close, , , 408605
May 7, 2018	Vendor Name		
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)	Type of		
Own Damage	Services		

Actions

Next Step

PAST DUE: Report that your block modify the Expected Completion Date.

Complete Work More

Primary Contact/Insured

LIM MEI LING
BLK 527, HOUGANG AVE 6, #11-209, 530527, Singapore
NLEMKNG@SINGNET.COM.SG

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SKW 8261J ESTIMATE.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	February 8, 2018
PRELI ADVISED SKW 8261J.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	February 8, 2018
NEW EMAIL.msg	Letters and Correspondence	Others	PATIL Amol	February 6, 2018
SKW8261J INSD GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	February 5, 2018
Email received from workshop with OD GIA & Estimate.msg	Letters and Correspondence	Others	PATIL Amol	February 5, 2018

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S8M008GG	Vehicle Information	
Reference		Incident Vehicle	SKW8261J
CS/ASM18002472/Gtts Date		Registration #	MAZDA
February 3, 2018		Model	2 1.5
February 6, 2018			Close, , 408605
May 7, 2018		Primary Contact/Insured	
LKK AUTO CONSULTANTS PTE LOSS LTD (OD)		LIM MEI LING	
Own Damage		BLK 527, HOUGANG AVE 6, #11-209, 530527, Singapore	
Services		NLEMKNG@SINGNET.COM.SG	

Next Step

PAST DUE: Report that your block modify the Expected Completion Date.

Complete Work

More



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKW8261J

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

11/18/2015



Mileage

31641

Age of Vehicle

2

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT... 2015

CATEGORY Driver Name

ASSESSMENT INFO...

2015

FNOL INFORMATI... LIM MEILING

POST SURVEY INF...

ASSESSMENT INFO...

JM6DJ2HAA01100260

FNOL INFORMATI...

19

CATEGORY

Engine No

POST SURVEY INF...

CATEGORY

Driver License #

POLICY INFORMAT...

P520275128

FNOL INFORMATI...

ASSESSMENT INFO...

P520275128

POST SURVEY INF...

CATEGORY

Engine Capacity

CATEGORY

License Type

POLICY INFORMAT...

1496 cc

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Sum Insured

License Issue Date

POLICY INFORMAT...

0

FNOL INFORMATI...

POST SURVEY INF...

ASSESSMENT INFO...

0

mm/dd/yyyy

CATEGORY

Market Value

CATEGORY

License Expiration Date

POLICY INFORMAT...

0

FNOL INFORMATI...

POST SURVEY INF...

mm/dd/yyyy

ASSESSMENT INFO...

73000

CATEGORY

Address

POST SURVEY INF...



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

TOYO 6mm

Rear left side

TOYO 6mm

Front right side

TOYO 6mm

Rear right side

TOYO 6mm

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR	Reviewing	4		
		2	SEALER ON THE WINDSCREEN GLASS	Reviewing	120	NECESSARY	
		3	SUNDRIES	Reviewing	20	NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$4,287.49	Claim Amount	\$4,287.49	

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$2,180.00	\$2,180.00
Miscellaneous	\$140.00	\$140.00
Spare Parts	\$1,967.49	\$1,967.49

Submit for Review