(08/11/17) Surveyor Rajesh | REF: III | 6,24G

ASSIGNMENT

From: | Date: 20.02.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFJ 7988E

at Workshop m/s Kah Motor

of 285 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured: | Excess:

(Client's Record)

Make of Veh: Sin Hai

After 9am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SFJ 7988E Yr Regn: 2018 / JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HONDA HRV 1.5 DX CVT c.c 1496

Colour WHITE A/C: Insured / Std / NI / NA

Sp.Reading 001754 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRU1810GX203494

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	03/02/18	D.O.I.	20/02/18

Survey held at KAH MOTOR

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($) ___S + RS ___SI

☐ : Interview ($) Photos

☐ : Tech. Invs ($) Others

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($)

TOTAL