

ASS. REC. BY:

REF: CS/FCI18002486/Atd3n2 Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Karen Tanof FCIDate/Time: 6/2/18 @ 3.53pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No:

SJL 9020B

Insured:

SHA1516Y

at Workshop m/s

Success United

Tel:

67461515

of

2 Kaki Bkt Ave 2 # 01-33 & #02-29 AutoHub

Policy No:

Claim No:

D18001101MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/1/18

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 10.21pm

Person Contacted:

SiniraVehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SJL 9020B-xSHA1516Y09/2/18 @ 1.29pm Informed Karen Tan, we are pending estimate from repairer.Finalised: 934.75 (Red, 599.45:390%)

REF:

ASSIGNMENT

Weekend car

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJL9020B Yr Regn: 2008 / Dec
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Altis. c.c. 1598
 Colour: Silver. A/C: Insured / Std / NI / NA
 Sp. Reading: 111562 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053ZEE106129310
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16.
 R: 205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 07/02/18.
 Survey held at Success United
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Gap

MV: 14,000 LTA: 7966 NV: 6034

MV: 14K

NV: 8K

Nett: 6K.

RECEIVED 20 APR 2018

Date/Time, File Pass to?

1) 20/4 Typist
 Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$) ☐ : S + RS (\$)
☐ : Interview (\$) ☐ : Photos
☐ : Tech. Invs (\$) ☐ : Others
☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 934.75)

TOTAL

100

50

50

21

221



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002480/Atd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1516Y	Veh. Inspected	SJL 9020B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001101MFSH	Excess (\$)	0.00	
Assign From	CWS (KAREN TAN)	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2018	Inspection Date	07/02/2018	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	06-02-2018	Our Ref No. D18001101MFSH
Accident Date	12-01-2018	Claim Type. Third Party
Insured Vehicle	SHA1516Y	Third Party Vehicle. SJL9020B
Survey Location	2 KAKI BUKIT AVE 2 #01-33 & #02-29KAKI BUKIT AUTOHUB	
Contact Person.	SIRINA SOON	
Contact No.	67461515/ 0	Fax No. 67485015
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SUCCESS UNITED PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234708)



PRI Documents



Close



PRI Header Details

Claim No	D18001101MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & SUCCESS
Workshop Name	SUCCESS UNITED PTE LTD (Contact Person : SIRINA SOON)	Survey Location & Contact Details	2 KAKI BUKIT AVE 2 #01-33 & #02-29KAKI BUKIT AUTO Mobile: 0 , Phone: 67461515 , Fax: 67485015 EmailId: SIRINASSK@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1516Y	TP Vehicle No	SJL9020B
PRI Recieved Date	06-02-2018 04:44:16 PM	Surveyor Appointed Date	06-02-2018 03:52:23 PM	Surveyor Accept Date	07-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-02-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 9 February 2018 1:29 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001101MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SJL 9020B on 07/02/2018.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 7 February 2018 11:04 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001101MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 6 February, 2018 3:53 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001101MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	1335I

Vehicle Details

Vehicle No.:	SJL9020B
Vehicle to be Exported:	No
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4831362
Chassis No.:	MR053ZEE106129310
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	16 Dec 2008
First Registration Date:	16 Dec 2008
Transfer Count:	0
Actual ARF Paid:	\$14,055.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility:	Yes (w.e.f 09 Dec 2017)
OPC Cash Rebate Eligibility Expiry Date:	15 Dec 2018
OPC Cash Rebate Amount:	\$365.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2018
PARF Rebate Amount:	\$7,027.00

Intended COE Rebate Details

COE Expiry Date:	15 Dec 2018
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,130.00
COE Rebate Amount:	\$939.00
Total Rebate Amount:	\$7,966.00

The information contained herein is correct as at 06 Feb 2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1335I
Vehicle Details	
Vehicle No.:	SJL9020B
Vehicle to be Exported:	Yes
Intended De-registration Date:	08 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4831362
Chassis No.:	MR053ZEE106129310
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	16 Dec 2008
First Registration Date:	16 Dec 2008
Transfer Count:	0
Actual ARF Paid:	\$14,055.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	Yes (w.e.f 09 Dec 2017)
OPC Cash Rebate Eligibility Expiry Date:	15 Dec 2018
OPC Cash Rebate Amount:	\$366.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2018
PARF Rebate Amount:	\$7,027.00
Intended COE Rebate Details	
COE Expiry Date:	15 Dec 2018
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$7,130.00
COE Rebate Amount:	\$936.00
Total Rebate Amount:	\$7,963.00



Toyota Corolla Altis 1.6A **\$15,800** **\$14,700 /yr** **12-Aug-2008** **1,598 cc** **120,000 km** **Sedan** **Available**

CREDIT OWNER

Posted: 03-Feb-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$15,800** **\$13,730 /yr** **25-Aug-2008** **1,598 cc** **110,000 km** **Sedan** **Available**

Superb Condition. Elegant White Colour. No Repairs Required, Well Kept, Reliable Model, Fuel Economical. Well Taken Care By Previous Owner. Price Negotiable.

Posted: 05-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$15,800** **\$13,680 /yr** **01-Sep-2008** **1,598 cc** **-** **Sedan** **Available**

Low Interest From 1.99%. Nice Bidded 3 Digit Number! 1 Owner Only! Low Mileage! Extended Warranty Available! A Reliable Family Sedan Well Maintained By Its Previous Owner, A Condition You Must View To...

Dickson Automobile

Posted: 12-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$17,500** **\$14,780 /yr** **22-Sep-2008** **1,598 cc** **135,000 km** **Sedan** **Available**

1 Owner, Perfect For COE Renewal. You Wouldn't Believe The Tip Top Condition Of This Unit Without Viewing It. No Financial Strain As We Provide In House Loans And Other Financial Services To Meet Your ...

Posted: 18-Dec-2017 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) **\$38,800** **\$7,760 /yr** **29-Sep-2008** **1,598 cc** **143,000 km** **Sedan** **Available**

Best Fuel Efficient And Reliable Japanese Sedan, The Brand Speaks For Itself! Well Taken Care Of, Accident Free And Comes With A Genuine Low Mileage With Services Records Too Prove! Great For A Daily ...

Tan Wei Auto Pte Ltd

Posted: 31-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$16,800** **\$12,280 /yr** **17-Oct-2008** **1,598 cc** **-** **Sedan** **Available**

Same Day Collection! \$0 Down Payment! Warranty Till Scrap Package! Inclusive Of Grooming Package! Rumor Of The Toughest Engine In The Market! Proven One Of The Best Fuel Efficient! Why Wait When You A...

Dickson Automobile

Posted: 25-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$13,800** **\$7,760 /yr** **07-Nov-2008** **1,598 cc** **-** **Sedan** **Available**

\$0 Down-payment Available! 1 Owner Only! High Trade-in! STA Certified Cars! All Time Favourite, Reliable Sedan Well Kept In Excellent Condition, View It To Believe! Buy It From Us With A Peace Of Mind...

Dickson Automobile

Posted: 18-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$18,088** **\$13,380 /yr** **10-Nov-2008** **1,598 cc** **-** **Sedan** **Available**

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 08-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (New 5-yr COE) **\$38,800** **\$7,760 /yr** **13-Nov-2008** **1,598 cc** **-** **Sedan** **Available**

\$2800 Down Payment, Monthly From \$688 Onwards. Lowest Interest At 3.68% Per Annum By GV Cars Financing. 100% Loan Approval. 2 Years Warranty By GV In House Workshop. New Paintwork And Leather Seats. 1...

GV Credit Pte Ltd

Posted: 07-Feb-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

PREMIUM AD



Toyota Corolla Altis 1.6A (OPC) (New 5-yr COE) **\$39,777** **\$7,950 /yr** **25-Nov-2008** **1,598 cc** **90,403 km** **Sedan** **Available**

New 5 Years COE! 1st Owner. Low Mileage. Regularly Serviced. Fully Refurbished Condition. Smooth Engine. Affordable Depreciation. Easy Financing. Probably Most Reliable, Comfortable, Yet Fuel Efficient...

Posted: 02-Feb-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A **\$16,800** **\$10,520 /yr** **10-Dec-2008** **1,598 cc** **-** **Sedan** **Available**

Well Maintained, Accident Free, Owner Always Park Car At Office, Powerful Engine And Smooth Transmission, Bank And In House Loan Available, Buy With Confidence! Trade In Are Welcome, Call Us Now To Ma...

Car (S) Pte Ltd

Posted: 06-Feb-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

PREMIUM AD

Toyota Corolla Altis 1.6A **\$18,000** **\$11,920 /yr** **11-Dec-2008** **1,598 cc** **313,200 km** **Sedan** **Available**

Posted: 29-Jan-2018 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

CREDIT OWNER



聯成汽車維修

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921

Tel: 6746 1515 / 6747 1787 Fax: 6748 5015

www.successunited.com.sg

Co. / GST Reg: 200402570G

Estimate : TP/18-022

M/s First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Date : 6th February 2018

Tel: 62482000
Fax: 63273014
Email : motor_claims@first-insurance.com.sg

Vehicle No : **SJL 9020B**
Make/ Model : Toyota Altis
Chassis No : MR053ZEE106129310
Acc. Date : 12.01.2018
Policy No :

Your Ref : SHA 1516Y

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1	Frt Bumper <i>alld</i>		\$ 493.80
2	2	Frt Bumper Side Holder L/R <i>~ 673</i>	\$ 89.60	\$ 179.20
3	1	Frt Bumper Reinforcement <i>~ 504.75</i>		\$ 372.60
				\$ 1,045.60
Less 25%				\$ 261.40
				\$ 784.20
<u>Labour</u>				
1	To Supply OPC plate, sealing & inspection fee			\$ 200.00
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.			\$ 250.00
3	To putty and respray painting on frt bumper.			\$ 300.00
Total				\$ 1,534.20


Success United Pte Ltd

total: 934.75
(P/P)
Admin Lj
L/S 07/02/18
02 Days

No of Days _____

Re-Survey Before/After Paint
Part By Part/Lump Sum

Surveyed By _____

Contact No. _____

Date of Survey _____

Fax No. _____

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18002480/Atd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1516Y	Veh. Inspected	SJL 9020B	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001101MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	06/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106129310	Colour	SILVER	
Odometer	111562	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2018	Inspection Date	07/02/2018	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 9020B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER	DEFORMED	493.80	493.80
2	FRT BUMPER SIDE HOLDE L/R @\$89.60	NECESSARY	179.20	179.20
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	372.60	-
	LESS 25% DISCOUNT		-261.40	-168.25
			784.20	504.75
LABOUR				
	TO SUPPLY OPC PLATE, SEALING & INSPECTION FEE.		200.00	80.00
	TO REMOVE, REPAIR AND REPLACED DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.		250.00	150.00
	TO PUTTY AND RESPRAY PAINTING ON FRT BUMPER.		300.00	200.00
			750.00	430.00
GRAND TOTAL			1,534.20	934.75
RECOMMENDED COST OF REPAIRS				934.75

Report Ref No. CS/FCI18002480/Atd3n2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$7,966.00=NETT VALUE: \$6,034.00

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.