

To Purvelli bus stop (near)

INDIA

MODEL : HYUNDAI 140

Not Done
US Repair
AA = paina power
LCC Auto (ma)
7/2/2008. 0
Sundays
gc (FRT)
efill Gas
As per
align

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.