

ASS. REC. BY:

REF: CS/msh18002493/mlvb

Special Instructions:

SURVIVOR:

Ma

ASSIGNMENT (Office)

Merimen

From (Person):

Christine Wong

of

msh

Date/Time:

07/02/2018 241pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QU 36750

Insured:

SJ6 5577P

at Workshop m/s

Chow Eoon Muler

Tel:

6464 1626

of

31k 10 Amk Ind Park 2A #01-15

Policy No:

A29067938 AMX

Claim No:

548396

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29012018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

07/02/2018 3:30pm

Person Contacted:

Grace

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

QU 36750 - X

SJ6 5577P - 183 / msh / 7002493 / 01b

183 / 221113

12/2/18

Send preli revised by merimen

26/4/18

Final fig \$ 1382.50 confirmed by email (Ref 203.80, 13/0)

26/4.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OO / TP / WS / TP RES / CO RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop No: _____

of: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Cum Sum: _____ % B Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: _____

Type: M/Cab / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading: _____

Eng No: _____

C No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Wonder / Jammed / Leaked / Burnt or

Brake: Wonder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____

R. Bal: _____

L. Bal: _____

D. O. I: _____

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

RECEIVED 27 APR 2010

Date/Time: File Room 01



Prel. Report



Final Report

Date/Time: File Room 01

27/4 - typist

Report Format

Jump Sum / (L.B.): _____

MR. men

1380.50

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



SHE 1/100



INTER 1/100



TECH 1/100



REPAIR 1/100

Survey Fee:

Transport:

L. 1/100

P. 1/100

T. 1/100

TOTAL

Survey Department Check List (Case Handler)

Reference No.: CS/MSG/802493/MIVB
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

VERON

27/4/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18002493/M1vb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 07-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 5577P	Veh. Inspected	SJU 3675D	
Policy No.	A29067938QMX	Coverage (\$)	0.00	
Claim No.	548396	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	07/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2018	Inspection Date	07/02/2018	
Survey held at	CHEW GOON MOTOR BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018 16:27 Sendback Est	06 Feb 2018 16:40 S\$1,431.05	07 Feb 2018 14:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	ANNA LEE, ID: S7627987Z		
Main Claimant:	NOVELTY PROJECT SERVICES PTE LTD, Co. Reg. No.: 200517894D		
Vehicle Reg. No.:	SJU3675D	Date of Loss:	29/01/2018 01:00 - :59
Claim Type:	TP / 548396	Policy/Cover Note No.:	A29067938QMX (Comprehensive) Coverage: 06/01/2018 - 30/01/2019
Vehicle Reg. No. (Insured):	SJG5577P	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Goon Motor (AMK) Bldg 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/02/2018]		
Driver/Custodian (Insured):	CYNTHIA POH SEOK HOON (), NRIC: S7134137B, Tel: +6597336655		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Christina Wong	Date:	12 Feb 2018
<u>Preliminary Advice</u>			

Insured Vehicle No	: SJG5577P	Accident Date	: 29/01/2018
TP Vehicle No	: SJU3675D	Assignment Date	: 07/02/2018
Make	: KIA CERATO FORTE	Est. Duration of Repair	: 3.00
Date of Inspection	: 07/02/2018		
Inspection At	CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,586.30
Revised Amount	:S\$	1,382.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,382.50
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7894D
Vehicle Details	
Vehicle No.:	SJU3675D
Vehicle to be Exported:	No
Intended De-registration Date:	12 Feb 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9H306184
Chassis No.:	KNAFU411MA5139554
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$11,051.00
Original Registration Date:	01 Dec 2009
First Registration Date:	01 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$11,051.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Nov 2019
PARF Rebate Amount:	\$6,078.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2019
COE Category:	A - Car (1600cc & below)

COE Period(Years):	10
QP Paid:	\$12,899.00
COE Rebate Amount:	\$2,321.00
Total Rebate Amount:	\$8,399.00

The information contained herein is correct as at 12 Feb 2018

OK

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5068032338-03

Cover : drivo CLASSIC

- | | |
|---|------------------------------------|
| 1. Index mark and Registration Number of Vehicle | : SJU3675D |
| Chassis Number | : KNAFU411MA5139554 |
| 2. Name of Policyholder | : NOVELTY PROJECT SERVICES PTE LTD |
| 3. Effective Date of Insurance | : 01 Dec 2017 |
| 4. Expiry Date of Insurance | : 30 Nov 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission. | |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession. | |

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: TAN HOCK NAM
NAMED DRIVER (1)	: CYNTHIA POH SEOK HOON
NAMED DRIVER (2)	: TAN SENG CHEE
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ALFA CREDIT PTE LTD (00000613905)
Date of Issue : 10 Nov 2017 21:11 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7134137B



Name
CYNTHIA POH SEOK HOON

Race
CHINESE

Date of birth
28-09-1971

Country of birth
SINGAPORE

Sex
F



REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of Cynthia Poh Seok Hoon

License Number: S7134137B

Name
POH SEOK HOON
(FU SHUYUN)

Birth Date: 28 Sep 1971

Issue Date: 02 Jul 2003

Barcode: 000019647A

488007

Barcode

NRIC No: S7134137B



Date of Issue
11-01-2011

Address
APT BLK 230 ANG MO KIO AVENUE 3
#10-124B
SINGAPORE 560230

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE
01 Jul 1993

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

NP 428A

Barcode: License No: S7134137B

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/01/2018 13:44
Date Of Accident	29/01/2018 01:15
Exact Location Of Accident	ARRIVAL ZONE 2 CARPARK LOT 12 WOODLANDS CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU3675D
Insured/Policyholder	
Name Of Registered Owner	NOVELTY PROJECT SERVICES PTE LTD
Co Reg No	200517894D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62549495

Vehicle Particulars

Manufacturer	KIA
Model	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5068032338-03
Cover Note Number	

Driver

Name of Driver	CYNTHIA POH SEOK HOON
NRIC No	S7134137B
Date Of Birth	28/09/1971
Occupation	OUTDOOR
Date Of Driving Pass	01/07/1993
Driving Experience	24 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97336655
Fax Number	
Contact Number	
Email Address	CYNTHIAPOH@OUTLOOK.COM

Address	BLK 230 ANG MO KIO AVENUE 3 #10-1248
Postcode	560230
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : PETER ANG GENDER: : MALE
Passenger 2	NAME: : MAGGIE KENG GENDER: : FEMALE
Passenger 3	NAME: : MAX CHOW GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

CAR SJG5577P WAS PARKED ON THE RIGHT SIDE AT ARRIVAL ZONE 2 WOODLANDS CUSTOM LOT 12. I INTEND TO PARK IN FRONT OF HIM, AS I DROVE PASS CAR SJG5577P ON HIS LEFT, SUDDENLY HIS FRONT LEFT PASSENGER DOOR OPEN AND HIS FRONT PASSENGER SAW MY CAR COMING IMMEDIATELY SHE CLOSED THE DOOR, AFTER THAT HIS LEFT REAR PASSENGER DOOR OPEN WITHOUT CHECKING THERE'S AN ON COMING VEHICLE AND HIT MY RIGHT PORTION OF MY CAR SJU3675D.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG5577P
Vehicle Make/Model/Colour	VOLVO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE YEW KONG

NRIC/Passport Number S7627423A
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Car SJG 5577P was parked on the right side, at Arrival Zone 2 Woodlands Customs Lot 12.

I intend to park in front of him. As I drove pass car SJG 5577P on his left, suddenly his front left passenger door open and his front passenger saw my car coming immediately she closed the door.

After that his left car passenger door open without checking there's an on coming vehicle & hit my right portion of my car SJU 3675D

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

30/1/18

Chew Goon Motor (Co Reg.No:22188000C)Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Tel: 64841626 Fax: 64840465 Email: aaronm3@chewgoonmotor.com.sg;chewgoon@singnet.com.sg

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)**NOVELTY PROJETCH SERVICES PTE LTD**

449 TAGORE INDUSTRIAL AVENUE #02-05 GREATLAND INDUSTRIAL BUILDING

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	290118_SJU3675D
Policy No:		Date of Loss:	29/01/2018
Vehicle Reg. No.:	SJU3675D	Driveable?	
Party At Fault:	THIRD PARTY		
Driver (Insured):	CYNTHIA POH SEOK HOON		
Make/Model:	KIA CERATO FORTE, 1.6 EX (A)	Vehicle Reg. Date:	01/12/2009
Vehicle Colour:	SILVER		
Engine No:	G4FC9H306184	Chassis No:	KNAFU411MA5139554
Odometer:	165409 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Description of CAR SJG5577P WAS PARKED ON THE RIGHT SIDE AT ARRIVAL ZONE 2
 Accident/Loss WOODLANDS CUSTOM LOT 12. I INTEND TO PARK IN FRONT OF HIM, AS I DROVE
 PASS CAR SJG5577P ON HIS LEFT, SUDDENLY HIS FRONT LEFT PASSENGER
 DOOR OPEN AND HIS FRONT PASSENGER SAW MY CAR COMING IMMEDIATELY
 SHE CLOSED THE DOOR, AFTER THAT HIS LEFT REAR PASSENGER DOOR OPEN
 WITHOUT CHECKING THERE'S AN ON COMING VEHICLE AND HIT MY RIGHT
 PORTION OF MY CAR SJU3675D.

Present Location: CHEW GOON MOTOR (AMK)

COST OF CLAIMS	Amount
Parts	721.05
Miscellaneous Items	0.00
Labour	710.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	1586.30	1,431.05
+ GST 7.00% (S\$)		100.17
Nett Amount (S\$)		<u>1,531.22</u>

This claim is handled by: LIU YAN JING

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Feb 2018)

Parts: 143 KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Chew Goon Motor/SJU3675D/06/02/2018 16:40

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR RH	0.00	0.00	*360.00 F
2	1		*FRONT DOOR STICKER (TOP)	0.00	0.00	*10.00 F
3	1		*FRONT DOOR STICKER (SIDE)	0.00	0.00	*10.00 F
4	1		*FRONT DOOR TOP HINGE	0.00	0.00	*12.00 F
5	1		*FRONT DOOR WING MIRROR	0.00	0.00	*210.00 F
6	1		*FRONT DOOR GLASS OUTER MOULDING	0.00	0.00	*25.00 F

F=Franchise part.

Sub Total (S\$) 627.00

+ Margin on L,N Items 15.00% (S\$) 94.05

Total Parts (S\$) 721.05

Chew Goon Motor/SJU3675D/06/02/2018 16:40. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL.	New	20 60.00
2	LABOUR CHARGE - PANEL BEATING, REPAIRING OF DOOR PILLAR, TRANSFER DOOR FITTING AND ACCESSORIES PARTS REPLACEMENT.	New	250 350.00
3	TO RESPRAY AFFECTED AREAS.	New	250 300.00
Gross Labour Cost (S\$)			710.00

Chew Goon Motor/SJU3675D/06/02/2018 16:40. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not Author
P/B Repair
Before paint P/B
Lab Auto (MTR)
7/2/2018.
3rd day 1


12/2/18.

Chew Goon Motor (Co.Reg.No:22188000C)Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Tel: 64841626 Fax: 64840465 Email: aaronm3@chewgoonmotor.com.sg;chewgoon@singnet.com.sg

(SUPPLEMENTARY)**TP INSURER:****MSIG Insurance (Singapore) Pte. Ltd. (HQ)****ANNA LEE**449 TAGORE INDUSTRIAL AVENUE #02-05 GREATLAND INDUSTRIAL BUILDING
Singapore**PARTICULARS OF CLAIM**

Claim Type: THIRD PARTY
 Policy No: A29067938QMX
 Vehicle Reg. No.: **SJU3675D**
 Party At Fault: THIRD PARTY
 Driver (Insured): CYNTHIA POH SEOK HOON

Ref. No: 290118_SJU3675D
 Date of Loss: 29/01/2018
 Driveable?

Make/Model: KIA CERATO FORTE, 1.6 EX (A)
 Vehicle Colour: SILVER
 Engine No: G4FC9H306184
 Odometer: 165409 KM

Vehicle Reg. Date: 01/12/2009
 Chassis No: KNAFU411MA5139554

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) **4**

Description of Accident/Loss

CAR SJG5577P WAS PARKED ON THE RIGHT SIDE AT ARRIVAL ZONE 2 WOODLANDS CUSTOM LOT 12. I INTEND TO PARK IN FRONT OF HIM, AS I DROVE PASS CAR SJG5577P ON HIS LEFT, SUDDENLY HIS FRONT LEFT PASSENGER DOOR OPEN AND HIS FRONT PASSENGER SAW MY CAR COMING IMMEDIATELY SHE CLOSED THE DOOR, AFTER THAT HIS LEFT REAR PASSENGER DOOR OPEN WITHOUT CHECKING THERE'S AN ON COMING VEHICLE AND HIT MY RIGHT PORTION OF MY CAR SJU3675D.

Present Location: CHEW GOON MOTOR (AMK)

COST OF CLAIMS	Amount
Parts	155.25
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	155.25
+ GST 7.00% (\$\$)	10.87
Nett Amount (\$\$)	166.12
+ Previous Estimates (\$\$)	1,531.22
Claim Total (\$\$)	1,697.34

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 08 Feb 2018)**Parts:** 143 KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Chew Goon Motor/SJU3675D/08/02/2018 16:28**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR WING MIRROR MOTOR RH	0.00	0.00	*135.00 F
						Sub Total (S\$)
						135.00
						+ Margin on L,N Items 15.00% (S\$)
						20.25
						Total Parts (S\$)
						155.25

F=Franchise part.

Chew Goon Motor/SJU3675D/08/02/2018 16:28. Not valid without Reference section.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Chew Goon Motor/SJU3675D/08/02/2018 16:28. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6385 1255 FAX: 6385 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPERBLADES (JAE)
Dept Direct: 6417 8791 / 6745 9028



Dept Direct: 6417 8794

Dept Direct: 6417 9756

Dept Direct: 6417 9756

Dept Direct: 6417 9756

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Furch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CHEW GOON MOTOR
BLK 10 #01-15/16/17
ANG MO KIO IND PARK 2A
AMK AUTOPOINT
SINGAPORE 568047
TEL : 64841626 / 64841976 FAX : 64840465
ATTN : ALLAN

TAX INVOICE : AR201802-05043
DATE : 08/02/2018
CUSTOMER ID : CHE006
VEH REG. NO. : SJU3675U
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1 KS822201M000 FORTE 09--	MOULDING.F DOOR RH	CC CC7-D-09A	1	25.00	25.00

SUB-TOTAL : 25.00
ADD GST 7.00 % 1.75

E. & O.E TOTAL AMOUNT S\$: 26.75

[P] 08/02/2018 11:17:56AM

[E] 08/02/2018 11:07:00AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: ALAN

This is computer generated document.
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: Niss (Nissan Wiper blades, Silver (Made in Korea))
Ford (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CHEW GOON MOTOR
BLK 10 #01-15/16/17
ANG MO KIO IND PARK 2A
AMK AUTOPOINT
SINGAPORE 568047
TEL : 64841626/ 64841976 FAX : 64840465
ATTN : ALLAN
KNAFU411MA5139554

TAX INVOICE : AR201802-04803
DATE : 08/02/2018
CUSTOMER ID : CHE006
VEH REG. NO. : SJU3675U
TERMS : 30 DAYS
PO NO.
PAGE NO.
CURR. : S\$

Page 1 of 1
S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
HY87620-69120	SIDE MIRROR MOTOR RH	U1	1	135.00	135.00
AVANTE 06-11		U1L1-D3-F14-C			

SUB-TOTAL : 135.00
ADD GST 7.00 % 9.00

E & OE TOTAL AMOUNT S\$: 144.00

[P] 08/02/2018 9:11:23AM

[E] 08/02/2018 9:10:24A

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ALAN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WIPER BLADE
Dept Direct: 6417 9791 / 6749 9928



Dept Direct: 6417 9794

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Dept Direct: 6417 9799

Wiper blade: NWEI (Nippon Wiper blade), Silex (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

CHEW GOON MOTOR
BLK 10 #01-15/16/17
ANG MO KIO IND PARK 2A
AMK AUTOPOINT
SINGAPORE 568047
TEL : 64841626/ 64841976 FAX : 64840465
ATTN : ALLAN

KNAFU411MA5139554

CHECK BEFORE SEND

TAX INVOICE : AR201802-04763
DATE : 07/02/2018
CUSTOMER ID : CHE006
VEH REG. NO. : SJU36750
TERMS : 30 DAYS
PO NO. :
PAGE NO. : Page 1 of 1
CURR : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	KS760041M011 FORTE SD/HB 2011	F.DOOR RH (760041M010)	CC CC7-G-06A	1	360.00	360.00
2.	KS863721M000 FORTE	F.DOOR RH TOP STRIPE	CC CC7-E-10AE	1	10.00	10.00
3.	KS863731M000 FORTE 09-	F.DOOR RH PILLAR STRIPE	CC CC7-D-10AO	1	10.00	10.00
4.	KS876201M000/1M200 FORTE 09	SIDE MIRROR ASSY RH(6 PIN FAT LEN)	CC CC7-C-01D	1	210.00	210.00

SUB-TOTAL : 590.00
ADD GST 7.00 % 41.30

E. & O. E

TOTAL AMOUNT S\$: 631.30

[P] 07/02/2018 6:10:13PM

[E] 07/02/2018 5:59:53PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: ALAN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 April 2018 9:48 AM
To: 'Chew Goon Motor(ad3)'; Winnie Foo (LKKAUTO); Ma C.F (LKKAUTO)
Cc: KKLau; Celine Fong (LKKAUTO); SUR; chewgoon@singnet.com.sg
Subject: RE: SJU3675D Date of acc: 29.01.2018

Dear Grace,

Noted with thanks.

Final invoice and all supporting documents sent over to MSIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chew Goon Motor(ad3) [mailto:ad3@chewgoonmotor.com.sg]
Sent: Thursday, 26 April 2018 9:34 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Winnie Foo (LKKAUTO) <QA-A@lkkauto.com>; Ma C.F (LKKAUTO) <MaCF@lkkauto.com>
Cc: KKLau <kklau@lkkauto.com>; Celine Fong (LKKAUTO) <celinefong@lkkauto.com>; SUR <sur@lkkauto.com>; chewgoon@singnet.com.sg
Subject: RE: SJU3675D Date of acc: 29.01.2018

Dear Veron,

Confirm P/P amount \$1382.50 and 3 working days.

Thanks & Regards,
Grace

Chew Goon Motor

Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15, 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 25 April 2018 2:14 PM

To: Winnie Foo (LKKAUTO); Ma C.F (LKKAUTO); Chew Goon Motor(ad3)
Cc: KKLau; Celine Fong (LKKAUTO); SUR
Subject: RE: SJU3675D Date of acc: 29.01.2018

Dear Grace,

WITHOUT PREJUDICE

Finalize amount \$1,382.50 before GST

No of days: 3 days.

Please confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chew Goon Motor(ad3) [<mailto:ad3@chewgoonmotor.com.sg>]
Sent: Thursday, 19 April, 2018 3:44 PM
To: Ma C.F (LKKAUTO); Joy Irene (LKKAUTO)
Cc: chewgoon@singnet.com.sg
Subject: FW: SJU3675D Date of acc: 29.01.2018

Dear Mr Ma,

Gentle reminder.

Kindly refer to the attached document for finalise.

Thanks & Regards,
Grace

Chew Goon Motor
Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

From: Chew Goon Motor(ad3)
Sent: Thursday, 29 March 2018 11:16 AM
To: Ma C.F (LKKAUTO)
Cc: chewgoon@singnet.com.sg; Eric
Subject: SJU3675D Date of acc: 29.01.2018

Dear Mr Ma,

Kindly refer to the attached document for finalise.

Thanks & Regards,
Grace

Chew Goon Motor

Blk 10, Ang Mo Kio Ind Park 2A,
Ave 5 #01-15 , 16 & 17,
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6484 1626
Fax : 6484 0465

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2018 16:27 Sendback Est	06 Feb 2018 16:40 \$1,431.05	07 Feb 2018 14:41 Edit Adj Rpt	\$1,382.50 Edit Estimates	\$1,382.50 View Rpt		Pending for Survey Report Cancel Case
Supp #1	08 Feb 2018 16:26	08 Feb 2018 16:28 \$155.25	08 Feb 2018 16:28			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ANNA LEE , ID: S76279872		
Main Claimant:	NOVELTY PROJECT SERVICES PTE LTD , Co. Reg. No.: 200517894D		
Vehicle Reg. No.:	SJU3675D	Date of Loss:	29/01/2018 01:00 - :59 [97 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 548396	Policy/Cover Note No.:	A29067938QMX (Comprehensive) Coverage: 06/01/2018 - 30/01/2019
Vehicle Reg. No. (Insured):	SJG5577P	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 09/03/2018]		
Driver/Custodian (Insured):	CYNTHIA POH SEOK HOON (J), NRIC: S7134137B, Tel: +6597336655		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJU3675D (548396)
 [SJG5577P]
 TP
 NOVELTY PROJECT SERVICES PTE LTD
 Jan 29 2018 1:00AM
 [ANNA LEE]
 Chew Goon Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	06/02/18 16:40	Repairer Estimates	Load HTM	
2	08/02/18 16:28	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/18 14:13	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/18 11:09	General View	Load JPG	☒
2	12/02/18 11:09	General View	Load JPG	☒
3	12/02/18 11:09	General View	Load JPG	☒
4	12/02/18 11:09	General View	Load JPG	☒
5	12/02/18 11:09	General View	Load JPG	☒
6	12/02/18 11:09	General View	Load JPG	☒
7	12/02/18 11:09	General View	Load JPG	☒
8	12/02/18 11:09	General View	Load JPG	☒
9	12/02/18 11:09	General View	Load JPG	☒
10	12/02/18 11:09	General View	Load JPG	☒
11	12/02/18 11:09	General View	Load JPG	☒
12	12/02/18 11:09	General View	Load JPG	☒
13	12/02/18 11:09	General View	Load JPG	☒
14	12/02/18 11:09	Reinspection Photo	Load JPG	☒
15	12/02/18 11:09	Reinspection Photo	Load JPG	☒
16	12/02/18 11:09	Reinspection Photo	Load JPG	☒
17	12/02/18 11:09	Reinspection Photo	Load JPG	☒
18	12/02/18 11:09	Reinspection Photo	Load JPG	☒
19	12/02/18 11:09	Reinspection Photo	Load JPG	☒
20	12/02/18 11:09	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Chew Goon Motor (AMK)	Thumbnail	Print
1	06/02/18 16:37	E-filed GIA report	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/04/18 17:33	SUPPLEMENTARY PART	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002493/M1VBQ2

Date: 27/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29067938QMX

Claimant Vehicle No : SJU3675D

Insured Vehicle No : SJG5577P

Date of Loss: 29/01/2018

Nature of Claim: TP

Claim No: 548396

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU3675D

Make & Model: KIA CERATO FORTE, 1.6 EX (A)

Engine No: G4FC9H306184

Reg. Date: 01/12/2009 (Man. Year: 2009)

Chassis No: KNAFU411MA5139554

Colour: Silver

Odometer: 165409 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	876.30	862.50	13.80	1.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	710.00	520.00	190.00	26.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,586.30	1,382.50	203.80	12.85
+ GST 7.00/7.00% (S\$)	111.04	96.78	14.26	12.84
Nett Amount (S\$)	1,697.34	1,479.28	218.06	12.85

INSPECTION

Date of Assignment: 07/02/2018 Present Location:

Chew Goon Motor (AMK)

Date Inspected: 07/02/2018 Inspected At:

Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: MA CHIN FOOK

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2018)
Parts: 143	KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU3675D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Deformed	360.00 F	*360.00 F
2	1		*FRONT DOOR STICKER (TOP)	Necessary	10.00 F	*10.00 F
3	1		*FRONT DOOR STICKER (SIDE)	Necessary	10.00 F	*10.00 F
4	1		*FRONT DOOR TOP HINGE	Serviceable	12.00 F	*. F
5	1		*FRONT DOOR WING MIRROR	Cracked	210.00 F	*210.00 F
6	1		*FRONT DOOR GLASS OUTER MOULDING	Cut	25.00 F	*25.00 F
Supplementary #1						
7	1		*FRONT DOOR WING MIRROR MOTOR RH	Jammed / Shorted	135.00 F	*135.00 F
F=Franchise part.						
Sub Total (S\$)					762.00	750.00
+ Margin on L,N Items 15.00/15.00% (S\$)					114.30	112.50
Total Parts (S\$)					876.30	862.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL.	New	60.00	20.00
2	LABOUR CHARGE - PANEL BEATING, REPAIRING OF DOOR PILLAR, TRANSFER DOOR FITTING AND ACCESSORIES PARTS REPLACEMENT.	New	350.00	250.00
3	TO RESPRAY AFFECTED AREAS.	New	300.00	250.00
Gross Labour Cost (\$\$)			710.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >