

12/03/2002

ASS. REC. BY:

REF: CS/MSG18002559/G9d36 Special Instruction:

Survivor:

Meinmen

GQ

ASSIGNMENT (Office)

From (Person):

Monica chung

of

M81G

Date/Time:

8/2/18 @ 9:26am

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 5056E

Insured:

FBG 7618L

at Workshop m/s

Efhicar2

Tel:

63844404

of

56 Loyang Way #04-04

Policy No:

MSD/VMS/17-375938

Claim No:

MSC/V/18-000215

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/2/2018

CA / REV / REP. / REV 24 HRS

up

9/2/18 @ Morning

H.O.D. Endorsement:

Date/Time:

2:19pm @ 8/2/18

Person Contacted:

Kim

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLP 5056E-X

FBG 7618L-X

12/7/18 @ 5:51pm revised to Monica Chung via Meinmen.

03/9/18 @ 10:11am confirmed with Katherine LS 2400, 4 days by email.

(Red \$1430, 37%)

Sumit V.

Handwritten signature

REF:

MSIG

ASSIGNMENT

From: _____ Date: 9/2/18
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLP 5056E
 at Workshop no: Ethicarz
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record) Morning
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAO Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS wp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLP 5056E Reg: 14 May 2013
 Type: ☒ M Cycle / Bus / Van / Lorry / Taxi / Prime Mover
 Truck / Trailer or _____
 Make: Volkswagen Polo cc: 1390
 Colour: Red A/C: _____ Insured / Std / NI / NA
 Sp/Reading: 117014 T-Rack: Insured / Std / NI / NA
 Eng No: _____
 C No: WVV Z88 6R8A4 038067
 Gen. Condi: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Incl / Jammed / Leaked / Burnt or
 Brake: ☒ Incl / Jammed / Leaked / Burnt or
 Mod: NII / S / R / STD A/Rim or
 Tyre Size: F: 215/40R17
 R: 11
 BS / DUN / EXNOVA ☒ FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R.Bal: 6 mm R.Bal: 6 mm
 L.Bal: 6 mm L.Bal: 6 mm
 D.O.A: _____ D.O.A: 09-02-18
 Survey held at: W/S 12pm
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Roof/Top or
O/S FA
 The ☒ U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Handwritten signature

RECEIVED 05 SEP 2018

Handwritten signature

3/9/2018

Date/Time File Pass to? ☐ : Preli. Report
05/9/2018 ☐ : Final Report
 Date/Time File Return to? _____

Days Of Repair: 4
 Resurvey No. of Trips: _____

Add Fee: ☐ Steel Ind: \$
☐ Inter: \$
☐ Test: \$
☐ Re-Eng: \$

Survey Fee	300
Transportance	
Other	
	10
	310

Report Format: Mer-TP
 Lum Sum: 2400

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Feb 2018		08 Feb 2018 09:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	RAMLIE BIN SAINI, ID: S7513993D, Tel: +6592422928, Email: ramliesaini77@gmail.com		
Main Claimant:	TAN YEOW KWANG, ID: S8515807D		
Vehicle Reg. No.:	SLP5056E	Date of Loss:	02/02/2018 20:00 - :59
Claim Type:	TP / MSC/V/18-000215	Policy/Cover Note No.:	MSD/VMS/17-375938-CA (TP, Fire & Theft) Coverage: 20/12/2017 - 19/12/2018
Vehicle Reg. No. (Insured):	FBG7618L	Policy No. (Claimant):	
		Excess:	
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/02/2018]		
Driver/Custodian (Insured):	RAMLIE BIN SAINI (42 / Male), NRIC: S7513993D, Tel: +6592422928		
Adj Asg. Remarks:	Pls assign Adrian Ling to survey		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18002559/Gqd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-02-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBG 7618L	Veh. Inspected	SLP 5056E	
Policy No.	MSD/VMS/17-375938-CA	Coverage (\$)	0.00	
Claim No.	MSC/V/18-000215	Excess (\$)	0.00	
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	08/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/02/2018	Inspection Date		
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Shiau Chan (LKKAuto)

From: katherinechan@ethicarz.sg
Sent: Monday, 3 September 2018 10:11 AM
To: Shiau Chan (LKKAuto); Hsiao Tong (LKKAuto)
Cc: heng@ethicarz.sg; Guo Qiang (LKKAuto); SUR; CS A Team; Admin A
Subject: RE: FINALISED

WITHOUT PREJUDICE

Dear Ms Shiau,

We accept your finalised @ \$ 2,400.00 / 4 days (SLP5056E).

Is direct settle with yours ?

Thanks!

HAVE A NICE DAY

Regards,
Katherine Chan

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Monday, 3 September 2018 9:44 AM
To: katherinechan@ethicarz.sg; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: heng@ethicarz.sg; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: FINALISED

Dear Katherine,

As per your requested.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: katherinechan@ethicarz.sg <katherinechan@ethicarz.sg>
Sent: Monday, 3 September 2018 9:37 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: heng@ethicarz.sg; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: FINALISED

Dear Ms Shiau,

Kindly let us have the mark estimate SLP5056E.

Thanks!

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 12 Feb 2018

Preliminary Advice

Insured Vehicle No	: FBG7618L	Accident Date	: 02/02/2018
TP Vehicle No	: SLP5056E	Assignment Date	: 08/02/2018
Make	: VOLKSWAGEN POLO	Est. Duration of Repair	: 4.00
Date of Inspection	: 09/02/2018		
Inspection At	: ETHICARZ PTE LTD (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,670.00 (SN + LABOUR)
Revised Amount	:S\$	940.00
Check Items (Estimated)	:S\$	150.00
Total	:S\$	1,090.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5807D
Vehicle Details	
Vehicle No.:	SLP5056E
Vehicle to be Exported:	No
Intended De-registration Date:	12 Feb 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 AT 6R13E7
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	CGG333010
Chassis No.:	WVWZZZ6RZAU038067
Maximum Power Output:	63.0 kW (84 bhp)
Open Market Value:	\$15,073.00
Original Registration Date:	14 May 2010
First Registration Date:	14 May 2010
Transfer Count:	2
Actual ARF Paid:	\$15,073.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2020
PARF Rebate Amount:	\$9,043.00
Intended COE Rebate Details	
COE Expiry Date:	13 May 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,502.00
COE Rebate Amount:	\$4,167.00
Total Rebate Amount:	\$13,210.00

The information contained herein is correct as at 12 Feb 2018

OK

▶ polo Used Vehicle List (5 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Volkswagen Polo 1.4A	\$25,800	\$8,210 /yr	05-May-2010	1,390 cc	-	High Speed Motor	Available

Road Tax Till May 2018, In Top Condition, No Repairs Needed As The Car Has Been Regularly Serviced, Interior/Exterior Condition Looks New, Hot Red Exterior With Red And Black Interior, Bank And In Hou...

Office No. - 64568190

Harjinder Singh - 93386317 | Manjit Singh - 98581265

Volkswagen Polo 1.4A	\$26,800	\$8,090 /yr	02-Jul-2010	1,390 cc	66,000 km	Asgard Automobile	Available
-----------------------------	-----------------	-------------	-------------	----------	-----------	-------------------	------------------

Popular Conti Hatch In Pristine Condition. Genuine Low Mileage Done. Affordable VW Hatch With Decent Cabin Space Well Suited For Young Families Or Executives. Original Paintwork, 100% Accident Free, S...

Office No. - -

Edward Chee - 88133111 | Jimmy Tan - 97469909

Volkswagen Polo 1.4A	\$26,800	\$8,030 /yr	12-Jul-2010	1,390 cc	-	Autolink Holdings Pte Ltd	Available
-----------------------------	-----------------	-------------	-------------	----------	---	---------------------------	------------------

Wear And Tear Parts Replaced With Receipts To Prove! Excellent Condition. Buy With Peace Of Mind From Award Accredited Company. Attractive Loan Package And Competitive Trade In Price! Call Now To Find...

Office No. - 63463383

Lee - 98468156 | Erik Tan - 94500673 | John Lim - 96419096

Volkswagen Polo 1.2A	\$29,888	\$8,720 /yr	26-Jul-2010	1,197 cc	126,000 km		Available
-----------------------------	-----------------	-------------	-------------	----------	------------	--	------------------

Reason For Selling Due Upgrading. Newly Renewed 6 Months Road Tax, Low Maintenance. Low Depreciation And I'm A Direct Owner.

Office No. - -

Mr Lim - 97731086

Volkswagen Polo 1.4A	\$29,800	\$8,490 /yr	27-Sep-2010	1,390 cc	96,000 km	Trillium Automobile Pte Ltd	Available
-----------------------------	-----------------	-------------	-------------	----------	-----------	-----------------------------	------------------

1 Year Free Servicing! 120 Points STA Check And Accident Free Report For A Peace Of Mind Welome! High Trade In And In House Financing Available! View Today!

Office No. - 64632050

Nic - 91182220 | Sky - 91191186 | Ben - 90830001

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	05/02/2018 13:15
Date Of Accident	02/02/2018 20:00
Exact Location Of Accident	JURONG WEST ST 52 TOWARDS JURONG WEST AVE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP5056E
Insured/Policyholder	
Name Of Registered Owner	TAN YEOW KWANG
NRIC No	S8515807D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96531163
Alternative Phone No	OFFICE-96531163
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	POLO 1.4 AT 6R13E7
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093614697 CLASSIC
Cover Note Number	
Driver	
Name of Driver	TAN YEOW KWANG
NRIC No	S8515807D
Date Of Birth	21/05/1985
Occupation	INDOOR
Date Of Driving Pass	20/02/2013
Driving Experience	4 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96531163
Fax Number	
Contact Number	OFFICE-96531163
EMail Address	NOEMAIL

Address	BLK 185B #08-113 RIVERVALE CRESCENT
Postcode	542185
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG7618L
Vehicle Make/Model/Colour	YAMAHA JUPITER MX (HC)
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the G A Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: **5 FEB 2018**


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED DATE AND TIME ON THE STATED VENUE
I VEHICLE(A SLP 5056E) WAS TRAVELLING STRAIGHT ON MY
LANE, SUDDENLY VEHICLE(B FBG 7618L) SWERVE INTO MY
LANE AND HIT ONTO MY CAR FRONT RIGHT PORTION CAUSING
DAMAGE TO MY CAR

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time: - 5 FEB 2018

2. If the driver is not the policyholder, the


Driver's Signature
(if driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
 Loyang Enterprise Building, Email: johnong@ethicarz.sg
 Tel: 63844404, FAX: 63840444

VECHICLE NUM:	SLP5056E
MAKE & MODEL:	VOLKSWAGON POLO
MILEAGE:	117012
TYRE:	EAGLE 215/40R17
CHASSIS NUM:	WVWZZZ6RZAU38067

ATTN:		
QTY	DESCRIPTION - PARTS	PRICE
1	FRONT WINDSCREEN MOULDING X	
1	FRONT BONNET X	
1	FRONT BONNET OPENER X	
1	HEADLAMP RH / Scr	
10	HEADLAMP CLIPS RH X	
1	HEADLAMP PANEL RH X	
1	FRONT GRILLE X	
1	FRONT GRILLE LOGO - VW X	
10	FRONT GRILLE CLIPS X	
1	FRONT BUMPER / CMA	
1	FRONT BUMPER REINFORCEMENT X	
2	FRONT BUMPER RETAINER LH+RH 4tl - Cut	
2	FRONT BUMPER BRACKET LH+RH X	
1	FRONT BUMPER SPONGE X	
1	FRONT BUMPER LOWER GRILLE X	
1	FRONT BUMPER LOWER GRILLE CLIPS X	
1	FRONT BUMPER FOG LAMP COVER RH X	
1	FRONT BUMPER LOWER / Cut.	
1	FRONT FENDER RH X Repair.	
1	FRONT FENDER COWLING RH / TW	
10	FRONT FENDER COWLING CLIPS / MC.	
1	SIDE MIRROR ASSY X Repair.	
1	FRONT SUPPORT PANEL X	
1	FRONT RIM RH / Cut	
1	FRONT ABSORBER ?	
1	FRONT KNUCKLE ?	
1	FRONT KNUCKLE BEARING /	
1	FRONT KNUCKLE LOWER ARM ?	

Stamford Tyres International Pte Ltd

31 Loyang Way
Singapore 508729

Phone Number: 65423355

Fax Number: 65423066

Customer:		Date:	2/7/2018 5:37 PM
Company:		VIN	
License NO:	SLP5056E	Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

VOLKSWAGEN, POLO Standard Suspension, 08-09 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	4°36'	3°58'	4°58'	4°30'
		Right	4°35'	3°58'	4°58'	4°18'
	Camber	Left	-0°42'	-0°58'	0°02'	-0°48'
		Right	-1°12'	-0°58'	0°02'	-1°48'
	Toe	Left	0°03'	-0°05'	0°05'	0°12'
		Right	-0°03'	-0°05'	0°05'	2°06'
Total		0°00'	-0°10'	0°10'	2°18'	
Rear	Camber	Left	-1°18'	-1°24'	-1°12'	-1°24'
		Right	-1°30'	-1°24'	-1°12'	-1°30'
	Toe	Left	0°12'	0°05'	0°15'	0°09'
		Right	0°09'	0°05'	0°15'	0°12'
		Total	0°21'	0°10'	0°30'	0°21'
	Thrust Angle		0°01'	----		-0°01'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	14°00'	----	----	14°00'	
	Right	14°38'	----	----	14°38'	
Included Angle	Left	13°18'	----	----	13°12'	
	Right	13°26'	----	----	12°50'	
Toe Out On Turns	Left	----	----	----	----	
	Right	----	----	----	----	
Max Turn Inside	Left	----	----	----	----	
	Right	----	----	----	----	
Toe Curve Change	Left	----	----	----	----	
	Right	----	----	----	----	
Setback	Front	2mm	----	----	2mm	
	Rear	0mm	----	----	0mm	
Track Width Diff.		9mm			9mm	
Wheel Base Diff.		2mm			2mm	
Front Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Rear Ride Height	Left	----	----	----	----	
	Right	----	----	----	----	
Frame Angle					----	



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04

Loyang Enterprise Building, Email: johnong@ethicarz.sg

Tel: 63844404, FAX: 63840444

VEHICLE NUM:	SLP5056E
MAKE & MODEL:	VOLKSWAGON POLO
MILEAGE:	117012
TYRE:	EAGLE 215/40R17
CHASSIS NUM:	WVWZZZ6RZAU38067

ATTN:		
QTY	DESCRIPTION - PARTS	PRICE
1	FRONT WINDSCREEN MOULDING X	115
1	FRONT BONNET X	1094.35
1	FRONT BONNET OPENER X	111.85
1	HEADLAMP RH / Scr	647.
10	HEADLAMP CLIPS RH X	100
1	HEADLAMP PANEL RH X	63.68
1	FRONT GRILLE X	428.10
1	FRONT GRILLE LOGO - VW X	166.78
10	FRONT GRILLE CLIPS X	100
1	FRONT BUMPER / CMA	1077.83
1	FRONT BUMPER REINFORCEMENT X NN	547.80
2	FRONT BUMPER RETAINER LH+RH 41-Cut	158.85x2
2	FRONT BUMPER BRACKET LH+RH X	62x2.
1	FRONT BUMPER SPONGE X	33.50
1	FRONT BUMPER LOWER GRILLE X	218.70
1	FRONT BUMPER LOWER GRILLE CLIPS X	100
1	FRONT BUMPER FOG LAMP COVER RH X	120
1	FRONT BUMPER LOWER / Cut.	580
1	FRONT FENDER RH X Repair.	566.38
1	FRONT FENDER COWLING RH / TN	192.23
10	FRONT FENDER COWLING CLIPS / MC.	100
1	SIDE MIRROR ASSY X Repair.	152.60
1	FRONT SUPPORT PANEL X NN	923.78
1	FRONT RIM RH / Cut	823
1	FRONT ABSORBER X NN	338
1	FRONT KNUCKLE X NN	476.08
1	FRONT KNUCKLE BEARING / MC	455.5
1	FRONT KNUCKLE LOWER ARM X NN	323.53

317.70

124

1982.63
10%: 1784.37

QTY	DESCRIPTION - SPECIAL NETT	PRICE
1	FRONT TYRE RH / SUR 100	\$ 600.00
1	FRONT WINDSCREEN SEALANT X { NN	\$ 120.00
1	FRONT FENDER SEALANT X	\$ 120.00
SPECIAL NETT TOTAL		\$ 840.00

QTY	DESCRIPTION - LABOUR	PRICE
1	TO RNR ACCIDENT AFFECTED FRONT 200	\$ 1,500.00
1	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT 450	\$ 1,300.00
1	TO RUST PROOF ACCIDENT AFFECTED FRONT NN / X	\$ 150.00
1	TO RNR FRONT WINDSCREEN X	\$ 250.00
1	TO CHECK WIRING AND HEADLAMP FOCUS 30	\$ 250.00
1	TO RNR FRONT UNDERCARRIAGE SYSTEM NN	\$ 150.00
1	TO ALIGN FRONT WHEEL 60	\$ 150.00
1	TO CHECK WATER SEEPAGE NN X	\$ 80.00
840		
LABOUR TOTAL		\$ 3,830.00

4 Days

PARTS = \$4004.41

SPECIAL NETT = \$100

LABOUR = \$990

15017 39

Complete Repair

GROSS REPAIR = \$5094.41

After repair photos

LESS 20% = \$1018.88

NET REPAIR = \$4100

End Q. Rep.

09/2/18

2044.37

20%: 2400

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Feb 2018		08 Feb 2018 09:26 Edit Adj Rpt	S\$2,400.00 Edit Estimates	S\$2,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	RAMLIE BIN SAINI , ID: S7513993D, Tel: +6592422928, Email: ramliesaini77@gmail.com								
Main Claimant:	TAN YEOW KWANG , ID: S8515807D								
Vehicle Reg. No.:	SLP5056E	Date of Loss:	02/02/2018 20:00 - :59 [92 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000215	Policy/Cover Note No.:	MSD/VMS/17-375938-CA (TP, Fire & Theft) Coverage: 20/12/2017 - 19/12/2018						
Vehicle Reg. No. (Insured):	FBG7618L	Policy No. (Claimant):							
		Excess:							
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/03/2018]								
Driver/Custodian (Insured):	RAMLIE BIN SAINI (42 / Male), NRIC: S7513993D, Tel: +6592422928								
Adj Asg. Remarks:	Pls assign Adrian Ling to survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


































Claim Documents

***SLP5056E (MSC/V/18-000215)**
[FBG7618L]

TP
TAN YEOW KWANG
Feb 2 2018 8:00PM
[RAMLIE BIN SAINI]
Ethicarz Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print	
1	08/02/18 09:08	MSIG Insurance (Singapore) Pte. Ltd. (HQ) Accident Statement From: SC - Reg. No: FBG7618L, Claimant: RAMLIE BIN SAINI	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	12/02/18 17:51	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	03/09/18 10:23	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	03/09/18 10:23	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
32	03/09/18 10:23	Chassis Number	Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	03/09/18 10:23	General View	Load JPG	<input checked="" type="checkbox"/>
34	03/09/18 10:23	General View	Load JPG	<input checked="" type="checkbox"/>
35	03/09/18 10:23	General View	Load JPG	<input checked="" type="checkbox"/>
36	03/09/18 10:23	General View	Load JPG	<input checked="" type="checkbox"/>
37	03/09/18 10:23	General View	Load JPG	<input checked="" type="checkbox"/>
38	03/09/18 10:23	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/02/18 09:10	SLP5056E GIA REPORT	Load PDF	
2	08/02/18 09:25	TP WORKSHOP NOMINATE ADRIAN LING FROM LKK TO BE THE SJE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002559/GQD3E2

Date: 06/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17-375938-CA
Claimant Vehicle No :	SLP5056E	Insured Vehicle No :	FBG7618L
Date of Loss:	02/02/2018	Nature of Claim:	TP
		Claim No:	MSCN/18-000215

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP5056E		
Make & Model:	VOLKSWAGEN POLO, 1.4 (A)	Engine No:	CGG333010
Reg. Date:	14/05/2010 (Man. Year: 2010)	Chassis No:	WWWZZZ6RZAU038067
Colour:	Red	Odometer:	117014 km
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/40 R17	Rear Tyre Size:	215/40 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,187.39	2,204.37	8,983.02	80.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	840.00	2,990.00	78.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,017.39	3,044.37	11,973.02	79.73
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	15,017.39	2,400.00	12,617.39	84.02
+ GST 7.00/7.00% (S\$)	1,051.22	168.00	883.22	84.02
Nett Amount (S\$)	16,068.61	2,568.00	13,500.61	84.02

INSPECTION

Date of Assignment:	08/02/2018	
Date Inspected:	09/02/2018 Inspected At:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING Singapore 508775

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2018)
Parts: 144	VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP5056E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN MOULDING	Not Necessary	115.00 F	*- FL
2	1		*FRONT BONNET	Not Necessary	1,094.35 F	*- FL
3	1		*FRONT BONNET OPENER	Not Necessary	111.85 F	*- FL
4	1		*HEADLAMP RH	Scratched	647.00 F	*486.00 FL
5	10		*HEADLAMP CLIPS RH	Not Necessary	100.00 F	*- FL
6	1		*HEADLAMP PANEL RH	Not Necessary	63.68 F	*- FL
7	1		*FRONT GRILLE	Not Necessary	428.10 F	*- FL
8	1		*FRONT GRILLE LOGO - VW	Not Necessary	166.78 F	*- FL
9	10		*FRONT GRILLE CLIPS	Not Necessary	100.00 F	*- FL
10	1		*FRONT BUMPER	Cracked	1,077.83 F	*810.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	547.80 F	*- FL
12	1		*FRONT BUMPER RETAINER LH + RH	N/S Cut	317.70 F	*62.40 FL
13	2		*FRONT BUMPER BRACKET LH + RH	Not Necessary	124.00 F	*- FL
14	1		*FRONT BUMPER SPONGE	Not Necessary	33.50 F	*- FL
15	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	218.70 F	*- FL
16	10		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	100.00 F	*- FL
17	1		*FRONT BUMPER FOG LAMP COVER RH	Not Necessary	180.00 F	*- FL
18	1		*FRONT BUMPER LOWER	Cut	550.00 F	*86.40 FL
19	1		*FRONT FENDER RH	Repair	566.38 F	*- FL
20	1		*FRONT FENDER COWLING RH	Torn	192.23 F	*192.23 FL
21	1		*FRONT FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
22	1		*SIDE MIRROR ASSY	Repair	152.60 F	*- FL
23	1		*FRONT SUPPORT PANEL	Not Necessary	923.78 F	*- FL
24	1		*FRONT RIM RH	Cut	823.00 FS	*300.00 FS
25	1		*FRONT ABSORBER	Not Necessary	338.00 F	*- FL
26	1		*FRONT KNUCKLE	Not Necessary	496.08 F	*- FL
27	1		*FRONT KNUCKLE BEARING	Necessary	455.50 F	*345.60 FL
28	1		*FRONT KNUCKLE LOWER ARM	Not Necessary	323.53 F	*- FL
29	1		*FRONT TYRE RH	Scratched	600.00 FS	*100.00 FS
30	1		*FRONT WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
31	1		*FRONT FENDER SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,187.39	2,402.63
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	198.26
Total Parts (\$\$)	11,187.39	2,204.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RNR ACCIDENT AFFECTED FRONT	New	1,500.00	300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED FRONT	New	1,300.00	450.00
3	TO RUST PROOF ACCIDENT AFFECTED FRONT	New	150.00	0.00
4	TO RNR FRONT WINDSCREEN	New	250.00	0.00
5	TO CHECK WIRING AND HEADLAMP FOCUS	New	250.00	30.00
6	TO RNR FRONT UNDERCARRIAGE SYSTEM	New	150.00	0.00
7	TO ALIGN FRONT WHEEL	New	150.00	60.00
8	TO CHECK WATER SEEPAGE	New	80.00	0.00
Gross Labour Cost (\$\$)			3,830.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >