

12/23/2017

ASS. REC. BY:

REF: CS/MSG18002580/ G9d3

Special Instruction:

Survivor:  
Menmen

From (Person):

Christina Wong

ASSIGNMENT (Office)

of MSG

Estimated Cost:

Bill to:

Date/Time: 8/2/18 @ 10:27am

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FW 9183D

Insured: GBB 27774

at Workshop m/s

Pan Euro Bikes

Tel: 9731 7133

of

21 Moonstone Lane #01-01

Policy No: MSD/VCT/17-002506

Claim No: MSC/V/18-000216

Sum Insured:

Make of Veh:

(Client's Record)

Excess:

D.O.A. 02/02/2018

9/2/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS w/p

Date/Time: 1:52pm @ 8/2/18

Person Contacted: Kin Wah

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FW 9183D - NS/INC18002277/K196

GBB 27774 - NA/MSG18002166/24

D.O.A: 2/2/18

D.O.A: 2/2/18

12/2/18 @ 5:41pm revised to Christina Wong via Menmen.

IDAO Accident Report

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs

5

days

Fee:

Yes or No

Lum Sum

5

3 Val:

Yes or No

R/Bal:

5

mm

mm

L/Bal:

mm

mm

D.O.A:

D.O.A:

09-02-18

Survey held at

W/S

2:30pm

Des of Damages: 0000 NS / UC / Roof top

CA / REV / REP. / 24 HRS w/p

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time

Action/Instruction

part price checked. - Gmo Corp.

Finalized \$ 5258.60 (Red \$ 430.80, 8%)

26/7/2018

RECEIVED 25 JUL 2018.

Date/Time File Pass to:

☐

: Prelim. Report

Days Of Repair:

5

26/7/2018

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time File Return to:

Survey Fee

Transporter

Add Fee:

☐

Spec Ins:

\$

☐

Mech Rep:

\$

☐

Tech Ins:

\$

☐

Fresh Rep:

\$

Report Format:

Mop TP

Lum Sum / L/Bal:

5258.60



## enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8486Z
Vehicle Details	
Vehicle No.:	FW9183D
Vehicle to be Exported:	No
Intended De-registration Date:	15 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400SF2J
Primary Colour:	Red
Secondary Colour:	Black
Manufacturing Year:	2002
Engine No.:	NC23E2040418
Chassis No.:	NC391040968
Maximum Power Output:	-
Open Market Value:	\$8,300.00
Original Registration Date:	04 Jul 2003
First Registration Date:	04 Jul 2003
Transfer Count:	5
Actual ARF Paid:	\$1,245.00
Intended PARF Rebate Details	
PARF Eligibility:	No

## PARFICOE Rebate Enquiry

Category:	D - Motorcycle
Period(Years):	10
PQP Paid:	\$1,730.00
COE Rebate Amount:	\$931.00
<b>Total Rebate Amount:</b>	<b>\$931.00</b>

The information contained herein is correct as at 13 Feb 2018

OK



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18002580/Gqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-02-2018	
		Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GBB 2777U	Veh. Inspected	FW 9183D
Policy No.	MSD/VCT/17-002506	Coverage (\$)	0.00
Claim No.	MSC/V/18-000216	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	08/02/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	02/02/2018	Inspection Date	
Survey held at	PAN EURO BIKES PTE LTD 21 MOONSTONE LANE #01-01 POH LENG BUILDING SINGAPORE 328462.		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Feb 2018		08 Feb 2018 10:27 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>KST LEASING &amp; SERVICING</b> , Co. Reg. No.: 49392700W		
Main Claimant:	<b>VINOTH S/O A GUNASHEKARRAN</b> , ID: S9028486Z		
Vehicle Reg. No.:	<b>FW9183D</b>	Date of Loss:	02/02/2018 08:00 - :59
Claim Type:	<b>TP / MSC/V/18-000216</b>	Policy/Cover Note No.:	MSD/VCT/17-002506 (Third Party Only) Coverage: 11/11/2017 - 10/11/2018
Vehicle Reg. No. (Insured):	<b>GBB2777U</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Pan Euro Bikes Pte Ltd (HQ)</b> 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Imm.Advice due 09/02/2018]</b>		
Driver/Custodian (Insured):	<b>RAMALINGAM ASHOK KUMAR ()</b> , NRIC: G7770113W, Tel: +6582670428		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Hasrianah Binte Hassan

---

**From:** Woon Choo Kwok  
**Sent:** Tuesday, 6 February, 2018 4:35 PM  
**To:** Hasrianah Binte Hassan; Irene Tan  
**Cc:** Christopher Chionh; Foo Ai Ngoh  
**Subject:** FW: Survey Request - Accident between FW 9183D/GBB 2777U on 02.02.2018 between MANDAI AVE twds BKE.  
**Attachments:** FW9183D\_02022018.pdf; CCF02062018.pdf

Dear IT & HAS

FYA

Best Regards

**Kwok Woon Choo**

Senior Administrative Officer, Claims Services

Direct line +65 6643 1330 | Direct fax +65 6225 7402 | [woonchoo\\_kwok@sg.msig-asia.com](mailto:woonchoo_kwok@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**From:** Agnes Lee

**Sent:** Tuesday, February 06, 2018 2:31 PM

**To:** Woon Choo Kwok <[WoonChoo\\_Kwok@sg.msig-asia.com](mailto:WoonChoo_Kwok@sg.msig-asia.com)>

**Subject:** FW: Survey Request - Accident between FW 9183D/GBB 2777U on 02.02.2018 between MANDAI AVE twds BKE.

**From:** PanEuroBikes [<mailto:paneurobikes@singnet.com.sg>]

**Sent:** 06 February 2018 12:33

**To:** Claims <[claims@sg.msig-asia.com](mailto:claims@sg.msig-asia.com)>

**Subject:** Survey Request - Accident between FW 9183D/GBB 2777U on 02.02.2018 between MANDAI AVE twds BKE.

Dear Claims,

Kindly arrange a 3<sup>rd</sup> Party claims survey for our vehicle FW 9183D referenced to the subject matter. Please find estimate and GIA report attached.

Kindly ask your appointed surveyor to contact Kin Wah at 9731-7133, and do also advise who the OIC is, thank you.

Best Regards,

Kin Wah

Pan Euro Bikes Pte Ltd

Tel : +65 6299-4929

Fax : +65 6299-4430

Mobil : +65 9731-7133, +65 8121-2173  
Email : [paneurobikes@singnet.com.sg](mailto:paneurobikes@singnet.com.sg)

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 12 Feb 2018

**Preliminary Advice**

Insured Vehicle No	: GBB2777U	Accident Date	: 02/02/2018
TP Vehicle No	: FW9183D	Assignment Date	: 08/02/2018
Make	: HONDA CB 400 F3WYB	Est. Duration of Repair	: 5.00
Date of Inspection	: 09/02/2018		
Inspection At	: PAN EURO BIKES PTE LTD (HQ) 21 MOONSTONE LANE #01-01 POH LENG BUILDING SINGAPORE 328462		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & rear portion, o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,689.40
Revised Amount	:S\$	5,258.60
Check Items (Estimated)	:S\$	39.60
Total	:S\$	5,298.20

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.



## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8486Z
Vehicle Details	
Vehicle No.:	FW9183D
Vehicle to be Exported:	No
Intended De-registration Date:	12 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	CB400SF2J
Primary Colour:	Red
Secondary Colour:	Black
Manufacturing Year:	2002
Engine No.:	NC23E2040418
Chassis No.:	NC391040968
Maximum Power Output:	-
Open Market Value:	\$8,300.00
Original Registration Date:	04 Jul 2003
First Registration Date:	04 Jul 2003
Transfer Count:	5
Actual ARF Paid:	\$1,245.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jul 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,730.00
COE Rebate Amount:	\$932.00
<b>Total Rebate Amount:</b>	<b>\$932.00</b>

The information contained herein is correct as at 12 Feb 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/02/2018 14:34
Date Of Accident	02/02/2018 08:30
Exact Location Of Accident	MANDAI AVE TWDS BKE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FW9183D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	VINOTH S/O A GUNASHEKARRAN
NRIC No	S9028486Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94891509
Alternative Phone No	OTHERS-94891509

### Vehicle Particulars

Manufacturer	HONDA
Model	CB400SF2J
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5072511100-02 (TPFT)
Cover Note Number	

### Driver

Name of Driver	VINOTH S/O A GUNASHEKARRAN
NRIC No	S9028486Z
Date Of Birth	15/08/1990
Occupation	INDOOR
Date Of Driving Pass	04/07/2014
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94891509
Fax Number	
Contact Number	OTHERS-94891509
Email Address	NOEMAIL

Address	21 YISHUN STREET 51 #02-03
Postcode	768085
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	YISHUN SOUTH NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT NO. T/20180203/2002 ATTACHED. (ATTENDED BY CHRISTINA)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB2777U
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	RAMALINGAM ASHOK KUMAR
NRIC/Passport Number	G7770113W
Contact Number	82670428
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD3596L
-----------------------------	----------

Vehicle Make/Model/Colour	HYUNDAI TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TEO EE SUAN
NRIC/Passport Number	S1466387H
Contact Number	96611013
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3

#### DETAILS OF INJURED PERSON 1

Name	VINOTH S/O A GUNASHEKARRAN
Approximate Age	
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	FW9183D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

03 FEB 2010

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

## DECLARATION

I/We declare the foregoing participation to be true in every respect.

02 FEB 2019

Policyholder's Signature: \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature:  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature :  
Name :  
NRIC/FIN No :





**SINGAPORE  
POLICE FORCE**



T/20180203/2002

1 of 4

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

Report No. T/20180203/2002

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 03/02/2018 00:13	Vide Report No.:	Station Diary No.: 2
--	------------------	-------------------------

**Informant's Particulars**

Name of Informant: VINOTH S/O A GUNASHEKARRAN			Address: 21 YISHUN STREET 51 #02-03 SINGAPORE 768085		
ID Type / ID No.: NRIC NO / S9028488Z			Contact No.: Home/Office: Mobile: 94891509		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 15/08/1990	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: LAB ANALYST			Driving Licence Information: Class: 2B,2A,3,4		
			Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/02/2018 20:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 MANDAI AVENUE BUKIT TIMAH EXPRESSWAY near to Traffic Light junction turning right to SLE (Woodlands)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FW9183D	Motorcycle	HONDA	CB400SF2J	Red	Totally Damaged	0
GBB2777U	Lorry	TOYOTA		White	Slightly Damaged	0
SHD3596L	Car	HYUNDAI		Blue	Slightly Damaged	2

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20180203/2002

2 of 4

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street #1 SINGAPORE 768458  
Tel No: 1800-8522999

Report No. T/20180203/2002

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FW9183D	NTUC Income Insurance Co-Operative Limited	5072511100-02	04/07/2017	03/07/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	VINOTH S/O A GUNASHEKARRAN		ID No.	S9028486Z
Related Vehicle	FW9183D (Motorcycle)		Contact No.	94891509
Hospital/Clinic	KHOO TECK PUAT HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,2A,3,4 Date of Expiry: NIL
Date Treatment	02/02/2018		Date Discharge	02/02/2018
No. of Days granted Medical Leave	07		Degree of Injury	Slight
Driver				
Name	RAMALINGAM ASHOK KUMAR		ID No.	G7770113W
Related Vehicle	GBB2777U (Lorry)		Contact No.	82670428
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	TEO EE SUAN		ID No.	S1466387H
Related Vehicle	SHD3596L (Car)		Contact No.	96611013
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL





**SINGAPORE  
POLICE FORCE**



T/20180203/2002

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

3 of 4

Report No. T/20180203/2002

**CONTINUATION OF REPORT**

**Brief Details.**

On 02/02/2018 at around 8.30pm, I was riding along Mandai Avenue going towards BKE at the centre lane of a 3 lane road. While approaching a traffic junction, I noticed that there was a black Mercedes on the right lane, wanting to change lane onto the centre lane. The right lane was only for right turn into SLE (Woodlands). A taxi which was in-front and myself slowed down when we approach the traffic junction as we had noticed that the said Mercedes car had wanted to change lane.

Suddenly, the said Mercedes car had changed lane abruptly and it causes both the taxi and me to jam brake. I managed to brake on time and avoid hitting the taxi in-front of me. However, a lorry which was driving behind me did not managed to brake on time and hit onto my motorbike which causes my motorbike to hit onto the rear of the taxi. The said Mercedes car did not stop and just drove off.

Traffic Police had then attended to the accident scene and I was also conveyed by the ambulance to Khoo Teck Puat Hospital. My motorbike had to be towed away. I wished to state that the said taxi have an in car camera and had recorded the accident.

I was given 7 days MC (02/02/2018 - 08/02/2018).



**SINGAPORE  
POLICE FORCE**



T/20180203/2002

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

4 of 4

Report No. T/20180203/2002

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474685 stating the **report number** as reference.

Signature Of Officer Recording The Report: F/ Sr Staff Sgt ELRENO BIN SUBARI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 03/02/2018 00:13
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
Contact No.:	
Authentication Stamp: NP168	

# PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462  
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg  
Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT  
MSIG INS (S) PTE LTD

DATE: 06.02.2018

## ESTIMATED COST OF REPAIRS TO HONDA CB 400 VTEC SPEC II

ENGINE NO : CHASSIS NO :  
VEHICLE NO : FW 9183D ACCIDENT ON : 02.02.2018  
INSURED : VINOTH S/O A GUNASHEKARRAN

1 PC	REAR NO. PLATE LIGHT ASSY	CRA	\$	82.00
1 PC	REAR REFLECTOR, RED	Di's	\$	24.00
1 PC	REAR MUDGUARD	Cut	\$	280.00
1 PC	TAILLAMP(VTEC SPEC III)	CRA	\$	485.00
1 PC	TAIL COVER(VTEC SPEC III)	CRA	\$	398.00
1 PC	EXHAUST HEADER	Cut	\$	988.00
1 PC	RH PILLION FOOTREST	Cut	\$	68.00
1 PC	THROTTLE CONE	NN	\$	44.00
1 PC	THROTTLE CABLES	BR	\$	78.00
1 PC	RH SWITCH	CRA	\$	155.00
1 PC	HEADLAMP	NN	\$	168.00
1 PC	HEADLAMP RIM	Cut	\$	96.00
TOTAL			\$	2,866.00

LESS 10% \$ 286.60

SUB TOTAL \$ 2,579.40

### NETT ITEMS:

1 PC	REAR NO. PLATE	Cut	\$	12.00
	SEND BIKE FOR HEAT-STRAIGHTENING OF REAR FRAME		\$	280.00
1 SET	YOSHIMURA CYCLONE EXHAUST	Cut	\$	1,155.00
1 PC	TRANSPORT/SERVICE TO SEND BIKE FOR EXHAUST HOMOLOGATION		\$	135.00
2 PCS	EXHAUST GUARD, R&G	Cut	\$95 x 2	\$ 190.00
1 SET	ENGINE CRASHBAR, CHROME	Cut	\$	75.00
1 SET	HANDLE GRIPS, ALLOY	Cut	\$	65.00
1 SET	LEVERS SET, ASV ADJUSTABLE, BLACK	BR	\$	280.00
1 PVC	FRONT NO. PLATE	BT	\$	10.00
2 SETS	FRONT FORK OIL SEALS/DUST COVER	MBC	\$30 x 2	\$ 60.00
2 SIDES	FRONT FORK OIL	MBC	\$	28.00
	SEND FRONT MUDGUARD/TAIL COVER FOR SPRAY PAINTING		\$	260.00
	TOWING(TP TO IDAC, IDAC BAK TO WORKSHOP)		\$40 x 2	\$ 80.00
	LABOUR CHARGE		\$	480.00
TOTAL			\$	5,689.40

### REMARKS:

Kindly send a surveyor down for an 3rd Party claim against your insured GBB 2777U.

Thank You.

LKK Auto Consultants hence notify  
Kin Wah: 9731-7133

- The Repairer of the following
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ADD 7% GST

\$ 398.26

GRAND TOTAL

\$ 5,291.14

5 Days.

part by part.

After repair photos.

Guo Q. ap.

09/2/18

13/2/18

# PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462  
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg

Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT  
MSIG INS (S) PTE LTD

DATE: 16.06.2018

## ESTIMATED COST OF REPAIRS TO HONDA CB 400 VTEC SPEC II

ENGINE NO : CHASSIS NO :  
VEHICLE NO : FW 9183D ACCIDENT ON : 02.02.2018  
INSURED : VINOTH S/O A GUNASHEKARRAN

1 PC	REAR NO. PLATE LIGHT ASSY	S	82.00
1 PC	REAR REFLECTOR, RED	S	24.00
1 PC	REAR MUDGUARD	S	280.00
1 PC	TAILLAMP(VTEC SPEC III)	S	485.00
1 PC	TAIL COVER(VTEC SPEC III)	S	398.00
1 PC	EXHAUST HEADER	S	988.00
1 PC	RH PILLION FOOTREST	S	68.00
1 PC	THROTTLE CONE	REMOVED	
1 PC	THROTTLE CABLES	S	78.00
1 PC	RH SWITCH	S	155.00
1 PC	HEADLAMP	REMOVED	
1 PC	HEADLAMP RIM	S	96.00
TOTAL		S	2,654.00
LESS 10%		S	265.40
SUB TOTAL		S	2,388.60

### NETT ITEMS:

1 PC	REAR NO. PLATE	S	12.00
SEND BIKE FOR HEAT-STRAIGHTENING OF REAR FRAME		S	240.00
1 SET	YOSHIMURA CYCLONE EXHAUST	S	1,155.00
1 PC	TRANSPORT/SSERVICE TO SEND BIKE FOR EXHAUST HOMOLOGATION	S	135.00
2 PCS	EXHAUST GUARD, R&G	\$95 x 2	S 190.00
1 SET	ENGINE CRASHBAR, CHROME	S	75.00
1 SET	HANDLE GRIPS, ALLOY	S	65.00
1 SET	LEVERS SET, ASV ADJUSTABLE, BLACK	S	280.00
1 PVC	FRONT NO. PLATE	S	10.00
2 SETS	FRONT FORK OIL SEALS/DUST COVER	\$30 x 2	S 60.00
2 SIDES	FRONT FORK OIL	S	28.00
SEND FRONT MUDGUARD/TAIL COVER FOR SPRAY PAINTING		S	260.00
TOWING(TP TO IDAC, IDAC BAK TO WORKSHOP)		\$40 x 2	S 80.00
LABOUR CHARGE		S	280.00
TOTAL		S	5,258.60

### REMARKS:

For a 3rd Party claim against your insured GBB 2777U.

Thank You.

Kin Wah: 9731-7133

ADD 7% GST

GRAND TOTAL

S 368.10

S 4,890.50

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Feb 2018		08 Feb 2018 10:27 <a href="#">Edit Adj Rpt</a>	<b>S\$5,258.60</b> <a href="#">Edit Estimates</a>	<b>S\$5,258.60</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------



































<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by Insurer]</b>			
Insured:	<b>KST LEASING &amp; SERVICING</b> , Co. Reg. No.: 49392700W					
Main Claimant:	<b>VINOTH S/O A GUNASHEKARRAN</b> , ID: S9028486Z					
Vehicle Reg. No.:	<b>FW9183D</b>	Date of Loss:	02/02/2018 08:00 - :59 <b>[174 Months and 29 Days From LTA Reg Date (Man Yr)]</b>			
Claim Type:	<b>TP / MSC/V/18-000216</b>	Policy/Cover Note No.:	MSD/VCT/17-002506 (Third Party Only) Coverage: 11/11/2017 - 10/11/2018			
Vehicle Reg. No. (Insured):	<b>G882777U</b>	Policy No. (Claimant):				
		Excess:				
Repairer:	<b>Pan Euro Bikes Pte Ltd (HQ)</b> 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929					
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]					
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 10/03/2018]</b>					
Driver/Custodian (Insured):	RAMALINGAM ASHOK KUMAR (J), NRIC: G7770113W, Tel: +6582670428					
















































<b>ASSOCIATED MAIL RECEIVED</b>	<b>View All</b>	<b>Compose Case Mail</b>
There are no mail for this case.		


<b>ALL ASSOCIATED TASKS</b>	<b>View All</b>	<b>Search Tasks</b>	<b>Create New Task</b>	<b>Complete</b>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>
				<b>Handler</b>
				<b>Assigned By</b>
				<b>Completed On</b>
				<b>Created On</b>
				<b>Done?</b>
No results.				

## Claim Documents

\*FW9183D (MSC/V/18-000216)  
[GBB2777U]  
TP  
VINOTH S/O A GUNASHEKARRAN  
Feb 2 2018 8:00AM  
[KST LEASING & SERVICING]  
Pan Euro Bikes Pte Ltd

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	07/02/18 18:11	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>Accident Statement</b> <small>From: SC - Reg. No: GBB2777U, Claimant: KST LEASING &amp; SERVICING</small>	 <a href="#">Load HTM</a>	
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	Thumbnail	Print
1	12/02/18 17:41	<b>Adjuster Immediate Advice</b>	 <a href="#">Load HTM</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	26/07/18 12:13	<b>LKK Auto Consultants Pte Ltd (HQ)</b> <b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
2	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
3	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
4	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
5	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
6	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
7	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
8	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
9	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
10	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
11	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
12	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
13	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
14	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
15	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
16	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
17	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
18	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
19	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
20	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
21	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
22	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
23	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
24	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
25	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
26	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
27	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
28	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
29	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
30	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
31	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	<input checked="" type="checkbox"/>
32	26/07/18 12:13	<b>General View</b>	 <a href="#">Load JPG</a>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
38	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/07/18 12:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	26/07/18 12:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/02/18 18:11	FW9183D GIA Rpt From: SC - Reg. No: G882777U, Claimant: KST LEASING & SERVICING	 Load PDF	
2	07/02/18 18:11	SHD3596L GIA Rpt From: SC - Reg. No: G882777U, Claimant: KST LEASING & SERVICING	 Load PDF	
3	07/02/18 18:11	Estimate	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
4	07/02/18 18:18	Email frm TP - PRI	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18002580/QD3Q2

Date: 26/07/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCT/17-002506		
Claimant Vehicle No :	FW9183D	Insured Vehicle No :	GBB2777U		
Date of Loss:	02/02/2018	Nature of Claim:	TP	Claim No:	MSC/V/18-000216

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FW9183D	Engine No:	NC23E2040418
Make & Model:	HONDA CB 400 F3WYB, 399cc (M)	Chassis No:	NC391040968
Reg. Date:	04/07/2003 (Man. Year: 2002)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	399 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	120/60 ZR17	Rear Tyre Size:	160/60 ZR17
Front Left Side:	Mezller 5 mm	Rear Left Side:	Mezller 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,454.40	4,263.60	190.80	4.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,235.00	995.00	240.00	19.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,689.40</b>	<b>5,258.60</b>	<b>430.80</b>	<b>7.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>398.26</b>	<b>368.10</b>	<b>30.16</b>	<b>7.57</b>
<b>Nett Amount (S\$)</b>	<b>6,087.66</b>	<b>5,626.70</b>	<b>460.96</b>	<b>7.57</b>

### INSPECTION

Date of Assignment:	08/02/2018	
Date Inspected:	09/02/2018 Inspected At:	Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Jul 2018)	
<b>Parts:</b>	N/A	HONDA CB 400 F3WYB 399cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FW9183D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NO.PLATE LIGHT ASSY	Cracked	82.00 FL	*82.00 FL
2	1		*REAR REFLECTOR .RED	Distorted	24.00 FL	*24.00 FL
3	1		*REAR MUDGUARD	Cut	280.00 FL	*280.00 FL
4	1		*TAILLAMP (VTEC SPEC LH)	Cracked	485.00 FL	*485.00 FL
5	1		*TAIL COVER (VTEC SPEC LH)	Cracked	398.00 FL	*398.00 FL
6	1		*EXHAUST HEADER	Cut	988.00 FL	*988.00 FL
7	1		*RH PILLION FOOTREST	Cut	68.00 FL	*68.00 FL
8	1		*THROTTLE CONE	Not Necessary	44.00 FL	*- FL
9	1		*THROTTLE CABLES	Broken	78.00 FL	*78.00 FL
10	1		*RH SWITCH	Cracked	155.00 FL	*155.00 FL
11	1		*HEADLAMP	Not Necessary	168.00 FL	*- FL
12	1		*HEADLAMP RIM	Cut	96.00 FL	*96.00 FL
13	1		*REAR NO.PLATE	Cut	12.00 FS	*12.00 FS
14	1		*SET YOSHIMURA CYCLONE EXHAUST	Cut	1,155.00 FS	*1,155.00 FS
15	2		*EXHAUST GUARD ,R&G	Cut	190.00 FS	*190.00 FS
16	1		*SET ENGINE CRASHBAR ,CHROME	Cut	75.00 FS	*75.00 FS
17	1		*SET HANDLE GRIPS ,ALLOY	Cut	65.00 FS	*65.00 FS
18	1		*SET LEVERS SET ,ASY ADJUSTABLE ,BLACK	Broken	280.00 FS	*280.00 FS
19	1		*FRONT NO.PLATE	Bent	10.00 FS	*10.00 FS
20	2		*SETS FRONT FORK OIL SEALS /DUST COVER	Necessary	60.00 FS	*60.00 FS
21	1		*SIDES FRONT FORK OIL	Necessary	28.00 FS	*28.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,741.00</b>	<b>4,529.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	286.60	265.40
<b>Total Parts (\$\$)</b>	<b>4,454.40</b>	<b>4,263.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SEND BIKE FOR HEAT-STRAIGHTENING OF REAR FRAME	New	280.00	240.00
2	TRANSPORT /SSERVICE TO SEND BIKE FOR EXHAUST HOMOLOGATION	New	135.00	135.00
3	SEND FRONT MUDGUARD /TAIL COVER FOR SPRAY PAINTING	New	260.00	260.00
4	TOWING (TP TO IDAC ,IDAC BAK TO WORKSHOP)	New	80.00	80.00
5	LABOUR CHARGE	New	480.00	280.00
Gross Labour Cost (S\$)			1,235.00	995.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >