

12/03/2002

ASS. REC. BY:

REF: CS/FCI18002584/ Atd3ek Special Instruction:

Surveyor:

CWS

Adrian

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 7/2/18 @ 4:22pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG4171C

Insured:

SHA75384

at Workshop m/s

New Hock Teck

Tel:

67479241

of

1, Kaki Bkt Ave 6 Blk C # 01-43 Autobay

Policy No:

Claim No:

D1800113SMFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/02/2008

CA / REV / REP. / REV 24 HRS

'wpr'

H.O.D. Endorsement:

Date/Time:

9:06am @ 8/2/18

Person Contacted:

Sukyi

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓)

Estimate

GBC4171C-X

SHA75384-CS3/FCI18004091/Ggh3d1

D.O.A.: 23/2/16

09/2/18 @ 1:28pm

Informed Eileen, we are pending estimate from repairer

Lump Sum \$2100/- (Red: 3026.50, 59%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBG417LC Yr Regn: 2017 AugustType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia K2500 C.C. 2497Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 6139 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNCSTX76LG7116136Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15R: S-00R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 08/02/18Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap

Date/Time. File Pass to?

☐

Preli. Report

☒

Final Report

Date/Time. File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ 2100/-)Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS, _____ SI

) Photos

) Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

TOTAL

140
90
28
218



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC18002584/td3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 7538U	Veh. Inspected	GBG 4171C
Policy No.		Coverage (\$)	0.00
Claim No.	D18001135MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	08/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/02/2018	Inspection Date	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 9 February 2018 1:28 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001135MFSH/1

Dear Eileen,

Please be informed that we have inspected the vehicle GBG 4171C on 08/02/2018.

We are pending estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Thursday, 8 February 2018 9:28 AM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18001135MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 7 February 2018 4:21 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001135MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

MOTOR SURVEY ASSIGNMENT

Date	06-02-2018	Our Ref No. D18001135MFSH
Accident Date	05-02-2018	Claim Type. Third Party
Insured Vehicle	SHA7538U	Third Party Vehicle. GBG4171C
Survey Location	1 KAKI BUKIT AVE 6 BLK C #01-43 AUTOBAY@KAKI BUKIT	
Contact Person.	NA	
Contact No.	67479241/ 0	Fax No. 67417276
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	NEW HOCK TECK MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234751)



PRI Documents



Close



PRI Header Details

Claim No	D18001135MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & NEW HOC
Workshop Name	NEW HOCK TECK MOTOR PTE LTD (Contact Person : NA)	Survey Location & Contact Details	1 KAKI BUKIT AVE 6 BLK C #01-43 AUTOBAY@KAKI BUI Mobile: 0 , Phone: 67479241 , Fax: 67417276 EmailId: ADMIN@NHTMOTOR.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7538U	TP Vehicle No	GBG4171C
PRI Recieved Date	06-02-2018 10:45:21 PM	Surveyor Appointed Date	07-02-2018 04:21:09 PM	Surveyor Accept Date	08-02-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-02-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	7919N

Vehicle Details

Vehicle No.:	GBG4171C
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Feb 2018
Vehicle Make:	KIA
Vehicle Model:	K2500 6M/T
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	D4CBG100290
Chassis No.:	KNCSJX76LG7116136
Maximum Power Output:	-
Open Market Value:	\$17,539.00
Original Registration Date:	08 Aug 2017
First Registration Date:	08 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$877.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details



COE Expiry Date:	07 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,809.00
COE Rebate Amount:	\$34,247.00
Total Rebate Amount:	\$34,247.00

The information contained herein is correct as at 06 Feb 2018

OK

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

NO 07

A: ABG4171C

B: SHH7530U

KNOW NOT PD

A

B

↑

↓

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to "notice of reporting".

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NOTICE OF REPORTING

This is to confirm that Chinniah Muragan, PIN: E8423665N, has reported to the Police a non-injury traffic accident which

occurred along 87 Kheam Road.

On 05/02/2018 at about 1430pm on the following details:

Other vehicle: SHA/5580 and my vehicle: GBG4171C.

I am the only driver of vehicle GBG4171C.

I am involved in a non-injury accident with the above said vehicle.

Brief facts:

On 05/02/2018 at about 1430hrs, my vehicle was parked and stationary outside 87 Kheam Hock Road as I was at doing servicing at the swimming pool inside the mall. A taxi SHA7538U bumped into my stationary vehicle and caused 1 inch dent damages on the right driver door area. I went out and made a check and we exchanged particulars.

I told my Boss, Mr Leong, and I was told to inform the police about the accident.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 94(2) of the Road Traffic Act, Cap 276.

Rank/Name of issuing Officer: SSGT 1120050 Jeremy Teo

Date: 05/02/2018 Time: 1413hrs

aS/D Ref No:52

Police Posu/Inlc: Rush Timah NPC

Original - to be issued to informant

Duplicate - to be submitted to Traffic Police



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

Adnan LKK - First Capital.

SAQUARIES INYERNATIONAL PTE LTD

06/02/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP 1st Cap.

Denise

Accident date: 06/02/2018

Estimated repair cost for vehicle no: GBG4171C KIA K2500 2.5 M '17

CHASSIS: KNCSJX76LG7116136

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front R/H Head Lamp <i>lt</i>		\$290.00 ✓
2	1	Front R/H Side Panel <i>Dented</i>		\$182.00 ✓
3	1	Front Bumper <i>lt</i>		\$365.00 ✓
4	8	Front Bumper Clip <i>~</i>	\$6.50	\$52.00 <i>30</i>
5	1	Front R/H Bumper Side Retainer <i>~</i>		\$28.00 ✓
6	1	Front R/H Door <i>Dented</i>		\$848.00 ✓
7	1	Front R/H Door K2500 Sticker <i>~</i>		\$28.50 ✓
8	1	Front R/H Door Sticker <i>~</i>		\$30.00 ✓
9	1	Front R/H Door Side Mirror <i>3rd</i>		\$290.00 <i>x</i>
10	1	Front R/H Door Outer Handle <i>~</i>		\$75.00 <i>x</i>
11	1	Front R/H Door Signal Lamp <i>cracked</i>		\$48.00 ✓
12	1	Front R/H Door Gear Motor Assy <i>~</i>		\$420.00 <i>x</i>
13	1	Front R/H Door Body Logo (Special Nett) <i>~</i>		\$400.00 <i>150(SN)</i>

Subtotal:- \$3,056.50

1849.50 S.N: 150

1664.55

Labour charges

To remove & refit front R/H door, gear motor, lock, glass & trim board		\$180.00 60
To remove & refit body logo		\$180.00 50
To check wiring		\$60.00 30
Tuff kote		\$150.00 X
Panel beating	840	\$750.00 400
Spray painting		\$750.00 300

Subtotal:- \$2,070.00

Total:- \$5,126.50

total. 2654.55

Hs: 2.1K.

04 Days.

2.1K

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002584/Atd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-03-2018



Code : FCI2

1. Policy Particulars - THIRD PARTY CLAIM

Insured Veh.	SHA 7538U	Veh. Inspected	GBG 4171C
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001135MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	07/02/2018

2. Vehicle Particulars & Condition

Make & Model	KIA K2500	c.c	2497
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNCSJX76LG7116136	Colour	BLUE
Odometer	6139	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	KUMHO	6 mm
L/H Front Tyre	195 R15	KUMHO	6 mm
R/H Rear Tyre	5.00 R12	KUMHO	6 mm
L/H Rear Tyre	5.00 R12	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/02/2018	Inspection Date	08/02/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 4171C

Qty	Description of Parts	Condition	Estimated By Workshop (\$)	Our Estimated (\$)
REPLACEMENT OF PARTS				
1	FRONT R/H HEAD LAMP	CUT	290.00	290.00
1	FRONT R/H SIDE PANEL	DENTED	182.00	182.00
1	FRONT BUMPER	CUT	365.00	365.00
8	FRONT BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
1	FRONT R/H BUMPER SIDE RETAINER	NECESSARY	28.00	28.00
1	FRONT R/H DOOR	DENTED	848.00	848.00
1	FRONT R/H DOOR K2500 STICKER	NECESSARY	28.50	28.50
1	FRONT R/H DOOR STICKER	NECESSARY	30.00	30.00
1	FRONT R/H DOOR SIDE MIRROR	NOT NECESSARY	290.00	-
1	FRONT R/H DOOR OUTER HANDLE	NOT NECESSARY	75.00	-
1	FRONT R/H DOOR SIGNAL LAMP	CRACKED	48.00	48.00
1	FRONT R/H DOOR GEAR MOTOR ASSY	NOT NECESSARY	420.00	-
	LESS 10% DISCOUNT		-	-184.95
			2,656.50	1,664.55
SPECIAL NETT ITEMS				
1	FRONT R/H DOOR BODY LOGO (SN)	NECESSARY	400.00	150.00
			400.00	150.00
LABOUR				
	TO REMOVE & REFIT FRONT R/H DOOR, GEAR MOTOR, LOCK, GLASS & TRIM BOARD.		180.00	60.00
	TO REMOVE & REFIT BODY LOGO.		180.00	50.00
	TO CHECK WIRING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	PANEL BEATING.		750.00	400.00
	SPRAY PAINTING.		750.00	300.00
			2,070.00	840.00
GRAND TOTAL			5,126.50	2,654.55

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				100.00
---	--	--	--	---------------

Report Ref No. CS/FCI18002584/Atd3e2



Report Ref No. CS/FCI18002584/Atd3e2

A handwritten signature in black ink, appearing to read 'A.L.P.' or similar.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.