

INS. CASE OWNER:

Stacey CC 4/ASM1800 7658 / T1 96352 IDAC: 30703

SIR/MS/MT:

Tambikh

DOI:

ASSIGNMENT

12/1/18

Date / Time:

Registered in Merimen:

9/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJB 8806K

Name of Insured:

CHA SLOW CHING

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

8/2/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHA HAP MONG

Driver Tel No.:

96439069

(V/L: YES / NO)

Claim No.:

S8M080R

Policy No.:

GA 050820/1

Make / Model:

7-Rush (500)

Place of Accident:

Junction of BKE 132 & 131 JNM
Bulat mang c/p.

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLF9115U



INSRS:

WSP:

Tel:

Liability:

RMKS:

Vermogen



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/1/18

20/1/18

23022018 @

4.28pm

SLF9115U, X; SJB 8806K-X

Spoke to OIO (Mr CHA). Confirmed accident det
and OIO moving out from minor road (with spall)
OJ will send any additional photos via email. Inform
det TP claim, aware of NCO rules and agree to set
Sensalitter to OJ.

24.9.18 FINE PASS TO TYPIST TO PREPARE REPORT.

RECEIVED 24 APR 2018

RECEIVED 10 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time: 19.4.18

Confirm with: PHUO

Confirm by: MIA

Repair Cost:

43

SS2,400

(

6

days)

Reduction:

68

%

Email

Call

FINAL SETTLEMENT

Date/Time: 26.7.18

Confirm with: EZEL

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

10

If NO or B 28, Ass. Lia:

Repair Cost:

2/1/18

SS2,568.00

Loss of Rental (LOR):

SS -

(

days)

Loss of Use (LOU):

SS 880.00

(\$

80

x

11

days)

Note

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS3,450

Global Sum SS:

FINAL PAYMENT

Date/Time: 30.7.18

Confirm with: EZEL

Email

Call

Payee 1:

SS3,450.00

Name 1:

VERMOGEN ACE PIE MD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18002658/T1ka3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 09-02-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 8806K	Veh. Inspected	SLF 9115U	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M008OR	Excess (\$)	0.00	
Assign From		Assign Date	09/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/02/2018	Inspection Date	12/02/2018	
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



SLF9115U

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 8/2/2018

Vehicle Reg. No. : SLF9115U
Vehicle Reg. Date: 15-Sep-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4404848
Chassis No. : RU11204848

COST OF CLAIMS

Parts Cost / List Items : \$ 5,530.00
Plus/Less 20% \$ 1,106.00
Total Cost / List : \$ 4,424.00
Special Nett Items : \$ 350.00
Total Parts Amount : \$ 4,774.00
Total Labour Amount : \$ 2,780.00
Gross Total : \$ 7,554.00
GST % : 7% \$ 528.78
Nett Amount : \$ 8,082.78

Surveyor Name and Company :

Tanjin 97495749
Date of survey : 12/2/18 @ 1440
Part by Part / Lump Sum : 6 days
Resurvey Before Paint / After Paint After Paint
Authorize/Not Authorize/Without Prejudice Without Prejudice
Email : sur@khanh.vn
Fax No : _____
HP No : _____

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF9115U**

Vehicle Reg. Date: **9/15/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4404848**

Chassis No. : **RU11204848**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Front door LH	Rx	\$ 1,350.00		
2	1	Front door sticker LH	X w	\$ 46.00		
3	1	Rear door LH	bt	\$ 1,042.00		±841
4	1	Rear door front rubber LH	R	\$ 40.00		
5	1	Rear door bottom rubber LH	X w	\$ 40.00		
6	1	Rear door back rubber LH	X	\$ 32.00		
7	1	Rear door sticker LH	nei	\$ 46.00		
8	1	Rear door hinge upper LH	Rx	\$ 72.00		
9	1	Rear door hinge lower LH	Rx	\$ 75.00		
10	1	Rear door stopper LH	X w	\$ 20.00		
11	1	Rear door moulding LH	X	\$ 85.00		
12	1	Rear door weather strip LH	nei	\$ 95.00		
13	1	Rear door regulator LH	R	\$ 477.00		
14	1	Rear door lock mechanism LH	X w	\$ 377.00		
15	1	Side Skirt LH	ant	\$ 520.00		±320
16	1set	Side skirt LH clips	nei	\$ 50.00		±40
17	1	Rear fender arch garnish LH	ant	\$ 163.00		
18	1	Rear fender arch garnish clips LH	nei	\$ 50.00		
19	1	Rear rim LH	ant	\$ 950.00	450	
20	1	TYRE 215/60R16 (RR LH)	X w		\$ 350.00	
21	1	0				
22	1	0				
23	1	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBLAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M008OR
Our ref: CC4/ASM18002658/T1ka3

Date: 14.02.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SLF 9115U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.02.2018 at the premises of M/s Vermogen Ace Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	7,554.00
Revised Estimate Amount	: S\$	3,462.80
"Check" Items Amount	: S\$	471.20
Total (Including Check Items)	: S\$	3,934.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
N/S Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 6.0 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser



MANDATE REQUEST FOR S8M0080R

Story

Type

🔗 Question

Message

Liability: Insured make a left turn into the main road collided with TP. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$2,568.00 (w/GST) Loss of Use: \$880.00 (11days x \$80) Uber Driver LTA: \$2.00 Total: \$3,450.00 Revised Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (23/05/2018)

Reply



Re:MANDATE REQUEST FOR S8M0080R

Type

 Information

Message

Pls proceed

Reply

TO:

Dear Sirs,

CLAIMANT:

ACCIDENT INVOLVING SLF9115U and SJB8806K on

08/02/2018 At 1120HRS

I/WE LCRF PTE LTD, am/are the registered Owner of Vehicle No. SLF9115U.

Please note that I have assigned all compensation monies due -to me/us in the above said accident to **Vermogen ACE Pte Ltd**.

I/We, hereby authorize you to release all compensation monies pertaining to the above said accident to **Vermogen ACE Pte Ltd** and forward your settlement cheque to **Vermogen ACE Pte Ltd** whom I/we had authorized to collect the said compensation monies..

Thankyou.



Signature of Claimant
(company Stamp, if applicable)

Name : _____
NRIC No. : _____
Date : _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJB 8806K (Insd veh)	Model:	HONDA
	SLF 9115U (TP veh)		VEZEL 1.5X CVT
Date of Accident:	08/02/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,266.20
Final Repair Cost	:	\$	2,568.00
Loss of Use	:	\$	880.00
Rental (if any)	:	\$	11 days at \$80.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others: : \$

	:	\$	
Final Settlement Sum	:	\$	3,450.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ 100____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown	
1) VERMOGEN ACE PTE LTD	: \$ 3,450.00

NUR SHAQILAH BTE ABDOL
WAHAB

29/08/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

<< Service Request Details

Claim	S8M0080R	
Reference	CC4/ASM18002658/T1ea3s2  Loss Date	
February 8, 2018	Request Date	
February 9, 2018	Due Date	
February 9, 2019	Vendor Name	
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss	
Third Party Vehicle Damage	Services	
Pending verification - Direct Settlement		
Actions Next Step Finish the work Complete Work More Document Type Document SubType Upload Documents		
Vehicle Information		
Incident Vehicle Registration #	SLF9115U	Service Address
Make		
TPVD HONDA	Model	
VEZEL	Primary Contact/Insured	
CHIA SIOW CHING (XIE XIAOJUN) BLK 132 JALAN BUKIT MERAH, #01-1338, 160132, Singapore		
Claim Handler		
NG Stacey 6568804351 stacey.ng@axa.com.sg		
Additional Instructions		
NAME	TYPE	SUB-TYPE AUTHOR DATE UPLOADED
Accident Statement Reports & Statement Meritmen		
Messages Invoices History Documents		
Assessment Metrics Notes		

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S8MD080R	Actions		Add
Reference	CC4/ASM18002658/T1ea3sz 	Next Step	Finish the work	Complete Work
Loss Date	February 8, 2018			Move
Request Date	February 9, 2018			
Due Date	February 9, 2019			
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)			
Type of Loss	Third Party Vehicle Damage			
Services	Pending verification - Direct Settlement			
Vehicle Information				
Incident Vehicle Registration #	SLF9115U	Make	Service Address	
TPVD HONDA		Model	...	
VEZEL		Primary Contact/Insured		
CHIA SIOW CHING (XIE XIAOJUN)				
BLK 132 JALAN BUKIT MERAH, #01-1338, 160132, Singapore				
Claim Handler				
NG Stacey				
6568804351				
stacey.ng@axa.com.sg				
Additional Instructions		Messages	Invoices	History
		Assessment	Melrics	Notes
CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS
				SHARE
				CLONE



Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Vehicle & Driver Details

Vehicle Registration#	SLF911SU	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	09/15/2016
Mileage	101497	Age of Vehicle	1

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FINCL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year		2016	Driver Name	LEE YOKE LEONG	
Make	TPVD HONDA	HONDA	Date of Birth	April 17, 1960	mm/dd/yyyy
Model	VEZEL	VEZEL 1.5X CVT	Age	58	
Type			Occupation	Unknown	
Type of Paint			Education Qualification	Other	
Chassis No		RU11204848	Driving Experience	0	
Engine No		L15B4404848	Driver License #		
Engine Capacity		1496 cc			



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	02/12/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unnamed Driver Excess	0		Pre-accident condition	Good
Other Excess			Tyre Condition	
Age of Tyres			Spare wheel	
Front Tyre Size	215/60R16		Rear Tyre Size	215/60R16
Front left side	DUNLOP 6mm		Rear left side	DUNLOP 6mm
Front right side	DUNLOP 6mm		Rear right side	DUNLOP 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details										Vehicle & Driver Details			Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC QUNTY	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE									
	1	1			FRONT DOOR LH			Repair	0		20		0	Reviewing										
	2	1			FRONT DOOR STICKER LH			Serviceable	0		20		0	Reviewing										
	3	1			REAR DOOR LH			Bent	841		20		672.8	Reviewing										
	4	1			REAR DOOR FRONT RUBBER LH			Serviceable	0		20		0	Reviewing										
	5	1			REAR DOOR BOTTOM RUBBER LH			Serviceable	0		20		0	Reviewing										
	6	1			REAR DOOR BACK RUBBER LH			Serviceable	0		20		0	Reviewing										
	7	1			REAR DOOR STICKER LH			Necessary	46		20		36.8	Reviewing										
	8	1			REAR DOOR HINGE UPPER LH			Repair	0		20		0	Reviewing										
	9	1			REAR DOOR HINGE LOWER LH			Repair	0		20		0	Reviewing										
	10	1			REAR DOOR STOPPER LH			Serviceable	0		20		0	Reviewing										
	11	1			REAR DOOR MOULDING LH			Serviceable	0		20		0	Reviewing										

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		5		TO REMOVE AND TRANSFER REAR DOOR COMPONENTS LHS.	60	0	0	Reviewing		
		6		TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA. FRONT DOOR LH, CENTER PILLAR LH, REAR DOOR LH, REAR FENDER LH	600	0	0	Reviewing		
		7		TO REMOVE AND REPLACE REAR TYRE & RIM LH.	30	0	0	Reviewing		
		8		TO CONDUCT WHEEL ALIGNMENT.	80	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

EDIT	SIR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		6	
	2	TYRE 215/60R16 (RR LH)	Reviewing	0	NOT NECESSARY	

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$3,044.00

Claim Amount

\$3,044.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,440.00	\$1,440.00
Spare Parts	\$1,604.00	\$1,604.00

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE

1

FINAL LUMP SUM

Reviewing

2400