

ASS. REC. BY:

REF: CS/CTI18002678/M1xd3 Special Instruction:

Surveyor:

MA

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time: 8/2/18 @ 4.07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 8228B

Insured:

GBE 2486T

at Workshop m/s

Kum Chew Motor

Tel:

64536256

of

160 8in Ming Drive #05-08

Policy No:

DMCVSN 3078211700

Claim No:

SNM18D0629C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

11:18am @ 9/2/18

Person Contacted:

seow choo

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 8228B - X

GBE 2486T - X

19/6/18

@ 1024am Final fig \$1564.08 confirmed with mdm Lim
(Red 2325.84 60%)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop mis: Lum Green
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAO Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

veh No: SL08228 Vc Page: JUN 2017
 Type: M/C M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: MIT LANCER C: 1590
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp Reading: 20977 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C.No: JMYSRCYIAGU006749
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60/R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Yoko

Front: _____ Rear: _____
 R.Bal: 7 mm R.Bal: 7 mm
 L.Bal: 7 mm L.Bal: 7 mm
 D.O.A. 25/10/2018 D.O.I. 13/02/2018

Survey held at: _____
 Des. of Damages: Frt. / Rear / O/S / N/S / U/C / Rooftop or
Re body,
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

NO ESTIMATE upon Survey.

RECEIVED 19 JUN 2018

Date/Time File Pass to?

☐

: Prel. Report

X

: Final Report

Date/Time File Return to?

1 19/6- typist

Days Of Repair: 4Resurvey No. of Trip: 1Survey Fee
Transportation220

Add Fee:

☐
☐
☐
☐

Site Insp: \$

Interview: \$

Technician: \$

Access: \$

Lab Fee: \$

Photo: \$

Draw: \$

Report Format:

Merimen

Lump Sum / I.B.I. / S

1564.08



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18002678/M1vd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 09-02-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 2486T	Veh. Inspected	SLQ 8228B
Policy No.	DMCVSN3078211700	Coverage (\$)	0.00
Claim No.	SNM17D06209C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	09/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/10/2018	Inspection Date
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Feb 2018		08 Feb 2018 16:07 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YIHO GLASS PTE. LTD., Co. Reg. No.: 201208969G		
Main Claimant:	HENG CHANG SIONG, ID: S7642688J		
Vehicle Reg. No.:	SLQ8228B	Date of Loss:	25/10/2017 09:00 - :59
Claim Type:	TP / SNM17D06209C02	Policy/Cover Note No.:	DMCVSN3078211700 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE2486T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kum Chew Motor Workshop (HQ) 12 Sin Ming Industrial Estate, #01-71, 575656 Sin Ming - Tel: 6456 3715		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/02/2018]		
Driver/Custodian (Insured):	YONG CHEE TYAN (40 / Male), NRIC: S7789443H, Tel: +6592721038		
Adj Asg. Remarks:	NO EST, ASSIGN TO LKK WITH SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

KUM CHEW MOTOR WORKSHOP

Your Ref. No: GBE 2486 T

Our Ref. No: KC/TP8228/1802-05

Date: 05/02/2018

To: CHINA TAIPING INSURANCE (S) PTE LTD

FAX No. 62247175

Dear Sirs

**RE : ACCIDENT INVOLVING SLQ 8228 B & GBE 2486 T AT
WOODLAND SECTOR 1 WOODLANDLANE SPECTRUM 1 CAR
PARK ON 25/10/2017.**


We act for Mr Heng Chang Siong, the owner of vehicle no. SLQ 8228 B was involved in the said accident with your insured's vehicle no. GBE 2486 T.

Please be informed that the said vehicle can be inspected at the following venue:

KUM CHEW MOTOR WORKSHOP
160, SIN MING DRIVE #05-08
SIN MING AUTOCITY, SINGAPORE 575722.
TEL NO: 6453 6256/6456 3715
FAX NO: 6455 7754

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Your faithfully,



.....

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2017 15:23
Date Of Accident	25/10/2017 09:45
Exact Location Of Accident	WOODLAND SECTOR 1 WOODLAND SPECTRUM 1 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ8228B
Insured/Policyholder	
Name Of Registered Owner	HENG CHANG SIONG
NRIC No	S7642688J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93803969
Alternative Phone No	OTHERS-93803969
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER EX 1.6 AT LED TAIL LAMP

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number	
Cover Note Number	

Driver

Name of Driver	SIM LAI SENG
NRIC No	S0087996G
Date Of Birth	15/02/1954
Occupation	INDOOR
Date Of Driving Pass	30/03/2004
Driving Experience	13 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



On 25 Oct 2017 9.45am, we receive a call from Mr Yong Chee Tyan (Yiho Glass Pte Ltd) 9272 1038 informing me that the my vehicle SLQ8228B has been damage by Mr Yong's Vehicle which was driven by his employee - The lorry GBE2486T has a metal frame that fell on My car and scratch/knock into the driver door and right side of bonnet. My vehicle was parked in the lot and I did not see the accident but was told by Mr Yong when he describe the accident at the Location of the car at the parking lot at Woodlands Sector 1 Woodlands spectrum 1.

I would want to claim for damage and repair of the car at Cycle carriage as my car is new. And also the replacement vehicle during the period that my car is sent for repairs.

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
SIN MING AUTOCITY, SINGAPORE 575722.
Tel No. : 64536256/64563715 Fax No. : 64557754
E-Mail : kumchew1@singnet.com.sg
GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3, ANSON ROAD #16-00
SPRINGLEAF TOWER, SINGAPORE 079909.

Attention : Motor Claim Department
Contact : 63896111 Fax No. : 62221033

Estimate : ES004323

Date : 19/03/2018
Vehicle Num. : SLQ 8228 B
Make/Model : MIT LANCER EX-2017
Chassis/Eng# : JMYSRCY1AGU006749/4A92CP4101
Accident Date : 25/10/2017
Claim No. :
Reference : KC/TP8228/1802-05
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|----|--------|-----------------------------|
| 1. | 1 PC | LIST ITEMS : |
| 2. | 1 PC | FRT BUMPER |
| 3. | 12 PCS | FRT BUMPER RETAINER - RH |
| 4. | 1 PC | FRT BUMPER CLIPS |
| 5. | 1 PC | FRT HEADLAMP - RH |
| 6. | 1 PC | FRT FENDER - RH |
| 7. | 1 PC | FRT FENDER DUST COVER - RH |
| 8. | 1 PC | FRT FENDER DUST COVER CLIPS |
| | | SIDE MIRROR - RH |

List TotalS\$:
20.00% Discount S\$:

839.00	SUCK
13.00	
81.60	
671.00	
496.00	
107.00	SUCK
6.80	SUCK
573.00	
2,787.40	
557.48	
2,229.92	

LABOUR :

- TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.
- TO SPRAY & PAINT ON ACCIDENT PORTION.
- TO CHECK WIRING FUNCTIONS.
- TO ANTI-RUST AFFECTED AREAS.

Labour Total S\$:

480.00	400
850.00	600
150.00	30
180.00	NNX
1,660.00	

SingDollars : Three Thousand Eight Hundred Eighty-Nine & Cents Ninety-Two Only

Total S\$: 3,889.92

KUM CHEW MOTOR WORKSHOP

8 days

P/P

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 25 May 2018 4:15 PM
To: Kum Chew (kumchew1@singnet.com.sg)
Subject: SLQ 8228B-DOA: 25/10/2017 (CHINA TAIPING TP)
Attachments: IMG.pdf

Dear Sir,

WITHOUT PREJUDICE

Offer P/P \$1564.08 @ 4 working days.

Please confirmed and forward us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Feb 2018		08 Feb 2018 16:07 Edit Adj Rpt	S\$1,564.08 Edit Estimates	S\$1,564.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YIHO GLASS PTE. LTD., Co. Reg. No.: 201208969G		
Main Claimant:	HENG CHANG SIONG, ID: S7642688J		
Vehicle Reg. No.:	SLQ8228B	Date of Loss:	25/10/2017 09:00 - :59 [4 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM17D06209C02	Policy/Cover Note No.:	DMCVSN3078211700 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE2486T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kum Chew Motor Workshop (HQ) 12 Sin Ming Industrial Estate, #01-71, 575656 Sin Ming - Tel: 6456 3715		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 20/02/2018]		
Driver/Custodian (Insured):	YONG CHEE TYAN (40 / Male), NRIC: S7789443H, Tel: +6592721038		
Adj Asg. Remarks:	NO EST, ASSIGN TO LKK WITH SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLQ8228B (SNM17D06209C02)**
[GBE2486T]

TP

HENG CHANG SIONG

Oct 25 2017 9:00AM

[YIHO GLASS PTE. LTD.]

Kum Chew Motor Workshop

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/10/17 15:46	Accident Statement	 Load HTM	☒

Photos/Images

3 per page ▼ ☒

No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/10/17 15:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
2	25/10/17 15:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
3	25/10/17 15:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
4	25/10/17 15:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
5	25/10/17 15:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
6	25/10/17 15:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
7	25/10/17 15:46	Accident Photo [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/18 16:13	General View	 Load JPG	☒
2	14/02/18 16:13	General View	 Load JPG	☒
3	14/02/18 16:13	General View	 Load JPG	☒
4	14/02/18 16:13	General View	 Load JPG	☒
5	14/02/18 16:13	General View	 Load JPG	☒
6	14/02/18 16:13	General View	 Load JPG	☒
7	14/02/18 16:13	General View	 Load JPG	☒
8	14/02/18 16:13	General View	 Load JPG	☒
9	14/02/18 16:13	General View	 Load JPG	☒
10	14/02/18 16:13	General View	 Load JPG	☒
11	14/02/18 16:13	General View	 Load JPG	☒
12	14/02/18 16:13	General View	 Load JPG	☒
13	14/02/18 16:13	General View	 Load JPG	☒
14	14/02/18 16:13	General View	 Load JPG	☒
15	14/02/18 16:13	General View	 Load JPG	☒
16	14/02/18 16:13	General View	 Load JPG	☒
17	14/02/18 16:13	General View	 Load JPG	☒
18	14/02/18 16:13	General View	 Load JPG	☒
19	14/02/18 16:13	General View	 Load JPG	☒
20	14/02/18 16:13	General View	 Load JPG	☒
21	14/02/18 16:13	General View	 Load JPG	☒
22	14/02/18 16:13	General View	Load JPG	☒

Assessment Reports				
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
23	19/06/18 10:23	Reinspection Photo	 Load JPG	☒
24	19/06/18 10:23	Reinspection Photo	 Load JPG	☒
25	19/06/18 10:23	Reinspection Photo	 Load JPG	☒
26	19/06/18 10:23	Reinspection Photo	 Load JPG	☒
27	19/06/18 10:23	Reinspection Photo	 Load JPG	☒
28	19/06/18 10:23	Reinspection Photo	 Load JPG	☒
29	19/06/18 10:23	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/02/18 16:07	PRS	 Load PDF	
2	08/02/18 16:07	OI GIA REPORT	 Load PDF	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/10/17 15:44	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/10/17 15:46	Accident Statement	 Load HTM	
Photos/Images			3 per page	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/10/17 15:46	Accident Photo	 Load JPG	☒
2	25/10/17 15:46	Accident Photo	 Load JPG	☒
3	25/10/17 15:46	Accident Photo	 Load JPG	☒
4	25/10/17 15:46	Accident Photo	 Load JPG	☒
5	25/10/17 15:46	Accident Photo	 Load JPG	☒
6	25/10/17 15:46	Accident Photo	 Load JPG	☒
7	25/10/17 15:46	Accident Photo	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	25/10/17 15:44	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18002678/M1VD3S2
Date: 29/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3078211700
 Claimant Vehicle No: SLQ8228B Insured Vehicle No: GBE2486T
 Date of Loss: 25/10/2017 Nature of Claim: TP Claim No: SNM17D06209C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ8228B**
 Make & Model: MITSUBISHI LANCER EX, 1.6 Led Tail Lamp (A) Engine No: 4A92CP4101
 Reg. Date: 19/06/2017 (Man. Year: 2017) Chassis No: JMYSRCY1AGU006749
 Colour: Blue Odometer: 20977 km
 Engine Capacity: 1590 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,229.92	534.08	1,695.84	76.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,030.00	630.00	37.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,889.92	1,564.08	2,325.84	59.79
+ GST 7.00/7.00% (S\$)	272.29	109.49	162.80	59.79
Nett Amount (S\$)	4,162.21	1,673.57	2,488.64	59.79

INSPECTION

Date of Assignment: 08/02/2018
 Date Inspected: 13/02/2018 Inspected At: Kum Chew Motor Workshop
 160 Sin Ming Drive #05-08
 Singapore 575721
 Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jun 2018)

Parts: 143 MITSUBISHI LANCER EX 1.6 Led Tail Lamp (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLQ8228B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Serviceable	839.00 FL	*- FL
2	1		*FRT BUMPER RETAINER - RH	Necessary	13.00 FL	*13.00 FL
3	12		*FRT BUMPER CLIPS	Necessary	81.60 FL	*81.60 FL
4	1		*FRT HEADLAMP - RH	Serviceable	671.00 FL	*- FL
5	1		*FRT FENDER - RH	Repair	496.00 FL	*- FL
6	1		*FRT FENDER DUST COVER - RH	Serviceable	107.00 FL	*- FL
7	1		*FRT FENDER DUST COVER CLIPS	Serviceable	6.80 FL	*- FL
8	1		*SIDE MIRROR - RH	Cracked	573.00 FL	*573.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	2,787.40	667.60
- List Item Discount on L Items 20.00/20.00% (S\$)	557.48	133.52
Total Parts (S\$)	2,229.92	534.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.	New	480.00	400.00
2	TO SPRAY & PAINT ON ACCIDENT PORTION.	New	850.00	600.00
3	TO CHECK WIRING FUNCTIONS.	New	150.00	30.00
4	TO ANTI-RUST AFFECTED AREAS.	New	180.00	0.00
Gross Labour Cost (S\$)			1,660.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >