

22/02/2018

ASS. REC. BY:

REF: CS/ASM18002750/Ti yd32k

Special Instruction:

Surveyor:

Tawfikh.

ASSIGNMENT (Office)

From (Person):

Kitty Teo

of

ASM

Date/Time:

12/02/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SVJ 8928L

Insured:

at Workshop m/s

Mova Automotive

Tel:

62723892

of

Bik 1008, Bik Meruh Lane 3 # 01-04

Policy No:

Claim No:

S8M00811

Sum Insured:

Excess:

NIL

Make of Veh:

(Client's Record)

D.O.A 30/01/2018

CA (REV)

/ REP. / REV 24 HRS

14.02.2018 @ 12pm owner waiting

H.O.D. Endorsement:

Date/Time:

10.50am 12/2/18

Person Contacted:

Nifka

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimate

SVJ 8928L - NA / FCI 10018 228/s

D.O.A: 13/04/2018

12/2/18

Minor repair by SMART

15/2/18

Send preli revised by SMART claim

15/2/18

Informed Jacely c/a ex NIL by email

23/4/18

Final fig \$3090 confirmed by email (Ref 320, 139)

23/4/18


Taufik

ASM

Date 14/12/18

STV 8928L 2010 Jan.

Estimated Cost
① 22 HRS 175 TR RES 00 RES 1500 INVT
To inspect vehicle No **STV 8928L**
at location No **Mova Automotive**
Blk 1008, Blk Merah Lane 3 #01-04
Insured
Policy No
Damage
Sum Insured Excess **NIL**
Claims Record **12pm @ owner waiting**
Name of Van



Policy Condition
Remarks: The van had commenced its repair at the time of inspection.
Basis of Market Value **946K**
DAG Accident Report Consistent? Yes or No
DAG PP Seen Consistent? Yes or No
Est Repairs days Repair Yes or No
LHM Sum Yes or No

CA **REV** REP 24 HRS
Date Person Contacted **Jedyn**

① Toyota Mark X 2.5 2499
Silver
St Peering 2 90259
Eng No
GRX1306000920
Gen Data 0000 Fair Post Burnt
Steering Locked Jammed Leaked Burnt or
Brake Jammed Leaked Burnt or
Mod AP 0000 STD 4.0L
Tire Size 245/40 X 18
BS DUNLOP NOVA 00 FS 02A NO CHTSL PP SUM
TOYO YOKO
Front 6 Rear 6
L Ba 6 L Ba 6
DAG 14/2/18
Surveyed by **Mova BM.**
Des of Damages Frt Rear CS NS LO Roached Frt
Frt of 1/2
The L O Chassis frame Body Structure affected due to 1st

RECEIVED 24 APR 2018

Date Time File Passed
☐ Prel. Report
☐ Final Report

Days Of Repair 3
Resurvey No of Trk 1

24/4- typist

Add Fee:
☐ Sheet 1
☐ Sheet 2
☐ Sheet 3
☐ Sheet 4

Report Referral
LHM Sum **SMART claim 2090/2**

Sum Fee 150

150

Survey Department Check List (Case Handler)

Reference No. : CS/ASM 1800>750/Tivch

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp. Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des. of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

23/4/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18002750/T1vd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 12-02-2018



Code : ASM

1. Policy Particulars : OWN DAMAGE

Insured Veh.		Veh. Inspected	SJV 8928L
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00811	Excess (\$)	0.00
Assign From	SMARTCLAIM (KITTY TEO)	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/01/2018	Inspection Date	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A) THE MARKET VALUE IS S\$——— (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 15 February 2018 10:31 AM
To: SUR; 'Jacelyn'
Cc: 'Jia Yu'; Alan Chng; 'Billy'
Subject: SJV 8928L-DOA: 30/1/2018 (AXA OD)

Dear Jacelyn,

As instructed by our client AXA , please proceed to repair the insured vehicle **SJV 8928L (Excess NIL/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



IA SUBMITTED

Type

🔔 Question

Message

Dear Kitty, Please be informed that IA submitted, Repairer's Estimate (Gross) : S\$ 2,410.00 Revised Estimate Amount : S\$ 2,090.00 "Check" Items Amount : S\$ Total : S\$ 2,090.00 Market Value : S\$ 46,000.00 COE/PARF Rebate : S\$ 20,995.00 Nett Value : S\$ 25,005.00 Thanks,Veron Chen

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00811

Our ref: CS/ASM18002750/T1vd3

Date: 15/2/2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD


Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SJV 8928L

Repairer's Estimate (Gross)	: S\$	2,410.00
Revised Estimate Amount	: S\$	2,090.00
"Check" Items Amount	: S\$	
Total	: S\$	2,090.00
Market Value	: S\$	46,000.00
COE/PARF Rebate	: S\$	20,995.00
Nett Value	: S\$	25,005.00

Description of Damage:

The vehicle sustained damages at the
front o/s portion



Survey date and time: 14/2/2018 at 12.15PM

No of days: 3 days

We have authorise repair.

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

**SJV8928L**

Type

🔍 Question

Message

Hi Workshop has submitted their estimate, please authorise if damages consistent and within economical repair limit. Thanks.

[Reply](#)




LKK AUTO CONSULTANTS PTE LTD (OD) ▼

Service Request Details

Claim

S8M008II

Reference

None 

Loss Date

January 30, 2018

Request Date

February 9, 2018

Due Date

February 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated workshop survey

Actions

Next Step

Agree to perform service

[Decline Work](#)[Accept Work](#)

Vehicle Information

Incident Vehicle Registration #

SJV8928L

Make

TOYOTA

Service Address

Blk 1008, , , 159722

Primary Contact/Insured

CHENG YUEN KEONG

688A CHOA CHU KANG DRIVE, #08-342, 681688, Singapore

93863263

WENGFENG33@YAHOO.COM

Claim Handler

TEO Kitty

6568804602

kitty.teo@axa.com.sg

Additional Instructions

EXCESS NIL

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

TYPE



SENT

2/9/18 3:37 PM

FROM

TEO Kitty

SUBJECT

SJV8928L

BODY

Hi Please survey WP and get estimate. Thanks.



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0723Z

Vehicle Details

Vehicle No.: SJV8928L

Vehicle to be Exported: No

Intended De-registration Date: 15 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: MARK X 2.5 A

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 4GR0607001

Chassis No.: GRX1306000920

Maximum Power Output: 149.0 kW (199 bhp)

Open Market Value: \$31,889.00

Original Registration Date: 22 Jan 2010

First Registration Date: 22 Jan 2010

Transfer Count: 0

Actual ARF Paid: \$31,889.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Jan 2020

PARF Rebate Amount: \$17,538.00

Intended COE Rebate Details

COE Expiry Date: 21 Jan 2020

COE Category: E - Open Category

COE Period(Years):	10
QP Paid:	\$17,889.00
COE Rebate Amount:	\$3,457.00
Total Rebate Amount:	\$20,995.00

The information contained herein is correct as at 15 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 13:51
Date Of Accident	30/01/2018 11:00
Exact Location Of Accident	CHOA CHU KANG DR BLK 687 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV8928L
Insured/Policyholder	
Name Of Registered Owner	CHENG YUEN KEONG
NRIC No	S7680723Z
Email Address	WENGFENG33@YAHOO.COM
Mobile Phone No	(LOCAL) +65-93863263
Alternative Phone No	OFFICE-93863263

Vehicle Particulars

Manufacturer	TOYOTA
Model	MARK X-2.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA007070
Cover Note Number	

Driver

Name of Driver	CHENG YUEN KEONG
NRIC No	S7680723Z
Date Of Birth	04/10/1976
Occupation	INDOOR
Date Of Driving Pass	07/06/2001
Driving Experience	16 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93863263
Fax Number	
Contact Number	OFFICE-93863263
Email Address	WENGFENG33@YAHOO.COM

Address	BLK 688A CHOA CHU KANG DR #08-342
Postcode	681688
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NPC
Police Station Address	ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.


(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: _____
NRIC/EIN No.: _____

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policeholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 3



**SINGAPORE
POLICE FORCE**



T/20180130/2121

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 3

Report No. T/20180130/2121

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/01/2018 17:15		Vide Report No.:	Station Diary No.: 81
Informant's Particulars			
Name of Informant: CHENG YUEN KEONG		Address: APT BLK 688A CHOA CHU KANG DRIVE #08-342 SINGAPORE 681688	
ID Type / ID No.: NRIC NO / S7680723Z		Contact No.: Home/Office: Mobile: 93863263	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 41	Date of Birth: 04/10/1976	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: RENOVATION CONTRACTOR		Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 30/01/2018 11:00	Type of Location: Car Park
Location: CHOA CHU KANG DRIVE in mscp blk 687 choa chu kang drive				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No:	Type:	Make:	Model:	Color:	Condition:	No of Passenger:
SJV8928L	Car	TOYOTA	MARK X 2.5 A	Silver	Slightly Damaged	0

Details of Vehicle Insurance					
Vehicle No:	Insurance Company:	Insurance No:	Effective:	Expiry Date:	
SJV8928L	AXA INSURANCE SINGAPORE PTE LTD	GA007070	22/01/2018	21/01/2019	



**SINGAPORE
POLICE FORCE**



T/20180130/2121

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

2 of 3

Report No. T/20180130/2121

CONTINUATION OF REPORT

Brief Details.

On 30 January 2018 at about 0530hrs, I parked my car (SJV8928L) at Blk 687 Choa Chu Kang Drive MSCP deck 1B Lot 49.

On 30 January 2018 at about 1100hrs, I went back to drive out my car when I noticed the right front side of my car badly dented and scratched. I do not know who did it. In addition, I do not have an in-car camera installed in my car. There is CCTV at the ground level of the multi story carpark.



**SINGAPORE
POLICE FORCE**



T/20180130/2121

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

3 of 3


Report No. T/20180130/2121


CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 2 FIRAH RADHIAH BINTE ZULKIFLI	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 30/01/2018 17:15
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt LIM WOON TIONG Contact No.: 65476418	Classification Of Case:

Authentication Stamp


S8M00811
CK130772

« Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 TOYOTA MARK X 2.5 (SVJ8928L)

Date of Loss

January 30, 2018

Time of Loss

11.00

Loss Description

SVJ8928L (INSD) PARKED AND FOUND DAMAGED

Comment

Tanjun 97495749
14/2/18 @ 1215 pm
Revert Not Authorised
EX: NIL.Resurvey before paint.
3 days
Sur @ lkkauto.com
14/2/18

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

Target Date of Completion *

02/13/2018

Days of work completion *

4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





«

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC OUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			HEADLAMP RH			ut ✓	590		590	Reviewing	
	2	1			FRONT BUMPER			de ✓	720		720	Reviewing	
	3	1			FRONT BUMPER SIDE RETAINER RH			un ✓	35		35	Reviewing	
	4	10			FRONT BUMPER CLIPS			un ✓	2.5		25	Reviewing	
	5	1			FRONT FENDER RH - REPAIR			Rp	0		0	Reviewing	
	6	1			FRONT FENDER COWLING RH - REPAIR			R x	0		0	Reviewing	
	7	1			FRONT SUPPORT HEADLAMP PANEL RH - REPAIR			Rx	0		0	Reviewing	

Labour

Add

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO INSPECT FRONT LIGHTING MECHANISM	0	40 20'	0	Reviewing		
	2		TO REPAIR ON FRONT FENDER RH, HEADLAMP PANEL TO REMOVE & REPLACE DAMAGED ITEMS. REALIGN CONNECTION	0	500 300	0	Reviewing		
	3		TO SPRAY PAINT ON REPAIRED AREAS	0	0 400	500	Reviewing		

« Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio
Parts & Labour	Miscellaneous	Summary	

Claim Amount
\$2,410.00

CATEGORY	Labour
ESTIMATE	\$540.00
REVISED AMOUNT	\$540.00
CATEGORY	Spare Parts
ESTIMATE	\$1,370.00
REVISED AMOUNT	\$1,370.00
CATEGORY	Paint
ESTIMATE	\$500.00
REVISED AMOUNT	\$500.00

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 23 April 2018 9:05 AM
To: 'Jacelyn'; SUR
Cc: 'Jia Yu'; 'Alan Chng'; 'Billy'
Subject: RE: SJV 8928L-DOA: 30/1/2018 (AXA OD)

Dear Jacelyn,

Confirmed finalize \$2090/-

No of days: 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jacelyn [mailto:jacelyn@movas.com.sg]
Sent: Friday, 20 April 2018 5:18 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Jia Yu' <jiaYu@movas.com.sg>; 'Alan Chng' <tuckmeng@movas.com.sg>; 'Billy' <billy@movas.com.sg>
Subject: RE: SJV 8928L-DOA: 30/1/2018 (AXA OD)

Dear Veron,

Please find the attached email for your reference.

Kindly help to finalize.

Thank you, have a nice day.

Best Regards,

Jacelyn Ooi

Estimator

9686-9275

Email: jacelyn@movas.com.sg

Mova Automotive Pte Ltd

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 20 April 2018 4:25 PM
To: SUR; Jacelyn
Cc: Jia Yu; Alan Chng; Billy
Subject: RE: SJV 8928L-DOA: 30/1/2018 (AXA OD)

Dear Jacelyn,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 15 February 2018 10:31 AM

To: SUR <sur@lkkauto.com>; 'Jacelyn' <jacelyn@nova.com.sg>

Cc: 'Jia Yu' <jiaYu@nova.com.sg>; Alan Chng <tuckmeng@nova.com.sg>; 'Billy' <billy@nova.com.sg>

Subject: SJV 8928L-DOA: 30/1/2018 (AXA OD)

Dear Jacelyn,

As instructed by our client AXA , please proceed to repair the insured vehicle **SJV 8928L (Excess NIL/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

invalid ▾

Menu ←

88M00811
CK130772

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 TOYOTA MARK X 2.5 (SVJ8928L)

Date of Loss

January 30, 2018

Time of Loss

11.00

Loss Description

SVJ8928L (INSD) PARKED AND FOUND DAMAGED

Tanjik 97495749
14/2/18 @ 1215pm
Revert Not Authorised
EX: NIL.
Recovery before paint.
3 days
Sur @ (khandu.com)

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

Target Date of Completion *

02/13/2018



Days of work completion *

4

PART = \$ 1370-00
LAB = \$ 720-00
\$ 2090-00



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNT	PART PRICE(Net)	ACTION (PARTS)	REMOVE
<input type="checkbox"/>		1	1			HEADLAMP RH			ut ✓	590		590	Reviewing	
<input type="checkbox"/>		2	1			FRONT BUMPER			de ✓	720		720	Reviewing	
<input type="checkbox"/>		3	1			FRONT BUMPER SIDE RETAINER RH			ut ✓	35		35	Reviewing	
<input type="checkbox"/>		4	10			FRONT BUMPER CLIPS			ut ✓	25		25	Reviewing	
<input type="checkbox"/>		5	1			FRONT FENDER RH - REPAIR			Rp	0		0	Reviewing	
<input type="checkbox"/>		6	1			FRONT FENDER COWLING RH - REPAIR			x	0		0	Reviewing	
<input type="checkbox"/>		7	1			FRONT SUPPORT HEADLAMP PANEL RH - REPAIR			fx	0		0	Reviewing	

Labour

Add

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR PER	LABOUR REPAIR	PART	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		1		TO INSPECT FRONT LIGHTING MECHANISM	0	40 20	0	Reviewing		
<input type="checkbox"/>		2		TO REPAIR ON FRONT FENDER RH, HEADLAMP PANEL TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION	0	500 200	0	Reviewing		
<input type="checkbox"/>		3		TO SPRAY PAINT ON REPAIRED AREAS	0	0 200	500	Reviewing		

1370-00

720-00



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Claim Amount

\$2,410.00

CATEGORY

Labour

ESTIMATE

\$540.00

REVISED AMOUNT

\$540.00

CATEGORY

Spare Parts

ESTIMATE

\$1,370.00

REVISED AMOUNT

\$1,370.00

CATEGORY

Paint

ESTIMATE

\$500.00

REVISED AMOUNT

\$500.00



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: MOVA AUTOMOTIVE PTE LTD

BLK 1008 #01-04
BUKIT MERAH LANE 3
SINGAPORE 159722
SJV8928L
JACELYN

NO: DLI9200191
PAGE: 1
DATE: 28/02/2018
A/C CODE: LDMV315
TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	T81145-22B20	HFLAMP UNIT RH	DDS	1 590.00	590.00
2	T52119-22A40-A0	BUMPER FR	DB3AA	1 720.00	720.00
3	T52535-22100	RETAINER FRT BP SIDE RH	DUIAD13-2 ✓	1 35.00	35.00
4	T52161-16010	CLIP	DUIAD11-3 ✓	10 2.50	25.00
TOTAL QUANTITY:			13	TOTAL	SIN 1,370.00
				ADD GST @ 7%	95.90
				GRAND TOTAL	<u>SIN 1,465.90</u>

BLK 1001 #01-51 BUKIT MERAH

Reprint: 1 / MT / 27/03/2018 10:21:22 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

GOODS RECEIVED BY

