## COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE\*

VEHICLE NO: SHA 4071T

MAKE

MODEL : HYUNDAI i40

AlG-LKK DATE 9/2/2018 9:39 RIGHT TRONT 玉

Qty	Parts Description/ Labour	Type	Unit Price	_	Amount	4
	Front Door Outer Moulding (RH)			\$	63.70	
	Front Door Mirror (RH)			\$	980.50	
	SUB TOTAL			\$	1,044.20	1
						- 1
	LESS 20%		L 1-4-1 10	\$	208.84	-
	DISCOUNTED TOTAL			\$	835.36	4
	Front Door Comfort Logo (RH)			\$	75.00	1
						1
	Labour Charge				200	
	Panel Beating			\$	350.00	7
	Spray Painting Charge		410	8	100.00	1
	Wiring Charge		<i>F</i> ***	\$	50.00	-
				100		L.
	Tuff Kote			\$	50.00	
	TOTAL LABOUR			\$	850.00	1
	ESTIMATE TOTAL			\$	1,760.36	
	10 a los 16 KK					
	1(a/m /LK/s)  1/2/18 1335L  2/75					
			LKK Auto Consultants he	nce n	otify	+
	217		To resurvey before/after spray     To display damage.	ng: paintii	ng	
	PIP Part pl		Third party survey	rmatic	survey	
	Dec.		* Supplementar	-60		
			Acknowledged by Repairer	i surai	nce Company	
	This is an initial estimate based on a visual inspection of the		Signature:		V/-3-	+



member of COMFORTDELGRO

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline +65 6383 6280 Facsimile +65 6280 9755

Service Centres

205 Braddell Road Singapore 579701

45 Pandan Road Singapore 690286

7 Sungai Kadut Way Singapore 728791

24 Senoko Loop Singapore 758156





JOB REQUISI	TION FOR BREAKDOWN / TO	WING SERVICE
Job Requisition		
1. Date: OP J / P Time Received: ( 2. New SPARK Kakis Name of Customer: Cow Contact No.: 81339665  Vehicle No.: SHA LOTIT Make/Model/Colour: (Co / Rue)	5. Nature of Service:  Jumpstart  Recovery	Flat Bed Crane-up  6. Parts Replaced/Remarks:
Email :	Change Tyre / Ba	attery
7. Location: Che Hard Ave,  9. Preferred Workshop:  Braddell Loyang  Sin Ming Sungei Kadut  Senoko Komoco (UBI / Leng Ke	Pandan Ubi Cycle & Carriage (PD)	8. Vehicle Tow - In Workshop:  Smoky Exhaust Wheel Jammed Overheating Steering Faulty Brake Faulty Alternator Faulty Starting Problem Loss Power Accident Engine Stalled Return Taxi
10. Odometer Reading :	11. Radio / CD OK OK Not t	
Job Attended		Northean III
12. Tow Truck / Recovery Van : VRS VRS Van : VRS VRS Vehicle No. : Vehicle No. : VRS Vehicle No. : Vehicle No. : Vehicle No. : VRS Vehicle No. : VRS Vehicle No. : VRS VRS Vehicle No. : VRS VRS Vehicle No. : VRS	GA GAO TZ YISHUN TOWING  TOWING  TOWING  TOWING	#: Cracked /: Scatched O: Missing  Signature of Customer
Cash Invoice Details (if applicable)		
13. Cash Invoice No. :		
Customer Acknowledgement		
<ul> <li>a. I have been advised to remove all valuable items in my cash cards, spectacles, pen, etc.</li> <li>b. I understand that any items left behind are at my own</li> <li>c. Surcharge: Towing fee will be levied if the customer decomposition.</li> </ul>	risk and SPARK Car Care™ will not be held	
Date	Time	Signature of Customer
14. WORKSHOP		
Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard
		CUSTOMER'S COP