

12/03/2002

ASS REC BY:

REF:

CS/SMD/PD 7778/100307

Surveyor: Wilson

ASSIGNMENT (Office)

From (Person): Grade 700

of

SMD

Date/Time:

12/2/02 @ 11:44 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 8596 U

Insured:

SK x 1948 C

at Workshop m/s

Allswell Motor

Tel:

9147 8545

of

25. Def tune 9

Policy No:

Claim No:

CMTD1800668 / NSW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/02/2008

CA / REV / REP. / REV 24 HRS / wp

H.O.D. Endorsement:

Date/Time:

12:37 pm @ 12/2/02

Person Contacted:

Ben

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLK 8596U - NA / INC 18 00 2380 / h4
	SK x 1948C - X

D O A: 6/02/2008


# ASSIGNMENT

01/7/18

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OO/TP/NYS/TP/RES/OD/RES/EVA/INV/IN/\_\_\_\_\_  
 To inspect Vehicle No. SLK 85964  
 at Workshop no. Alhwell  
 at No. 25, Delta Lane 9  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The Veh had commenced its repair at the time of inspection.



Sal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 7 days Res.: Yes or No  
 Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No. SLK 85964 Yr Reg: \_\_\_\_\_  
 Type: LL Car / LL Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Mercedes CC 1797  
 Colour: Dark Grey AC Insured / Std / NI / NA  
 Sp. Reading: 83054 T. Radio Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C/Nr: ZVW 50-6069350  
 Gen Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brakes: In order / Jammed / Leaked / Burnt or  
 Mod: Hil / S/Rim / STD A/Rim or  
 Tyre Size F: 195 / 65 R15  
 R: 195 / 65 R15  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRT / SUM /  
 TOYO / YOKO or FIRENZA  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Eal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Sal. 4 mm  
 D.O.A. 9/2/2018 D.O.I. 12/9/2018  
 Survey held at: Alhwell  
 Des. of Damages: FR / Rear / O/S / N/S / U/C / Roof top or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/2/2018 No Incident Report

9/4/2018 Finalized work at shop @ #815 / 2 Days (Ref \$541.10, 40%) (Part By Part)

RECEIVED 10 APR 2018

Date Time PM Person: \_\_\_\_\_  
☐ : Prel. Report  
☐ : Final Report  
 Date Time PM Return: \_\_\_\_\_

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transporter

Photo

Drawn

Add Fee: ☐ Site Insp. \$5  
☐ Interview \$5  
☐ Techn. Insp. \$5  
☐ Weighing \$5

Report Format:

Lump Sum / I.B.I. \$

7P

815

290

290

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Monday, 12 February 2018 11:44 AM  
**To:** admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** OOI, Ben; Edmund Ng; Mark Mark; account5 leasing; Ngo, Sau Wei Shawn; Henry, Irene James  
**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Our Reference: CMTD1800668/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for SLK8596U.

Please be informed that Shawn Ngo the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** OOI, Ben [mailto:ben@allswellmotor.com.sg]

**Sent:** Monday, February 12, 2018 11:20 AM

**To:** Teo, Grace

**Cc:** Edmund Ng; Mark Mark; account5 leasing; Ngo, Sau Wei Shawn; Henry, Irene James

**Subject:** Re: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Dear Grace...

Thank you for your reply..

Please get **LKK to be SJE** and survey as soon as possible...

Thanks in advance...

Truly

OOI, Ben

Allswell Motor Traders  
25, Defu Lane 9  
Singapore 539266  
Office: +65 6679 1146  
Mobile: +65 9147 8545  
Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

On Mon, Feb 12, 2018 at 9:48 AM, Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)> wrote:

Our Reference : CMTD1800668/NSW

Your Reference: SLK8596U

**Without Prejudice**

Date: 12<sup>th</sup> February 2018

**Attention:**

**M/S ALLSWELL MOTOR TRADERS**

Dear Ben,

**ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018**

We refer to your Notice of Accident dated 10/02/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** OOI, Ben [<mailto:ben@allswellmotor.com.sg>]

**Sent:** Saturday, February 10, 2018 11:20 AM

**To:** Claims - Motor Survey

**Cc:** Edmund Ng; Mark Mark; account5 leasing

**Subject:** Fwd: SLK8596U Accident - 3rd party claim against Sompo Insurance insured SKX1948C on 09.02.2018

Dear motor survey of Sompo Insurance

See attached correspondence..

Thanks

Truly

OOI, Ben

Allswell Motor Traders

[25, Defu Lane 9](#)

[Singapore 539266](#)

[Office: +65 6679 1146](#)

[Mobile: +65 9147 8545](#)

Email: [Ben@allswellmotor.com.sg](mailto:Ben@allswellmotor.com.sg)

----- Forwarded message -----

From: **OOI, Ben** <[ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)>

Date: Sat, Feb 10, 2018 at 11:10 AM

Subject: SLK8596U Accident - 3rd party claim against Sompo Insurance insured SKX1948C on 09.02.2018

To: "Choo, Thelma" <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>, "Henry, Irene James" <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>, "Ngo, Sau Wei Shawn" <[shawn.ngo@sompo.com.sg](mailto:shawn.ngo@sompo.com.sg)>

Cc: Edmund Ng <[edmund@allswellmotor.com.sg](mailto:edmund@allswellmotor.com.sg)>, Mark Mark <[mark@allswellmotor.com.sg](mailto:mark@allswellmotor.com.sg)>, account5 leasing <[account5@allswellmotor.com.sg](mailto:account5@allswellmotor.com.sg)>

Dear Sompo ( motor claims department )

We are the owner of the vehicle **SLK8596U** and your insured vehicle **SKX1948C** came in contact with our vehicle at the material time.

Before we proceed to repair our damaged vehicle, please us know within 2 working days till **13.02.2018** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you, we will proceed repair without any more reference to you.

Truly

**OOI, Ben**

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: +65 6679 1146

Mobile: +65 9147 8545

Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 5 April 2018 3:45 PM  
**To:** 'Ngo, Sau Wei Shawn'; SUR  
**Cc:** 'Henry, Irene James'; 'Teo, Grace'; assignments  
**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018  
**Attachments:** front right photo.pdf

Dear Shawn,

Sorry for delay in reply, as we are checking with the M/s: Allswell Motor to gather facts.

The damages sustained to SLK 8596U on 6<sup>th</sup> February 2018 was on front right portion. (see attached) whereas the damages on 9<sup>th</sup> February 2018 was on rear portion.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Thursday, 15 March 2018 11:36 AM

**To:** 'Ngo, Sau Wei Shawn' <[Shawn.Ngo@sompo.com.sg](mailto:Shawn.Ngo@sompo.com.sg)>; Wilson (LKKAuto) <[wilson@lkkauto.com](mailto:wilson@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Cc:** 'Henry, Irene James' <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; 'Teo, Grace' <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Dear Shawn,

Thank you for your email.

Dear Wilson / Shiau Chan,

**FYNA. Our Ref: CS/SMO18002778/Wqd3**

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ngo, Sau Wei Shawn [<mailto:Shawn.Ngo@sompo.com.sg>]

**Sent:** Thursday, 15 March, 2018 10:50 AM

**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>; Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)>

**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018



Hi,

Reference to our assignment to you on 12.02.2018.

Please be informed that the third party vehicle bearing registration number, SLK8596U had involved in another accident on 06.02.2018 which was 3 days prior to this accident. Hence please gather the facts for the accident on 06.02.2018 from Allswell motor to determine the damages sustained from that accident before finalizing the accident for this accident.

Thanks.

Best Regards,

**Shawn Ngo**

Claims Division

D: 6329 5202 | T: 6461 6555 | F: 6221 3147

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Teo, Grace

**Sent:** Monday, February 12, 2018 11:44 AM

**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** OOI, Ben; Edmund Ng; Mark Mark; account5 leasing; Ngo, Sau Wei Shawn; Henry, Irene James

**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Our Reference: CMTD1800668/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for SLK8596U.

Please be informed that Shawn Ngo the handler of this case.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** OOI, Ben [<mailto:ben@allswellmotor.com.sg>]

**Sent:** Monday, February 12, 2018 11:20 AM

**To:** Teo, Grace

**Cc:** Edmund Ng; Mark Mark; account5 leasing; Ngo, Sau Wei Shawn; Henry, Irene James

**Subject:** Re: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Dear Grace...

Thank you for your reply..

Please get **LKK to be SJE** and survey as soon as possible...

Thanks in advance...

Truly

OOI, Ben

Allswell Motor Traders  
25, Defu Lane 9  
Singapore 539266  
Office: +65 6679 1146  
Mobile: +65 9147 8545  
Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

On Mon, Feb 12, 2018 at 9:48 AM, Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)> wrote:

Our Reference : CMTD1800668/NSW

Your Reference: SLK8596U

**Without Prejudice**

Date: 12<sup>th</sup> February 2018

**Attention:**

**M/S ALLSWELL MOTOR TRADERS**

Dear Ben,

**ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018**

We refer to your Notice of Accident dated 10/02/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** OOI, Ben [<mailto:ben@allswellmotor.com.sg>]

**Sent:** Saturday, February 10, 2018 11:20 AM

**To:** Claims - Motor Survey

**Cc:** Edmund Ng; Mark Mark; account5 leasing

**Subject:** Fwd: SLK8596U Accident - 3rd party claim against Sompo Insurance insured SKX1948C on 09.02.2018

Dear motor survey of Sompo Insurance

See attached correspondence..

Thanks

Truly

OOI, Ben

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: +65 6679 1146

Mobile: +65 9147 8545

Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

----- Forwarded message -----

From: **OOI, Ben** <[ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)>

Date: Sat, Feb 10, 2018 at 11:10 AM

Subject: SLK8596U Accident - 3rd party claim against Sompo Insurance insured SKX1948C on 09.02.2018

To: "Choo, Thelma" <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>, "Henry, Irene James" <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>, "Ngo, Sau Wei Shawn" <[shawn.ngo@sompo.com.sg](mailto:shawn.ngo@sompo.com.sg)>

Cc: Edmund Ng <[edmund@allswellmotor.com.sg](mailto:edmund@allswellmotor.com.sg)>, Mark Mark <[mark@allswellmotor.com.sg](mailto:mark@allswellmotor.com.sg)>, account5 leasing <[account5@allswellmotor.com.sg](mailto:account5@allswellmotor.com.sg)>

Dear Sompo ( motor claims department )

We are the owner of the vehicle **SLK8596U** and your insured vehicle **SKX1948C** came in contact with our vehicle at the material time.

Before we proceed to repair our damaged vehicle, please us know within 2 working days till **13.02.2018** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you, we will proceed repair without any more reference to you.

Truly

OOI, Ben

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: +65 6679 1146

Mobile: +65 9147 8545

Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

## Wilson (LKKAuto)

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 15 March, 2018 11:36 AM  
**To:** 'Ngo, Sau Wei Shawn'; Wilson (LKKAuto); SUR  
**Cc:** 'Henry, Irene James'; 'Teo, Grace'; assignments  
**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Dear Shawn,

Thank you for your email.

Dear Wilson / Shiao Chan,

FYNA. Our Ref: CS/SMO18002778/Wqd3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Ngo, Sau Wei Shawn [mailto:Shawn.Ngo@sompo.com.sg]

**Sent:** Thursday, 15 March, 2018 10:50 AM

**To:** admin-d@lkkauto.com; assignments@lkkauto.com

**Cc:** Henry, Irene James <irene.henry@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Hi,

Reference to our assignment to you on 12.02.2018.

Please be informed that the third party vehicle bearing registration number, SLK8596U had involved in another accident on 06.02.2018 which was 3 days prior to this accident. Hence please gather the facts for the accident on 06.02.2018 from Allswell motor to determine the damages sustained from that accident before finalizing the accident for this accident.

Thanks.

Best Regards,

Shawn Ngo

Claims Division

D: 6329 5202 | T: 6461 6555 | F: 6221 3147

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom

With reference to the accident which SLK 8596U was involved on 6/2/2018 resulted damaged on its Right Front Portion.

Hence, the above accident damaged is not related to the accident which SLK 8596U was involved on 9/2/2018 resulted damaged on its rear portion.

Sorry for delay in reply, as we are checking with the Allswell motor to gather facts.

The damages sustained to SLK 8596U on 6th Feb 2018 was on right front

disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Teo, Grace  
**Sent:** Monday, February 12, 2018 11:44 AM  
**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Cc:** OOI, Ben; Edmund Ng; Mark Mark; account5 leasing; Ngo, Sau Wei Shawn; Henry, Irene James  
**Subject:** RE: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Our Reference: CMTD1800668/NSW

Dear LKK AUTO,

Please make arrangement to conduct the survey for SLK8596U.

Please be informed that Shawn Ngo the handler of this case.

Best Regards  
**Grace Teo**  
Claims Division  
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** OOI, Ben [<mailto:ben@allswellmotor.com.sg>]  
**Sent:** Monday, February 12, 2018 11:20 AM  
**To:** Teo, Grace  
**Cc:** Edmund Ng; Mark Mark; account5 leasing; Ngo, Sau Wei Shawn; Henry, Irene James  
**Subject:** Re: CMTD1800668/NSW - ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018

Dear Grace...

Thank you for your reply..

Please get **LKK to be SJE** and survey as soon as possible...

Thanks in advance...

Truly



OOI, Ben

Allswell Motor Traders  
25, Defu Lane 9  
Singapore 539266  
Office: +65 6679 1146  
Mobile: +65 9147 8545  
Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

On Mon, Feb 12, 2018 at 9:48 AM, Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)> wrote:

Our Reference : CMTD1800668/NSW

Your Reference: SLK8596U

**Without Prejudice**

Date: 12<sup>th</sup> February 2018

**Attention:**

**M/S ALLSWELL MOTOR TRADERS**

Dear Ben,

**ACCIDENT INVOLVING SKX1948C & SLK8596U ON 09.02.2018**

We refer to your Notice of Accident dated 10/02/2018.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** OOI, Ben [mailto:[ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)]

**Sent:** Saturday, February 10, 2018 11:20 AM

**To:** Claims - Motor Survey

**Cc:** Edmund Ng; Mark Mark; account5 leasing

**Subject:** Fwd: SLK8596U Accident - 3rd party claim against Sompo Insurance insured SKX1948C on 09.02.2018

Dear motor survey of Sompo Insurance

See attached correspondence..

Thanks

Truly

OOI, Ben

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: +65 6679 1146

Mobile: +65 9147 8545

Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

----- Forwarded message -----

From: **OOI, Ben** <[ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)>

Date: Sat, Feb 10, 2018 at 11:10 AM

Subject: SLK8596U Accident - 3rd party claim against Sompo Insurance insured SKX1948C on 09.02.2018

To: "Choo, Thelma" <[thelma.choo@sompo.com.sg](mailto:thelma.choo@sompo.com.sg)>, "Henry, Irene James" <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>, "Ngo, Sau Wei Shawn" <[shawn.ngo@sompo.com.sg](mailto:shawn.ngo@sompo.com.sg)>

Cc: Edmund Ng <[edmund@allswellmotor.com.sg](mailto:edmund@allswellmotor.com.sg)>, Mark Mark <[mark@allswellmotor.com.sg](mailto:mark@allswellmotor.com.sg)>, account5 leasing <[account5@allswellmotor.com.sg](mailto:account5@allswellmotor.com.sg)>

Dear Sompo ( motor claims department )

We are the owner of the vehicle **SLK8596U** and your insured vehicle **SKX1948C** came in contact with our vehicle at the material time.

Before we proceed to repair our damaged vehicle, please us know within 2 working days till **13.02.2018** whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you, we will proceed repair without any more reference to you.

Truly

**OOI, Ben**

Allswell Motor Traders

25, Defu Lane 9

Singapore 539266

Office: +65 6679 1146

Mobile: +65 9147 8545

Email: [ben@allswellmotor.com.sg](mailto:ben@allswellmotor.com.sg)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	10/02/2018 10:10
Date Of Accident	09/02/2018 13:25
Exact Location Of Accident	ALONG CASSIA LINK TOWARD GULLEMARD ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8596U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No	201432541Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64625405

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 S (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5087620250-01
Cover Note Number	

### Driver

Name of Driver	LEONG AH CHEOW
NRIC No	S6837725J
Date Of Birth	03/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	07/11/1988
Driving Experience	29 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90096823
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 316C ANCHORVALE LINK #05-203
Postcode	543316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 09/02/2018 , about 01:25pm , as i was driving along cassia link , i stopped near the junction between Gullemard Road and Cassia link ,due to red light.Suddenly,a subaru car hit the back of my car and make a impact.I went down from the car and witnessed on damage at the rear of my car.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX1948C
Vehicle Make/Model/Colour	SUBARU
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WONG CHEE KAN
NRIC/Passport Number	
Contact Number	96685424
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 9/2/2018


  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 9/2/2018

  
Reporting Centre Personnel's Signature

Name: Yanyee  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9/2/2018, about 1.25pm, as I was driving along Cassia Link, I stopped near the junction between Gullemard Road and Cassia Link, due to red light.

Suddenly, a Subaru car hit the back of my car and make a impact.

I went down from the car and witnessed an damage at the rear of my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 9/2/2018

Driver's Signature  
(If driver is not the policyholder)

Date & Time: 9/2/2018

Reporting Centre Personnel's Signature

Name: Yanyee


NRIC/FIN No.:



Accident Photo



Accident Photo




Accident Photo




Identification Card

TOYOTA MOTOR CORPORATION JAP.  
MODEL DAA-ZVW50-AHXEB  
ENGINE 2.7L-FXE  
FRAME NO. ZVW50-6069350 1797 mL  
COLOR TRIM  
1G3 FB20 A41  
WHEELS P610 -01A  
873

Accident Photo




Accident Photo



Accident Photo




Accident Photo





Accident Photo



## Wilson (LKKAUTO)

---

**From:** Wilson (LKKAUTO)  
**Sent:** Monday, 9 April, 2018 1:55 PM  
**To:** OOI, Ben  
**Subject:** SLK 8596U - FINALISATION

Dear ben,

Finalised the above at \$815 (Part By Part – Subject to Insurance Approval) / 2 Days Repair.

Rdgs.

Wilson Syrveyor  
LKK Auto Surveyor

MAMT18020204-01 / Allswell Motor Traders - HQ  
ENTRY DATE & TIME: 09/02/2018 16:11  
SUBMITTED BY: Chan Yan Yee

Your NCD will be affected due to late reporting  
Actual e-Filing Submission Date & Time: 09/02/2018 16:58

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2018 16:11
Date Of Accident	06/02/2018 09:25
Exact Location Of Accident	BOON TIONG ROAD TOWARDS HDB BLK 10B
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK8596U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ALLSWELL LEASING & LIMOUSINE PTE LTD
Co Reg No	201432541Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64625405

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 S (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5087620250-01
Cover Note Number	

Driver

Name of Driver	LEONG AH CHEOW
NRIC No	S6837725J
Date Of Birth	03/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	07/11/1988
Driving Experience	29 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90096823
Fax Number	
Contact Number	

Address	APT BLK 316C ANCHORVALE LINK #05-203
Postcode	543316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER & LEASEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

At about 09:25am on 06/02/2018. As i was driving into Boon Tiong Road HDB block 10B to fetch a lady as i was private car driver. I stopped at the left of boon tiong road because the vehicle no SJD8306B stopped on opposite lane and the car had cut into the left lane and blocking my way to advance. Suddenly, the driver moved the car and hit the front of my car and he had made damages to my car.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD8306B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ZHANG GUANG LIANG
NRIC/Passport Number	
Contact Number	86825188
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 7/2/2018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 7/2/2018


Reporting Centre Personnel's Signature

Name: Wan Yee

NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At about 9:25am on 6/2/2018, As I was driving into Boon Tiong Road HDB Block 10B to fetch a lady as I was private car driver.

I stopped at the left of Boon Tiong Road because the vehicle no. SJD 8306B stopped on opposite lane and the car had cut into the left lane and blocking my way to advance.

Suddenly, the driver moved the car and hit the front of my car. And he had made damages to my car.



Policyholder's Signature  
Date & Time: 7/2/2018

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 7/2/2018

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Photo



Accident Photo





Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo




Accident Photo






Accident Photo




Accident Photo





TOYOTA MOTOR CORPORATION JAPAN	
MODEL	DAA-ZVW50-AHXEB
ENGINE	2ZR-FXE 1797 mL
FRAME No.	ZVW50-6069350
COLOR	TRIM PLANT OPTION
	1G3 FB20 A41
TRANS.MILE	P610 -01A 873



# Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE  
6, Kallies Quay #11-00 Singapore 048580  
Tel (65) 6224 0020 Fax (65) 6224 0030  
Operating Hours : Monday to Friday, 09:00 - 17:00  
URL: 566888205 / 857 Bpp. No.: 84400817735

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : NAAMT 18020204-01 Vehicle Registration No: SLK85964  
Name (as shown in NRIC) : Chen Yun Yee NRIC/FIN/Passport No : 628643080  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
Address : 25 befu lane 9 Singapore (539286)  
Contact (Tel) : 6679 1146 Mobile No. : \_\_\_\_\_  
Email Address : account@allsweethmotor.com.sg  
Date of Accident : 6/2/2018 Time of Accident : 09:25 am  
Place of Accident : Boon Tiong Road Towards HDB BLK 108  
Insurance Company : NTUC Income

### (B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Type of accident: head to collision

Policyholder / Driver's Signature

Date: 9/2/2018



Reporting Centre Personnel's Signature

Name: Yanyee

NRIC/FIN No.:

Date:

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146      email:ben@allswellmotor.com.sg

(3rd party claim against Sampo Insured suk8596U )

### Estimate repair

Vehicle No. : SUK 8596 U Submitted by : BUN  
 Make & Model : Toyota Prius hybrid Year Manufacture : end 2016  
 Chassis No. : \_\_\_\_\_ Engine No. : \_\_\_\_\_  
 Date of survey : \_\_\_\_\_

[illegible]

**Note:** If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

1356.10

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile****SOMPO INSURANCE SINGAPORE PL**

Ref : CS/SMO18002778/Wqd3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 16-04-2018



Code : SMO

**1. Policy Particulars - THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SKX 1948C	<b>Veh. Inspected</b>	SLK 8596U
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD1800668/NSW	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	12/02/2018

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	TOYOTA PRIUS	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	ZVW506069350	<b>Colour</b>	DARK GREY
<b>Odometer</b>	83084	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	FIRENZA	4 mm
<b>L/H Front Tyre</b>	195/65 R15	FIRENZA	4 mm
<b>R/H Rear Tyre</b>	195/65 R15	FIRENZA	4 mm
<b>L/H Rear Tyre</b>	195/65 R15	FIRENZA	4 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

<b>Accident Date</b>	09/02/2018	<b>Inspection Date</b>	12/02/2018
<b>Survey held at</b>	25 DEFU LANE 9		
<b>Repairer</b>	ALLSWELL MOTOR TRADERS		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>2 Working Days</b>
-------------------------------------	-----------------------



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 8596U**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<b>REPLACEMENT OF PARTS</b>	WARPED / SCRATCHED		
	REAR BUMPER (TOP)		876.10	660.00
	LESS 25% DISCOUNT		-	-165.00
			876.10	495.00
	<b>LABOUR</b>			
	DISMANTLE & ASSEMBLY.		120.00	120.00
	RESPRAY AFFECTED PART REAR BUMPER (TOP).		360.00	200.00
			480.00	320.00
<b>GRAND TOTAL</b>			<b>1,356.10</b>	<b>815.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>815.00</b>
------------------------------------	--	--	---------------

Report Ref No. CS/SMO18002778/Wqd3e2

**WILSON TEO CHENG MING**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.