

22/03/2002

ASS. REC. BY:

REF: CS

CTI1800-2796 / Krd317

Special Instruction:

Surveyor:

Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Chung Boon Sun

of

CTI

Date/Time:

12/2/18 @ 3:33pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGL 3534 K

Insured:

at Workshop m/s

S &amp; H Motor

Tel:

6453 4730

of

160 Sin Ming Drive #07-02

Policy No:

DMPC SN 3050241700

Claim No:

SNM18 D00738C01/4

Sum Insured:

Excess:

\$ 1500-00

Make of Veh:

(Client's Record)

D.O.A.

11/02/2018

CA / (REV) /

REP. / REV 24 HRS

13/2/18

02

H.O.D. Endorsement:

Date/Time:

1:35pm @ 12/2/18

Person Contacted:

Cynthia

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

Interview Insured to obtain

more information on accident &amp; obtain email address as well

SGL 3534 K - X


14/2/18

Revert vehicle T/L by merimen

9/3/18 double check with Cynthia d.o.a. is 1/2/2018

ASSIGNMENT

Report No. SGL 3534K Page 09 08  
 Date 13/02/18  
 Estimated Cost  
 ( ) TP / WS / TP RES / CD RES / EVA / INV / MV  
 To inspect Vehicle No. SGL 3534K  
 at Workshop this S&H Motor  
 of 160 Sin Ming Drive #07-02  
 Insured  
 Policy No.  
 Claims No.  
 Sum Insured: \$1,500.00 Excess  
 Clients Record: Interview Insured to obtain more information on accident & obtain email address as well.  
 Make of Vehicle  
 Policy Condition  
 Remarks: The veh had commenced its repair at the time of inspection.  
 Ball or Market Value: \$37K  
 DAD Accident Report Consistent? : Yes or No  
 G.A. / PP. Seen Consistent? : Yes or No  
 Est. Repairs: days Res.: Yes or No  
 LTM Sum: \$ 3 Yr.: Yes or No  
 CA (REV) REP. / 24 HRS  
 Date 13/21 Person Contacted: Vehicle IN/OUT  
 Type of Car: Medium Bus/Van/Carry Van Prime No. of  
 Truck/Trailer no.  
 Make Kedws 15250 2500  
 Colour Black Insured: Std. N. V.  
 Self-Insuring — T-Party Insured: Std. N. V.  
 Eng. No.  
 Chassis No. JTHBK-2620021618  
 Gen. Cond. Good / Paint / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brakes: In order / Jammed / Leaked / Burnt or  
 Model: NISSAN / STD A/Ratio  
 Tyre Size: R. 13.5 225/45 R17  
 BS / DUN / EXNOVA / GY / PS / LIZA / MIO / HOTSU / PR / SUM  
 TOYO / YOKO  
 Front Rear  
 R.Bal. 7 L.Bal. 6  
 C.O.A. 1/2/18 D.O.A. 13/2/18  
 Survey noted: ✓  
 Des. of Damages: Front Rear / O/S / N/S / U/O / Roof/Top or  
Acc. O/S, O/S body & R/B N/S  
 The U.O. of Chassis's frame & Body Structure affected due to collision ✓



Date	Time	Action	Instruction
14/2		File pass to	Catherine

12/18 Submit Uneconomical total loss report  
 MV: \$37K, LTA: \$20,341.00, NV: \$16,659.00

RECEIVED 2018 file pass back to handler (ed. G. G.)

Date/Time File Pass to: 13/21 : Prell. Report ☐ : Final Report ☒  
 typist  
 Date/Time File Returned:  
 Add Fee: ☐ Site Insp. \$ 180  
☐ Mobile \$  
☐ Testing \$  
☐ Resurvey \$  
 Report Format: OD - Total loss  
 LTM Sum: \$  
 Survey Fee: 220  
 TOTAL: 220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18002796/Krd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-02-2018



Code : CTI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGL 3534K
Policy No.	DMPCSN3050241700	Coverage (\$)	0.00
Claim No.	SNM18D00738C01/4	Excess (\$)	1,500.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	12/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	01/02/2018	Inspection Date	
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Feb 2018 <a href="#">Sendback Est</a>	09 Feb 2018 15:47 <b>\$700.00</b>	12 Feb 2018 15:33 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

Insured:	LARRY TAN CHIN GUAN, ID: S6999002I, Tel: +6588699933, Email: NOEMAIL			
Vehicle Reg. No.:	SGL3534K	Date of Loss:	01/02/2018 03:00 - :59	
Claim Type:	OD / SNM18D00738C01/4	Policy/Cover Note No.:	DMPCSN3050241700 (Comprehensive)	
		Excess:	\$1,500.00	
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/02/2018]			
Driver/Custodian:	LARRY TAN CHIN GUAN (48 / Male), NRIC: S6999002I, Tel: +6588699933			
Adj Asg. Remarks:	Please survey vehicle & interview Insured to obtain more information on accident & obtain email address as well.			

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Chong Boon Sen	
<b>Date:</b> 14 Feb 2018	

**Preliminary Advice**

<b>Vehicle No</b>	: SGL3534K	<b>Accident Date</b>	: 01/02/2018
<b>Make</b>	: LEXUS IS	<b>Policy No.</b>	: DMPCSN3050241700
<b>Assignment Date</b>	: 12/02/2018	<b>Excess</b>	: S\$1,500.00
<b>Date of Inspection</b>	: 13/02/2018	<b>Est. Duration of Repair</b>	: 0.00
<b>Inspection At</b>	S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion, front n/s portion and o/s body. The undercarriage and body structure affected due to collision, and parts claimed are consistent to the accident.

<b>Repairer's Estimate (Gross)</b>	:S\$	<b>TOTAL LOSS</b>
<b>Revised Amount</b>	:S\$	<b>TOTAL LOSS</b>
<b>Check Items (Estimated)</b>	:S\$	0.00
<b>Total</b>	:S\$	0.00

<b>Lump Sum Repair</b>	:S\$
------------------------	------

**Total Loss Consideration**

<b>New for Old Value</b>	:S\$	
<b>Pre-Accident Value</b>	:S\$	37,000.00
<b>COE / PARF Rebate</b>	:S\$	20,341.00
<b>Salvage Value</b>	:S\$	
<b>Margin for Repair</b>	:S\$	16,659.00

<b>Brake System</b>	: Leaked
<b>Steering System</b>	: Jammed
<b>Tyre Condition (Front)</b>	: 7/7 MM
<b>Tyre Condition (Rear)</b>	: 6/6 MM

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments : Pending interview insured.

# Print Received Message

This mail is associated with :

**SGL3534K (SNM18D00738C01/4)**

OD

Feb 1 2018 3:00AM

[LARRY TAN CHIN GUAN]

S & H Motor Pte Ltd

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 02/03/2018 14:38 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$0.00) - SGL3534K - Claim Handler: Chong Boon Sen

Approved:0.00:PLEASE PROCEED TO FINALIZE REPORT & FORWARD BILL FOR SERVICES RENJDERED  
WHILE WE CREATE TENDER ON THE WRECK.

# Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9002I
<b>Vehicle Details</b>	
Vehicle No.:	SGL3534K
Vehicle to be Exported:	No
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	4GR0232074
Chassis No.:	JTHBK262002021618
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$36,637.00
Original Registration Date:	13 Sep 2006 <i>bought in 2017 - renew COE 3 yrs.</i>
First Registration Date:	13 Sep 2006
Transfer Count:	4
Actual ARF Paid:	\$40,301.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	12 Sep 2021
COE Category:	E - Open Category



<b>COE Period(Years):</b>	<b>5</b>
<b>PQP Paid:</b>	<b>\$28,418.00</b>
<b>COE Rebate Amount:</b>	<b>\$20,341.00</b>
<b>Total Rebate Amount:</b>	<b>\$20,341.00</b>

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Feb 2018

OK

## Enquire Transfer Fee

### Vehicle Details

Vehicle No. :	SGL3534K
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	TOYOTA
Vehicle Model :	LEXUS IS250 AUTO STD
Chassis No. :	JTHBK262002021618
Propellant :	Petrol
Engine No. :	4GR0232074
Engine Capacity :	2500 cc
Maximum Power Output :	153.0 kW ( 205 bhp)
Maximum Laden Weight :	2045 kg
Unladen Weight :	1625 kg
Year Of Manufacture :	2006
Original Registration Date :	13 Sep 2006
Lifespan Expiry Date :	-
COE Category :	E - Open Category
PQP Paid :	\$28,418.00
COE Expiry Date :	12 Sep 2021

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/02/2018 16:08
Date Of Accident	02/02/2018 03:30
Exact Location Of Accident	EXPRESSWAY (KL-MUAR) MALAYSIA
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL3534K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LARRY TAN CHIN GUAN
NRIC No	S6999002I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88699933
Alternative Phone No	Office-88699933

### Vehicle Particulars

Manufacturer	TOYOTA
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3050241700
Cover Note Number	

### Driver

Name of Driver	LARRY TAN CHIN GUAN
NRIC No	S6999002I
Date Of Birth	15/04/1969
Occupation	INDOOR
Date Of Driving Pass	27/07/2009

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

### ADDENDUM

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MSNH1819165 Vehicle Registration No: SGL 3534K  
Name (as shown in NRIC) : Larry Tan Chien Guan NRIC/FIN/Passport No : S6999002I  
(\*Vehicle Driver, Vehicle Owner)(\*) Please delete as appropriate  
Address : \_\_\_\_\_ Singapore( )  
Contact (Tel) : \_\_\_\_\_ Mobile No. : 886 99933  
Email Address : \_\_\_\_\_  
Date of Accident : 2/2/2018 Time of Accident : 0330hrs  
Place of Accident : Expressway (KL-Muar) Malaysia  
Insurance Company: Ching

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

The date of accident date should be  
2/2/2018.

Larry  
Policyholder / Driver's Signature  
Date: 19/3/18

[Signature]  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:  
Date: 19/3/18

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/02/2018 16:08
Date Of Accident	01/02/2018 03:30
Exact Location Of Accident	EXPRESSWAY (KL-MUAR) MALAYSIA
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL3534K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LARRY TAN CHIN GUAN
NRIC No	S6999002I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88699933
Alternative Phone No	OFFICE-88699933

### Vehicle Particulars

Manufacturer	TOYOTA
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3050241700
Cover Note Number	

### Driver

Name of Driver	LARRY TAN CHIN GUAN
NRIC No	S6999002I
Date Of Birth	15/04/1969
Occupation	INDOOR
Date Of Driving Pass	27/07/2009
Driving Experience	8 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88699933
Fax Number	
Contact Number	OFFICE-88699933
Email Address	NOEMAIL

Slk 397  
Yishu Ave 6.

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LARRY TAN CHIN GUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGL3534K

Were seat belts worn?

Was this injured conveyed to hospital by  
ambulance? NO

Address

Postcode

### SKETCH PLAN

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35  
36  
37  
38  
39  
40  
41  
42  
43  
44  
45  
46  
47  
48  
49  
50  
51  
52  
53  
54  
55  
56  
57  
58  
59  
60  
61  
62  
63  
64  
65  
66  
67  
68  
69  
70  
71  
72  
73  
74  
75  
76  
77  
78  
79  
80  
81  
82  
83  
84  
85  
86  
87  
88  
89  
90  
91  
92  
93  
94  
95  
96  
97  
98  
99  
100  
101  
102  
103  
104  
105  
106  
107  
108  
109  
110  
111  
112  
113  
114  
115  
116  
117  
118  
119  
120  
121  
122  
123  
124  
125  
126  
127  
128  
129  
130  
131  
132  
133  
134  
135  
136  
137  
138  
139  
140  
141  
142  
143  
144  
145  
146  
147  
148  
149  
150  
151  
152  
153  
154  
155  
156  
157  
158  
159  
160  
161  
162  
163  
164  
165  
166  
167  
168  
169  
170  
171  
172  
173  
174  
175  
176  
177  
178  
179  
180  
181  
182  
183  
184  
185  
186  
187  
188  
189  
190  
191  
192  
193  
194  
195  
196  
197  
198  
199  
200  
201  
202  
203  
204  
205  
206  
207  
208  
209  
210  
211  
212  
213  
214  
215  
216  
217  
218  
219  
220  
221  
222  
223  
224  
225  
226  
227  
228  
229  
230  
231  
232  
233  
234  
235  
236  
237  
238  
239  
240  
241  
242  
243  
244  
245  
246  
247  
248  
249  
250  
251  
252  
253  
254  
255  
256  
257  
258  
259  
260  
261  
262  
263  
264  
265  
266  
267  
268  
269  
270  
271  
272  
273  
274  
275  
276  
277  
278  
279  
280  
281  
282  
283  
284  
285  
286  
287  
288  
289  
290  
291  
292  
293  
294  
295  
296  
297  
298  
299  
300  
301  
302  
303  
304  
305  
306  
307  
308  
309  
310  
311  
312  
313  
314  
315  
316  
317  
318  
319  
320  
321  
322  
323  
324  
325  
326  
327  
328  
329  
330  
331  
332  
333  
334  
335  
336  
337  
338  
339  
340  
341  
342  
343  
344  
345  
346  
347  
348  
349  
350  
351  
352  
353  
354  
355  
356  
357  
358  
359  
360  
361  
362  
363  
364  
365  
366  
367  
368  
369  
370  
371  
372  
373  
374  
375  
376  
377  
378  
379  
380  
381  
382  
383  
384  
385  
386  
387  
388  
389  
390  
391  
392  
393  
394  
395  
396  
397  
398  
399  
400  
401  
402  
403  
404  
405  
406  
407  
408  
409  
410  
411  
412  
413  
414  
415  
416  
417  
418  
419  
420  
421  
422  
423  
424  
425  
426  
427  
428  
429  
430  
431  
432  
433  
434  
435  
436  
437  
438  
439  
440  
441  
442  
443  
444  
445  
446  
447  
448  
449  
450  
451  
452  
453  
454  
455  
456  
457  
458  
459  
460  
461  
462  
463  
464  
465  
466  
467  
468  
469  
470  
471  
472  
473  
474  
475  
476  
477  
478  
479  
480  
481  
482  
483  
484  
485  
486  
487  
488  
489  
490  
491  
492  
493  
494  
495  
496  
497  
498  
499  
500  
501  
502  
503  
504  
505  
506  
507  
508  
509  
510  
511  
512  
513  
514  
515  
516  
517  
518  
519  
520  
521  
522  
523  
524  
525  
526  
527  
528  
529  
530  
531  
532  
533  
534  
535  
536  
537  
538  
539  
540  
541  
542  
543  
544  
545  
546  
547  
548  
549  
550  
551  
552  
553  
554  
555  
556  
557  
558  
559  
560  
561  
562  
563  
564  
565  
566  
567  
568  
569  
570  
571  
572  
573  
574  
575  
576  
577  
578  
579  
580  
581  
582  
583  
584  
585  
586  
587  
588  
589  
590  
591  
592  
593  
594  
595  
596  
597  
598  
599  
600  
601  
602  
603  
604  
605  
606  
607  
608  
609  
610  
611  
612  
613  
614  
615  
616  
617  
618  
619  
620  
621  
622  
623  
624  
625  
626  
627  
628  
629  
630  
631  
632  
633  
634  
635  
636  
637  
638  
639  
640  
641  
642  
643  
644  
645  
646  
647  
648  
649  
650  
651  
652  
653  
654  
655  
656  
657  
658  
659  
660  
661  
662  
663  
664  
665  
666  
667  
668  
669  
670  
671  
672  
673  
674  
675  
676  
677  
678  
679  
680  
681  
682  
683  
684  
685  
686  
687  
688  
689  
690  
691  
692  
693  
694  
695  
696  
697  
698  
699  
700  
701  
702  
703  
704  
705  
706  
707  
708  
709  
710  
711  
712  
713  
714  
715  
716  
717  
718  
719  
720  
721  
722  
723  
724  
725  
726  
727  
728  
729  
730  
731  
732  
733  
734  
735  
736  
737  
738  
739  
740  
741  
742  
743  
744  
745  
746  
747  
748  
749  
750  
751  
752  
753  
754  
755  
756  
757  
758  
759  
760  
761  
762  
763  
764  
765  
766  
767  
768  
769  
770  
771  
772  
773  
774  
775  
776  
777  
778  
779  
780  
781  
782  
783  
784  
785  
786  
787  
788  
789  
790  
791  
792  
793  
794  
795  
796  
797  
798  
799  
800  
801  
802  
803  
804  
805  
806  
807  
808  
809  
810  
811  
812  
813  
814  
815  
816  
817  
818  
819  
820  
821  
822  
823  
824  
825  
826  
827  
828  
829  
830  
831  
832  
833  
834  
835  
836  
837  
838  
839  
840  
84

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer attached police report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



E/20180207/2052

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20180207/2052

I realised that there was another vehicle registration number: ABP9963 had collided to my vehicle. I do have inbuilt video captured the occurrences and I remembered that I placed in my vehicle as my vehicle need to tow back to Singapore.

Malaysian Police officers came to scene. At that point of time, I unable to speak well and I couldn't understand their language. I tried to search my wallet for my identification and my driving license however I was surprised that both of my cards were placed in my passport which kept by them without my permission. Ambulance came to scene however I refused to convey as I couldn't understand their language barrier.

My family came to scene and brought me back to SGH. I wished to state when I wished to report to my insurance company, I discovered that my inbuilt video which was placed in my vehicle went missing. Besides that, my mobile phone missing too.

I wished to state that there was a passer-by came to us and told us that the driver was at fault. He tried to control the vehicle however it was not working.

I am lodging this report for insurance claimed.

Subject Involved	
Victim	
Person Name	LARRY TAN CHIN GUAN (Informant)

Signature Of Officer Recording The Report:


E / Staff Sgt MOHAMAD FARID BIN JAMAL

Signature Of Informant:

Signature Of Interpreter:  
Not applicableDate/Time:  
07/02/2018 13:40Officer In-Charge Of Case:  
E / Tanglin Police Divisional Investigation Branch /  
Insp PANG YIN CHENG  
Contact No.: 63910000

Classification Of Case:

Authentication Stamp







INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM		
Claim Type:	OD (Own Damage)	Ref. No:
Policy No:	DMPCSN3050241700	Date of Loss: 01/02/2010
Vehicle Reg. No.:	SGL3534K	Driveable?
Driver Age/Info:	48 / MALE	Party At Fault: OWN
TP Injury Involved?	YES	Third Party Involved? YES
Insured/Claimant:	LARRY TAN CHIN GUAN	Contact No: +6588699933
Driver:	LARRY TAN CHIN GUAN	
Make/Model:	LEXUS IS, 250 (A)	Vehicle Reg. Date: 13/09/2006
Vehicle Colour:	Mica Black	
Engine No:	4GR0232074	Chassis No: JTHBK262002021618
Odometer:	0 KM	
Paint Type:		
Total Loss?	YES	
Est. Duration of Repair (day)	0	
Description of Accident/Loss	REFER ATTACHED POLICE REPORT.	
Present Location:	S & H MOTOR PTE LTD (SIN MING)	

COST OF CLAIMS	L&H Auto Consultants hereby certify the accuracy of the following:	Amount
Parts	• To provide a written estimate	0.00
Miscellaneous Items	• To display damaged parts during resurvey	700.00
Labour	• To provide a written estimate	0.00
Paintwork Labour	• To provide a written estimate	0.00
Towing	• No illegal modifications allowed	0.00
	• To provide a written estimate	0.00
	<b>Gross Total (\$\$)</b>	<b>700.00</b>
	<b>+ GST 7.00% (\$\$)</b>	<b>49.00</b>
	<b>Nett Amount (\$\$)</b>	<b>749.00</b>

This claim is handled by: LUM WEE KEAT

## Estimates on Miscellaneous Items


No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	Towing (from Malaysia)	700.00
<b>Sub Total (S\$)</b>			<b>700.00</b>

## Estimates on Labour

There are no labour items selected.

**S & H Motor Pte Ltd/SGL3534K/09/02/2018 15:47**. Not valid without Reference section.  
Generated using **Merimen e-Claims IEAS**

**< END OF ESTIMATES >**



Auto  
Consultants  
Pte Ltd

## STATEMENT

### PARTICULARS

Name : LARRY TAN CHIN GUAN  
NRIC / Passport No. : S6999002 I  
Address : BLK 397 YISHUN AVE 6 #12-1162  
S(760397)  
Telephone : (R) - (O) -  
(HP) 88699933  
Sex / Age : M / 48  
Occupation / Name of Company : HAWKER ASSISTANT / STALL AT ALEXANDRA VILLAGE  
Nationality : (FOREIGN) (SINGAPORE)

Recorded By : MUHAMMAD NAZIL Date : 20/02/18 Time : 1500  
Place Recorded : AS ABOVE  
Language Spoken : ENGLISH Interpreted By : N/A

### FACTS OF CASE:

I am the owner and driver of the vehicle bearing registration number SEL 3534 K involved in an accident on 2/2/18 at 0330 hours at the North-South Highway (Southbound) from Kuala Lumpur heading to Singapore.

I was alone. I went to Kuala Lumpur (KL) on 31/01/18 at 1100 hours to visit some friends. I left KL at about 0000 hours on 02/02/18 and was en route to Singapore via the North-South Highway. I was nearing the Muar Exit. I was travelling at the 1st lane at 110 kmph. The traffic was light, weather was clear and the road surface was dry.


I remember that I had overtaken a Malaysian-registered lorry on the 2nd lane. Suddenly, my car had flipped and rolled over many times before coming to a stop. The car was overturned at the final rest position. All my airbags had deployed and all 6 windows had shattered. While the car was overturning I remember the lorry was pushing my car forwards. By the time I regained composure, I realized that my hands and head were bleeding and I had suffered abrasions and felt pain.

Signed:

S6999002 I

Recorded by:

MUHAMMAD NAZIL  
CCK AUTO CONSULTANTS



Auto  
Consultants  
Pte Ltd

## STATEMENT

all over my body. My 1st reaction was to unbuckle my seatbelt and get out of my car as quickly as I could. I managed to unbuckle my seatbelt and crawled out the car and stopped at the side of the highway. A few people had gathered at the accident scene, the driver of the lorry approached me. A guy who could speak Malay and was Chinese told me that the lorry driver had hit onto my car and it could not brake on time. After though my car was rolling and kept pushing my car forwards. The police arrived shortly after followed by an ambulance and a tow truck. Paramedics examined me and helped tend to my wounds. I remember signing a form to consent of medical treatment by conveyance to a local hospital. After that the ambulance left. The tow truck personnel helped to overturn my car. I then borrowed a flashlight from them and searched my car for my passport. While waiting for the car to be overturned I searched for my personal belongings which may have fallen out of the car. I found my in-vehicle camera and threw it back into my car after it was overturned. I felt dizzy and pain all over and could not understand what they were talking as they were speaking in Malay. The police and tow truck left with my car. I was brought to a police station by someone I don't remember. The police officer asked for my IC and driving licence. I gave them the cards together with my passport. They took down my report but they did not give me my copy. By that time I was in tremendous pain and did not remember or realise what had happened. Later the same guy who brought me to the police station brought me to the tow truck. At the accident scene I used my handphone and called my son and asked him to fetch me at JB. The tow truck personnel charged me RM 2000 to tow my car to JB customs where the car will be transferred to another tow truck and brought to Singapore. I did not take any accident scene photos as I was too much in pain. The tow truck personnel gave me a piece of paper with ADP 9463 written on it. He said it was the lorry registration number. I followed the tow truck to a Shell station before the JB customs. While waiting for my son and mom to fetch me. They reached the Shell station at 1100 hours. My son paid the tow-truck personnel S\$100 and told him to tow the car to S & H Motor in Singapore. My son brought me to Singapore General Hospital (SGH) and I was admitted by 1300 hours. I stayed for 1 day and was discharged on 03/02/18 and given 14 days of medical leave.


My son informed me that he went to S & H Motor to view the car and told me that he did not find my in-vehicle camera in the car.

Signed:

S69990021

Recorded by:

MUNE NAIR  
LEE AUTO CONSULTANTS



Auto  
Consultants  
Pte Ltd

## STATEMENT

### PARTICULARS

Name : \_\_\_\_\_  
NRIC / Passport No. : \_\_\_\_\_  
Address : \_\_\_\_\_  
Telephone : (R) \_\_\_\_\_ (O) \_\_\_\_\_  
(HP) \_\_\_\_\_  
Sex / Age : \_\_\_\_\_  
Occupation / Name of Company : \_\_\_\_\_  
Nationality : \_\_\_\_\_  
Recorded By : \_\_\_\_\_ Date : \_\_\_\_\_ Time: \_\_\_\_\_  
Place Recorded: \_\_\_\_\_  
Language Spoken: \_\_\_\_\_ Interpreted By: \_\_\_\_\_

### FACTS OF CASE:

He brought me to S&H Motor on 07/02/18 to view the car. I also could not find the in-vehicle camera despite searching. We then went to the Thomson Police Post at 1346 hours to make a police report and returned to S&H Motor to pass them a copy and to file the insurance report at 1608 hours.

As I still felt pain in my chest and right rib I returned to S&H on 05/02/18 to see the doctor. X-rays taken showed there was no fracture and I was prescribed painkillers and given 2 days of medical leave from 05/02/18 to 07/02/18. The next day I got a call from a S&H doctor who informed me that I had a slight fracture of the right rib but it was not serious and that it would heal on its own.

There was no problem with my car while I was driving it. My last servicing was done in JB every 10,000 km but I do not keep the receipt.

I wish to state that I did not consume a alcohol and/or take any medication that may impair my ability to drive at the date and time of accident.

I wish to affirm that the above ~~written~~ statement is correct and true at the time it was written.

Signed: \_\_\_\_\_

Recorded by: \_\_\_\_\_

S 69990023

MUND NARAIL  
LKK AUTO CONSULTANTS

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Feb 2018 Sendback Est	09 Feb 2018 15:47 <b>S\$700.00</b>	12 Feb 2018 15:33 Edit Adj Rpt	<b>S\$0.00</b> Edit Estimates	<b>S\$0.00</b> View Rpt		<b>Pending for Survey Report</b> Cancel Case

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

**CLAIM SUBFOLDER DETAILS**

Insured:	<b>LARRY TAN CHIN GUAN</b> , ID: S6999002I, Tel: +6588699933, Email: NOEMAIL		
Vehicle Reg. No.:	<b>SGL3534K</b>	Date of Loss:	02/02/2018 03:00 - :59
Claim Type:	<b>OD / SNM18D00738C01/4</b>	Policy/Cover Note No.:	DMPCSN3050241700 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	<b>S &amp; H Motor Pte Ltd (Sin Ming)</b> 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 22/02/2018]		
Driver/Custodian:	LARRY TAN CHIN GUAN (48 / Male), NRIC: S6999002I, Tel: +6588699933		
Adj Asg. Remarks:	Please survey vehicle & interview Insured to obtain more information on accident & obtain email address as well.		

**ASSOCIATED MAIL RECEIVED**

View All | Compose Case Mail

- CHINA\_TAIPING (02/03/2018): **Alert - Adj Mandate Approved (S\$0.00) - SGL3534K - Claim Handler: Chong Boon Sen**
- CHINA\_TAIPING (02/03/2018): **Alert - Adj Mandate Maintained - SGL3534K - Claim Handler: Chong Boon Sen**

**ALL ASSOCIATED TASKS**

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**SGL3534K (SNM18D00738C01/4)**

**OD**

**Feb 2 2018 3:00AM**

**[LARRY TAN CHIN GUAN]**

**S & H Motor Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>		
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		<b>Thumbnail</b>	<b>Print</b>
1	09/02/18 15:47	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	14/02/18 13:29	Adjuster Immediate Advice	1	Load HTM	
<b>Photos/Images</b>					<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	14/02/18 12:55	General View	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>					<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	14/02/18 13:18	Log card (if available)	1	Load PDF	
2	01/03/18 17:48	SGL 3534K DRIVER INTERVIEW STATEMENT	1	Load PDF	
3	01/03/18 17:48	SGL 3534K INTERVIEW REPORT 1	1	Load PDF	
4	09/03/18 10:12	Investigation Report	1	Load PDF	

## Linked Accident Report Documents

				<b>View</b>	<b>View in Browser</b>	
<b>Assessment Reports</b>				1 per page		<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	07/02/18 16:40	Accident Statement	1	Load HTM		
2	19/03/18 17:28	Addendum Sheet	1	Load TIF		
3	19/03/18 17:31	Accident Statement Addm. #1	1	Load HTM		
<b>Photos/Images</b>				3 per page		<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	07/02/18 16:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>	
2	07/02/18 16:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>	
3	07/02/18 16:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>	
4	07/02/18 16:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>	
5	07/02/18 16:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>				1 per page		<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	07/02/18 16:23	Sketch Plan	1	Load TIF		
2	07/02/18 16:23	Sketch Plan #2	1	Load TIF		
3	07/02/18 16:23	Sketch Plan #3	1	Load TIF		
4	07/02/18 16:23	Sketch Plan #4	1	Load TIF		
5	07/02/18 16:23	Sketch Plan #5	1	Load TIF		

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<b>Reset</b>	<b>Save</b>	<b>Print</b>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin: 5px 0;"></div> <div style="text-align: right; margin-right: 5px;"> <span>^</span>  <span>v</span> </div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CT118002796/KRD3E2

Date: 20/03/2018

### REFERENCE

Insured/Claimant: LARRY TAN CHIN GUAN Policy No: DMPCSN3050241700

Date of Loss: 02/02/2018

Nature of Claim: OD

Claim No: SNM18D00738C01/4

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGL3534K

Make &amp; Model: LEXUS IS, 250 (A)

Engine No: 4GR0232074

Reg. Date: 13/09/2006 (Man. Year: 2006)

Chassis No: JTHBK262002021618

Colour: Metallic Black

Odometer: 0 km

Engine Capacity: 2500 cc

Market Value/New Car Price: S\$37,000.00

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Falken 7 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Falken 7 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	700.00	0.00	700.00	100.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>700.00</b>	<b>0.00</b>	<b>700.00</b>	<b>100.00</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>1,500.00</b>	<b>-1,500.00</b>	
<b>(S\$)</b>	<b>700.00</b>	<b>-1,500.00</b>	<b>2,200.00</b>	<b>314.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>49.00</b>	<b>-105.00</b>	<b>154.00</b>	<b>314.29</b>
<b>Nett Amount (S\$)</b>	<b>749.00</b>	<b>-1,605.00</b>	<b>2,354.00</b>	<b>314.29</b>

### INSPECTION

Date of Assignment: 12/02/2018 Present Location:

S &amp; H Motor Pte Ltd (Sin Ming)

Date Inspected: 13/02/2018 Inspected At:

160 Sin Ming Drive #07-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :       \$37,000.00  
OMV :               \$36,637.00  
PARF Rebate (1) :     \$0.00  
Quota Premium Paid :   \$28,418.00  
COE Rebate (2) :       \$20,341.00  
Total Rebate (1) + (2) = : \$20,341.00

The total amount incurred will be Market Value \$37,000.00 minus Total Rebate \$20,341.00 = \$16,659.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG                      **Version:** 1.0 (Last Synchronised: 09 Mar 2018)  
**Parts:** 143                                  **LEXUS IS 250 (A) (Catalogue:Merimen Singapore 1.0)**  
**Labour:** Repairer's                      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SGL3534K)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

No	Qty	Particulars	Repairer's	Amount
<b><u>Miscellaneous Items</u></b>				
1	1	Towing (from Malaysia)	700.00	0.00
<b>Sub Total (S\$)</b>			<b>700.00</b>	<b>0.00</b>

**Recommended Labour**

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >