

Sheet1

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sq

Company Registration No: 199506048W

Workshops

Braddell 205 Braddell Road Singapore 579701

Loyang 59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

6 Defu Avenue 1 Singapore 539537

Marymount 600 Sin Ming Avenue Singapore 575733

Via Fax:

Date of Acc:

Attn: Motor Claims Dept.

**Dear Sirs** 

Date:

Time of Fax:

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
  - I) Our initial estimate of repairs of the damaged vehicle.
  - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Jumari Masudin Tel no. 62148316 or Hp no. 98240811 Tel no. 62148315 or Hp no. 96355305

Chiang Liat Choon Lim Tien Siong

Tel no. 62148314

25 M. San Charles 2 . . . . Tel no. 62148398 or Hp no. 96358546

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully

for Vice President

Crash Repairs & Claims Recovery







## **COMFORTDELGRO ENGINEERING PTE LTD**

REPAIR ESTIMATE

12/2/2018 14:40

VEHICLE NO: SHC 1019E

MAKE :

MODEL	: TOYOTA PRIUS				_
	PARTS DESCRIPTION	QTÝ	UNIT PRICE	AMOUNT	
	REAR BUMPER			\$ 458.60	
	REAR BUMPER RE-INFORCEMENT			\$ 318.80	
	REAR BUMPER UNDER COVER			\$ 552.60	
	REAR BUMPER SIDE RETAINER			\$ 112.70	
	REAR BUMPER SPONGE			\$ 143.40	
	REAR BUMPER UNDER SIDE COVER (LH)	•		\$ 232.00	
	REAR BUMPER CLIPS			\$ 22.00	
	RETAINER, REAR BUMPER, SIDE, LH			\$ 94.80	
	SEAL, REAR BUMPER SIDE, LH			\$ 148.40	
	REAR FENDER, LH			\$ 817.50	
	REAR FENDER SHEILD (LH)			\$ 134.20	
	SUB TOTAL			\$ 3,035.00	1
	LESS 25%			\$ 758.75	
	DISCOUNTED TOTAL			\$ 2,276.25	1
	REAR BUMPER REVERSE SENSOR			\$ 135.70	NET
	REAR BUMPER RUBBER MAT			\$ 50.00	1
	FRONT DOOR COMFORT LOGO			\$ 75.00	
	REAR DOOR COMFORT & APPS STICKER			\$ 80.00	!
				\$ 340.70	
	Labour Charge				
	Panel Beating			\$ 1,000.00	
	Spray Painting Charge			\$ 600.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 50.00	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	
	Remove/Refix Rear Windscreen Glass			\$ 120.00	
	Remove/Refix Reverse Sensor			\$ 120.00	ļ
	TOTAL LABOUR			\$ 2,090.00	<u> </u>
	ESTIMATE TOTAL			\$ 4,706.95	   
				.,,,	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Page 1 of 1

MCD618020881 / ComfortDelGro Engineering Pte Ltd - Loyang ENTRY DATE & TIME: 12/02/2018 10:21 SUBMITTED BY: Janet Lim Siang Gek

### SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

**Driving Experience** 

Mobile Number Fax Number Contact Number

**EMail Address** 

Gender

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.			
	ACCIDENT STATEMENT		
Date Of Report	12/02/2018 10:21		
Date Of Accident	10/02/2018 11:20		
Exact Location Of Accident	MOULMEIN RD TWDS THOMSON B4 JALAN TAN TOCK SENG I		
Country/State of Loss	SINGAPORE		
C	DETAILS OF OWN VEHICLE		
Vehicle Registration Number	SHC1019E		
Insured/Policyholder			
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD		
Co Reg No	199303821R		
Email Address	FLEETSAFETY@CDGTAXI.COM.SG		
Mobile Phone No			
Alternative Phone No	OFFICE-65508768		
Vehicle Particulars			
Manufacturer	TOYOTA		
Model	PRIUS HYBRID 4G		
Exact Purpose for which vehicle was being used at time of accident			
Are you claiming under your own insurance policy for repair to your vehicle?	NO		
If No, Please state action to be taken	THIRD PARTY		
Vehicle Category	TAXI		
Insurance Company			
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD		
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT		
Fleet Policy	YES		
Policy Number	D-18088936MFSH		
Cover Note Number			
Driver			
Name of Driver	LIM TIONG HIAP		
NRIC No	S1779087J		
Date Of Birth	18/02/1966		
Occupation	OUTDOOR		
Date Of Driving Pass	21/07/1983		

34 YEARS AND 6 MONTHS

MALE

**NOEMAIL** 

Page 1 of 17

BLK 432 BUKIT PANJANG RING ROAD Address #03-613 Postcode 670432 Was driver an employee of the Insured's Company NO OTHER - TAXI DRIVER If No, Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident SIDE SWIPE Weather Conditions CLEAR DRY Road Surface Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles involved in the accident 2 Was any body injured in the Accident? YES Was any injured conveyed to hospital by NO ambulance? YES Was any other material or property damaged? I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. Number of Passengers (Including Driver) 2 Passenger 1 NAME: GENDER: : FEMALE **Details of Police Action** NO Was the accident reported to the police? If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes, against whom? **Circumstances of Accident** REFER ATTACHED Attachment(s) YES

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Remarks/ Reasons:

Was there any audio recorded?

**DETAILS OF OTHER VEHICLE PROPERTY 1** SKK7581E

YES

NO

Vehicle Registration Number Vehicle Make/Model/Colour

**Details Of Properties** 

COMMERCIAL VEHICLE Vehicle Category

LIM YANG ENG Name of Driver S7320758D NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

RH FRONT

No. Of Passenger (Including Driver)

# DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

LIM TIONG HIAP

NECK AND SHOULDER

SHC1019E

YES

NO

#### Sketch Plan Pg. 1

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, Investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO REG. NO. 199303821R

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GIARIAC ShelchFlanForm\_V3

gan)

-

# Sketch Plan Pg. 2

CHETCH OLAN		
SKETCH PLAN	THE THE PROPERTY OF THE PROPER	
	MODUMEN RD 7	ŌΦ.
		- ,
<del>╶╎╏╸╏╶╏╸╏</del> ╌╂ <del>╸╏</del> ╌╏		JA2
	TAN VOCA SEA	፲ል
		-
A: SHE 1019E	<del>╶<del>╏</del>╶╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╌╏╶╏╶╏╶╏╶╏</del>	
	<u>+++++++++++++++++++++++++++++++++++++</u>	-
++++++++++++		
B: SKR 758/E	<u> </u>	
Lim TANG EN		-
	9-1-1-2-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	
11 1/1 3/3 20/5		
<del></del>		
·		
	<del>                                     </del>	1.1
DESCRIBE CIRCUMSTANCES O	E THE ACCIDENT	
		$\dashv$
		$\neg$
		_
		- 1
	A. h. at. lad	$\dashv$
	As por attached	
		1
		_
		-
		_
	······································	Į
<del></del>		
DECLARATION	\	-
/We declare the foregoing particul	ars are true in every respect.	
MFORT TRANSPORTATION I		
CO. REG. NO. 199303821	PTE LTD 11/03/18	
OU. NEG. NO. 188808021	<i>y</i> \	
olicyholder's Signature	Driver's Signature Reporting Centre Personnel's Signature	
oncynology s signature  )ate & Time:	(If driver is not the policyholder)  Name:	
TOLE IS THEE.		
ole a fine,	Date & Time: NRIC/FIN No.:	

AMBIAC StetchFlonForm\_73

# Sketch Plan Pg. 3

Describe Circumstances of t	ne Accident	771		
On 10 Feb 2018 at about 11:	20 hrs I was	driving straigh	t on the center l	ane along Moulmein Rd
leading towards the direction	n of Thomso	n/Newton.		
Somewhere in front of the S	hell Petrol S	tation sudden	ly I felt an impac	t coming from the left
had side of my taxi followed	by a jerk.			
Shortly after I stopped my to	ixi and stepp	ed out to che	ck.	
Found that an ambulance Sh	(K7581E had	come from m	y left cut into my	y lane in a careless
manner. As a result of the d	river's failure	e to keep a pro	per lookout for	my taxi when filtering
to its right caused this accide	ent to happe	n.		
In the process the right hand	l side front o	of the ambular	ice hit and graze	d the left hand side
rear door towards the left h	and side rea	r including the	left hand side re	ear wheel of my taxi.
01 lady passenger on board	my taxi. No i	injury at the p	oint of the accid	ent. However after the
accident I felt pain to my ne	ck and shoul	der areas. I wi	ll consult a Doct	or later on.
Declaration				
/We declare the foregoing partic	ulars are true i	in every respect.		
OMFORT TRANSPORTATION F CO. REG. NO. 199303821		Jeff.		nbodla L
Policyholder's Signature/Date &	Driver's Signatu	ore(If driver is not the	policyholder)/Date	Witnessed by Reporting









