

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐		11	1		FRT FENDER LH			Bent	90				90
☐		12	1		FRT FENDER INNER SHIELD LH			Deformed	14				14
☐		13	8		FRT FENDER INNER SHIELD CLIP			Necessary	1.5				12
☐		14	1		FRT FENDER QUARTER GARNISH LH			Serviceable	0				0
☐		15	1		FRT DOOR LH			Repair	0				0
☐		16	1		FRT DOOR PROTECTOR WITH CHROME LH			Serviceable	0				0
☐		17	1		FRT SUPPORT PANEL COMPLETE			Bent	250				250
☐		18	1		FRT BATTERY TOP BRACKET			Bent	16				16
☐		19	1		FRT BATTERY TRAY			Cracked	25				25
☐		20	1		AIR INTAKE DUCT			Deformed	40				40
☐		21	1		FRT BONNET			Bent	320				320
☐		22	1		FRT BONNET LOCK			Repair	0				0
☐		23	2		FRT BONNET HINGES			Repair	0				0
☐		24	1		FRT SIDE SKIRT LH			Repair	0				0

Detailed Assessment

Inspection Date *

02/13/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

400

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185/65R14

Rear Tyre Size

185/65R14

FNOL INFORMATI... BLK 115 HO CHING ROAD, #04-100,
610115, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7669213J

CATEGORY

Make

POLICY INFORMAT...

TOYOTA

ASSESSMENT INFO...

TOYOTA

CATEGORY

Model

POLICY INFORMAT...

COROLLA 1.6

ASSESSMENT INFO...

COROLLA 1.6

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

MR053ZEC107101138

CATEGORY

Date of Birth

FNOL INFORMATI...

November 2, 1976

POST SURVEY INF ...

mm/dd/yyyy

CATEGORY

Age

FNOL INFORMATI...

41

POST SURVEY INF ...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF ...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF ...

CATEGORY

Driving Experience

Accelerated
workshop survey

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

DL CANNOT VIEW PLEASE RE-SUBMIT
PENDING ESTIMATE EXCESS \$400

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
--------------	--------------	------------------	-----------------	--------	-------	-------

ANG Yvonne	2/12/18 3:18 PM	2679	2679	Open	Share	Clone
------------	--------------------	------	------	------	-------	-------

Accelerated
workshop survey

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Additional Instructions

DL CANNOT VIEW PLEASE RE-SUBMIT
PENDING ESTIMATE EXCESS \$400

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
RESURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	July 17, 2018
SFZ 5025M DL , NRIC , CI.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	February 21, 2018
PRELI ADVISED.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	February 14, 2018