

REF: CS3/LPC18002835/Rlvd3

Special Instruction: Paper Survey

From (Person): Ong Li Li of LPC Date/Time: 11/03/2018
Estimated Cost: _____ Bill to: _____

Part by Part : \$6347.20

Third Parties:

Claimant:

Surveyor: Precision Appraisal

Workshop: Eng Hup Auto

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SKA 2685T Insured: SGS 5015S

at Workshop m/s Eng Hup Auto Insured: S115 S015
of Blk 1 Yew Tee Ind Est Tel: 9423 5006
3877

Policy No: _____ Claim No: 17/18/18/VP05/020398

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 7 days)

Date/Time: 4/4/18 Submit Final Fig \$4793.20, 6 days (Red \$ 1554 / 34 %; Original days)

[illegible]

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

RECEIVED 1963

Para(3) : Nett Value

PRS & PS

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date: _____

Basic & Add	
Transport	
Photos	
Others	
Total	

45

45

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 14 March, 2018 12:33 PM
To: Nivitha (LKK Auto); assignments@lkkauto.com
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: PRI SURVEY - SKA3685T Our Ref: 17/18/18/VP05/020398
Attachments: 20398 TPD SKA3685T SURVEY REPORT.pdf

Dear Nivitha

Attached is the TP survey report with photographs.

Please let us have your surveyor's comment.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 12 February, 2018 4:42 PM
To: GERALD POH WEE BIN; assignments@lkkauto.com
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: PRI SURVEY - SKA3685T

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Monday, 12 February 2018 12:13 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: PRI SURVEY - SKA3685T

Our Ref : 17/18/18/VP05/020398

Dear Catherine,

Kindly proceed to conduct a pre-repair survey
as per attached.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

ASS. REC. BY:

REF: CS3/LPC18002835/Rlv3

perial instruction:

Surveyor: Reisu

ASSIGNMENT (Office)

From (Person): Gerold Poh of LPE

Date/Time: 12/2/18 @ 12:13pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 3685T Insured: SGS 50155

at Workshop m/s Eng Hup Auto Tel: 9423 5006

of 31k1, No. 387J woodlands Rd Yew Tee Ind. Est

Policy No: Claim No: 17/18/18/vp05/020398

Sum Insured: Excess:

Make of Veh: D.O.A. 12/02/2018
(Client's Record)CA / REV / REP. / REV 24 HRS ^{wp}

H.O.D. Endorsement:

Date/Time: 12:12pm @ 12/2/18 Person Contacted: Ah Soon Vehicle ☒ IN ☐ OUT


Date/Time	Action/Instruction (X) Estimate
	SKA 3685T-x
	SGS 50155-CS3/DNT/5010509/Fbk3 DONT: 15/6/15
13/3/18	Rec file from assignment Team
	Dismantle: 12/2/18

PRM

REF

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / CD RES / EVA / INV / MV
To inspect vehicle No: **SKA 3685T**
at Workshop is: **EXH HUP guru**
of: **Buk, 13873 NORMAN RD**
Insured: **LPC / TP / up**
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Ver: _____



Remark: The veh had commenced its repair at the time of inspection.

Bail or Market Value: _____
IDAO Accident Report: _____ Consistent? : Yes or No
GIA / PR. Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Car No: **SKA 3685T** Reg: **11**
Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover
Truck / Trailer or
Make: **KIA CERATO** to: **1591**
Colour: **Grey** A/C: _____ Insured / Std / NI / NA
So. Reading: **136193** T. Radio: Insured / Std / NI / NA
Eng No: _____
C.No: **KNAFU4/MB5376041**
Gen. Condi: Good / ☒ Fair / Poor / Burnt
Steering: In order / ☒ Jammed / Leaked / Burnt or
Brake: In order / ☒ Jammed / Leaked / Burnt or
Modi: Nil / ☒ B/Rim / STD A/Rim or
Tyre Size: F: **215/45R17**
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
☒ TOYO / YOKO or
Front: _____ Rear: _____
R.Bal: **6** mm R.Bal: **6** mm
L.Bal: **6** mm L.Bal: **6** mm
D.O.A: **12/02/18** D.O: **12/02/18**
Survey held at: _____
Des. of Damages: Fnt / ☒ Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
14/3/18 **Submit PRS**

Date/Time File Passed: ☐ : Preli. Report
☐ : Final Report

Date/Time File Return: **14/3 - 24/3/18**

Report Format: **PRS**
Lump Sum U.S. Inc: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp: \$
☐ Inter. Insp: \$
☐ Tech: \$
☐ Des. Insp: \$

Survey Fee: _____


Transport: _____

1-PR, 1-1

2-PR, 1-1

3-PR, 1-1

4-PR, 1-1



Survey Department Check List (Case Handler)

Reference No.: CS3 | LPC | 800 2835 | Rlv3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-Inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 14/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18002835/R1vd3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 13-02-2018



Code : LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGS 5015S	Veh. Inspected	SKA 3685T
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020398	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/02/2018	Inspection Date	12/02/2018
Survey held at	ENG HUP AUTOPARTS ACCESSORIES CO. 387J BLK 1 WOODLANDS ROAD SINGAPORE 677899		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 12 February 2018 12:13 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: PRI SURVEY - SKA3685T
Attachments: 12022018120852.pdf

Our Ref : 17/18/18/VP05/020398

Dear Catherine,

Kindly proceed to conduct a pre-repair survey
as per attached.

Best Regards

Gerald Poh


Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

K. K. CHENG & CO

Advocates and Solicitors
101 Upper Cross Street #05-21
People's Park Centre
Singapore 058357
Tel: 6227 1272 Fax: 6227 5563



Our Ref: EHA/SKA3685T
Your Ref: SGS5015S
(Please quote our reference number when replying)

12 February 2018

Lonpac Insurance Bhd

By fax only: 62962706

Dear Sirs

NOTICE OF ACCIDENT
Claimant: LEE POH SENG

Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or before 1st April 2016 ("Protocol")

We refer to your letter dated 12th February 2018.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 12th February 2018.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 12th February 2018.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, *for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.*

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:

Name of Workshop	:	Eng Hup Auto Parts Accessories Co
Address	:	Blk 1 No. 387J Woodlands Road Yew Tee Industrial Estate Singapore 677954
Contact person	:	Ah Soon
Telephone No.	:	94235006

Yours faithfully

CHENG KIM KUAN

cc Workshop (Ref: SKA 3685T)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3563G
Vehicle Details	
Vehicle No.:	SKA3685T
Vehicle to be Exported:	No
Intended De-registration Date:	14 Mar 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO EX FORTE 1.6L 6A/T ABS AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	G4FCAH302824
Chassis No.:	KNAFU411MB5376041
Maximum Power Output:	91.2 kW (122 bhp)
Open Market Value:	\$10,932.00
Original Registration Date:	23 Feb 2011
First Registration Date:	23 Feb 2011
Transfer Count:	2
Actual ARF Paid:	\$10,932.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Feb 2021
PARF Rebate Amount:	\$6,559.00
Intended COE Rebate Details	
COE Expiry Date:	22 Feb 2021
COE Category:	A - Car (1600cc & below)

COE Period(Years):	10
QP Paid:	\$37,124.00
COE Rebate Amount:	\$10,916.00
Total Rebate Amount:	\$17,475.00

The information contained herein is correct as at 14 Mar 2018

OK

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKA3685T
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	KIA
Vehicle Model :	CERATO EX FORTE 1.6L 6A/T ABS AB 2WD 4DR
Chassis No. :	KNAFU411MB5376041
Propellant :	Petrol
Engine No. :	G4FCAH302824
Engine Capacity :	1591 cc
Maximum Power Output :	91.2 kW (122 bhp)
Maximum Laden Weight :	1720 kg
Unladen Weight :	1261 kg
Year Of Manufacture :	2010
Original Registration Date :	23 Feb 2011
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$37,124.00
COE Expiry Date :	22 Feb 2021
Road Tax Expiry Date :	22 Aug 2018
PARF Eligibility Expiry Date :	22 Feb 2021
Inspection Due Date :	22 Feb 2020

Intended Transfer Date : 14 Mar 2018

CO2 Emission : -

CO Emission : -

HC Emission : -

NOx Emission : -

PM Emission : -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/02/2018 11:44
 Date Of Accident 10/02/2018 09:00
 Exact Location Of Accident ALMOST THE JUNCTION OF CHOA CHU KANG NORTH 5
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKA3685T
 Name Of Registered Owner LEE POH SENG
 NRIC No S6943563G
 Email Address PSLE1909@YAHOO.COM
 Mobile Phone No (LOCAL) +65-94555489
 Alternative Phone No OFFICE-94555489
 Manufacturer KIA
 Model CERATO EX FORTE 1.6L 6A/T ABS AB 2WD 4DR
 Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1700033485

Cover Note Number

Name of Driver LEE POH SENG

NRIC No S6943563G

Date Of Birth 15/12/1969

Occupation OUTDOOR

Date Of Driving Pass 31/08/1994

Driving Experience 23 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-94555489

Fax Number OFFICE-94555489

Contact Number PSLE1909@YAHOO.COM

E-Mail Address*

Address

BLK767 CHO A CHU KANG ST54 #08-49 SINGAPORE 680767

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : WIFE
GENDER: : FEMALE

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

REFER TO SKETCH PLAN.

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGS5015S

Vehicle Make/Model/Colour MITSUBISHI LANCER

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LEE KOK MENG

NRIC/Passport Number S7723091B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

ABD SALAM BIN ABD MAJEED

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

W 10/2/2018

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature:


Name:

ERIC/PAH MOJOH KHER KIAN

GIANC SketchPlan Pg. 1

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

the left my not deal all vehicle

Vehicle is changing traffic light and am stop at that moment. But the back of the vehicle still moving forward my vehicle and the impact cause my car to move forward and touch the front car. But no damage can be seen on the front car.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), there is a FOURTEEN (14) DAYS CLAIMS PERIOD WHICH MUST BE MADE WITHIN the stipulated time frame from the day of the occurrence.

- Reporting Only

- Claim OD

- Claim TP

- Claim OD/TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

Policyholder's signature

Date & Time

10/02/2018

Driver's Signature

(If driver not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name: Toh Khar Kian

Nric/Fin No.

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

Lee Poh Seng

767 Choa Chu Kang Street 54

#08-49 Singapore 680767

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As above
Accident Date : -
Assignment Date : 12 February 2018
Inspection Date : 12 February 2018
Our Reference No. : PAS/EH/180227/TP

Inspection Report Date : 26 February 2018

Workshop Name :

Eng Hup AutoParts Accessories Co.

Inspection Address :

Block 1, 387J Woodlands Road Yew Tee

Industrial Estate Singapore 677954

PARTICULARS OF VEHICLE

Registration No.	: SKA 3685 T	Mileage	: 136193	Km/h
Make/Model	: Kia Cerato Ex Forte 1.6L 6A/T ABS AB 2WD 4DR	Radio/Casette	: Fitted	
Yr of Manuf/Regn	: 2011	CD Disc Player	: Fitted	
Carrying Capacity	: 4Seater	Air Conditioner	: Fitted	
Chassis No.	: KNAFU411MB5376041	Clock	: Fitted	
Engine No.	: G4FCAH302824	Seat Belt	: Fitted	
Colour	: Metallic Silver	Wing Mirror	: Fitted	
Class	: Passenger (Private)	Other Accessories	: Fitted	

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent Eng : None
Modifications

VEHICLE VALUE

Market Value : -

Wreck Value (Part) : -

TYRE SIZE & CONDITION

Front N/s Size : 215/45R17 80 %
Make : Toyo
Rear N/s size : 215/45R17 80 %
Make : Toyo
Spare Size : 215/45R17 80 %
Make : Toyo

Front O/s Size : 215/45R17 80 %
Make : Toyo
Rear O/s Size : 215/45R17 80 %
Make : Toyo

Spare Size

Make

Jack & Tools : Intact/Missing


Type of Wheel Rims: Alloy

Note: The above percentage % represent the estimated remaining tyre threads.

POINT OF IMPACT

Direction of impact/damage marked (→) (X)

**The vehicle
sustained impact
on its Rear
Portion. (see
Diagram D)**

**GENERAL DESCRIPTION OF DAMAGES**

Parts damaged were :

The bootlid, both rear fender and chassis, rear bumper and reinforcement, rear panel were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 12/02/2018 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s Eng Hup AutoParts Accessories Co as per attached Appraisement Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Part-By-Part Repair Basis of \$ 6,347.20 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	<u>Repairer's</u>		<u>Our</u>	
	<u>Estimate</u>	<u>Amount</u>	<u>Revised</u>	<u>Amount</u>
Sp. Parts	4326	00	3307	20
ing Charges	-		-	
PB Labour Charges	1600	00	1400	00
Others Misc Charges	350	00	240	00
Paintwork	1600	00	1400	00
Total	\$ 7876	00	\$ 6347	20


Under normal circumstances, the duration of repairs should not exceed Seven (07) days.

Attached photographs taken during inspection Sixty - Nine (69) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 13/02/2018, we examined the extent of damages
3. On 19/02/2018, we examined the new replacement parts
4. On 22/02/2018, we examined the repaired vehicle.

Yours Faithfully,




T F NG PHILIP FOO
ACII CAE, AMIMI
AIAME, AMSAE-A
Licensed Appraiser/Adjuster

Inspection Report Date: 26 February 2018

VEHICLE REGN NO :

SKA3685T

OUR REFERENCE :

PAS/EH/180227/TP

INSPECTION REPORT DATE :

26-Feb-18

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO :

1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
<u>PARTS SUPPLY - LIST ITEMS</u>					
1	1pc	Bootlid	Badly dented	\$ 747.00	\$ 747.00
2	1pc	Bootlid hinges o/s	Bent	65.00	65.00
3	1pc	Bootlid hinges n/s	Bent	65.00	65.00
4	1pc	Bootlid centre logo	Necessary	51.00	51.00
5	1pc	Bootlid 'Cerato' emblem	Necessary	28.00	28.00
6	1pc	Bootlid 'Forte' emblem	Necessary	24.00	24.00
7	1pc	Bootlid 'C&C' emblem	Necessary	32.00	32.00
8	1pc	Bootlid lamp n/s	Cracked	140.00	140.00
9	1pc	Bootlid lamp pad n/s	Cracked	5.00	5.00
10	1pc	Bootlid lamp o/s	Cracked	140.00	140.00
11	1pc	Bootlid lamp pad o/s	Cracked	5.00	5.00
12	6pcs	Bootlid n/s lamp clips@\$3.50	Necessary	28.00	28.00
13	1pc	Boot rubber	Torn	90.00	90.00
14	1pc	Bootlid upper lock	Bent	113.00	113.00
15	1pc	Bootlid lower lock	Bent	27.00	27.00
16	3pcs	N/s Taillamp clips@\$5	Necessary	15.00	15.00
17	1pc	N/s Taillamp	Cracked	197.00	197.00
18	1pc	N/s Taillamp pad	Necessary	5.00	5.00
19	1pc	O/s Taillamp pad	Necessary	5.00	5.00
20	1pc	Rear panel	Badly dented	282.00	282.00
21	1pc	Rear panel garnish	Bent	54.00	54.00
22	1set	Rear panel garnish clips	Necessary	27.00	27.00
23	1pc	Rear bumper	Badly dented	601.00	601.00
24	1pc	Rear bumper bracket n/s	Bent	42.00	42.00
25	1pc	Rear bumper side retainer n/s	Bent	22.00	22.00
26	1pc	Rear bumper reinforcement	Badly dented	304.00	304.00
27	1set	Rear bumper clips	Necessary	35.00	35.00
28	1pc	Rear bumper sponge	Torn	134.00	134.00
29	1pc	Rear bumper lower spoiler	Badly dented	688.00	Repair
30	1set	Rear bumper lower spoiler clips	Necessary	25.00	25.00
				3996.00	3308.00
Less: 10% discount				-	330.80
				3996.00	2977.20
<u>SPECIAL NETT ITEMS</u>					
1	1set	Rear bumper sensor	Dented/Jammed	280.00	280.00
2	1pc	Rear no. plate	Dented	50.00	50.00
Total spare parts				4326.00	3307.20
<u>LABOUR & MISC. CHARGES</u>					
1		Remove the necessary affected parts, cut/weld rear panel, straighten rear n/s fender and chassis, repair rear bumper spoiler and replace parts		1800.00	1400.00
2		Putty and Spraypaint (include rear bumper and spoiler)		1800.00	1400.00
3		Check electrical		50.00	30.00
4		Tuff Kote		150.00	120.00
5		Remove and refit rear bumper sensors		100.00	60.00
6		Rewire rear portion		50.00	30.00
				8276.00	6347.20
xxx SUB / GRAND TOTAL					

SUB / GRAND TOTAL

PRECISION APPRAISAL SERVICES

6 days





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC18002835/R1vd3e2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-04-2018



Code : LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGS 5015S	Veh. Inspected	SKA 3685T
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020398	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	12/02/2018

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KNAFU411MB5376041	Colour	GREY
Odometer	136193	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	TOYO	6 mm
L/H Front Tyre	215/45 R17	TOYO	6 mm
R/H Rear Tyre	215/45 R17	TOYO	6 mm
L/H Rear Tyre	215/45 R17	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/02/2018	Inspection Date	12/02/2018
Survey held at	ENG HUP AUTOPARTS ACCESSORIES CO. 387J BLK 1 WOODLANDS ROAD SINGAPORE 677899		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 3685T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BADLY DENTED	747.00	747.00
1	BOOTLID HINGES O/S	NOT NECESSARY	65.00	-
1	BOOTLID HINGES N/S	NOT NECESSARY	65.00	-
1	BOOTLID CENTRE LOGO	NECESSARY	51.00	51.00
1	BOOTLID 'CERATO' EMBLEM	NECESSARY	28.00	28.00
1	BOOTLID 'FORTE' EMBLEM	NECESSARY	24.00	24.00
1	BOOTLID 'C&C' EMBLEM	NECESSARY	32.00	32.00
1	BOOTLID LAMP N/S	CRACKED	140.00	140.00
1	BOOTLID LAMP PAD N/S	NOT NECESSARY	5.00	-
1	BOOTLID LAMP O/S	NOT NECESSARY	140.00	-
1	BOOTLID LAMP PAD O/S	NOT NECESSARY	5.00	-
6	BOOTLID N/S LAMP CLIPS @\$3.50	NOT NECESSARY	28.00	-
1	BOOT RUBBER	TORN	90.00	90.00
1	BOOTLID UPPER LOCK	BENT	113.00	113.00
1	BOOTLID LOWER LOCK	NOT NECESSARY	27.00	-
3	N/S TAILLAMP CLIPS @\$5.00	NOT NECESSARY	15.00	-
1	N/S TAILLAMP	CRACKED	197.00	197.00
1	N/S TAILLAMP PAD	NOT NECESSARY	5.00	-
1	O/S TAILLAMP PAD	NOT NECESSARY	5.00	-
1	REAR PANEL	BADLY DENTED	282.00	282.00
1	REAR PANEL GARNISH	BENT	54.00	54.00
1	SET REAR END PANEL CLIPS	NECESSARY	27.00	27.00
1	REAR BUMPER	BADLY DENTED	601.00	601.00
1	REAR BUMPER BRACKET N/S	BENT	42.00	42.00
1	REAR BUMPER SIDE RETAINER N/S	BENT	22.00	22.00
1	REAR BUMPER REINFORCEMENT	BADLY DENTED	304.00	304.00
1	SET REAR BUMPER CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER SPONGE	TORN	134.00	134.00
1	REAR BUMPER LOWER SPOILER	TO REPAIR SEE LABOUR	688.00	-
1	SET REAR BUMPER LOWER SPOILER CLIPS	NECESSARY	25.00	25.00

Report Ref No. CS3/LPC18002835/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-294.80
			3,996.00	2,653.20
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER SENSOR (SN)	DENTED /JAMMED	280.00	200.00
1	REAR NO.PLATE (SN)	NOT NECESSARY	50.00	-
			330.00	200.00
	LABOUR			
	REMOVE THE NECESSARY AFFECTED PARTS, CUT/WELD REAR PANEL, STRAIGHTEN REAR N/S FENDER AND CHASSIS, REPAIR REAR BUMPER SPOILER AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER SPOILER.		1,800.00	800.00
	PUTTY AND SPRAYPAINT (INCLUDE REAR BUMPER AND SPOILER) .		1,800.00	1,000.00
	CHECK ELECTRICAL.		50.00	15.00
	TUFF KOTE.		150.00	60.00
	REMOVE AND REFIT REAR BUMPER SENSORS.		100.00	50.00
	REWIRE REAR PORTION.		50.00	15.00
			3,950.00	1,940.00
GRAND TOTAL			8,276.00	4,793.20

RECOMMENDED COST OF REPAIRS			4,793.20
------------------------------------	--	--	-----------------

Report Ref No. CS3/LPC18002835/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.