

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18002861/K1qbn2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 22-02-2018	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 8920L	Veh. Inspected	SHC 3146H	
Policy No.	5088873880-01	Coverage (\$)	0.00	
Claim No.	MT/0982534-001	Excess (\$)	0.00	
Assign From		Assign Date	12/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	KMHET41VMBA804512	Colour	BLUE	
Odometer	702194	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HANKOOK	7 mm	
L/H Front Tyre	215/60 R16	HANKOOK	7 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	7 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/02/2018	Inspection Date	12/02/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		