

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI18002871/Wd3⁵⁷

Special Instruction:

range & days

Surveyor:
Menmen

Wilson

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CTI

Date/Time: 12/2/18 @ 5.21pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 6970F

Insured:

PC 62082

at Workshop m/s

Super Modern Services

Tel:

91525152

of 25 Kaki Bk Rd 4 # 01-26

Policy No:

DMB1SN1750191700

Claim No:

SNM18D00805C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

10.29am @ 13/2/18

Person Contacted:

Ah loi

Vehicle IN/OUT

Date/Time

Action/Instruction (x) Estimate

YP 6970F -X

PC 62082 -X

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/INV: _____
 To inspect Vehicle No: YP 6970E
 at Workshop m/s: Super Modern Svc.
 of: 25, Kaler Bulat Rd 4 # 2-26
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Ven: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: YP 6970E Yr Regn: Not Available
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Tow Truck
 Make: Isuzu CC: _____
 Colour: Yellow / Black Insured / Std / NI / NA
 Sp. Reading: 37978 T. Radio: Insured / Std / NI / NA
 *Co. Reg. No. Error
 Eng. No: _____
 C/No: JAANPR TSKH101510
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size F: 215 / 85 R16
 R: 215 / 85 R16
 BS / DUN / EXHOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Bridge Stone
 Front: _____ Rear: _____
 R/Bal: 4 mm R/Bal: 4 mm
 L/Bal: 4 mm L/Bal: 4 mm
 D.O.A: 5/2/2018 D.O.I: 13/2/2018
 Survey held at: As Above
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Right Rear Side
 The U/C / Chassis frame / Body Structure affected due to collision

Range #4000 - #4500
4 days

9/4/2018

RECEIVED 1 APR 2018

Date/Time File Pass to: ☐ : Preli. Report
 10042018 ☐ : Final Report
 Date/Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transducer

1. S - RS - S

Phone

Others

Add Fee: ☐ Site Insp (S)
☐ Interview (S)
☐ Tech. Insp (S)
☐ Weekend (S)

Report Format: PRS

Lump Sum / I.B.I. (S)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18002871/Wd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-02-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	PC 6208Z	Veh. Inspected	YP 6970E
Policy No.	DMB1SN1750191700	Coverage (\$)	0.00
Claim No.	SNM18D00805C02	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/02/2018	Inspection Date	13/02/2018
Survey held at	SUPER MODERN SERVICES 25 KAKI BUKIT ROAD 4 #01-26 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		12 Feb 2018 17:21 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	SUPERSONIC MAINTENANCE SERVICES PTE LTD		
Vehicle Reg. No.:	YP6970E	Date of Loss:	05/02/2018 00:00 - :59
Claim Type:	TP / SNM18D00805C02	Policy/Cover Note No.:	DMB1SN1750191700
Vehicle Reg. No. (Insured):	PC6208Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Super Modern Services Pte Ltd (Kaki Bukit) Synergy @ KB, Kaki Bukit road 4 , # 01-26, 417800 Kaki Bukit - Tel: 91525152/62568830		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/02/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 12:11
Date Of Accident	05/02/2018 13:05
Exact Location Of Accident	ALONG AYE (TUAS) PORTDOWN ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP6970E
Insured/Policyholder	
Name Of Registered Owner	SUPERSONIC MAINTENANCE SERVICES PTE LTD
Co Reg No	198401352W
Email Address	BENTAN@SUPERSMS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64677444

Vehicle Particulars

Manufacturer	ISUZU
Model	NPR75UK5W
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017-V0101827-VCV
Cover Note Number	

Driver

Name of Driver	WONG ENG HOW
NRIC No	S7835015F
Date Of Birth	17/11/1978
Occupation	OUTDOOR
Date Of Driving Pass	13/07/2006
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98757196
Fax Number	
Contact Number	
EMail Address	BENTAN@SUPERSMS.COM.SG

Address	BLOCK 162A PUNGGOL CENTRAL #12-55
Postcode	821162
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ANGAPPAN THIRUKKUMARAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	KIM KEAT NPP - PLEASE REFER TO THE ATTACHED POLICE REPORT
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please refer to the attached Sketch Plan and the Police Report for the accident details

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC6208Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	ANG ENG KIM
NRIC/Passport Number	S0171423F
Contact Number	98187998
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

06/02/2018

1155 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Incident happened on 05/02/2018 at 1305 hrs.

As said location CTE/AIE VP 697EF was proceed back to Outram Hill @ CTE/AIE port down EXIT U-Turn while VP 697EF was stationary due to Red Light @ Left Lane PC 620RZ from Rear Right Lane try to squeeze into the Right Lane and contact VP 697EF vehicle Equipment Black surface causing PC 620RZ Left Side mirror (circle) damage As Res make a check and into the PC 620RZ Drive this left VP 697EF was governed properly. Res secure the vehicle particular and thereafter left the location.

I, Khor Eng Hui, 88876123A is doing this reporting on behalf of driver, Wang Eng Hui 87835015E, contact number having 98757196

Please refer to police report attached reference no. 7/20180205/2194

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

06/02/2018
1155hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180205/2188

1 of 3

Police Station Of Origin:

Kim Keat NPP

231 Lorong 8 Toa Payoh #01-186

SINGAPORE 310231

Tel No: 1800-2529999

Report No. T/20180205/2188

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/02/2018 21:00	Vide Report No.:	Station Diary No.: 46
--	------------------	--------------------------

Informant's Particulars

Name of Informant: WONG ENG HOW			Address: APT BLK 162A PUNGGOL CENTRAL #12-55 SINGAPORE 821162	
ID Type / ID No.: NRIC NO / S7835015F			Contact No.:	Mobile: 98757196
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email:	
Sex: Male	Age: 39	Date of Birth: 17/11/1978	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: TOW TRUCK DRIVER			Driving Licence Information: Class: 3,4,5	Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 05/02/2018 13:05	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY PORTDOWN ROAD EXIT (NEAR TO AYE TOWARDS TUAS) LANE TWO				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicles Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PC6208Z	Bus/Coach/Minibus					0
YP6970E	Lorry				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA	

Sketch Plan #2 Pg. 2



**SINGAPORE
POLICE FORCE**



T/20180205/2188

2 of 3

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-188
SINGAPORE 310231
Tel No: 1800-2529999

Report No. T/20180205/2188

CONTINUATION OF REPORT

Name	ANG ENG KIM	ID No.	S0171423F
Related Vehicle	PC6208Z (Bus/Coach/Minibus)	Contact No.	98187998
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	WONG ENG HOW	ID No.	S7835015F
Related Vehicle	YP6970E (Lorry)	Contact No.	98757196
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05/02/2018 at about 1100hrs, I commenced my work as an EMAS Recovery Towing Truck Driver together with my assistant namely as "Thirukkungan". The vehicle that was assigned to me is YP6970E.

At about 1305hrs, I was driving along AYE towards Tuas and had exited Portdown Road exit as I am making a U-turn to go Outram Hill. The traffic light was red as such I stopped my vehicle on the slope at the extreme left lane. As I was waiting for the red light to turn, suddenly one mini-bus tried to squeeze into my lane and as a result, the mini-bus collided onto the right side of my vehicle. I immediately stopped my vehicle to make a check and discovered that the surface of the equipment rack was cracked and there were scratches on the said affected area. The mini-bus left mirror was detached.

I took down the driver's particular and after which left the location.

I was advised by my company to lodge a Police report.



**SINGAPORE
POLICE FORCE**



T/20180205/2188

3 of 3

Report No. T/20180205/2188

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

E /

Sr Staff Sgt MOHAMAD FAZLI BIN MOHAMAD
ZAIN

Signature Of Informant:

[Handwritten Signature]
U.059 F.06.1111

Signature Of Interpreter:

Not applicable

Date/Time:

05/02/2018 21:00

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING
Contact No.: 65476430

Classification Of Case:




**SINGAPORE
POLICE FORCE**



SN 064

Authentication Stamp
NP168

SIGNATURE

Sketch Plan #2 Pg. 4







For Customer Service please visit
1 Pickering Street
#01-01 Great Eastern Centre
Tel: 1900 248 2888 Fax: 6327 3080

Certificate Of Insurance

ORIGINAL	
<small>Road Transport Act 1987 (Federation of Malaysia) The Motor Vehicles (Third-Party Risks) Rules, 1955 (Federation of Malaysia) The Motor Vehicles (Third-Party Risks and Compensation) Act, (Cap.189 of the Revised Edition) (Republic of Singapore) The Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960, (Republic of Singapore)</small>	
Policy No : 2017-V0101827-VCV Policy Type : Commercial Vehicle	Risk# : 001 Cover : COMPREHENSIVE
FORM M2300	
DESCRIPTION OF VEHICLES: Vehicle Registration No : YP6970E Vehicle Make & Model : ISUZU NPR75UK5W	
Name of Insured : SUPERSONIC MAINTENANCE SERVICES PTE LTD AS AUTHORISED DRIVERS AND LAND TRANSPORT AUTHORITY AS REGISTERED OWNERS FOR THEIR RESPECTIVE RIGHTS AND INTERESTS	
Period of Insurance : 24-07-2017 (0000HRS) to 23-07-2018	
PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE * Any person who is driving on the Policyholder's order or with their permission.	
* Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
LIMITATIONS AS TO USE (1) Use in Connection with the Policyholder's business. (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. (3) Use for social, domestic and pleasure purposes. The policy does not cover :- (1) Use for racing, pace-making, reliability trial or speed-testing. (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle. (3) Use for the carriage of passengers for hire or reward.	
Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)	
Signed for and on behalf of the Company	
<div style="text-align: center;"> _____ Authorised Signature </div>	

GPGICSS

26-07-2017

Great Eastern General Insurance Limited (Reg. No. 1920 00003W)
 (A wholly-owned subsidiary of Great Eastern Holdings Limited)
 1 Pickering Street, #01-01 Great Eastern Centre, Singapore 048659
 Tel +65 6246 2000 Fax +65 6532 2214 greateasterngeneral.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018		12 Feb 2018 17:21 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	SUPERSONIC MAINTENANCE SERVICES PTE LTD		
Vehicle Reg. No.:	YP6970E	Date of Loss:	05/02/2018 00:00 - :59 [337 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00805C02	Policy/Cover Note No.:	DMB1SN1750191700
Vehicle Reg. No. (Insured):	PC6208Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Super Modern Services Pte Ltd (Kaki Bukit) Synergy @ KB, Kaki Bukit road 4 , # 01-26, 417800 Kaki Bukit - Tel: 91525152/62568830		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 22/02/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YP6970E (SNM18D00805C02)
[PC6208Z]

TP

SUPERSONIC MAINTENANCE SERVICES PTE LTD
Feb 5 2018 12:00AM

[-]

Super Modern Services Pte Ltd

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Documentation

1 per page ▼ ☒

No	Finalized On			Thumbnail	Print
1	12/02/18 17:20	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/04/18 16:33	LKKPhotosIn6-1	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18002871/WD3S2
 Date: 16/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1750191700
 Claimant Vehicle No: YP6970E Insured Vehicle No: PC6208Z
 Date of Loss: 05/02/2018 Nature of Claim: TP Claim No: SNM18D00805C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP6970E
 Make & Model: ISUZU NPR75U, 5.2 D (M) Engine No: HIDDEN
 Reg. Date: 01/01/1990 (Man. Year: 1990) Chassis No: JAANPR75KH7101570
 Colour: Yellow/Black Odometer: 37978 km
 Engine Capacity: 0 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/85R16 Rear Tyre Size: 215/85R16
 Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
 Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 12/02/2018
 Date Inspected: 13/02/2018 Inspected At: Super Modern Services Pte Ltd
 25 KAKI BUKIT ROAD 4
 #01-26 SYNERGY @ KB
 SINGAPORE 417800
 Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/16/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$4,500.00.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Apr 2018)	
Parts:	N/A	ISUZU NPR75U 5.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP6970E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >