

RECEIVED 0 6 JAN 2018RECEIVED 26 APR 2018

COPY SENT

REF: III

ASSIGNMENT

From: Date: 13.02.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLG 666A

at Workshop m/s: Vfix Auto

of: 60 Kaki Bukit Aveb

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

100mm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Van No: SLG 666A Yr Regn: 5 11

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: JAGUAR XJ5.0Lcc 17000

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 61922 T.Radio: Insured / Std / NI / NA

Eng/No:

Cr/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Locked / Jammed / Leaked / Burnt or

Brake: Locked / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255-35ZR20

R: 285-30ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PDI / SUMI /

TOYO / YOKO or

Front:

R/Bal: 6 mm

Rear:

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 7/2/18

D.O.I: 13/2/18

Survey held at:

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

As per.

The UIC / Chassis frame / Body Structure affected due to collision.

13/2/18 confirmed L/S & 1200 w/h m. chnl

red: \$3098 / 87%

Date/Time: File Pass to?

☐ : Prel. Report

Days Of Repair:

1) Date/Time: File Return to?

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

2) Date/Time: File Return to?

Transporter:

Add Fee: ☐ Site Insp: \$

J \$ + R3 \$

☐ Inter. Insp: \$

P. Insp:

☐ Tech. Insp: \$

Other:

☐ Weekend: \$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CC4/III18002893/Uks3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 13-02-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8485X		Veh. Inspected	SLG 666A
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	13/02/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/02/2018		Inspection Date	13/02/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Foreign Identification Number
Owner ID:	5668P

Vehicle Details

Vehicle No.:	SLG666A
Vehicle to be Exported:	No
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XJ 5.0L AT ABS D/AB 2WD 4DR GAS/D SR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	10111823514508PN
Chassis No.:	SAJAC22F4BLV15997
Maximum Power Output:	283.0 kW (379 bhp)
Open Market Value:	\$87,797.00
Original Registration Date:	19 May 2011
First Registration Date:	19 May 2011
Transfer Count:	2
Actual ARF Paid:	\$87,797.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 May 2021
PARF Rebate Amount:	\$57,068.00

Intended COE Rebate Details

COE Expiry Date:	18 May 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$62,010.00
COE Rebate Amount:	\$20,182.00
Total Rebate Amount:	\$77,250.00

The information contained herein is correct as at 14 Feb 2018

M/S INDIA INT'L INS PTE LTD
64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

ESTIMATE

DATE : 12/02/2018
ACC DATE : 07/02/2018
REF NO. : VFIX-TP20180420
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO.SLG 666 A JAGUAR XL

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
1 1 FRONT SHOCK ABSORBER LH	11	3,520.00
2 1 FRONT WHEEL KNUCKLE LH	11	1,253.00
3 1 FRONT LOWER ARM LH	11	985.00
4 1 SPORT RIM	10/3rd	1,540.00
		1000s
		\$ 7,298.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panels with all necessary components/attach- ments apply hot-works where necessary	200 1,000.00
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	200 1,000.00
1 To conduct front wheel alignment	100.00
	\$ 2,000.00

GRAND TOTAL : \$ 9,298.00

SINGAPORE DOLLARS : NINE THOUSAND TWO HUNDRED & NINETY EIGHT ONLY

Vfix Auto Service Pte Ltd

Vfix Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 12 February 2018 4:37 PM
To: vfix auto; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Manivel Priyadarshini
Subject: RE: PRE-REPAIR INSPECTION FOR SLG666A AND SHC8485X ON 07/02/2018
Attachments: III NOA.DOCX

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLG666A and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

4.44pm @ 12/2/2018
vehicle In
person @ Irene
Average on 13/02/2018

From: vfix auto [mailto:vfixauto@gmail.com]

Sent: 12 February, 2018 3:24 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: PRE-REPAIR INSPECTION FOR SLG666A AND SHC8485X ON 07/02/2018

Dear Gabriel

We would like to appoint LKK.

Thanks

Irene

Vfix Auto Services Pte Ltd

60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 | E: vfixauto@gmail.com | T: +65 64552957 | F: +65 64452368

On Mon, Feb 12, 2018 at 2:01 PM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: vfix auto [mailto:vfixauto@gmail.com]

Sent: 12 February, 2018 11:59 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: RE: PRE-REPAIR INSPECTION FOR SLG666A AND SHC8485X ON 07/02/2018

Dear Sir / Mdm,

Please find attached copy for your arrangement.

Thanks

Irene

Vfix Auto Services Pte Ltd

60 Kaki Bukit Ave 6 Ark@KB Singapore 417892 | E: vfixauto@gmail.com | T: +65 64552957 | F: +65 64452368

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6

Ark@KB Singapore 417892

Email: vfixauto@gmail.com

Tel: 64489268 Fax: 64452368

Your Vehicle No. : SHC8485X

Our Vehicle No. : SLG666A

07 FEB 2018

M/S INDIA INT'L INS PTE LTD

64 CECIL STREET

05-01 IOB BUILDING

SINGAPORE 049711

ATTN: MOTOR CLAIMS DEPT

Dear Sir / Madam,

ACCIDENT INVOLVING SLG666A AND SHC8485X ON 07 FEB 2018

We refer to the above matter.

We hereby give 2 days' notice to conduct a pre-repair inspection of vehicle

number **SLG666A** at 60 Kaki Bukit Ave 6, ARK@KB, Singapore 417892.

Thank you.

Yours faithfully,

Vfix Auto Service Pte Ltd

05 APR 2018

vfix

Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6

Ark@KB Singapore 417892

Email: vfixauto@gmail.com

Tel: 64489268 Fax: 64452368

Co Reg No: 201602964H

GST Reg No: 201602964H

Our Ref. No. : VFIX-TP20180420

**MOTOR CLAIMS DEPT
INDIA INT'L INS PTE LTD**

64 CECIL STREET
#05-01 IOB BUILDING
SINGAPORE 049711

WITHOUT PREJUDICE

Dear Sir / Madam

PROPERTY CLAIM ONLY

**ACCIDENT INVOLVING SLG666A AND SHC8485X ON 07 FEB 2018
ALONG CAVENAGH ROAD TOWARDS ORCHARD ROAD**

We refer to the above-mentioned accident.

We are writing on behalf of **MS XIANG MEI LIN** the registered owner
of motor vehicle number **SLG666A** which was involved in the above accident.

We are instructed that the above accident was caused by the negligence and management of your
insured's vehicle number **SHC8485X**. As a result of the above accident, our client's vehicle
was damaged and our client's has been put to loss and expense, particulars of which are as follows :-

1	Cost of Repair	:S\$	1,284.00
2	Loss of Use (1 days X \$ 120.00)	:S\$	120.00
3	LTA Fees	:S\$	7.45
TOTAL AMOUNTS		:S\$	1,411.45

We enclosed a list of the supporting documents :-

- (a) Original Final Repair Bill
- (b) LTA Tax Invoice
- (c) GIA / Police Report lodged by Our Client
- (d) Letter of Authority

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly
appreciated.

**Any settlement reached is strictly without prejudice to and shall not affect any other claims arising
from this accident. Settlement is solely for the items claimed only.**

Yours Faithfully,
VFIX AUTO SERVICE PTE LTD




Kelvin Poh

To: INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Dear Sir / Madam,

Claimant:

ACCIDENT INVOLVING SLG 666A AND SAC 845 X ON 07/02/18 AT
CAVENAGH RD TRANS ORCHARD RD

I/We, XIANG NEI LIN, am/are the registered owner of
motor car no. SLG 666A.

Please be informed that I have assigned all compensation monies due to me/us in the above
accident to VFIX AUTO SERVICE PTE LTD.

I/We hereby authorized you to release all monies pertaining to the above mentioned accident
to VFIX AUTO SERVICE PTE LTD and forward the settlement cheque to VFIX AUTO SERVICE PTE
LTD whom I/we have authorized to collect the said compensation monies.

Thank you,

Signature of Claimant &
Company Stamp if applicable

IC no.: G0425668P

Date: 05/04/2018

Signature of Witness

IC no.: S1527552 I

Date: 05/04/18

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18020225
Claimant Ref: SLG 666A

We/I, VFIX AUTO SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 1,284.00 (repair cost), S\$ 120.00 (loss of use/rental), S\$ 7.45 (search fee), vehicle no. SLG 666A that was damaged pursuant to the accident which occurred on 07/02/2018 (date) at CAVENAGH RD TWOS ORCHARD RD (location) involving vehicle no. SHC 8485X (insured vehicle). This is pursuant to the inspection conducted on 13/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner XIANG MEI LIN ("the third party claimant") of vehicle no. SLG 666A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLG 666A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,411.45 to VFIX AUTO SERVICE PTE LTD

Dated this 9 day of APRIL 2019

CLAIMANT:

Signature:


Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by "the workshop" (with chop)

Joanne Leng

S7781159A

60 KAKI BANCIT AVE 6

ARK@KBS (S) 417892

Malaysian

Admin.



WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



CKS

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933



Vfix Auto Service Pte Ltd

60 Kaki Bukit Ave 6

Ark@KB Singapore 417892

Email: vfixauto@gmail.com

Tel: 64489268 Fax: 64452368

Co Reg. No: 201602964H

GST Reg No: 201602964H

INDIA INT'L INS PTE LTD

64 CECIL STREET

#05-01 IOB BUILDING

SINGAPORE 049711

FINAL REPAIR BILL

DATE : 05/04/2018

VEHICLE NO : SLG666A

MAKE/MODEL : JAGUAR XJ

ACC DATE : 07/02/2018

CLAIM NO : VFIX-TP2018042

POLICY NO :

AMOUNT S\$

LUMP SUM REPAIR COST

Repair Amount	1,200.00
7% GST	84.00
Total	<u><u>1,284.00</u></u>

SINGAPORE DOLLARS : ONE THOUSAND TWO HUNDRED
& EIGHTY FOUR ONLY

VFIX AUTO SERVICE PTE LTD



Kelvin Poh

Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

SLG 666 A

Print Date/Time : 07 Feb 2018 / 14:09:58

Receipt Date/Time : 07 Feb 2018 / 14:09:47

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180207-001026

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHC8485X

As at 07 Feb 2018/08:25:00

Insurance Co: INDIA INT'L INS PTE LTD

1 Insurance Enquiry - SHC8485X

Enquiry Fee

20180207140904483967

7.00	0.49	7.49
------	------	------

Sub-Total

7.00	0.49	7.49
------	------	------

Total Before Rounding

7.00	0.49	7.49
------	------	------

Rounding Difference

		0.04
--	--	------

Total Amount Payable

		7.45
--	--	------

Paid By

XXXXXXXXXXXX8539

Credit Card: Visa
/MasterCard

		7.45
--	--	------

Total

		7.45
--	--	------

Cash Change

		0.00
--	--	------

Tendered Amount

		7.45
--	--	------

Excess Refundable Amount

		0.00
--	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement










CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018 Edit Reg		12 Feb 2018 00:00 Edit Adj Rpt	\$51,200.00 Edit Estimates	\$51,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	XIANG MEI LIN , ID: G0425668P								
Vehicle Reg. No.:	SLG666A	Date of Loss:	07/02/2018 00:00 - :59 [80 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18020225	Policy/Cover Note No.:	MCDM0015						
Vehicle Reg. No. (Insured):	SHC8485X	Policy No. (Claimant):	GA181989						
		Excess:							
Repairer:	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 64552957								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (18/04/2018): Alert - Adj Mandate Approved (\$1411.45) - SLG666A - Claim Handler: Priya III_SG (28/02/2018): Alert - Adj Mandate Approved (\$0.00) - SLG666A - Claim Handler: Priya 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG666A (MCT18020225)
[SHC8485X]
TP
XIANG MEI LIN
Feb 7 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Vfix Auto Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/04/18 13:53	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/18 15:00	ACKNOWLEDGEMENT EMAIL TO III DO 12.02.2018	 Load PDF	
2	13/02/18 15:00	NOTIFICATION FROM WORKSHOP	 Load PDF	
3	19/02/18 13:44	TP GIA REPORT	 Load PDF	
4	19/02/18 13:44	TP ESTIMATE- MARKED	 Load PDF	
5	27/04/18 09:10	WORKSHOP INVOICE	 Load PDF	
6	27/04/18 09:10	AUTHORISATION TO ACT FORM	 Load PDF	
7	27/04/18 09:10	DISCHARGE VOUCHER	 Load PDF	
8	27/04/18 09:10	LTA SEARCH	 Load PDF	
9	27/04/18 09:10	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	14/02/18 08:43	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18002893/UEB3Q2

Date: 27/04/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SLG666A Insured Vehicle No: SHC8485X
 Date of Loss: 07/02/2018 Nature of Claim: TP Claim No: MCT18020225

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG666A**
 Make & Model: JAGUAR XJ, 5.0 (A) Engine No: 10111823514508PN
 Reg. Date: 19/05/2011 (Man. Year: 2010) Chassis No: SAJAC22F4BLV15997
 Colour: White Odometer: 61922 km
 Engine Capacity: 5000 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35Z R20 Rear Tyre Size: 285/30Z R20
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,298.00	1,000.00	6,298.00	86.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	500.00	1,600.00	76.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,398.00	1,500.00	7,898.00	84.04
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	9,398.00	1,200.00	8,198.00	87.23
+ GST 7.00/7.00% (S\$)	657.86	84.00	573.86	87.23
Nett Amount (S\$)	10,055.86	1,284.00	8,771.86	87.23
+ Loss of Use (1.0 x S\$120.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,411.45		

INSPECTION

Date of Assignment: 12/02/2018
 Date Inspected: 13/02/2018 Inspected At: Vfix Auto Service Pte Ltd (HQ)
 60 Kaki Bukit Ave 6, ARK@KB
 Singapore 417892

Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2018)
Parts: 143	JAGUAR XJ 5.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG666A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SHOCK ABSORBER LH	Not Necessary	3,520.00 F	*- F
2	1		*FRONT WHEEL KNUCKLE LH	Not Necessary	1,253.00 F	*- F
3	1		*FRONT LOWER ARM LH	Not Necessary	985.00 F	*- F
4	1		*SPORT RIM	Dented / Bent	1,540.00 FS	*1,000.00 FS
					Total Parts (S\$)	7,298.00 1,000.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED BODY PANELS WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY	New	1,000.00	200.00
2	TO SPRAY PAINT REPLACED /REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	1,000.00	200.00
3	TO CONDUCT FRONT WHEEL ALIGNMENT	New	100.00	100.00
Gross Labour Cost (S\$)			2,100.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >