

22/02/2018

ASS. REC. BY:

REF: CS3/EG1/8002895/Gd362

range 2 days

Special Instruction:

Surveyor:

## ASSIGNMENT (Office)

From (Person):

Yee per Li

of

EGI

Date/Time:

13/2/18 @ 10:45am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKQ 23464

Insured:

YM510E

at Workshop m/s

Wee Hoe Auto

Tel:

6858 0019

of

19 Kim Chuan Terrace

Policy No:

Claim No:

DSMCLV1800273

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/02/2018

CA / REV / REP. / REV 24 HRS

Wp/

14/02/2018

H.O.D. Endorsement:

Date/Time:

12:02pm @ 13/2/18

Person Contacted:

Mr. Lee

Vehicle:

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKQ 23464 - NA/INC18002526/24

D.O.A: 6/2/18

YM510E - NA/INC18002526/24

D.O.A: 6/2/18

After repair: 14/2/2018

PRS *YHL*

REF: EGI

ASSIGNMENT

From: \_\_\_\_\_ Date: **14/02/2018**  
Estimated Cost: \_\_\_\_\_  
OD: ☒ TP WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV  
To inspect Vehicle No: **SKQ 23464**  
at Workshop this: **Wee Hoe Auto**  
of: **19 Kim Chuan Terrace**  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

NS	O/S

Est. of Market Value: \_\_\_\_\_  
IDAO Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
Lum Sum: \_\_\_\_\_ % S'Val: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SKQ 23464** In Regn: **2008 Oct 28**  
Type: ☒ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or  
Make: **Toyota wish** DO: **1794**  
Colour: **Silver** A/C: ☐ Insured: ☐ Std / ☐ NI / ☐ NA  
Sp Reading: **236654** T-Radio: ☐ Insured: ☐ Std / ☐ NI / ☐ NA  
Eng No: \_\_\_\_\_  
C No: **JTDER-12W503000822**  
Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt  
Steering: ☒ In / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
Brake: ☒ In / ☐ Jammed / ☐ Leaked / ☐ Burnt or  
Mod: ☐ Nil / ☐ S/Rim / ☒ STD / ☐ Air / ☐ Sum or  
Tyre Size: F: **195/65 R15**  
R: **11**  
BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R.Bal: **6** mm R.Bal: **6** mm  
L.Bal: **6** mm L.Bal: **6** mm  
D.O.A: \_\_\_\_\_ D.O.A: **14-02-18**  
Survey held at: **W/S** **11:30 Am**  
Des. of Damages: **o/s Rear**  
The UIC / Chassis frame / Body Structure affected due to collision.

Date Time Action / Instruction  
**\* Repair Estimate : S\$ 3000 - 4000**  
**\* 3 days**  
RECEIVED 16 MAY 2018

Date/Time File Pass to: ☐ : Prelim. Report  
Date/Time File Return to: ☐ : Final Report  
Days Of Repair: **3**  
Resurvey No. of Trip: **1**  
Add Fee: ☐ Site Visit \$  
☐ Night \$  
☐ Tech. Fee \$  
☐ Reg. Fee \$  
Survey Fee: **50**  
Transportation: **50**  
Photos: **5**  
Other: **100**  
Report Format: **PRS**  
Lum Sum / L.Bal: \_\_\_\_\_

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS3/EGI18002895/Gd3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 13-02-2018



Code : EGI

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

Insured Veh.	YM 510E	Veh. Inspected	SKQ 2346U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	13/02/2018

**2. Vehicle Particulars & Condition**

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--

**5. General Information**

Accident Date	06/02/2018	Inspection Date
Survey held at	WEE HOE AUTO SERVICE 19 KIM CHUAN TERRACE SINGAPORE 537041	

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**Nivitha (LKK Auto)**

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Tuesday, 13 February 2018 10:45 AM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : YM510E / TP : SKQ2346U/LKK / DOA : 06/02/2018 (DSMCV1800273)  
**Attachments:** YM510E - SAS.pdf; SKQ2346U - SAS.pdf; SKQ2346U - PRI NOTICE.pdf

Dear Catherine,

We have rejected to their PRS list, please assist to conduct this survey VISION LAW LLC,

ADDRESS : **WEE HOE AUTO SERVICE**  
19 KIM CHUAN TERRACE  
SINGAPORE 537041

PERSON TO CONTACT : KIAT @ 6858 0019

ERGO OFFICER-IN-CHARGE : ROHAINI

***Note: To survey on without prejudice basis. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please update the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are insured and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

**Kindly acknowledge receipt of this email.**

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
ONG BOCK KEE  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
TAN YINGXIAN SELWYN

Company Registration No. 200721148H

 **Head Office:**  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
**Branch:**  
490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## HEAD OFFICE:

TEL : 65342811 (Hunting)  
FAX : 65356802 (General)

 E-MAIL: [annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)

## BRANCH

TEL : 63580703  
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-W30-SKQ2346U-2017 - [please reply to: annatan@visionlawllc.com](mailto:annatan@visionlawllc.com)  
YOUR REF: YM510E

13 February 2018

## ERGO INSURANCE PTE LTD

5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

Attn: Motor Claims Department

## BY FAX 6829 9247 & EMAIL

[claims@ergo.com.sg](mailto:claims@ergo.com.sg)

Dear Sirs

NAME OF CLAIMANT: AUTOHOME TRADING

VEHICLE NUMBER: SKQ 2346 U

YOUR INSURED VEHICLE NUMBER: YM 510 E

ACCIDENT ALONG WOODLANDS AVE 9 BEFORE JUNCTION WOODLANDS AVE 2 ON 6  
FEB 2018 AT ABOUT 1050HOURS

We refer to your email dated 13 February 2018 wherein there is no agreement to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

**WEE HOE AUTO SERVICE**  
19 KIM CHUAN TERRACE  
SINGAPORE 537041  
TEL: 6858-0019 (KIAT)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



(Head Office)

cc. **SKQ 2346 U** - By fax 6858-0195 only

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature) :

Date & Time of Inspection :

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

[> Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SKQ2346U		
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	WISH 1.8 AUTO		
Chassis No. :	JTDER12W503000822		
Propellant :	Petrol		
Engine No. :	1ZZ3144059		
Engine Capacity :	1794 cc		
Maximum Power Output :	97.0 kW ( 130 bhp )		
Maximum Laden Weight :	1885 kg		
Unladen Weight :	1310 kg		
Year Of Manufacture :	2008		
Original Registration Date :	28 Oct 2008		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
Quota Premium :	\$14,400.00		
COE Expiry Date :	27 Oct 2018		
Road Tax Expiry Date :	27 Oct 2018		
PARF Eligibility Expiry Date :	27 Oct 2018		
Inspection Due Date :	27 Apr 2019		
Intended Transfer Date :	16 May 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	7128L
<b>Vehicle Details</b>	
Vehicle No.:	SKQ2346U
Vehicle to be Exported:	No
Intended De-registration Date:	16 May 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1ZZ3144059
Chassis No.:	JTDER12W503000822
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,803.00
Original Registration Date:	28 Oct 2008
First Registration Date:	28 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$18,803.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Oct 2018
PARF Rebate Amount:	\$9,401.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Oct 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$14,400.00
COE Rebate Amount:	\$642.00
<b>Total Rebate Amount:</b>	<b>\$10,043.00</b>

The information contained herein is correct as at 16 May 2018

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/02/2018 19:16
Date Of Accident	06/02/2018 10:50
Exact Location Of Accident	WOODLANDS AVE 9 BEFORE JUNC WOODLANDS AVE 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ2346U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AUTOHOME TRADING
Co Reg No	52827128L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90088701
Alternative Phone No	OFFICE-90088701

### Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH 1.8 AUTO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	5083939856-01
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD FARID BIN SARIP
NRIC No	S9002493J
Date Of Birth	22/01/1990
Occupation	OUTDOOR
Date Of Driving Pass	27/03/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97921842
Fax Number	
Contact Number	OFFICE-97921842
EMail Address	NOEMAIL



Address	BLK 879 YISHUN STREET 81 #03-249
Postcode	760879
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20180206/7007.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM510E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

## Accident Sketch Plan

SKQ 2346U\_SKETCH PLAN0001.jpg

7/2/14 5:22 pm

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **revoke policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and/or make such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the internal cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and at future claims;
  - (e) the information as notified under (a) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
    - (ii) complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:

about:blank

Page 1 of 1

## SNQ 2346U\_SKETCH PLAN0002.jpg

7/2/16 9:22 pm

### SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

800m 21. 2011. 09. 04. - 7/2018024, 7227

## DECLARATION

 Continuing education is true in every respect.



\_\_\_\_\_  
Date: \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Representative's Signature  
Name:  
Title:

**about:blank**

Page 1 of 1

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20180206/7007

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20180206/7007

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/02/2018 12:12		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: MUHAMMAD FARID BIN SARIP			Address: APT BLK 751 WOODLANDS CIRCLE #01-590 SINGAPORE 730751		
ID Type / ID No.: NRIC NO / S9002493J			Contact No.: Home/Office: Mobile: 97921842		
Nationality: SINGAPORE CITIZEN			Email: farid_dila@hotmail.com		
Sex: Male	Age: 28	Date of Birth: 22/01/1990	Type of Informant: Driver		
Race: Javanese			Language: English		Institution / School Name:
Occupation: Other car and light goods vehicle drivers nec			Driving Licence Information: Class: 3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 06/02/2018 10:50	Type of Location: Straight Road
Location:  WOODLANDS AVENUE 9  BEFORE TRAFFIC JUNCTION OPPOSITE REPUBLIC POLYTECHNIC				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 60 Km/h
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Persons
SKQ2346U	Car	TOYOTA	WISH	Grey	Slightly Damaged	1

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20180206/7007

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3  
Report No: T/20180206/7007

## CONTINUATION OF REPORT

Driver			
Name	MUHAMMAD FARID BIN SARIP	ID No.	S9002493J
Related Vehicle	SKQ2346U (Car)	Contact No.	97921842
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

JUST PICK UP A PASSANGER FROM 844 WOODLAND AVE 4 .WHILE IM DRIVING AT WOODLAND AVE 9 GOING STRAIGHT WHEN A LORRY(YM510E) SUDDENTLY CHANGE LANE AND HIT MY RIGHT REAR SIDE.DRIVER STOP AWHILE TO MAKE A PHONE CALL AND TOOK PHOTO THEN DRIVE OFF.DRIVER REFUSE TO EXCHANGE PATICULAR WHEN ASK TO.

Police Report



**SINGAPORE  
POLICE FORCE**



T/20180206/7007

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20180206/7007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
06/02/2018 12:12

Classification Of Case:




**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT				
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18002895/Gd3e2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 17-05-2018		
FIVE SINGAPORE 038985		Code: EGI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	YM 510E	Veh. Inspected	SKQ 2346U	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1800273	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	13/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA WISH	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JTDER12W503000822	Colour	SILVER	
Odometer	236654 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
<b>5. General Information</b>				
Accident Date	06/02/2018	Inspect Date / Time	14/02/2018 ( 11:30 AM )	
Survey held at	WEE HOE AUTO SERVICE 19 KIM CHUAN TERRACE SINGAPORE 537041			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	

Report Ref No. CS3/EGI18002895/Gd3e2

**Inspected By**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.