

ASS. REC. BY:

REF: CS3/AIG/8002898/Sd321

Special Instruction:

DAR & days

mfg m

Surveyor: Subashan

ASSIGNMENT (Office)

From (Person): Md. Ishak

of

AIGDate/Time: 13/2/18 @ 11:43am

Estimated Cost:

Bill to:

OD ☒ TP ☐ WS ☐ TP RES / OD RES / EVA / INV / MV ☐ CS

To Inspect Vehicle No:

FBC 5146R

Insured:

SLS 7104X

at Workshop m/s

Brothers Motor

Tel:

9643 2546

of

Bik 1016 Yishun Ind. Prk A #01-218

Policy No:

Claim No:

0855467075SG003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/01/2018

CA / REV / REP. / REV 24 HRS

wp14/02/2018

H.O.D. Endorsement:

Date/Time:

1:06pm @ 13/2/18

Person Contacted:

Mr. TatVehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	<u>FBC 5146R - CS/INC/30.205.20/Hlgm 3k3</u>
	<u>SLS 7104X - X</u>
	<u>After repair: 12/3/2018</u>

D.O.A.: 2/7/2013

ASSIGNMENT

From: _____ Date: **14/02/18**

Estimated Cost: _____

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FBC 5146R

at Workshop rms:

Brothers Motorof **Blk 1016, Yishun Ind. Prk A #01-218**

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Mr. Tat @ 96432540

Make of Veh.:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Sal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

QIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lum Sum:

3

Valid:

Yes or No

CA / REV / REP. / 24 HRS **wp**

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: **FBC 5146R** Reg No: **16/4/2008**

Type: M/Car / M/Truck / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Yamaha X-1RCC: **135**

Colour:

Red / White

A/C

Insured

Std / NI / NA

Sp Reading:

405537

T-Radio: Insured / Std / NI / NA

Eng No:

S No:

455201593Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: In ☒ Out / Jammed / Leaked / Burnt orBrake: In ☒ Out / Jammed / Leaked / Burnt or

Mod:

NO S/Rim / STD A/Rim or

Tyre Size:

F: 70/90-17R: **"**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Dunlop

Front:

Rear:

R.Bal:

6

mm

R.Bal:

6

mm

L.Bal:

6

mm

L.Bal:

6

mm

D.O.A.

27/1/18

D.O.A.

14/2/18

Survey held at:

Brother MotorDes. of Damages: ☒ Front / ☒ Rear / ☒ OS / ☒ US / U/C / Roof top or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 18 APR 2018

Date/Time: File Pass to:

☐ : Preli. Report
☐ : Final Report
Days Of Repair: **4**

Date/Time: File Return to:

Resurvey No. of Trip:

Survey Fee

180

Transportation

Fuel

Food

Other

20**200**

Report Format:

DAR

Lum Sum / I.B. / I.S.

Add Fee:

Steered: \$

Interfered: \$

Towed: \$

Reserved: \$

-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS7104X AND FBC5146R ON 29/01/2018

From: Md Ishak, Mohd Imran
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Lim, Sheng Yang, Chan, Yoke Shi, Supramaniam, Darshene, Abu Kassim, Noor Mariesa, Fan, Winnie-LW
Sent: 13/2/2018 11:43:36 AM
Attachments: 0155-12022018095558.pdf

WITHOUT PREJUDICE

Hi,

Please refer to the enclosed request from **Centro-Legal Law Corporation**

Claim no : 0855467075SG003
Case Owner : NORSIAH MD NOOR

If you have any queries/concerns, please let us know.
Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: ling@centrolc.com.sg
To: Imran.Ishak@aig.com
Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, ShengYang.Lim@aig.com, yokeshi.chan@aig.com, Darshene.Supramaniam@aig.com, NoorMariesa.AbuKassim@aig.com
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS7104X AND FBC5146R ON 29/01/2018
Date: Tue, 13 Feb 2018 03:34:13 +0000
Dear Sirs,

We refer to the above matter.

Confirm.

Thank you and have a nice day.

Best Regards,

MR LING

Centro-Legal Law Corporation
151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939
H/P: 96628304

From: Md Ishak, Mohd Imran [mailto:Imran.Ishak@aig.com]
Sent: Tuesday, 13 February 2018 10:38 AM
To: ling@centrolc.com.sg
Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS7104X AND FBC5146R ON 29/01/2018

REMINDER

Dear Sir

Please confirm that you are nominating Kenneth Kong named in the list of surveyors to conduct the pre-repair survey and appointed as the Single Joint Expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

From: Md Ishak, Mohd Imran

Sent: Monday, February 12, 2018 4:37 PM

To: 'ling@centrolc.com.sg'

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Chan, Yoke Shi; Supramaniam, Darshene; Abu Kassim, Noor Mariesa

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS7104X AND FBC5146R ON 29/01/2018

Dear Sir

Please confirm that you are nominating Kenneth Kong named in the list of surveyors to conduct the pre-repair survey and appointed as the Single Joint Expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

From: ling@centrolc.com.sg [<mailto:ling@centrolc.com.sg>]

Sent: Monday, February 12, 2018 11:37 AM

To: Md Ishak, Mohd Imran

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Chan, Yoke Shi; Supramaniam, Darshene; Abu Kassim, Noor Mariesa

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS7104X AND FBC5146R ON 29/01/2018

Dear Sirs,

We refer to the above matter.

We choose:

Kenneth Kong (LKK Auto Consultants Pte Ltd)

Kindly arrange with Mr Tat 9643 2540 before going to workshop.

Thank you and have a nice day.

Best Regards,

MR LING

Centro-Legal Law Corporation
151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876

Tel: 6235 0633
Fax: 6235 6939
H/P: 96628304

From: Md Ishak, Mohd Imran [mailto:imran.ishak@aig.com]

Sent: Monday, 12 February 2018 11:23 AM

To: ling <ling@centrolc.com.sg>

Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Supramaniam, Darshene <Darshene.Supramaniam@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLS7104X AND FBC5146R ON 29/01/2018

WITHOUT PREJUDICE

Your Reference : CLLC.0155.2018LI
Our Reference : 0855467075SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOI, SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

-----Original Message-----

From: ling@centrollc.com.sg [mailto:ling@centrollc.com.sg]

Sent: Monday, February 12, 2018 10:00 AM

To: Lim, Sheng Yang; Chan, Yoke Shi

Subject: PRE-REPAIR INSPECTION - OUR REF: CLLC.0155.2018 - YOUR REF: SLS7104X

Dear Sirs,

Kindly refer to the attachment.

Thank you and have a nice day.

Best Regards,

MR LING

Centro-Legal Law Corporation

151 Chin Swee Road

#02-21 Manhattan House

Singapore 169876

Tel: 6235 0633

Fax: 6235 6939

H/P: 96628304

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

Your ref : SLS7104X
Our ref : CLLC.0155.2018 LI

12 February 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way #07-16 AIG Building
Singapore 079120
Fax: 6835 7416

BY FAX & EMAIL

Attn: **Officer-In-Charge**
Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF RE-ACTION PROTOCOL
FOR NIMA CASE**

We act for MUHAMMAD NUR ARIFF, the owner of motor vehicle **FBC5146R**, who has appointed us to act on his behalf to claim against your insured's vehicle no SLS7104X in regards to the road traffic accident on 29.01.2018

Please be informed that the said motor vehicle can be inspected at:-

BROTHERS MOTOR
Blk 1016 Yishun Industrial Park A
#01-218 Singapore 768758
Tel: 9643 2540 | Fax: 6754 2558
Email: brothermotors@live.com.sg

Kindly contact: **Mr Tat Tel: 9643 2540**

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

CENTRO-LEGAL LAW CORPORATION
Cc **Mr Tat**
FAX NO: 6754 2558

UEN NO.201302032G

CENTRO-LEGAL LAW CORPORATION is incorporated as a company in Singapore



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CS3/AIG18002898/Sd3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 13-02-2018	
			Code : AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLS 7104X	Veh. Inspected	FBC 5146R	
Policy No.		Coverage (\$)	0.00	
Claim No.	0855467075SG003	Excess (\$)	0.00	
Assign From	MD ISHAK MD IMRAN	Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/01/2018	Inspection Date		
Survey held at	BROTHER MOTORS BLK 1016 YISHUN INDUSTRIAL PARK A #01-218 SINGAPORE 768758			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3884Z
Vehicle Details	
Vehicle No.:	FBC5146R
Vehicle to be Exported:	No
Intended De-registration Date:	19 Feb 2018
Vehicle Make:	YAMAHA
Vehicle Model:	X-1R
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	4S3201593
Chassis No.:	4S3201593
Maximum Power Output:	-
Open Market Value:	\$1,952.00
Original Registration Date:	16 Apr 2008
First Registration Date:	16 Apr 2008
Transfer Count:	4
Actual ARF Paid:	\$293.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	31 Jan 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$5,910.00
COE Rebate Amount:	\$5,879.00
Total Rebate Amount:	\$5,879.00

The information contained herein is correct as at 19 Feb 2018

OK

MSI11802067# / STA INSPECTION PTE LTD - Sin Ming
ENTRY DATE & TIME: 10/02/2018 15:59
SUBMITTED BY: Wong Lip Yang

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 10/02/2018 16:07

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/02/2018 15:59
Date Of Accident 29/01/2018 16:15
Exact Location Of Accident ALONG WOODLANDS RING ROAD JUNCTION TO DR 42
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Insured/Policyholder

Name of Registered Owner

NRIC No

Email Address

Mobile Phone No

Alternative Phone No

Vehicle Particulars

Manufacturer

Model

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage THIRD PARTY

Fleet Policy NO

Policy Number MSD/MT/17-372528-CA

Cover Note Number

Driver

Name of Driver MUHAMMAD NUR ARIFF BIN ZAILAN

NRIC No S9523884Z

Date Of Birth 07/07/1995

Occupation OUTDOOR

Date Of Driving Pass 27/06/2016

Driving Experience 1 YEAR AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90912844

Fax Number

Contact Number OTHERS-90912844

Email Address ARIFFZAILAN@GMAIL.COM

Address BLK 664 WOODLANDS RING ROAD #08-196
SINGAPORE
Postcode 730664
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name WOODLANDS WEST NPC
Police Station Address ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLS7104X
Vehicle Make/Model/Colour
Details Of Properties PRIVATE CAR
Vehicle Category
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

Accident Sketch Plan Pg. 1

**SINGAPORE
POLICE FORCE**

T/20180206/2189

2 of 3

Police Station Of Origin:
Woodlands West N.P.C.
9 Marsiling Lane SINGAPORE 739146
Tel No: 1800-363 9999

Report No. T/20180206/2189

CONTINUATION OF REPORT

Brief Details.


On 04/02/2018 at about 1719hrs, my son namely, Muhammad Nur Ariff Bin Zailan, S9523884Z, already lodged police report online vide report F/20180204/7019 with in-charge case TP IO Wong Sieu Lui, Tel: 65476151. However, after report was confirmed. My son realized that he would like to make amendments as followed:

The said car did not give way or signal to indicate that he was going to turn into the junction.

I wish to state that my son was conveyed to KTPH conscious and was admitted from 29/01/2018 to 02/02/2018. He was then given 28 days of MC from 29/01/2018 to 23/02/2018. I am lodging this report on behalf of my son as he was still injured and unable to proceed to Police Station to make the above mentioned amendments.

Sketch Plan #2 Pg. 1

SKETCH PLAN



Refer Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SIAMC SketchPlanForm_v3

Melospiza sp. 1c

NAC	INC	Item	CON	AC	Qty
10007	991326	Front Fumber Plate			
10001	995065	Front Tyre			
10002	995095	Front Rim			
10003	994272	Front Tyre Rim Spoke			
10004	991771	Front Fender Wheel Guard	CUT	✓	
10005	991283	Front Brake Disc			
10006	991281	Front Brake Caliper			
10007	991785	Front Fork Assy			
10008	991787	Front Fork Inner Tube			
10009	991789	Front Fork Outer Tube			
10010	991167	Front Fork Bracket			
10011	991132	Front Fork Oil Seal			
10012	991174	Front Fork Garnish			
10013	992376	Front Headlamp Rim			
10014	992328	Front Headlamp	DM	✓	
10015	992337	Front Headlamp Bracket	SR	✓	
10016	992345	Front Headlamp Fairing			
10017	992130	Front Windshield	SCR	✓	
10018	992134	Front Wing Mirror	BR	✓	
10019	995245	Front LH Signal Lamp	SCR	✓	
10020	995246	Front RH Signal Lamp			
10021	992556	Meter Casing	BR	✓	
10022	992553	Meter Assy			
10023	991019	ERP Bracket	DD	✓	
10024	991020	ERP Unit	CUT	✓	
10025	992446	Ignition Switch			
10026	992442	Ignition Key Assy			
10027	990706	Cowling Stay			
10028	994470	Steering Stem			
10029	994427	Steering Cone			
10030	992299	Handle Bar			
10031	992312	Handle Bar Switch			
10032	992310	Handle Bar Grip	CUT	✓	
10033	995184	Handle Bar Balancer LH	MS	✓	
10034	992300	Handle Bar Balancer RH	MS	✓	
10035	992179	Fuel Tank			
10036	990438	Brake Reservoir			
10037	990621	Clutch Lever	CUT	✓	
10038	992293	Hand Brake Lever	CUT	✓	
10039	991119	Side Fairing	CUT	✓	
10040	994220	Side Fairing Top Garnish			
10041	994219	Side Fairing Inner Garnish			
10042	991118	Fairing Shield	BR	✓	
10043	992047	Front Top Fairing Inner Garnish			
10044	991173	Fairing Top Garnish			
10045	990538	Center Fairing	BR	✓	
10046	993378	Rear Fairing	CUT	✓	
10047	991121	Fairing Stopper			
10048	991117	Fairing + Rear Guard	DM	✓	

Vehicle No: FBC 5146 R

NAC	INC	Item	CO	AC	Qty
3043	992738	Radiator	DM	✓	
3046	994146	Radiator Cowling			
3047	990915	Seat Assy			
3048	990928	Engine Crank Bar			
3049	990219	Engine Guard	CUT	✓	
3050	990224	Battery			
3051	990224	Battery Cover			
3052	990224	Battery Bracket			
3053	991144	Foot Brake	BR	✓	
3054	991154	Front Foot Rest	DM	✓	
3055	991779	Front Foot Rest Bracket	DD	✓	
3056	994269	Side Stand	DD	✓	
3057	992549	Main Stand			
3058	990615	Clutch Engine Cover			
3059	992478	Kick Starter Rubber	CUT	✓	
3060	992477	Kick Starter Lever			
3061	991145	Foot Gear Shifter			
3062	993500	Rear Foot Rest	DM	✓	
3063	993501	Rear Foot Rest Bracket			
3064	992581	Exhaust Muffler Heat Shield	CUT	✓	
3065	991058	Exhaust Muffler Assy			
3066	993719	Rear LH Shock Absorber			
3067	993720	Rear RH Shock Absorber			
3068	995065	Rear Tyre			
3069	991200	Rear Rim			
3070	994872	Rear Tyre Rim Spoke			
3071	993474	Rear Fender Wheel Guard			
3072	993443	Rear Fender Mudflap			
3073	992940	Rear Brake Disc			
3074	992936	Rear Brake Caliper			
3075	995236	Rear Spocket			
3076	990585	Chain			
3077	990580	Chain Guard			
3078	994530	Swing Arm			
3079	993819	Rear Sub frame			
3080	995245	Rear LH Signal Lamp			
3081	995246	Rear RH Signal Lamp			
3082	995251	Rear Taillamp			
3083	993626	Rear Number Plate			
3084	994192	Side Box			
3085	992927	Rear Box Front Box	BR	✓	
3086	992928	Rear Box Bracket Front Box	DD	✓	
3087	991328	Emblem			
3088	990247	Sticker			

* 4 days

* 4 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 Edit Reg		13 Feb 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	GOH PEI SHAN (WU PEISHAN), Co. Reg. No.: -		
Main Claimant:	MUHAMMAD NUR ARIF		
Vehicle Reg. No.:	FBC5146R	Date of Loss:	29/01/2018 00:00 - :59 [117 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0855467075SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLS7104X	Policy No. (Claimant):	
		Excess:	
Repairer:	Brother Motors (HQ) BLK 1016 YISHUN INDUSTRIAL PARK A, #01-218, 768758 Yishun - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 12/04/2018]		
Claimant's Solicitor:	CENTRO-LEGAL LAW CORPORATION - Tel: 6235 0633		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (04/04/2018): TP GIA REPORT







































ALL ASSOCIATED TASKS











[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)





















Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBC5146R (0855467075SG)
[SLS7104X]
TP
MUHAMMAD NUR ARIF
Jan 29 2018 12:00AM
[GOH PEI SHAN (WU PEISHAN)]
Brother Motors

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
												Load JPG	<input checked="" type="checkbox"/>	
1	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
2	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
3	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
4	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
5	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
6	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
7	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
8	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
9	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
10	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
11	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
12	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
13	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
14	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
15	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
16	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
17	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
18	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
19	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
20	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
21	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
22	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
23	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
24	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
25	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
26	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
27	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
28	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
29	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
30	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
31	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
32	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
33	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
34	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
35	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
36	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>
37	03/04/18 17:42	General View											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
39	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
40	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
41	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
42	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
43	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
44	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
45	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
46	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
47	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
48	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
49	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
50	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
51	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
52	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
53	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
54	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
55	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
56	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
57	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
63	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
64	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
65	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
66	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
67	03/04/18 17:42	General View	 Load JPG	<input checked="" type="checkbox"/>
68	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
84	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	18/04/18 18:02	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/04/18 12:34	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18002898/SD3E2

Date: 20/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBC5146R

Insured Vehicle No : SLS7104X

Date of Loss: 29/01/2018

Nature of Claim:

TP

Claim No: 0855467075SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBC5146R

Make & Model: YAMAHA X-1R, 135cc (M)

Engine No: 4S3201593

Reg. Date: 16/04/2008 (Man. Year: 2007)

Chassis No: 4S3201593

Colour: Red/White

Odometer: 405537 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size:

70/90-17

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/02/2018

Date Inspected: 14/02/2018 Inspected At:

Brother Motors (HQ)

BLK 1016 YISHUN INDUSTRIAL PARK A,

#01-218

Singapore 768758

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT HEADLAMP	Damaged	0.00 F	*- F
3	1		*FRONT HEADLAMP BRACKET	Broken	0.00 F	*- F
4	1		*FRONT WINDSHIELD	Scratched	0.00 F	*- F
5	1		*FRONT WING MIRROR	Broken	0.00 F	*- F
6	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
7	1		*METER CASING	Broken	0.00 F	*- F
8	1		*ERP BRACKET	Dented	0.00 F	*- F
9	1		*ERP UNIT	Cut	0.00 F	*- F
10	1		*HANDLE BAR GRIP	Cut	0.00 F	*- F
11	1		*HANDLE BAR BALANCER LH	Missing	0.00 F	*- F
12	1		*HANDLE BAR BALANCER RH	Missing	0.00 F	*- F
13	1		*CLUTCH LEVER	Cut	0.00 F	*- F
14	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
15	1		*SIDE FAIRING	Cut	0.00 F	*- F
16	1		*FAIRING SHIELD	Broken	0.00 F	*- F
17	1		*CENTER FAIRING	Broken	0.00 F	*- F
18	1		*REAR FAIRING	Cut	0.00 F	*- F
19	1		*FAIRING REAR GUARD	Damaged	0.00 F	*- F
20	1		*RADIATOR	Damaged	0.00 F	*- F
21	1		*ENGINE GUARD	Cut	0.00 F	*- F
22	1		*FOOT BRAKE	Broken	0.00 F	*- F
23	1		*FRONT FOOT REST	Damaged	0.00 F	*- F
24	1		*FRONT FOOT REST BRACKET	Dented	0.00 F	*- F
25	1		*SIDE STAND	Dented	0.00 F	*- F
26	1		*KICK STARTER RUBBER	Cut	0.00 F	*- F
27	1		*REAR FOOT REST	Damaged	0.00 F	*- F
28	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
29	1		*FRONT BOX	Broken	0.00 F	*- F
30	1		*FRONT BOX BRACKET	Dented	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >