

ASS. REC. BY:

REF: CS3 / CT218002902 / Wbez

Special Instructions:

Range & days

Surveyor: Wilson

ASSIGNMENT (Office)

From (Person): Ange Foo of CT Date/Time: 12022018 2:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: 96V 7016K Insured:at Workshop m/s Hup Lek Automobile Tel: 9660 1347of 160 Sin Ming Drive # 05-17Policy No: DMCVSN3071461701 Claim No: SNM18D00767 (02)

Sum Insured: Excess:

Make of Veh: D.O.A.
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time: 13-02-2018 12:13pm Person Contacted: Han Wei Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>96V 7016K - X</u>
	<u>Resurvey Dismantling - 21/02/18</u>
	<u>Resurvey After Repair - 27/02/18</u>

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

ST-V 7016K

Yr Regn:

25/6/2007.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

C.C.

1595

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading:

101500

T/Radio:

Insured / Std / NI / NA

Eng/No:

G/No:

JHMTD46207S200856

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F:

205/55 R16

R:

205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

8/2/2018

D.O.I.

13/12/2018

Survey held at

Hiap Lek

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

#3900 - #4900

5 Days Repair

RECEIVED 10 APR 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

150

Transportation

) \$ + RS \$

) Photos

) Other

TOTAL:

150

Report Format:

PRS

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Catherine Chong (LKK Auto)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Monday, 12 February, 2018 2:09 PM
To: assignments
Subject: FW: OUR REF: PRS/SNM18D00767C02/3 & YR REF: MKR/104/7778/2018/AS.WL - TO CONDUCT PRE REPAIR SURVEY -SGV7016K
Attachments: SNM18D00767C02 20180208 FR ROY & PARTNERS -PRS LTR.pdf

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

13-02-2018 @ 12.13pm
Han wli veh in

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]
Sent: Monday, 12 February 2018 2:07 PM
To: roynpartners <roynpartners@roynpartners.com.sg>
Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: OUR REF: PRS/SNM18D00767C02/3 & YR REF: MKR/104/7778/2018/AS.WL -TO CONDUCT PRE REPAIR SURVEY -SGV7016K

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Ashley,

We refer to your email on even date.

We are objecting to your list of surveyors and shall be appointing M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Calvin / Marcus,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Jowyn Tay 63896174

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower

Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: roynpartners [mailto:roynpartners@roynpartners.com.sg]
Sent: Monday, 12 February, 2018 1:51 PM
To: Angie Foo
Cc: Jowyn Tay
Subject: RE: OUR REF: PRS/SNM18D00767C02/3 & YR REF: MKR/104/7778/2018/AS.WL -TO CONDUCT PRE REPAIR SURVEY -SGV7016K
Importance: High

Dear Angie,

We refer to your email of 12th February 2018.

Our client reject your list of proposed motor surveyors and propose their list of surveyors as follows :-

1. PAR Automotive Consultancy
Contact Person: Mr. Loi Boon Juan
2. United Appraisal and Management Pte Ltd
Contact Person: Mr. Marc
3. Oh Appraisal Services
Contact Person: Mr. Oh Han Cheong
4. SK Auto Consultants
Contact Person: Mr. Kuma
5. Lee Automobile Appraisers Services
Contact Person: Mr. Lee K. W.
6. CM Automotive Consultancy
Contact Person: Mr. Ng Cheng Meng
7. ISP Management Pte Ltd
Contact Person: Mr. Zali Saidi
8. Auto Performance Appraisal
Contact Person: Mr. Lek Boon Hwee

Pursuant to the new NIMA protocol, kindly let us know within 2 working days of receipt of our letter whether you agree or has any objections to any of the motor surveyors proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors listed by our client.

BCC – Client – For your information
(Ref: SGV 7016K)

Thanks & regards,

Ashley Su (Mr)
Legal Executive
M/s Roy & Partners
101 Cecil Street
#11-09 Tong Eng Building
Singapore 069533
Tel : 6536 8466 Fax : 6536 1963
Email : ashley@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

From: Angie Foo [<mailto:angie.foo@sg.cntaiping.com>]
Sent: Monday, 12 February, 2018 11:37 AM
To: roynpartners@roypartners.com.sg
Cc: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Subject: FW: OUR REF: PRS/SNM18D00767C02/3 & YR REF: MKR/104/7778/2018/AS.WL -TO CONDUCT PRE REPAIR SURVEY -SGV7016K

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sirs,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Jowyn Tay 6389 6174.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com


Disclaimer:

This message is confidential, its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Virus-free. www.avg.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 5827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.4
Company Ownership

MOTORMAX-COMMERCIAL
Comprehensive

Certificate No. A 80431973 MCX

Excess : SGD500
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle
SGV7016X
2. Name of Policyholder
ACE SEMI-TOOL PTE LTD
3. Effective Date of the Commencement of Insurance for the purposes of the Act
11/05/2017
4. Date of Expiry of Insurance
10/05/2018
5. Persons or Classes of Persons entitled to drive*
PARK JUHA
Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to use*
Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Signature / Date

Counter-Signatory:

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

Amy Lar
Senior Vice President, Agencies

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/02/2018 11:08
Date Of Accident	08/02/2018 14:15
Exact Location Of Accident	SLIP ROAD OF AMK AVE 5 TWDS TPE (CITY)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGV7016K
Insured/Policyholder	
Name Of Registered Owner	ACE SEMI-TOOL PTE LTD
Co Reg No	- 2006 17902 E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90711002
Alternative Phone No	OFFICE-90711002

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80431973MCX (COMP)
Cover Note Number	

Driver

Name of Driver	PARK JUHA
NRIC No	G0811472U
Date Of Birth	10/09/1980
Occupation	OUTDOOR
Date Of Driving Pass	22/09/2012
Driving Experience	5 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84799419
Fax Number	
Contact Number	OTHERS-84799419
Email Address	NOEMAIL

Address	BULLION PARK 166 TOWER 3 LENTOR LOOP
Postcode	789097
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9073K
Vehicle Make/Model/Colour	TOYOTA DYNA
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]


09 FEB 2018



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 08/02/18 @ about 08/02/18 @ 2:15pm, I am travelling along Ang Mo Kio Ave S towards CTE City. At the Slip Road of Ang Mo Kio Ave S, I stopped my vehicle to give way to the on coming traffic. When the traffic is clear, I started to move off. When suddenly, I felt an impact on my rear portion. When I got down I saw that vehicle (B) hit onto the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018		13 Feb 2018 19:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------







CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	KIAN YEE RENOVATION CONTRACTOR, Co. Reg. No.: -	
Main Claimant:	ACE SEMI TOOL PTE LTD	
Vehicle Reg. No.:	SGV7016K	Date of Loss: 08/02/2018 13:00 - :59 [127 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00767C02	Policy/Cover Note No.: DMCVSN3071461701
Vehicle Reg. No. (Insured):	GBD9073K	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	Hlap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 23/02/2018]	
Adj Asg. Remarks:	PLEASE SURVEY THIRD PARTY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS. KINDLY LET US HAVE YOUR RECOMMENDED REPAIR AMOUNT IF THERE IS NOT ESTIMAE PROVIDED DURING PRE REPAIR.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SGV7016K (SNM18D00767C02)**
[GBD9073K]
TP
ACE SEMI TOOL PTE LTD
Feb 8 2018 1:00PM
[KIAN YEE RENOVATION CONTRACTOR]
Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/04/18 10:42	LKK SURVEYOR PHOTO 1	 Load PDF	
2	16/04/18 10:42	LKK SURVEYOR PHOTO 2	 Load PDF	
3	16/04/18 10:42	LKK SURVEYOR PHOTO 3	 Load PDF	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/02/18 19:29	INSURED SAS REPORT GBD9073K	 Load PDF	
2	13/02/18 19:29	THIRD PARTY SGV7016K -FROM ROY & PARTNERS -PRS LTR	 Load PDF	
3	13/02/18 19:31	THIRD PARTY SAS REPORT SGV7016K	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118002902/WBE2

Date: 18/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3071461701

Claimant Vehicle
No : SGV7016KInsured Vehicle
No : GBD9073K

Date of Loss: 08/02/2018

Nature of Claim: TP

Claim
No: SNM18D00767C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGV7016K**

Make & Model: HONDA CIVIC, 1.5 VTi (A)

Engine No: R16A12001555

Reg. Date: 25/06/2007 (Man. Year: 2007)

Chassis No: JHMF46207S200856

Colour: Red

Odometer: 101500 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 3 mm	Rear Left Side:	Continental 3 mm
Front Right Side:	Continental 3 mm	Rear Right Side:	Continental 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/02/2018

Date Inspected: 13/02/2018 Inspected At:

Hiap Lek Automobile Trading (HQ)
160 Sin Ming Drive, #05-17 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900.00 - \$4,900.00

REPAIR DETAILS

Reference

Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 18 Apr 2018)
Parts:	143	HONDA CIVIC 1.5 VTi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGV7016K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >