

ASS. REC. BY:

REF: CS/MSG18002911/P1/bcz Special Instruction:

SURVIVOR

Rasul

ASSIGNMENT (Office)

From (Person):

Clara Milch Teo

of

MSG

Date/Time: 13022018 11.08am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

WC 8911E

Insured:

at Workshop m/s

Say Wah Welding

Tel:

of

No 211 Kranji Rd

Policy No:

828985078MKF

Claim No:

548834

Sum Insured:

Excess:

\$1500.00

Make of Veh:

D.O.A. 04022018

(Client's Record)

CA / REV / REP. / REV 24 HRS

Marina Grove Plant

T330 lot 00433T (PT)

Marina Grove (Stalin - 9489 6144)

H.O.D. Endorsement:

Date/Time: 13022018

Person Contacted:

Stalin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Investigation & Check on caused of dis/budget drum

WC 8911E - X

15/2/18-

Report via merisken, Pending investigation mark value & part price from other sources.

Submit preli report, case has been repudiated.

Karan

REF:

2622062660

ASSIGNMENT

From _____ Date _____

Estimated Cost: _____

☒ TP / WS / TP RES / CO RES / EVA / INV / MV

To inspect vehicle No: **WC 8911E**

at Workshop no: **MARINA GARDEN PLANT**

of _____

Insured: **MSIG/00**


Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: **1500**

(Client's Record)

Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: **120K**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

QA / ☒ REP / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Van No: **WC 8911E** Page: **2015 APR**

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

☒ Truck / Trailer or _____

Make: **ISUZU CYH 52S** Ch: **15681**

Colour: **WHITE** A/C: _____ Insured / Std / NI / NA

Sp Reading: **80454** T-Radio: Insured / Std / NI / NA

Eng No: _____

C/N: **JAL CYH 52SE 7000205**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt or

Brake: ☒ Jammed / Leaked / Burnt or

Mod: ☒ N / S/Rim / STD A/Rim or

Tyre Size: F: **295/80R22-5** R: **D/P**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **FIRENZA**

Front: _____ Rear: _____

R.Bal: **8** mm L.Bal: **8** mm

D.O.A: **04/04/18** D.O.I: **14/04/18**

Survey held at: **ALLIANCE CONCRETE**

Des. of Damages: Frt / Rear / OS ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

milah@sg.msig-asia.com

Leong Workshop
 61etu Lane 12 Mr Leong 91795889

RECEIVED 1 JUL 2010

Vehicle now located at this place → Marina Mall
 Alliance Concrete Plant behind Corporate

Cost Time File Pass: ☒ Prel. Report ☐ Final Report

11A Typist

Date Time File Return: _____

Days Of Repair: **17**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp: \$ ☐ Material: \$ ☐ Test: \$ ☐ Retaining: \$

800/17

440
10
440

Report Format: _____

Lump Sum / I.B. / I.C. _____

MSIG

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		13 Feb 2018 11:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Alliance Concrete Singapore Pte Ltd, Co. Reg. No.: 200516266D		
Vehicle Reg. No.:	WC8911E	Date of Loss:	04/02/2018 12:00 - :59
Claim Type:	OD / 548834	Policy/Cover Note No.:	B28985078MKF(COMP) (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
		Excess:	S\$1,500.00
Repairer:	Say Wah Welding & Construction Pte Ltd (HQ) NO. 211 KRANJI ROAD, 739461 Kranji - Tel: 62690090		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/02/2018]		
Driver/Custodian:	SATHAJAH KARUPPIAH (48 / Male), NRIC: G7309227U, Tel: +6582501185		
Adj Asg. Remarks:	To contact OI (please refer to email). To check on the caused of dislodged drum. To revert. Thanks.		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***WC8911E (548834)**

OD

Feb 4 2018 12:00PM

[Alliance Concrete Singapore Pte Ltd]
Say Wah Welding & Construction Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 11/07/2018 11:16 AM.
To LKK_HQ
Subject Alert - Adj Mandate Revoked - WC8911E - Claim Handler: Clara Milah Yeo

Revoked: We repudiated liability. Please submit your bill inclusive of investigation fee.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 15 Feb 2018

Preliminary Advice

Vehicle No	: WC8911E	Accident Date	: 04/02/2018
Make	: ISUZU CYH52S	Policy No.	: B28965078MKF(COMP)
Assignment Date	: 13/02/2018	Excess	: S\$1,500.00
Date of Inspection	: 14/02/2018	Est. Duration of Repair	: 18.00
Inspection At	: SAY WAH WELDING & CONSTRUCTION PTE LTD (HQ) NO. 211 KRANJI ROAD SINGAPORE 739461		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	76,219.00
Revised Amount	:S\$	62,505.00
Check Items (Estimated)	:S\$	9,810.00
Total	:S\$	72,315.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	TBA
COE / PARF Rebate	:S\$	39,400.00
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- (x) The vehicle is economical for repair. Pending investigation, Pending Market Value, Pending part price check on other sources.
- () The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Milah Yeo

Date: 15 Feb 2018

Preliminary Advice

Vehicle No	: WC8911E	Accident Date	: 04/02/2018
Make	: ISUZU CYH52S	Policy No.	: B28985078MKF(COMP)
Assignment Date	: 13/02/2018	Excess	: S\$1,500.00
Date of Inspection	: 14/02/2018	Est. Duration of Repair	: 18.00
Inspection At	: SAY WAH WELDING & CONSTRUCTION PTE LTD (HQ) NO. 211 KRANJI ROAD SINGAPORE 739461		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	76,219.00
Revised Amount	:S\$	62,505.00
Check Items (Estimated)	:S\$	9,810.00
Total	:S\$	72,315.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	450,000.00
COE / PARF Rebate	:S\$	39,400.00
Salvage Value	:S\$	
Margin for Repair	:S\$	410,600.00

Remarks

- (☒) The vehicle is economical for repair. Pending investigation.
- (☐) The above survey was conducted on a 'without prejudice' basis.

MVA218017410 / VAC - Sin Ming
 ENTRY DATE & TIME: 05/02/2018 11:57
 SUBMITTED BY: CHRISTINA ONG Mui Lan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/02/2018 11:57
 Date Of Accident 04/02/2018 12:30
 Exact Location Of Accident SHEARS AVENUE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number WC8911E
Insured/Policyholder
 Name Of Registered Owner JASS TRADE & SHIPPING PTE LTD
 Co Reg No -
 Email Address JASSSHIPPING1@GMAIL.COM
 Mobile Phone No (LOCAL) +65-82501185
 Alternative Phone No Office-62911706

Vehicle Particulars

Manufacturer ISUZU
 Model -
 Exact Purpose for which vehicle was being used at time of accident WORK PURPOSE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number B28985078MKF (COMP)
 Cover Note Number

Driver

Name of Driver SATHAIAH KARUPPIAH
 NRIC No G7309227U
 Date Of Birth 03/05/1969
 Occupation OUTDOOR
 Date Of Driving Pass 06/06/2016
 Driving Experience 1 YEAR AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-82501185

Fax Number
Contact Number OTHERS-82501185
EMail Address NOEMAIL
Address BLK 25 JALAN BERSEH #01-120
Postcode 200025
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

05 FEB 2018



Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A - WC 8911E
DOA - 4/2/18

WC8911E My lorry driving at 12.30 Pm
around I was want to delivery the
concrete address Bedok Station. I am
going on 30 km speed in central Blvd
the time right side suddenly heavy sound
in my lorry back side that down was
fall down No body injury I am also safe
then we clear the road traffic police
also help to us. Police advise to report
my insurance company.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

05 FEB 2018

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7800, Fax +65 6827 7800
Co Reg No. 200412212G, GST Reg No. 20-0412212G

936

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form H.2.301
Goods Carrying Vehicle - 8th II

COMMERCIAL VEHICLE - FLEET
Comprehensive

Certificate No. B 28985078 MKP

Excess: SGD1,500

1. Index Mark and Registration Number of Vehicle
WC8911E

Excess: SGD2,000 for Young &
Inexperienced Driver

2. Name of Policyholder

Jess Trade & Shipping Pte Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act
01/07/2017

4. Date of Expiry of Insurance
30/06/2018

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use in connection with the Policyholder's business.
Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business.
Use for social domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.
- (3) Use for the carriage of passengers for hire or reward.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers

for Chief Executive Officer

AGS201707071637

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	<u>4379G</u>
Vehicle Details	
Vehicle No.:	WC8911E
Vehicle to be Exported:	No
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	6WG1422730
Chassis No.:	JALCYH52SE7000205
Maximum Power Output:	-
Open Market Value:	\$86,512.00
Original Registration Date:	<u>13 Apr 2015</u>
First Registration Date:	13 Apr 2015
Transfer Count:	1
Actual ARF Paid:	\$4,326.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	<u>12 Apr 2025</u>
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
QP Paid:	\$55,011.00
COE Rebate Amount:	\$39,400.00
Total Rebate Amount:	\$39,400.00

The information contained herein is correct as at 14 Feb 2018

OK

120,100
39,400
80,600

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Feb 2018		13 Feb 2018 11:08 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Alliance Concrete Singapore Pte Ltd, Co. Reg. No.: 200516266D		
Vehicle Reg. No.:	WC8911E	Date of Loss:	04/02/2018 12:00 - :59
Claim Type:	OD / 548834	Policy/Cover Note No.:	B28985078MKF(COMP) (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
		Excess:	S\$1,500.00
Repairer:	Say Wah Welding & Construction Pte Ltd (HQ) NO. 211 KRANJI ROAD, 739461 Kranji - Tel: 62690090		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 14/02/2018]		
Driver/Custodian:	SATHAIAH KARUPPIAH (48 / Male), NRIC: G7309227U, Tel: +6582501185		
Adj Asg. Remarks:	To contact OI (please refer to email). To check on the caused of dislodged drum. To revert. Thanks.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**SAY WAH WELDING & CONSTRUCTION PTE.LTD.**

Factory Address: No 211 Kranji Road Singapore 739461
Mailing Address: Blk 209 Boon Lay Place #08-259 Singapore 640209
Office/Fax no: 6269 0090
Email : saywahmachinery@gmail.com
Co.Reg.No.: 201508801Z GST Reg.No.: 201508801Z

Date	Quotation No.
9/2/2018	SWCQ1802011

Quotation To:

MSIG INSURANCE (SINGAPORE) PTE.LTD.
4 SHENTON WAY, #21-01,
SGX CENTRE 2,
SINGAPORE 068807

QUOTATION

Vehicle No.
T936,WC8911E

Attn:

Item No.	Description	Qty	U/M	Unit Price	Amount
AT936	ALLIANCE VEHICLE: T936,WC8911E			0.00	0.00
ACM01	CEMENT MIXER CONTAINER C/W HYDRAULIC MOTOR, CHAIN SET, MOTOR DRIVING & DRIVEN GEAR CONTAINER ROLLER BEARING 2 SETS & ETC	1	SET	38,000.00	38,000.00
ACM02	CEMENT MIXER CONTAINER ASSY WITH REAR SUPPORT BRACKET	1	SET	3,500.00	3,500.00
ACM03	CEMENT MIXER REAR CHUTE C/W BRACKET	1	SET	1,800.00	1,800.00
ACM04	2ND AXLE WHEEL MUDGUARD ASSY L/H	1	UNIT	1,500.00	1,500.00
ACM05	2ND AXLE WHEEL RIM L/H	1	UNIT	950.00	950.00
ACM06	2ND AXLE WHEEL TYRE L/H	1	UNIT	450.00	450.00
ACM07	3RD & 4TH AXLE WHEEL MUDGUARD ASSY L/H	1	UNIT	1,800.00	1,800.00
ACM08	3RD AXLE WHEEL RIM L/H	1	UNIT	950.00	950.00
ACM09	3RD AXLE WHEEL TYRE L/H	1	UNIT	450.00	450.00
ACM10	L/H SIDE GUARD RAIL	1	UNIT	1,800.00	1,800.00
ACM11	ISUZU EXHAUST CANISTER SILENCE ASSY	1	SET	6,000.00	6,000.00
				Subtotal	
				Add 7% GST	
				Total Amount SGD	



Authorised by

Received by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor Signature

Name:

Contact no.

**SAY WAH WELDING & CONSTRUCTION PTE.LTD.**

Factory Address: No.211 Kranji Road Singapore 739461
 Mailing Address: Blk 209 Boon Lay Place #08-259 Singapore 640209
 Office/Fax no: 6269 0090
 Email : saywahmachinery@gmail.com
 Co.Reg.No.: 201508801Z GST Reg.No.: 201508801Z

Date	Quotation No.
9/2/2018	SWCQ1802011

Quotation To:

MSIG INSURANCE (SINGAPORE) PTE.LTD.
 4 SHENTON WAY, #21-01,
 SGX CENTRE 2,
 SINGAPORE 068807

QUOTATION**Vehicle No.**

T936,WC8911E

Attn:

Item No.	Description	Qty	U/M	Unit Price	Amount
ACM12	EXHAUST CANISTER SILENCE BRACKET	2	PCS	120.00	240.00
ACM13	ISUZU EXHAUST CANISTER PROTECTOR PANEL	1	UNIT	650.00	650.00
ACM14	FUEL TANK ASSY	1	SET	4,900.00	4,900.00
ACM15	FUEL TANK BRACKET	2	PCS	400.00	800.00
ACM16	FUEL TANK HOSE	1	PCS	150.00	150.00
ACM17	FUEL TANK FUEL FILTER	1	PCS	120.00	120.00
ACM18	FUEL TANK CAP	1	PCS	125.00	125.00
ACM19	FRONT L/H DOOR REAR QUARTER PANEL	1	UNIT	793.00	793.00
ACM20	FRONT L/H DOOR REAR QUARTER PANEL GLASS WITH RUBBER MOULDING	1	UNIT	121.00	121.00
ACM21	ALLIANCE CEMENT STICKER	1	SET	120.00	120.00
ACM22	NUMBER STICKER "936"	1	SET	100.00	100.00
ACM23	REAR WATER CYLINDER TANK	1	UNIT	1,850.00	1,850.00
ACM24	REAR WATER CYLINDER TANK SUPPORT BRACKET	1	UNIT	930.00	930.00
LACM01	TOWING FEE TO RECOVERY OF MIXER CONTAINER ON ACCIDENT SITE	1	PCS	500.00	500.00
				Subtotal	
				Add 7% GST	
				Total Amount SGD	



Authorised by

Rasul
 HP 90010068

18 days Received by

7/P

14/02/18 @ 1120

EXCESS: 1500

Revert

Reg 54 point

Page 2

Surveyor Signature

Name:

Contact no.

**SAY WAH WELDING & CONSTRUCTION PTE.LTD.**

Factory Address: No 211 Kranji Road Singapore 739461
Mailing Address: Blk 209 Boon Lay Place #08-259 Singapore 640209
Office/Fax no: 6269 0090
Email : saywahmachinery@gmail.com
Co.Reg.No : 201508801Z GST Reg.No.: 201508801Z

Date	Quotation No.
9/2/2018	SWCQ1802011

QUOTATION

Vehicle No.
T936,WC8911E

Quotation To:

MSIG INSURANCE (SINGAPORE) PTE.LTD.
4 SHENTON WAY, #21-01,
SGX CENTRE 2,
SINGAPORE 068807

Attn:

Item No.	Description	Qty	U/M	Unit Price	Amount
LACM02	TO REMOVE & REFIX FRONT DOOR REAR QUARTER PANEL GLASS	1	PCS	120.00	120.00
LACM03	TO REMOVE & REPLACE EXHAUST CANISTER SILCENCE ASSY	1	PCS	300.00	300.00
LACM04	TO REMOVE & REPLACE FUEL TANK ASSY, FUEL TANK FILTER AND BLEED SYSTEM AFAR	1	PCS	400.00	400.00
LACM05	LABOUR TO REMOVE & REPLACE DAMAGE MIXER, HYDRAULIC MOTOR, CHAIN SET, DRIVING & DRIVEN GEAR, BRACKET & ETC	1	PCS	3,800.00	3,800.00
LACM06	WORKMANSHIP TO SPRAY PAINTING ON EFFECTED DAMAGE PARTS	1	PCS	3,000.00	3,000.00
	Tax collected on sales			7.00%	5,335.33
				Subtotal	\$76,219.00
				Add 7% GST	\$5,335.33
				Total Amount SGD	\$81,554.33

**Authorised by****Received by****Terms & Condition:**

- a) All prices quoted are valid for 2 weeks from the date of quote.
b) Any additional repair & maintenance or spare parts provided subject to back charge to you accordingly.

Surveyor Signature**Name:****Contact no.**

Dear Sir/Madam

NOTICE OF INSPECTION FOR VEHICLE NO. WC8911E

Lund Transport & Authority

Your vehicle is required to be inspected by 12 Apr 2018 at any of the inspection centres listed overleaf.

- Please note that it is an offence under Section 91 of the Road Traffic Act (Cap 276) for a person who uses, or causes or permits to be used, a motor vehicle for which there is no inspection certificate.
- Please produce the valid inspection certificate issued for this inspection when you renew your road tax.

Registrar of Vehicles

(This is a computer-generated printout. No signature is required.)

VEHICLE INFORMATION FOR INSPECTION

MAKE	ISUZU
MODEL	CYBEX
VEHICLE DESCRIPTION	GOODS CARRYING VEHICLE MINIBUS/MINIBUS
ADDITIONAL ATTACHMENT 1	NO ATTACHMENT
ADDITIONAL ATTACHMENT 2	
ADDITIONAL ATTACHMENT 3	
ORIGINAL REGISTRATION DATE	13 APR 2015
CHASSIS NO	JALCYH52SE7000206
ENGINE NO/MOTOR NO	6WGL4227307
PROPULSANT	DIESEL
ENGINE CAPACITY (kW/POWER RATING (kW)	14.2/19.5kW
MAXIMUM POWER OF 1P/1T (kW/HP)	14.2/19.5kW
UNLADEN WEIGHT/MAX LOADED WEIGHT (kg)	1420/3400
PASSENGER CAPACITY	12
NO. OF AXLES	4
TYRE SIZE (FRONT/REAR)	205/80R22.5(S) N2 / 205/80R22.5(D) N2
IN VEHICLE UNIT NO	3010498697
NO. PLATE SEAL NO. (FRONT/REAR)	7
SIDEMARKING	NOT REQUIRED

MESSAGES FOR YOUR ATTENTION:

FOR FURTHER INFORMATION, PLEASE CONTACT THE LUND TRANSPORT & AUTHORITY AT 1800 220 3626.

Leong Workshop

No.6 Defu Lane 12, Singapore 539115. Tel: 6281 8518 Fax: 6281 8864 Email: jennyskk@hotmail.com
Mr. Leong H/P: 9179 5889 Company Registration No. : 53330082K

General Repair & Servicing of Cement Mixer & Truck
修理洋灰攪拌車，嘜哩

M/s JASS Trade & Shipping Pte Ltd
Blk 668 Chander Road, #01-14 Singapore 210668.

Invoice No. : 20916

Date : 09 Aug 2017

Truck No. : WC8911E (936 Alliance)

Attn: Mr. N. Stalin

Item	Description	Qty	Unit Price	Amount (\$\$)
1.	Servicing (Euro 5)	1 no.	340.00	340.00
2.	Tear & Wear Neck Rubber	1 no.	50.00	50.00
3.	Tear & Wear Bumper Rubber	2 pcs	30.00	60.00
4.	Tear & Wear Signal Light (Rear, Left)	1 no.	25.00	25.00
5.	Greasing	1 no.	25.00	25.00
6.	40km Label	2 pcs	4.00	8.00
	(Singapore Dollars: Five Hundred & Eight only.)			
E. & O.E.			Total:	508.00

Cheques are to be crossed and made payable to **Leong Workshop**

DBS Current Account No. : 023-905361-0

Leong Workshop

Authorised Signature

Acknowledge by Driver

Google Maps Sheares Avenue



Images may be subject to copyright.

From the web

Photo



Google Maps Sheares Avenue



Images may be subject to copyright.

From the web

Photo



JOB CYCLE REPORT 4-2-18

VEHICLE	LOAD Q	CUMUL PROJECT SITE	LOAD TIME	LEFT PLANT	ARRIVED JOBSITE	LEFT JOBSITE
MG936	8	PROJECT JEWEL@CH#	04-Feb-2018 08:47	04-Feb-2018 08:59	04-Feb-2018 09:26	04-Feb-2018 10:05
MG936	8.5	68 T312-SUNGEI BEDOK	04-Feb-2018 12:18	04-Feb-2018 12:34	-	ACCIDENT

T936 SPEED REPORT 4-FEB-18

TIMESTAMP	VEHICLE	LOCATION	SPEED (kph)
04-Feb-2018 08:39:20	MG936	Marina Grove Plant (MG), 15 Marina Grove	1
04-Feb-2018 08:41:58	MG936	Marina Grove Plant (MG), 15 Marina Grove	3
04-Feb-2018 08:50:58	MG936	Marina Grove Plant (MG), Marina Coastal Expressway	1
04-Feb-2018 08:51:58	MG936	Marina Grove Plant (MG), Marina Coastal Expressway	9
04-Feb-2018 08:52:58	MG936	Marina Grove Plant (MG), Marina Coastal Expressway	1
04-Feb-2018 08:57:58	MG936	Marina Grove Plant (MG), Marina Coastal Expressway	13
04-Feb-2018 08:58:58	MG936	15 Marina Grove	33
04-Feb-2018 08:59:58	MG936	30 Marina Coastal Drive	40
04-Feb-2018 09:00:58	MG936	30 Marina Coastal Drive	6
04-Feb-2018 09:01:58	MG936	Marina Street	54
04-Feb-2018 09:04:58	MG936	8 Bayfront Avenue	56
04-Feb-2018 09:05:58	MG936	East Coast Parkway	57
04-Feb-2018 09:06:58	MG936	500 East Coast Parkway	62
04-Feb-2018 09:07:58	MG936	500 East Coast Parkway	57
04-Feb-2018 09:08:58	MG936	730 East Coast Parkway	57
04-Feb-2018 09:09:58	MG936	902 East Coast Parkway	54
04-Feb-2018 09:10:58	MG936	900 East Coast Parkway	53
04-Feb-2018 09:11:58	MG936	2001 East Coast Parkway	49
04-Feb-2018 09:12:58	MG936	1030 East Coast Parkway	45
04-Feb-2018 09:13:58	MG936	1110 East Coast Parkway	53
04-Feb-2018 09:14:58	MG936	1210 East Coast Parkway	54
04-Feb-2018 09:15:58	MG936	1300 East Coast Parkway	51
04-Feb-2018 09:16:58	MG936	1390 East Coast Parkway	52
04-Feb-2018 09:17:58	MG936	1410 East Coast Parkway	51
04-Feb-2018 09:18:58	MG936	1500 East Coast Parkway	50
04-Feb-2018 09:19:58	MG936	East Coast Parkway	50
04-Feb-2018 09:20:58	MG936	East Coast Parkway	52
04-Feb-2018 09:21:58	MG936	30 Airport Boulevard	52
04-Feb-2018 09:22:58	MG936	21 Airport Boulevard	50
04-Feb-2018 09:23:58	MG936	55 Airport Boulevard	48
04-Feb-2018 09:24:58	MG936	60 Airport Boulevard	41
04-Feb-2018 09:28:58	MG936	Woh Hup - Project Jewel @ Changi Airport, 75 Airport Boulevard	24
04-Feb-2018 09:30:58	MG936	Woh Hup - Project Jewel @ Changi Airport, T1 Departure Crescent	10
04-Feb-2018 09:31:58	MG936	Woh Hup - Project Jewel @ Changi Airport, T1 Departure Crescent	8
04-Feb-2018 10:02:58	MG936	Woh Hup - Project Jewel @ Changi Airport, T1 Departure Crescent	2
04-Feb-2018 10:03:58	MG936	Woh Hup - Project Jewel @ Changi Airport, 70 Airport Boulevard	52
04-Feb-2018 10:04:58	MG936	50 Airport Boulevard	63
04-Feb-2018 10:05:58	MG936	20 Airport Boulevard	57
04-Feb-2018 10:06:58	MG936	East Coast Parkway	57
04-Feb-2018 10:07:58	MG936	East Coast Parkway	57
04-Feb-2018 10:08:58	MG936	East Coast Parkway	57
04-Feb-2018 10:09:58	MG936	1500 East Coast Parkway	52
04-Feb-2018 10:10:58	MG936	1410 East Coast Parkway	54
04-Feb-2018 10:11:58	MG936	1300 East Coast Parkway	57
04-Feb-2018 10:12:58	MG936	1300 East Coast Parkway	56
04-Feb-2018 10:13:58	MG936	Laguna Flyover	56
04-Feb-2018 10:14:58	MG936	1110 East Coast Parkway	55
04-Feb-2018 10:15:58	MG936	1020 East Coast Parkway	55
04-Feb-2018 10:16:58	MG936	Marine Parade Flyover	54
04-Feb-2018 10:17:58	MG936	910 East Coast Parkway	56
04-Feb-2018 10:18:58	MG936	730 East Coast Parkway	54
04-Feb-2018 10:19:58	MG936	Tanjong Rhu Flyover	55
04-Feb-2018 10:20:58	MG936	500 East Coast Parkway	58
04-Feb-2018 10:21:58	MG936	East Coast Parkway	57
04-Feb-2018 10:22:58	MG936	East Coast Parkway	59
04-Feb-2018 10:23:58	MG936	1 Bayfront Avenue	57
04-Feb-2018 10:25:58	MG936	Marina City Pk	56
04-Feb-2018 10:26:58	MG936	15 Marina Grove	32
04-Feb-2018 10:28:58	MG936	Marina Grove Plant (MG), 15 Marina Grove	2

04-Feb-2018 10:36:58	MG936	Marina Grove Plant (MG), Marina Coastal Expressway	6
04-Feb-2018 10:53:58	MG936	Marina Grove Plant (MG), 15 Marina Grove	2
04-Feb-2018 12:18:57	MG936	Marina Grove Plant (MG), 15 Marina Grove	1
04-Feb-2018 12:20:57	MG936	Marina Grove Plant (MG), 15 Marina Grove	13
04-Feb-2018 12:24:57	MG936	Marina Grove Plant (MG), Marina Coastal Expressway	1
04-Feb-2018 12:26:57	MG936	Marina Grove Plant (MG), Marina Coastal Expressway	3
04-Feb-2018 12:32:57	MG936	Marina Grove Plant (MG), 15 Marina Grove	5
04-Feb-2018 12:33:57	MG936	20 Marina Mall	32
04-Feb-2018 12:35:57	MG936	30 Marina Coastal Drive	40
04-Feb-2018 12:36:57	MG936	Marina Gardens Drive	47
04-Feb-2018 12:53:57	MG936	Downtown Core	2
04-Feb-2018 13:03:57	MG936	Downtown Core	1
04-Feb-2018 13:13:57	MG936	Downtown Core	1
04-Feb-2018 13:23:57	MG936	Downtown Core	1
04-Feb-2018 13:43:57	MG936	Downtown Core	1
04-Feb-2018 13:53:57	MG936	Downtown Core	2
04-Feb-2018 14:03:57	MG936	Downtown Core	1
04-Feb-2018 14:12:50	MG936	Downtown Core	1
04-Feb-2018 14:22:57	MG936	Downtown Core	1
04-Feb-2018 14:32:57	MG936	Downtown Core	3
04-Feb-2018 14:42:57	MG936	Downtown Core	1
04-Feb-2018 15:04:22	MG936	Marina Grove Plant (MG), Downtown Core	1
04-Feb-2018 15:04:57	MG936	Marina Grove Plant (MG), Downtown Core	1
04-Feb-2018 15:14:57	MG936	Marina Grove Plant (MG), Downtown Core	1
04-Feb-2018 15:34:57	MG936	Marina Grove Plant (MG), Downtown Core	1
04-Feb-2018 16:44:57	MG936	Marina Grove Plant (MG), Downtown Core	1

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	05 Feb 2018		13 Feb 2018 11:08 Edit Adj Rpt	\$462,505.00 Edit Estimates	\$462,505.00 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	Alliance Concrete Singapore Pte Ltd, Co. Reg. No.: 200516266D		
Vehicle Reg. No.:	WC8911E	Date of Loss:	04/02/2018 12:00 - :59 [33 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 548834	Policy/Cover Note No.:	B28985078MKF(COMP) (Comprehensive) Coverage: 01/07/2017 - 30/06/2018
		Excess:	S\$2,000.00
Repairer:	Say Wah Welding & Construction Pte Ltd (HQ) NO. 211 KRANJI ROAD, 739461 Kranji - Tel: 62690090		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/03/2018]		
Driver/Custodian:	SATHALAH KARUPPIAH (48 / Male), NRIC: G7309227U, Tel: +6582501185		
Adj Asg. Remarks:	To contact Oi (please refer to email). To check on the caused of dislodged drum. To revert. Thanks.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- MSIG_SG (11/07/2018): Alert - Adj Mandate Revoked - WC8911E - Claim Handler: Clara Milah Yeo
- MSIG_SG (22/02/2018): Alert - Adj Mandate Approved (\$40.00) - WC8911E - Claim Handler: Clara Milah Yeo

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WC8911E (548834)

OD

Feb 4 2018 12:00PM

[Alliance Concrete Singapore Pte Ltd]
Say Wah Welding & Construction Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
1	05/02/18 15:42	VAC (Sin Ming) Accident Statement	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/18 11:00	Adjuster Immediate Advice	 Load HTM	
2	06/03/18 11:22	Adjuster Immediate Advice	 Load HTM	
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	13/02/18 11:06	MSIG Insurance (Singapore) Pte. Ltd. (HQ) REPAIR ESTIMATE	 Load PDF	
2	13/02/18 11:09	Email to request for survey (contact details & to confirm service schedule)	 Load PDF	
3	22/02/18 11:12	another quotation from another workshop	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/18 11:02	General Damage	 Load JPG	☒
2	15/02/18 11:02	General Damage	 Load JPG	☒
3	15/02/18 11:02	General Damage	 Load JPG	☒
4	15/02/18 11:02	General Damage	 Load JPG	☒
5	15/02/18 11:02	General Damage	 Load JPG	☒
6	15/02/18 11:02	General Damage	 Load JPG	☒
7	15/02/18 11:02	General Damage	 Load JPG	☒
8	15/02/18 11:02	General Damage	 Load JPG	☒
9	15/02/18 11:02	General Damage	 Load JPG	☒
10	15/02/18 11:02	General Damage	 Load JPG	☒
11	15/02/18 11:02	General Damage	 Load JPG	☒
12	15/02/18 11:02	General Damage	 Load JPG	☒
13	15/02/18 11:02	General Damage	 Load JPG	☒
14	15/02/18 11:02	General Damage	 Load JPG	☒
15	15/02/18 11:02	General Damage	 Load JPG	☒
16	15/02/18 11:02	General Damage	 Load JPG	☒
17	15/02/18 11:02	General Damage	 Load JPG	☒
18	15/02/18 11:02	General Damage	 Load JPG	☒
19	15/02/18 11:02	General Damage	 Load JPG	☒
20	15/02/18 11:02	General Damage	 Load JPG	☒
21	15/02/18 11:02	General Damage	 Load JPG	☒
22	15/02/18 11:02	General Damage	 Load JPG	☒
23	15/02/18 11:02	General Damage	 Load JPG	☒
24	15/02/18 11:02	General Damage	 Load JPG	☒
25	15/02/18 11:02	General Damage	 Load JPG	☒
26	15/02/18 11:02	General Damage	 Load JPG	☒
27	15/02/18 11:02	General Damage	 Load JPG	☒
28	15/02/18 11:02	General Damage	 Load JPG	☒
29	15/02/18 11:02	General Damage	 Load JPG	☒
30	15/02/18 11:02	General Damage	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
				☒
31	15/02/18 11:02	General Damage	 Load JPG	☒
32	15/02/18 11:02	General Damage	 Load JPG	☒
33	15/02/18 11:02	General Damage	 Load JPG	☒
34	15/02/18 11:02	General Damage	 Load JPG	☒
35	15/02/18 11:02	General Damage	 Load JPG	☒
36	15/02/18 11:02	General Damage	 Load JPG	☒
37	15/02/18 11:02	General Damage	 Load JPG	☒
38	15/02/18 11:02	General Damage	 Load JPG	☒
39	15/02/18 11:02	General Damage	 Load JPG	☒
40	15/02/18 11:02	General Damage	 Load JPG	☒
41	15/02/18 11:02	General Damage	 Load JPG	☒
42	15/02/18 11:02	General Damage	 Load JPG	☒
43	15/02/18 11:02	General Damage	 Load JPG	☒
44	15/02/18 11:02	General Damage	 Load JPG	☒
45	15/02/18 11:02	General Damage	 Load JPG	☒
46	15/02/18 11:02	General Damage	 Load JPG	☒
47	15/02/18 11:02	General Damage	 Load JPG	☒
48	15/02/18 11:02	General Damage	 Load JPG	☒
49	15/02/18 11:02	General Damage	 Load JPG	☒
50	15/02/18 11:02	General Damage	 Load JPG	☒
51	15/02/18 11:02	General Damage	 Load JPG	☒
52	15/02/18 11:02	General Damage	 Load JPG	☒
53	15/02/18 11:02	General Damage	 Load JPG	☒
54	15/02/18 11:02	General Damage	 Load JPG	☒
55	15/02/18 11:02	General Damage	 Load JPG	☒
56	15/02/18 11:02	General Damage	 Load JPG	☒
57	15/02/18 11:02	General Damage	 Load JPG	☒
58	15/02/18 11:02	General Damage	 Load JPG	☒
59	15/02/18 11:02	General Damage	 Load JPG	☒
60	15/02/18 11:02	General Damage	 Load JPG	☒
61	15/02/18 11:02	General Damage	 Load JPG	☒
62	15/02/18 11:02	General Damage	 Load JPG	☒
63	15/02/18 11:02	General Damage	 Load JPG	☒
64	15/02/18 11:02	General Damage	 Load JPG	☒
65	15/02/18 11:02	General Damage	 Load JPG	☒
66	15/02/18 11:02	General Damage	 Load JPG	☒
67	15/02/18 11:02	General Damage	 Load JPG	☒
68	15/02/18 11:02	General Damage	 Load JPG	☒
69	15/02/18 11:02	General Damage	 Load JPG	☒
70	15/02/18 11:02	General Damage	 Load JPG	☒
71	15/02/18 11:02	General Damage	 Load JPG	☒
72	15/02/18 11:02	General Damage	 Load JPG	☒
73	15/02/18 11:02	General Damage	 Load JPG	☒
74	15/02/18 11:02	General Damage	 Load JPG	☒
75	15/02/18 11:02	General Damage	 Load JPG	☒
76	15/02/18 11:02	General Damage	 Load JPG	☒
77	15/02/18 11:02	General Damage	 Load JPG	☒
78	15/02/18 11:02	General Damage	 Load JPG	☒
79	15/02/18 11:02	General Damage	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
80	15/02/18 11:02	General Damage	 Load JPG	☒
81	15/02/18 11:02	General Damage	 Load JPG	☒
82	15/02/18 11:02	General Damage	 Load JPG	☒
83	15/02/18 11:02	General Damage	 Load JPG	☒
84	15/02/18 11:02	General Damage	 Load JPG	☒
85	15/02/18 11:02	General Damage	 Load JPG	☒
86	15/02/18 11:02	General Damage	 Load JPG	☒
87	15/02/18 11:02	General Damage	 Load JPG	☒
88	15/02/18 11:02	General Damage	 Load JPG	☒
89	15/02/18 11:02	General Damage	 Load JPG	☒
90	15/02/18 11:02	General Damage	 Load JPG	☒
91	15/02/18 11:02	General Damage	 Load JPG	☒
92	15/02/18 11:02	General Damage	 Load JPG	☒
93	15/02/18 11:02	General Damage	 Load JPG	☒
94	15/02/18 11:02	General Damage	 Load JPG	☒
95	15/02/18 11:02	General Damage	 Load JPG	☒
96	15/02/18 11:02	General Damage	 Load JPG	☒
97	15/02/18 11:02	General Damage	 Load JPG	☒
98	15/02/18 11:02	General Damage	 Load JPG	☒
99	15/02/18 11:02	General Damage	 Load JPG	☒
100	15/02/18 11:02	General Damage	 Load JPG	☒
101	15/02/18 11:02	General Damage	 Load JPG	☒
102	15/02/18 11:02	General Damage	 Load JPG	☒
103	15/02/18 11:02	General Damage	 Load JPG	☒
104	15/02/18 11:02	General Damage	 Load JPG	☒
105	15/02/18 11:02	General Damage	 Load JPG	☒
106	15/02/18 11:02	General Damage	 Load JPG	☒
107	15/02/18 11:02	General Damage	 Load JPG	☒
108	15/02/18 11:02	General Damage	 Load JPG	☒
109	15/02/18 11:02	General Damage	 Load JPG	☒
110	15/02/18 11:02	General Damage	 Load JPG	☒
111	15/02/18 11:02	General Damage	 Load JPG	☒
112	15/02/18 11:02	General Damage	 Load JPG	☒
113	15/02/18 11:02	General Damage	 Load JPG	☒
114	15/02/18 11:02	General Damage	 Load JPG	☒
115	15/02/18 11:02	General Damage	 Load JPG	☒
116	15/02/18 11:02	General Damage	 Load JPG	☒
117	15/02/18 11:02	General Damage	 Load JPG	☒
118	15/02/18 11:02	General Damage	 Load JPG	☒
119	15/02/18 11:02	General Damage	 Load JPG	☒
120	15/02/18 11:02	General Damage	 Load JPG	☒
121	15/02/18 11:02	General Damage	 Load JPG	☒
122	15/02/18 11:02	General Damage	 Load JPG	☒
123	15/02/18 11:02	General Damage	 Load JPG	☒
124	15/02/18 11:02	General Damage	 Load JPG	☒
125	15/02/18 11:02	General Damage	 Load JPG	☒
126	15/02/18 11:02	General Damage	 Load JPG	☒
127	15/02/18 11:02	General Damage	 Load JPG	☒
128	15/02/18 11:02	General Damage	 Load JPG	☒
129	15/02/18 11:02	General Damage	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
130	15/02/18 11:02	General Damage	 Load JPG	☒
131	15/02/18 11:02	General Damage	 Load JPG	☒
132	15/02/18 11:02	General Damage	 Load JPG	☒
133	15/02/18 11:02	General Damage	 Load JPG	☒
134	15/02/18 11:02	General Damage	 Load JPG	☒
135	15/02/18 11:02	General Damage	 Load JPG	☒
136	15/02/18 11:02	General Damage	 Load JPG	☒
137	15/02/18 11:02	General Damage	 Load JPG	☒
138	15/02/18 11:02	General Damage	 Load JPG	☒
139	15/02/18 11:02	General Damage	 Load JPG	☒
140	15/02/18 11:02	General Damage	 Load JPG	☒
141	15/02/18 11:02	General Damage	 Load JPG	☒
142	15/02/18 11:02	General Damage	 Load JPG	☒
143	15/02/18 11:03	ESTIMATE	 Load PDF	
144	06/03/18 11:25	ESTIMATE LEONG AUTO	 Load PDF	
145	15/03/18 09:21	Investigation report	 Load PDF	
146	12/07/18 08:55	Investigation Report	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	05/02/18 15:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	05/02/18 15:41	Accident Photo	 Load JPG	☒
2	05/02/18 15:41	Accident Photo	 Load JPG	☒
3	05/02/18 15:41	Accident Photo	 Load JPG	☒
4	05/02/18 15:41	Accident Photo	 Load JPG	☒
5	05/02/18 15:41	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	05/02/18 12:18	Sketch Plan	 Load TIF	
2	05/02/18 12:18	Sketch Plan #2	 Load TIF	
3	05/02/18 12:18	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18002911/R1TBE2

Date: 12/07/2018

REFERENCE

Insured/Claimant: Alliance Concrete Singapore Pte Ltd

Policy No: B28985078MKF(COMP)

Date of Loss: 04/02/2018

Nature of Claim: OD

Claim No: 548834

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WC8911E

Make & Model: ISUZU CYH52S, 15.7 D (M)

Engine No: 6WG1422730

Reg. Date: 13/04/2015 (Man. Year: 2014)

Chassis No: JALCYH52SE7000205

Colour: White

Odometer: 80454 km

Engine Capacity: 15681 cc

Market Value/New Car Price: S\$120,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Firenza 8 mm

Rear Left Side: Firenza 8/8 mm

Front Right Side: Firenza 8 mm

Rear Right Side: Firenza 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	68,099.00	57,655.00	10,444.00	15.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,120.00	4,850.00	3,270.00	40.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	76,219.00	62,505.00	13,714.00	17.99
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	74,719.00	61,005.00	13,714.00	18.35
+ GST 7.00/7.00% (S\$)	5,230.33	4,270.35	959.98	18.35
Nett Amount (S\$)	79,949.33	65,275.35	14,673.98	18.35

INSPECTION

Date of Assignment: 13/02/2018

Date Inspected: 14/02/2018 Inspected At:

Say Wah Welding & Construction Pte Ltd
(HQ)NO. 211 KRANJI ROAD
Singapore 739461

Estimated Period of Repair: 18.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$9,810.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Jul 2018)	
Parts:	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WC8911E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET CEMENT MIXER CONTAINER ASSY WITH REAR SUPPORT BRACKET	Bent	3,500.00 F	*3,500.00 F
2	1		*SET CEMENT MIXER REAR CHUTE C/W BRACKET	Bent	1,800.00 F	*1,800.00 F
3	1		*2ND AXLE WHEEL MUDGUARD ASSY L/H	Bent	1,500.00 F	*1,500.00 F
4	1		*2ND AXLE WHEEL RIM L/H	* Check	950.00 F	*- F
5	1		*2ND AXLE WHEEL TYRE L/H	* Check	450.00 F	*- F
6	1		*3RD & 4TH AXLE WHEEL MUDGUARD ASSY L/H	Bent	1,800.00 F	*1,800.00 F
7	1		*3RD AXLE WHEEL RIM L/H	* Check	950.00 F	*- F
8	1		*3RD AXLE WHEEL TYRE L/H	* Check	450.00 F	*- F
9	1		*L/H SIDE GUARD RAIL	Bent	1,800.00 F	*1,800.00 F
10	1		*ISUZU EXHAUST CANISTER SILENCE ASSY	* Check	6,000.00 F	*- F
11	2		*EXHAUST CANISTER SILENCE BRACKET	* Check	240.00 F	*- F
12	1		*ISUZU EXHAUST CANISTER PROTECTOR PANEL	Bent	650.00 F	*650.00 F
13	1		*SET FUEL TANK ASSY	Bent	4,900.00 F	*4,900.00 F
14	2		*FUEL TANK BRACKET	Bent	800.00 F	*800.00 F
15	1		*FUEL TANK HOSE	* Check	150.00 F	*- F
16	1		*FUEL TANK FUEL FILTER	* Check	120.00 F	*- F
17	1		*FUEL TANK CAP	Missing	125.00 F	*125.00 F
18	1		*FRONT L/H DOOR REAR QUARTER PANEL (BENT)	Old Damaged	793.00 F	*- F
19	1		*FRONT L/H DOOR REAR QUARTER PANEL GLASS WITH RUBBER MOULDING	Not Necessary	121.00 F	*- F
20	1		*SET ALLIANCE CEMENT STICKER	Not Necessary	120.00 F	*- F
21	1		*SET NUMBER STICKER 936	Not Necessary	100.00 F	*- F
22	1		*REAR WATER CYLINDER TANK	Cracked	1,850.00 F	*1,850.00 F
23	1		*REAR WATER CYLINDER TANK SUPPORT BRACKET	Bent	930.00 F	*930.00 F
24	1		*SET CEMENT MIXER CONTAINER C/W HYDRAULIC MOTOR, CHAIN SET, MOTOR DRIVING & DRIVEN GEAR CONTAINER ROLLER BEARING 2 SETS & ETCS	Broken	38,000.00 F	*38,000.00 F

F=Franchise part.

Total Parts (S\$) 68,099.00 57,655.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE TO RECOVERY OF MIXER CONTAINER ON ACCIDENT SITE (* Check)	New	500.00	0.00
2	TO REMOVE & REFIX FRONT DOOR REAR QUARTER PANEL GLASS	New	120.00	0.00
3	TO REMOVE & REPLACE FUEL TANK ASSY, FUEL TANK FILTER AND BLEED SYSTEM REPAIR	New	400.00	200.00
4	LABOUR TO REMOVE & REPLACE DAMAGE MIXER, HYDRAULIC MOTOR, CHAIN SET, DRIVING & DRIVEN GEAR, BRACKET & ETC	New	3,800.00	3,000.00
5	WORKMANSHIP TO SPRAY PAINTING ON EFFECTED DAMAGE PARTS	New	3,000.00	1,500.00
6	TO REMOVE & REPLACE EXHAUST CANISTER SILCENCE ASSY	New	300.00	150.00
Gross Labour Cost (S\$)			8,120.00	4,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >