Sketch Plan Pg. 3





Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No: 1800-4849999								Report	t No. T/20180203/2048
REPORT OF A TRAFFIC ACCIDENT									
Date/Time Report Made: 03/02/2018 10:48			V	Vide Report No.;				S 3	tation Diary No.: 1
Informant's	Particul	ars							
Name of Informant: LOW LIN YI			Al	Address: APT BLK 636 ANG MO KIO AVENUE 6 #06-5167 SINGAPORE 560636					
ID Type / ID		7	C	Contact No.:					
NRIC NO / S Nationality:	9516767	Έ		Home/Office: Mobile: 93375725 Email:				5725	
SINGAPORE	CITIZE	N							
1	Age: 22	Date of Birt 12/05/1995		Type of Informant:					
Race:			La	Language: Institut			ıtion / School Name:		
Occupation:				Driving Licence Information:					
Marketing Ex								of Expiry:	
General Information of the Accident Type of Accident: Non-Injury Hit and Run			ent	Drink Date/Time of Drive: Accident: No 22/01/2018 20:30			Type of Location: Car Park		
Location: Along Road 1 JALAN LEBAN Car Park At Jalan Leban opposite SPC petrol Kiosk									
Weather:			R	Road Surface:				Road Speed Limit:	
Clear Traffic Flow:				Dry Traffic Control:				Traffic Volume:	
Hallic Flow.			1	Tranic Control.			Traine volume.		
Type of Collision: Moving Vehicle Against - Parked Vehic			√ehicle	sle			Anyone conveyed by ambulance:		
Telephone Colonia 200	\$100 € \$2, € \$100 ± \$2.516.00 ± \$100.00	18 martin 2005 200 200 1870	Server Server Construction					65.07.0000	
Vehicle No. Type Make				Ţ,	Model	Color	18.	and and	No of December
SJZ684X	Car	iviak		1	viouei	G0101	No	ndition	No of Passenger
01/7/0005								mage	
SKZ4928E	Car								0

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJZ684X	Car				No Damage	2
SKZ4928E	Car					0

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA			

Sketch Plan Pg. 4





Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 2 of 3 Report No. T/20180203/2048

Tel No: 1800-4849999

CONTINUATION OF REPORT

Driver				
Name	LOW LIN YI		ID No	S9516767E
Related Vehicle	SJZ684X (Car)		Contact No.	93375725
Hospital/Clinic	NIL .		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Disc	harge NIL	
No. of Days gran	Degree of	Injury NIL		

Brief Details.

On 22/1/2018 at about 2030hrs, I was driving my vehicle SJZ684X out of a car park lot located opposite Jalan Leban SPC petrol kiosk. When I reversed my car out, I felt that I might have collided into another parked car. I went down to make a check on my vehicle and there was nothing amiss. I also made a check on the vehicles that was parked behind my car and nothing was amiss. No vehicle was damaged and no one was injured. Thus, I continued to move my car out of the car park lot and left the car park.

Sketch Plan Pg. 5





Police Station Of Origin: Ang Mo Kio North N.P.C 51 Ang Mo Kio Avenue 9 SINGAPORE 569784

3 of 3 Report No. T/20180203/2048

Tel No: 1800-4849999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
Sgt 2 JAYZ TAN ZHANG JIE	hard
Signature Of Interpreter:	Date/Time:
Not applicable	03/02/2018 10:48
Officer In Charge Of Case:	Classification Of Case:
SI TAN LEE HWANG DAWN	
Contact No.: 65476215	
Ochlact No.: 00470210	
Authentication Stamp	Δ.
ND169	/ V .