Surveyor:

REF: AXA

ASSIGNMENT

From: Date: 14.02.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDV 618E

at Workshop m/s Ah Lim Motor

of Blk 10 AMK Ind Park 2A #01-09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

12 pm

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1-B.P% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SDV 618E Yr Regn: 10 / 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Sports Car

Make: Merc SLK200 c.c 1796

Colour M Black A/C: Insured / Std / NI / NA

Sp.Reading 71036 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDB1714452F203867

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 255/35ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Habilead

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	5/2/18	D.O.I.	14/2/18

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/2	File pass to Minita

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) __S + RS __SI

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation

Photos

Others

TOTAL