

ASS. REC. BY: _____ REF: CS/III18002931/Svd3e2 Special Instruction: _____
 Surveyor: Subscription ASSIGNMENT (Office)
 From (Person): Mennen Gabriel Wee of III Date/Time: 13/2/18 @ 12:04pm
 Estimated Cost: _____ Bill to: _____
 OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SJP 6159J Insured: _____
 at Workshop m/s Long Sheng Motor - Zhong Cheng Tel: 9338 2859
 of Blk 6, No. 399 Woodlands Rd Yew Tee Ind. Est
 Policy No: M490973W Claim No: MC20182150
 Sum Insured: _____ Excess: TBA 600
 Make of Veh: _____ D.O.A. 12/02/2018
 (Client's Record) 14/02/18 Insp: Zhong Cheng; Blk 6, 399J
 CA / (REV) REP. / REV 24 HRS H.O.D. Endorsement: _____
 Date/Time: 3:25pm @ 13/2/18 Person Contacted: Sini Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJP 6159J - X</u>
<u>19/2/18</u>	<u>Sent pref. thru mennen; Pending parts price</u>
<u>20/2/18</u>	<u>Part price not ready</u>
<u>22/2/18</u>	<u>@10.37am Spoken to Sini max repair cost \$6k</u>
<u>23/2/18</u>	<u>Repairer agree on LS not exceeding \$6k</u>

REF: 711

ASSIGNMENT

Estimated Cost:

① TP / WS / TP RES / CO RES / EVA / INV / MV

To inspect vehicle No: SJP 6159J

at Workshop no: Zhong Cheng

of: B1K 6-399J, Woodlands Rd

Insured

Policy No

Claims No

Sum Insured Excess: TBA

(Client's Record) Sini ② 93382859

Make of van

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

NS	OS

Est. or Market Value: 7k.

OAC Accident Report Consistent? Yes or No

DIA / PR Seen Consistent? Yes or No

Est. Repairs days Rep: Yes or No

Lum Sum % 3 Val: Yes or No

CA / REV REP / 24 HRS

Date Person Contacted Vehicle IN / OUT

Van No: SJP 6159J

Reg: 03 2009

Type: M ① / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer

Make: Chevrolet 1598

Colour: White A/C Insured Std N / N

Sp. Reading: 132602 T-Radio Insured Std N / N

Eng No:

Ch No: KL1N419C1384107720

Gen. Cond: Good / ② / Poor / Burnt

Steering: ③ / Jammed / Leaked / Burnt or

Brake: ④ / Jammed / Leaked / Burnt or

Mod: M / S Rim / STD A Rim or

Tyre Size: P 215/45R17

R: H

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTU / PIR / SUM

TOYO / YOKO or Goodyear

Front

Rear

R.Sa: 6 mm R.Sa: 6 mm

L.Sa: 6 mm L.Sa: 6 mm

D.O.A. D.O.: 14/7/18

Surveyed at: Zhong Cheng

Des. of Damages: Frt. / Rear / OS / NS / UC / Roof / or

The UC / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

14/7/18 No G14

23/2/18 Revert by merimen, est LS \$6000 p

26/2/18 Rce approved from laitha by merimen

Sebastian

Pls: check parts prices & see my remarks

26/2/18 @456pm Informed Sini on LS not more than \$6000 or \$600

3/7/18 LS \$6000 confirmed by email (Ref 7921.98, 5719)

RECEIVED 3 JUL 2018

Date Time File Pass of

☐

: Prel. Report

Days Of Repair: 7

☐

: Final Report

Resurvey No. of Trip: 1

Date Time File Return of

Survey Fee

390

3/7 - typist

Add Fee:

☐

Sine Insp: 4

☐

Photo: 4

☐

Tech: 4

☐

Clean: 4

Transporter

3-Pass

Passes

Costs

10

Report Format

merimen

Lum Sum LS: LS \$6000 p

360

Survey Department Check List (Case Handler)

Reference No.: CS) III 18002931 Svc3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 3/7/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III18002931/Svd3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 13-02-2018



Code : III2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SJP 6159J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From GABRIEL WEE	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 12/02/2018	Inspection Date
Survey held at ZHONG CHENG-BLK 6, 399J	
Repairer LONG SHENG MOTOR SERVICE	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

View Received Message

This mail is associated with :

***SJP6159J**
OD
Feb 12 2018 6:00AM
[JUMAT BIN ZAINAL]
Zhong Cheng Enterprise

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 26/02/2018 08:56 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6000.00) - SJP6159J - Claim Handler: Lalitha Krishnan

Approved:6000.00:Please let us have details of damaged items.

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 13 February 2018 12:04 PM
To: Zhong Cheng; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Lalitha Krishnan - III
Subject: RE: vehicle no. SJP 6159J GIA report
Attachments: SAS2357460 (1).pdf

Dear Sir/Mdm,

Please conduct an OD survey on our vehicle SJP6159J and let us have your report urgently.

This claim will be handled by Lalitha.

*Kindly create OD claim & upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Zhong Cheng [mailto:zhongchengauto@gmail.com]

Sent: 13 February, 2018 10:33 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: vehicle no. SJP 6159J GIA report

Dear Gabriel,

Please appoint LKK Auto.

Thank you

Sent from my iPhone

On 13 Feb 2018, at 9:19 AM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- Autoprobe Consultants
- VP Appraisal
- Quantum Risk Management
- Ajax Inspection Services Pte Ltd

- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Premier Appraisers Services
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Zhong Cheng [<mailto:zhongchengauto@gmail.com>]

Sent: 12 February, 2018 7:37 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Fwd: vehicle no. SJP 6159J GIA report

Dear Officer,

Attached GIA report FYI and approval for repairing this vehicle. Insured intention claim own damaged.

Please do not hesitate to contact us at 93382859 should you need further documents

Thank you

Sini Tan

Sent from my iPhone

Begin forwarded message:

From: "LSMTYC" <lsmstyc@singnet.com.sg>

Date: 12 February 2018 at 5:52:51 PM SGT

To: <zhongchengauto@gmail.com>

Subject: vehicle no. SJP 6159J GIA report

Hi,

Please refer attachment of vehicle no. SJP 6159J GIA report.

***Wishing you a happy Chinese new year
Gong Xi Fa Cai***

Best Regards,

Apple Sim

Long Sheng Motor Service
Blk 6 , No.399-G , Woodlands Road ,
Yew Tee Industrial Estate ,
Singapore 678007 .
Tel : +65 6763 9733
Fax: +65 6763 9866
Email : lsmsstyc@singnet.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.
Registration No. 198703792-K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	India International Insurance Pte Ltd 64 Cecil Street #04-00 IOB Building Singapore 049711	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Lalitha Krishnan	Date:	23 Feb 2018
<u>Preliminary Advice</u>			

Vehicle No	: SJP6159J	Accident Date	: 12/02/2018
Make	: CHEVROLET OPTRA5	Policy No.	: M490973W
Assignment Date	: 19/02/2018	Excess	: S\$600.00
Date of Inspection	: 14/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: ZHONG CHENG ENTERPRISE BLK 6 WOODLANDS ROAD, YEW TEE INDUSTRIAL ESTATE 399J SINGAPORE 678008		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,921.98
Revised Amount	:S\$	11,097.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair (estimated)	:S\$	6,000.00
-----------------------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	7,000.00
COE / PARF Rebate	:S\$	580.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,420.00

Remarks

<input checked="" type="checkbox"/>	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
<input type="checkbox"/>	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
<input type="checkbox"/>	Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Laliitha Krishnan

Date: 19 Feb 2018

Preliminary Advice

Vehicle No	: SJP6159J	Accident Date	: 12/02/2018
Make	: CHEVROLET OPTRA5	Policy No.	: M490973W
Assignment Date	: 19/02/2018	Excess	: S\$0.00
Date of Inspection	: 14/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: ZHONG CHENG ENTERPRISE BLK 6 WOODLANDS ROAD, YEW TEE INDUSTRIAL ESTATE 399J SINGAPORE 678008		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,435.00 (Labour Only)
Revised Amount	:S\$	2,415.00 (Labour Only)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,415.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	7,000.00
COE / PARF Rebate	:S\$	580.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,420.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING PART PRICES.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9117C
Vehicle Details	
Vehicle No.:	SJP6159J
Vehicle to be Exported:	No
Intended De-registration Date:	19 Feb 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	OPTRA 1.6AT MY7.5 FACELIFT
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	F16D32422731
Chassis No.:	KL1NA196E8H107720
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,939.00
Original Registration Date:	30 Mar 2009
First Registration Date:	30 Mar 2009
Transfer Count:	0
Actual ARF Paid:	\$1,055.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2019
PARF Rebate Amount:	\$580.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$580.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2018 11:04
Date Of Accident	12/02/2018 06:40
Exact Location Of Accident	ALONG SLE TOWARDS TO BKE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJ6159J
Insured/Policyholder	
Name Of Registered Owner	JUMAT BIN ZAINAL
NRIC No	S1729117C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97613567
Alternative Phone No	OTHERS-97613567

Vehicle Particulars

Manufacturer	CHEVROLET
Model	OPTRA5-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M490973W
Cover Note Number	

Driver

Name of Driver	JUMAT BIN ZAINAL
NRIC No	S1729117C
Date Of Birth	24/12/1965
Occupation	INDOOR
Date Of Driving Pass	14/03/1986
Driving Experience	31 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97613567
Fax Number	
Contact Number	OTHERS-97613567
EMail Address	NOEMAIL

Address	APT BLK 665 CHOA CHU KANG CRESCENT #04-277 SINGAPORE 680665
Postcode	680665
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

To the above mentioned accident along SLE going to BKE EXIT I was on second lane, with heavy morning traffic in front of my vehicle SKG 1361J B.M.W X3 silver colour suddenly stop due to few vehicle was jam brake. Due to limited view in front of me I can't brake on time and hit his rear bumper.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

Vehicle A SJP 659J

Vehicle B SKG 1361J


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Today at 6.40am along SLE going to BKE exit I was on second lane, with heavy morning traffic in front of my vehicle - BMW X3 ^{SJP 659J} silver color suddenly stop due to low vehicle ~~few vehicle~~ was jam brake. Due to limited view in front of me I can't make brake on time and hit his rear bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 190703792N | GST Reg. No. M2-0078806-X
 64 Cecil Street #04/ #05/ #06-02 IOB Building Singapore 049711
 Office (65) 63476100 Email: insure@iil.com.sg
 Fax: (65) 62244174 Website: www.iil.com.sg

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1929 (MALAYSIA)

This certificate is not transferable to a new owner of the vehicle. If for any reason the insurance is terminated during its currency, the Certificate must be returned to the insurer, or if the Certificate has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the legislation relating to compulsory insurance.

The Certificate must be returned if the insurance is suspended during its currency.

WEEKEND CAR

Agency Code: 45060SE
 Comprehensive

Insured/ Named Drivers Excess: \$600/- Sect 1

Unnamed Drivers Excess: \$1100/- Sect. 1 & additional \$2500/- Sect. 1 for age < 21 years or > 65 years &/or S'pore D.L. < 2 years

Windscreen Excess: \$100/-

CERTIFICATE NO.

M490973W

1. Indus Mark and Registration Number of Vehicle

SJP 6159 J

2. Name of Policy Holder

Jumat Bin Zainal

3. Effective date of the Commencement of Insurance for the purposes of the Act

30th March 2017

4. Date of Expiry of Insurance

29th March 2018

5. Person or Classes of Persons entitled to drive*

(a) The Policyholder

The Policyholder may also drive a Motor Car not belonging to or hired (under a hire purchase agreement or otherwise) to him/her or his/her employer or his/her partner.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 2 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Date of Issue: 17/24.03.2017

for India International Insurance Pte. Ltd.
 (APPROVED INSURERS)

MX 1 (PRIVATE CAR)
 INDIVIDUAL OWNERSHIP

Authorized Signature

IMPORTANT NOTICE

Policyholders are hereby warned that under the Motor Vehicle (Third Party Risks and Compensation) Act (Cap. 189), it shall be unlawful for any person to use or to cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

Policyholders are further warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189).

The Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner they will endorse the policy accordingly and will issue a new Certificate of Insurance in the new owner's name.

IN THE EVENT OF AN ACCIDENT NOTIFICATION SHOULD BE GIVEN IMMEDIATELY TO THE COMPANY. FAILURE TO DO SO WILL BE LIAISON UNDERWRITERS DECISION ONLY.

Agent/Broker Name: Jurdline

Hire Purchase Company: NA

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO:

SJP 6159J

Adjustment of Spare Parts Costs for Repairs			Estimate by
Item	Qty	Vehicle parts description	
		front bumper ✓ CRK	
	2	front bumper side retainer ✓ NEC	
	1	front bumper reinforcement ?	
	2	front bumper fog lamp ?	
	1 set	front bumper fasteners ✓ NEC	
	2	head lamp RH CRK ✓ LH ?	
	2	headlamp lower bracket ?	
	2 set	headlamp fasteners ✓ NEC	
	1	front support panel R	
	1	front support panel top garnish ✓ CRK	
	1 set	front support panel top garnish fasteners ✓ NEC	
	2	front fender @S\$587.6 R LH RH ✓ BT	
	2 set	front fender fasteners @S\$20.00 ✓ NEC	
	1	radiator assy ?	
	2	radiator mounting w/bracket @S\$28.00 ?	
	1	A/C condensor ✓ BT	
	2	A/C condensor mounting w/bracket @S\$35.00 ✓ NEC	
	2	front fender inner shield @S\$75.60 ?	
	2 set	front fender inner shield fasteners @S\$25.00 ?	
	1	bonnet inner lock X	
	1	front bonnet ✓ BT	
	1	air con fan cowling ?	
	1	radiator fan cowling ?	
			0.00
		Less 20%	0
			0.00
		Special nett item	
	1	front bumper lower skirt ✓ CRK	
	3	front bumper lower skirt fasteners / clips ✓ NEC	
	11	number plate w casing ✓ BT	
		Total parts	0.00

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and front expandable items. 1400.00
1000

To remove and replaced damaged parts including straightening
and repositioning replacement parts & panel beat 1600.00
~~1000~~ 1100

Check wiring and rewire 50.00 30
to realign headlamp focus 35 ✓
to remove and reinstall radiator and A/C condensor 120 50
to vacuum and refill a/c refrigerant R134A 60 50
to anti-rust 120 50
to top up coolant 50 40

Total labour 3435.00

Sub Total 3435.00

7 days.

Sebastian.

14/2/18.

- Loop Sun Repair.
- Question mark Itan Photo.
- Photo After Paint.

90036121

sebastian.yeang@lkkauto.com

Revert

Excess - TBA.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


23/2/18

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: **SSP 6159J**

Adjustment of Spare Parts Costs for Repairs			Estimate by
Item	Qty	Vehicle parts description	
		front bumper ✓ CRK	
	2	front bumper side retainer ✓ NEC	
	1	front bumper reinforcement ? ✓ CRK	
	2	front bumper fog lamp ? ✓ CRK	
	1 set	front bumper fasteners ✓ NEC	
	2	head lamp RH CRK ✓ LH ? ✓ CRK	
	2	headlamp lower bracket ? ←	
	2 set	headlamp fasteners ✓ NEC	
	1	front support panel R	
	1	front support panel top garnish ✓ CRK	
	1 set	front support panel top garnish fasteners ✓ NEC	
	2	front fender @S\$587.6 R LH RH ✓ DT	
	2 set	front fender fasteners @S\$20.00 ✓ NEC	
	1	radiator assy ? ✓ DT	
	2	radiator mounting w/bracket @S\$28.00 ? ✓ NEC	
	1	A/C condensor ✓ DT	
	2	A/C condensor mounting w/bracket @S\$35.00 ✓ NEC	
	2	front fender inner shield @S\$75.60 ? ←	
	2 set	front fender inner shield fasteners @S\$25.00 ? ←	
	1	bonnet inner lock X	
	1	front bonnet ✓ DT	
	1	air con fan cowling ? ✓ CRK	
	1	radiator fan cowling ? ✓ BR	
			0.00
		Less 20%	0
			0.00
		Special nett item	
	1	front bumper lower skirt ✓ CRK	
	3	front bumper lower skirt fasteners / clips ✓ NEC	
	11	number plate w casing ✓ DT	
		Total parts	0.00

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and front expandable items.	1400.00 1000
To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat	1600.00 1000 1100
Check wiring and rewire	50.00 30
to realign headlamp focus	35 ✓
to remove and reinstall radiator and A/C condensor	120 50
to vacuum and refill a/c refrigerant R134A	60 50
to anti-rust	120 50
to top up coolant	50 40
Total labour	3435.00
Sub Total	3435.00

7 days

Sebastian.
14/2/18.
- Lump Sum Repair.
- Question mark Insurance Photo.
- Photo After Paint.
90036121
sebastianyong@lkk-auto.com
Revert
Excess : TBA.

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
--

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJP6159J

Adjustment of Spare Parts Costs for Repairs			Estimate by workshop
Item	Qty	Vehicle parts description	
	1	front bumper ✓ CRK	693.00
	2	front bumper side retainer ✓ NEC	56.00
	1	front bumper reinforcement ✓ CRK	579.00
	2	front bumper fog lamp ✓ CRK	258.00
	1 set	front bumper fasteners ✓ NEC	28.00
	2	head lamp @ \$757 each ✓ CRK @ 757	1594.00
	2 set	headlamp fasteners ✓ NEC	56.00
	1	front support panel R	99.00
	1	front support panel top garnish ✓ CRK	95.00
	1 set	front support panel top garnish fasteners ✓ NEC	28.00
	2	front fender @ \$650 each R LH R R ✓ DT	1300.00
	2 set	front fender fasteners @ \$20.00 ✓ NEC	40.00
	1	radiator assy ✓ DT	694.00
	2	radiator mounting w/bracket @ \$28.00 ✓ NEC	56.00
	1	A/C condensor ✓ DT 796 ←	825.00
	2	A/C condensor mounting w/bracket @ \$35.00 ✓ NEC	70.00
	2	front fender inner shield @ \$75.60 X NN	151.20
	2 set	front fender inner shield fasteners @ \$25.00 ✓ NEC	50.00 30
	1	bonnet inner lock X NN	45.00
	1	front bonnet ✓ DT 543.70 ←	1496.00
	1	air con fan cowling ✓ CRK	438.00
	1	radiator fan cowling ✓ CRK	448.00
			9099.20
		Less 10%	909.92
			8189.28
		Special nett item	
1	1	front bumper lower skirt ✓ CRK	350.00
3	1	front bumper lower skirt fasteners / clips ✓ NEC	38.00 30
11	2	number plate w casing ✓ DT	60.00 45
		Total parts	<u>448.00</u>

Adjustment of Labour Costs for Repairs

Supply paint material to the rear and front expandable items. 1496.00
1000

To remove and replaced damaged parts including straightening and

repositioning replacement parts & panel beat

1600.00 ⁷⁰⁰ ~~400~~ - too high? Δ

Check wiring and rewire

to realign headlamp focus

to remove and reinstall radiator and A/C condensor

to vacuum and refill a/c refrigerant R134A

to anti-rust

to top up coolant

50.00 ³⁰
35.00 ³⁰ } 30 Δ
120.00 ⁸⁰
60.00 ⁵⁰
120.00 ⁸⁰
50.00 ⁹⁰

Total labour

3435.00

Sub Total

12072.28

13,921.98

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SJP6159J

Adjustment of Spare Parts Costs for Repairs			Estimate by workshop
Item	Qty	Vehicle parts description	
	1	front bumper upper grille ✓ CRK	703.00
	1	front bumper lower grille ✓ CRK	98.00
	1	front bumper logo ✓ NEC	95.00
	2	front bumper fog lamp cover @ \$59 each X NA	118.00
	1 set	front bumper fasteners Reported	28.00
	2	head lamp panel @ \$256 each R	512.00
	1	radiator member X NN	279.00
			<hr/>
			1833.00
Less 10%			<hr/>
			183.30
			<hr/>
			1649.70

Labour

Towing for dismantle/ fixing of carplate seal 200.00
130

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 3 July 2018 3:16 PM
To: 'Zhong Cheng'
Cc: SUR
Subject: RE: Outstanding cases by Sebastian

Dear Sini,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zhong Cheng [<mailto:zhongchengauto@gmail.com>]
Sent: Tuesday, 3 July 2018 3:12 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: Outstanding cases by Sebastian

Hi Veron,

Ok to accept \$6000 and 7days.

Thanks

Sent from my iPhone

On 3 Jul 2018, at 1:32 PM, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Sini,

SJP 6159J -Offer Lump Sum Max \$6000/- before excess \$600

No of days: 7 days

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zhong Cheng [<mailto:zhongchengauto@gmail.com>]

Sent: Thursday, 28 June 2018 4:48 PM

To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: Re: Outstanding cases by Sebastian

Hi Veron/Catherine,

Understand Sebastian has left. Can u help me get Taufikh/Rasul to help finalise these cases? Its very long already.

SJQ7855X Oct 2017

SJW2342K Nov 2017

SJP6159J OD claim India Insurance (Urgent)

SJM5540M Jan 2018

Best Regards

Sini Tan

Zhong Cheng Enterprise Pte Ltd

Blk 6, 399J

Yew Tee Industrial Est

S678008

HP: 93382859 Fax: 68942883

On Fri, May 4, 2018 at 1:27 PM, Zhong Cheng <zhongchengauto@gmail.com> wrote:

Dear Veron,

Please help me to remind Sebastian to finalise these cases below soonest:

SJQ7855X Oct 2017

SJW2342K nov 2017

SJP6159J OD claim India Insurance

Thank you

Best Regards

Sini Tan

Zhong Cheng Enterprise Pte Ltd

Blk 6, 399J

Yew Tee Industrial Est

S678008

HP: 93382859 Fax: 68942883





































...CLAIM SUBFOLDER...(Pending for Survey Report)














































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2018 Edit Reg		13 Feb 2018 00:00 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: JUMAT BIN ZAINAL ID: S1729117C									
Vehicle Reg. No.: SJP6159J		Date of Loss: 12/02/2018 06:00 - :59 [106 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / MC20182150		Policy/Cover Note No.: M490973W (Comprehensive)							
		Excess: S\$600.00							
Repairer: Zhong Cheng Enterprise () Bldg 6 Woodlands Road, Yew Tee Industrial Estate 399J, 678008 Woodlands - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 28/02/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (26/02/2018): Alert - Adj Mandate Approved (S\$6000.00) - SJP6159J - Claim Handler: Lalitha Kri... III_SG (21/02/2018): Alert - Adj Mandate Maintained - SJP6159J - Claim Handler: Lalitha Krishnan 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJP6159J (MC20182150)
 OD
 Feb 12 2018 6:00AM
 [JUMAT BIN ZAINAL]
 Zhong Cheng Enterprise

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/02/18 17:02	Adjuster Immediate Advice		Load HTM	
2	23/02/18 08:39	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
2	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
3	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
4	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
5	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
6	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
7	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
8	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
9	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
10	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
11	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
12	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
13	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
14	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
15	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
16	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
17	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
18	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
19	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
20	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
21	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
22	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
23	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
24	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
25	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
26	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
27	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
28	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
29	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
30	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
31	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
32	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
33	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>
34	19/02/18 17:21	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
38	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	19/02/18 17:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	03/07/18 13:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/02/18 17:19	SJP 6159J ESTIMATE	 Load PDF	
2	22/02/18 10:01	MARK ESTIMATE	 Load PDF	
3	10/07/18 09:30	Supplementary	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/02/18 08:53	Singapore Accident Statement-with typo mistake of ID veh number	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III18002931/SVD3E2

Date: 10/07/2018

REFERENCE

Insured/Claimant: JUMAT BIN ZAINAL

Policy No: M490973W

Date of Loss: 12/02/2018

Nature of Claim: OD

Claim No: MC20182150

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP6159J

Make & Model: CHEVROLET OPTRA5, 1.6 (A)

Engine No: F16D32422731

Reg. Date: 30/03/2009 (Man. Year: 2008)

Chassis No: KL1NA196EBH107720

Colour: White

Odometer: 132602 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$7,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,286.98	7,937.93	2,349.05	22.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,635.00	2,110.00	1,525.00	41.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,921.98	10,047.93	3,874.05	27.83
Approved Total (Overridden) (S\$)		6,000.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	13,321.98	5,400.00	7,921.98	59.47

INSPECTION

Date of Assignment: 13/02/2018

Date Inspected: 14/02/2018 Inspected At:

Zhong Cheng Enterprise
Blk 6 Woodlands Road, Yew Tee Industrial
Estate 399J
Singapore 678008

Estimated Period of Repair: 7.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2018)
Parts: 144	CHEVROLET OPTRA5 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJP6159J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	693.00 FL	*693.00 FL
2	2		*FRONT BUMPER SIDE RETAINER	Necessary	56.00 FL	*56.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Cut	579.00 FL	*579.00 FL
4	2		*FRONT BUMPER FOG LAMP	Cracked	258.00 FL	*258.00 FL
5	1		*SET FRONT BUMPER FASTENERS	Necessary	28.00 FL	*28.00 FL
6	2		*HEAD LAMP	Cracked	1,594.00 FL	*1,594.00 FL
7	2		*SET HEADLAMP FASTENERS	Necessary	56.00 FL	*56.00 FL
8	1		*FRONT SUPPORT PANEL	Repair	99.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	95.00 FL	*95.00 FL
10	1		*SET FRONT SUPPORT PANEL TOP GARNISH FASTENERS	Necessary	28.00 FL	*28.00 FL
11	1		*FRONT FENDER	N/S Repair / O/S Dented	1,300.00 FL	*650.00 FL
12	2		*SET FRONT FENDER FASTENERS	Necessary	40.00 FL	*40.00 FL
13	1		*RADIATOR ASSY	Dented	694.00 FL	*694.00 FL
14	2		*RADIATOR MOUNTING W/BACKET	Necessary	56.00 FL	*56.00 FL
15	1		*A/C CONDENSOR	Dented	825.00 FL	*796.00 FL
16	2		*A/C CONDENSOR MOUNTING W/BACKET	Necessary	70.00 FL	*70.00 FL
17	2		*FRONT FENDER INNER SHIELD	Not Necessary	151.20 FL	*- FL
18	2		*SET FRONT FENDER INNER SHIELD FASTENERS	Necessary	50.00 FL	*30.00 FL
19	1		*BONNET INNER LOCK	Not Necessary	45.00 FL	*- FL
20	1		*FRONT BONNET	Bent	1,496.00 FL	*842.70 FL
21	1		*AIR CON FAN COWLING	Cracked	438.00 FL	*438.00 FL
22	1		*RADIATOR FAN COWLING	Cracked	448.00 FL	*448.00 FL
23	1		*FRONT BUMPER LOWER SKIRT	Cracked	350.00 FS	*350.00 FS
24	1		*FRONT BUMPER LOWER SKIRT FASTENERS / CLIPS	Necessary	38.00 FS	*30.00 FS
25	2		*NUMBER PLATE W CASING	Bent	60.00 FS	*45.00 FS
26	1		*FRONT BUMPER UPPER GRILLE	Cracked	703.00 FL	*703.00 FL
27	1		*FRONT BUMPER LOWER GRILLE	Cracked	98.00 FL	*98.00 FL
28	1		*FRONT BUMPER LOGO	Necessary	95.00 FL	*95.00 FL
29	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	118.00 FL	*- FL
30	1		*SET FRONT BUMPER FASTENERS	Repeated	28.00 FL	*- FL
31	2		*HEAD LAMP PANEL	Repair	512.00 FL	*- FL
32	1		*RADIATOR MEMBER	Not Necessary	279.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 11,380.20 8,772.70
 - List Item Discount on L Items 10.00/10.00% (S\$) 1,093.22 834.77

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					10,286.98	7,937.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SUPPLY PAINT MATERIAL TO THE REAR AND FRONT EXPANDABLE ITEMS	New	1,400.00	1,000.00
2	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS & PANEL BEAT	New	1,600.00	700.00
3	CHECK WIRING AND REWIRE }	New	50.00	30.00
4	TO REALIGN HEADLAMP FOCUS }	New	35.00	0.00
5	TO REMOVE AND REINSTALL RADIATOR AND A/C CONDENSOR	New	120.00	80.00
6	TO VACUUM AND REFILL A/C REFRIGERANT R134A	New	60.00	50.00
7	TO ANTI-RUST	New	120.00	80.00
8	TO TOP UP COOLANT	New	50.00	40.00
9	TOWING FOR DISMANTLE / FIXING OF CARPLATE SEAL	New	200.00	130.00
Gross Labour Cost (\$\$)			3,635.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >