

ASS. REC. BY:

REF: CS/ASM18002936/MI9d30 Special Instruction:

Surveyor: MA

ASSIGNMENT (Office)

From (Person): Khor Saw Theng

of

ASM

Date/Time: 13/02/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S12 6246M

Insured:

at Workshop m/s

K. Kim Hin Auto

Tel:

64527018

of

160 8th Ming Drive #02-20

Policy No:

Claim No:

88M00813

Sum Insured:

Excess:

\$300.00

Make of Veh:

(Client's Record)

D.O.A.

5/2/18

MV: 627K

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4:15pm 13/2/18

Person Contacted:

Sandra

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	S12 6246M - C04/ASM18002339/hb3 D.O.A: 5/2/18
12/3/18 @ 2.59pm	revised to Yvonne Ang via Smart Claim.
08/3/18 @ 5.34pm	Informed Shu Man, CAA & Ex: \$300 by email.
14/5/18 @ 4.56pm	confirmed with Meng that final fig \$1280, 4 days.
	added \$1258, 50%.
	no lump sum.



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
 TEL: 6453 1235, 6452 0850 FAX: 6453 7944
 24hrs Towing Services Tel: 9823 9898
 Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

LKK

EQ INSURANCE COMPANY LIMITED

NO. 5

MAXWELL RD #17-00 SINGAPORE 069110

MND COMPLEX

SINGAPORE 069110

Attention: TOBA PADANG

Contact : 98008646

Fax No. : 62243903

Estimate : QUOT201803-000238(00)

Date : 09/03/2018

Vehicle No. : GQ5994B

Make/Model : FIAT DOBLO CARGO MAXI 1.6MJ
DIESEL (MTA)

Mileage (km) : 0

Chassis No. : ZFA26300006106149

Accident Date : 03/03/2018 00:00:00

Claim No. :

Reference : GQ5994B

Policy No. : DMCPHQ17-007101



Not Authorized
 1.B.1
 Recovery Blenheim

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS				
1	Front bumper	1.0	889.00	889.00
2	Front bumper side retainer	2.0	95.00	190.00
3	Front bumper sponge	1.0	225.00	225.00
4	Front bumper reinforcement	1.0	525.00	525.00
5	Front bumper towing cover	1.0	45.00	45.00
6	Front bumper logo	1.0	118.00	118.00
7	Front bumper upper grille	1.0	325.00	325.00
8	Front bumper lower grille	1.0	315.00	315.00
9	Headlamp	2.0	550.00	1,100.00
10	Headlamp lower bracket	2.0	95.00	190.00
11	Bonnet	1.0	950.00	950.00
12	Bonnet lock	1.0	210.00	210.00
13	Bonnet hinge	2.0	105.00	210.00
14	Support top panel	1.0	835.00	835.00
15	A/c condenser	1.0	695.00	695.00
16	A/c discharge pipe	1.0	355.00	355.00
17	A/c suction pipe	1.0	490.00	490.00
18	A/c liquid pipe	1.0	480.00	480.00
19	Radiator	1.0	685.00	685.00
20	Radiator air guide - upper	1.0	80.00	80.00
21	Radiator air guide - lower	1.0	80.00	80.00
22	Fan cowling	1.0	245.00	245.00
23	Fan motor assy	1.0	585.00	585.00
24	Foglamp cover (without foglamp type)	2.0	115.00	230.00
25	Turbo intercooler	1.0	650.00	650.00
26	Power steering cooler pipe	1.0	485.00	485.00
27	Power steering fluid	1.0	68.00	68.00
28	Front RH fender	1.0	495.00	495.00
29	Radiator air shroud - upper	1.0	225.00	225.00
List Total :				11,975.00
10% Discount S\$				1,197.50
				10,777.50

SPECIAL NET

CONTINUE NEXT PAGE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18002936/M1qd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 13-02-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJZ 6246M
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00813	Excess (\$)	300.00
Assign From	SMARTCLAIM (KHOR SAW THENG)	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/02/2018	Inspection Date	
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/ASM18002936/M1qd3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 13-02-2018



Code : ASM

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SJZ 6246M
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00813	Excess (\$)	300.00
Assign From	SMARTCLAIM (KHOR SAW THENG)	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/02/2018	Inspection Date	
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.




Service Request Details

Claim

S8M008I3

Reference

None 

Loss Date

February 5, 2018

Request Date

February 13, 2018

Due Date

February 21, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJZ6246M

Make

HONDA

Service Address

Primary Contact/Insured

WRYE IV WALTER CLARK
2 SINARAN DRIVE, #26-03, 307467, Singapore

FRANCIS@ANVERON.COM

Claim Handler

KHOR Saw Theng
6568804754
sawtheng.khor@axa.com.sg

Additional Instructions
Basic excess \$300

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

 Upload Documents

NAME

 DL.pdf

TYPE

Forms / Claim Documents

SUB-TYPE

Driver's License / IDP

AUTHOR

K KIM HIN AUTO PTE LTD (VP)

DATE UPLOADED

February 10, 2018

NAME

 FIN number.pdf

TYPE

Forms / Claim Documents

SUB-TYPE

Identity card / Certificate

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 24 May 2018 4:56 PM
To: 'survey@kkimhin.com.sg'; Ma C.F (LKKAUTO)
Cc: SUR
Subject: RE: SJZ6246M OD-AXA FINALISATION

Dear Meng Huat,

Confirm final fig \$1,280.00 before excess \$300.00 and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: survey@kkimhin.com.sg [mailto:survey@kkimhin.com.sg]

Sent: Tuesday, 22 May 2018 7:22 PM

To: Ma C.F (LKKAUTO) <MaCF@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: SJZ6246M OD-AXA FINALISATION

Hi Mr Ma,

Enclosed you attention.

P/P=\$1,280.00

Please confirm.

Thank you.

Regard

Meng Huat

K.Kim Hin Auto



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S8M00813

Date: 12th March 2018

Our Ref: CS/ASM18002936/M1qd3

The Motor Claims Department
AXA Insurance Singapore Pte L td

Attn: Khor Saw Theng

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SJZ 6246M .


We thank you for the instruction on 13/02/2018 .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/03/2018 (1.29pm) at the premises of M/s K KIM HIN and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,538.00</u> .
Revised Estimate Amount	: S\$ <u>1,330.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Total	: S\$ <u>1,330.00</u> .
Market Value	: S\$ <u>22,000.00</u> .
LTA Reimbursement Value	: S\$ <u>0.00</u> .
Nett Value	: S\$ <u>22,000.00</u> .

Description of Damage:

The vehicle sustained damages at the o/s portion.



Comments/ Present Status:

Damages consistent.

Recommend days of repair: 4 days

We have authorised the repairs.

Yours faithfully

Ma C.F.
Automobile Assessor

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 8 March 2018 5:34 PM
To: 'admin1@kkimhin.com.sg'
Cc: 'Simon'; Survey KKH; assignments; SUR
Subject: VEHICLE SJZ 6246M (DOA: 05/02/2018)

Dear Shuman,

Refer to the tele-conversation between Catherine and you.

Please proceed to repair the insured vehicle **SJZ 6246M (excess \$300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Passport Country/Region: United States of America
Owner ID:	36157
Vehicle Details	
Vehicle No.:	SJZ6246M
Vehicle to be Exported:	No
Intended De-registration Date:	07 Feb 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	L13A4215625
Chassis No.:	GE61196902
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$13,745.00
Original Registration Date:	14 Dec 2010
First Registration Date:	14 Dec 2010
Transfer Count:	2
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2020
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00
Message	
This vehicle is eligible for pro-rated COE when it is converted from COE-exempted to non COE-exempted status. The COE is pro-rated to the number of years for the vehicle to be 10 years old, subject to a minimum of 5 years. Please call our Customer Service Hotline at 1800-CALL LTA (1800-2255 582) for further details.	

The information contained herein is correct as at 07 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2018 17:04
Date Of Accident	05/02/2018 19:15
Exact Location Of Accident	NOVENA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ6246M
Insured/Policyholder	
Name Of Registered Owner	WRYE IV WALTER CLARK
Passport No/FIN	G1510352W
Email Address	CHIPWRYE@YAHOO.COM
Mobile Phone No	(LOCAL) +65-93396431
Alternative Phone No	OFFICE-91292201

Vehicle Particulars

Manufacturer	HONDA
Model	FIT-1.3 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA047320
Cover Note Number	

Driver

Name of Driver	WRYE IV WALTER CLARK
Passport No/FIN	G1510352W
Date Of Birth	19/09/1971
Occupation	INDOOR
Date Of Driving Pass	30/09/1988
Driving Experience	29 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93396431
Fax Number	
Contact Number	OFFICE-91292201
EMail Address	CHIPWRYE@YAHOO.COM

Address	2 SINARAN DRIVE #26-03
Postcode	307467
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB8807G
Vehicle Make/Model/Colour	KIA
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SEE YONG KIAT, ALEX
NRIC/Passport Number	S7827990G
Contact Number	84539868
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

6/2/18 @
4pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

- Please refer to sketch -

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS IN LEFT LANE OF NEWTON RD HEADING ACROSS THOMSON RD ONTO MOULMEIN RD IN NOVENA AT APPROX 19/5, 5 FEB 2018. AS STOP LIGHT TURNED GREEN, VEHICLES HEADING NORTH ON THOMSON RD REMAINED IN THE INTERSECTION BLOCKING NEWTON RD TRAFFIC. CARS IN LEFT LANE (MY LANE) BEGAN MERGING RIGHT TO DRIVE AROUND THE STOPPED THOMSON RD TRAFFIC. CARS BEGAN ZIPPERING (ALTERNATING) PULLING INTO THE RIGHT LANE. I LOOKED RIGHT, SAW THE RIGHT (MIDDLE) LANE CLEAR, CONFIRMED IN SIDE & REAR MIRRORS, AND BEGAN PULLING RIGHT WHEN THE TRAFFIC LIGHT TURNED RED AND THE CAR IN RIGHT LANE STOPPED. I STOPPED PARTWAY INTO RIGHT LANE. VEHICLE B PULLED UP ON MY RIGHT AND SQUEEZED IN BETWEEN MY CAR AND CAR IN RIGHTMOST LANE. I PULLED OVER SLIGHTLY MORE. HE PULLED UP SLIGHTLY MORE. A WHILE LATER, LIGHT TURNED GREEN, I PULLED FORWARD AND MY CAR SCRAPED ALONG HIS CAR (VEH B, PREMIER TAXI). VEH 2 FOLLOWED ME THROUGH INTERSECTION AND WE BOTH STOPPED ON SIDE OF MOULMEIN RD TO INSPECT DAMAGE & EXCHANGE INFORMATION.

* I HAD MY RIGHT TURN SIGNAL ON BY THIS POINT.

** THERE MUST HAVE BEEN CONTACT BEFORE I PULLED FORWARD AS I DID NOT DRIVE RIGHTWARD AT THIS POINT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 5 Feb 2018

Company Chop (if applicable)

1600

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



A: SJZ 6246 M
B: SHB 8807 G.

WRT

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : GA047320
Accident Date : 05-Feb-2018

No. : 29528

Date : 07-Feb-2018

Our Ref : 180098 / SHUMAN

PAGE : 1

WRYE IV WALTER CLARK (MR)
C/O AXA INSURANCE PRIVATE LIMITED
8 SHENTON WAY
#24-01 AXA TOWER
Singapore 068811

ESTIMATED COST OF REPAIR FOR HONDA FIT 1.3G A (2009) SJZ6246M

1 pc o/s front door
1 pc o/s front door black sticker
-1 & 2
1 pc o/s rear door
1 pc o/s rear door black sticker-1
1 pc o/s rear sport rim (original)
-14"

X380.00 c R
X20.00 c R/N

X380.00 c R
X18.00 c N/N
300.00 400.00 sn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

380.00 -

To putty and respray on affected
portions.

800.00 Gov.

To remove door's fittings

160.00 X

Total : S\$ 2,538.00

Singapore Dollars Two Thousand Five Hundred and
Thirty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Revert
PIP Repair
A/c paint job
EXCESS \$300
Holidays

12/3/18



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

No. : 29528

Your Reference : GA047320

Accident Date : 05-Feb-2018

Date : 07-Feb-2018

Our Ref : 180098 / SHUMAN

PAGE : 1

WRYE IV WALTER CLARK (MR)
C/O AXA INSURANCE PRIVATE LIMITED
8 SHENTON WAY
#24-01 AXA TOWER
Singapore 068811

ESTIMATED COST OF REPAIR FOR HONDA FIT 1.3G A (2009) SJZ6246M

1 pc o/s front door	X380.00 c R
1 pc o/s front door black sticker -1 & 2	X20.00 c R/N
1 pc o/s rear door	X380.00 c R
1 pc o/s rear door black sticker-1	X18.00 c N/N
1 pc o/s rear sport rim (original) -14"	400.00 sn

GRAZER 300

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

380.00 —

To putty and respray on affected
portions.

800.00 Gov.

To remove door's fittings

160.00 X

Total : S\$ 2,538.00

Singapore Dollars Two Thousand Five Hundred and
Thirty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Revert
PIP Repair
A/c paid to
EXCESS \$300
Hawdys

\$300.00 SL
\$980.00 - 600
\$1280.00

Police Station Of Origin:
 Honggang N.P.C
 60 Honggang Avenue 9 SINGAPORE 338773
 Tel No: 1800-4890999



CONTINUATION OF REPORT

Report No. T/20120326/4146
 3 of 3



T/20120326/4146

Sketch Plan
 Informant is not able to provide sketch plan

[IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / TAN ZHI GUANG		Signature Of Interpreter: /	
Classification Of Case: IP / Officer In Charge Of Case: Contact No.:		Date: 26/03/2012 23:04	
Signature Of Informant: 2		Classification Of Case:	

