



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 HONDA FIT 1.3 (SJZ6246M)

Date of Loss

5 February 2018

Time of Loss

4.00

Loss Description

SJZ6246M (INSD) C/W SHB8807G

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$22,000.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

26/06/2018



Days of work completion *

133



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJZ6246M

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

14/12/2010



Mileage

59536

Age of Vehicle

7

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... HONDA

ASSESSMENT INFO...

CATEGORY Model

POLICY INFORMAT... FIT 1.3

ASSESSMENT INFO...

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... GE61196902

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF...



CATEGORY Age

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driver License #

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... L13A4215625

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI...
POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI...

PLEASE PRINT CLEARLY

POST SURVEY INF...

▼

CATEGORY

Gender

FNOL INFORMATI...

POST SURVEY INF...

▼

CATEGORY

Marital status

FNOL INFORMATI...

POST SURVEY INF...

▼

CATEGORY

Identification #

FNOL INFORMATI...

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

300

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

185/60R14

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Rear Tyre Size

185/60R14

Front left side

MICHELIN7mm

Front right side

MICHELIN7mm

Rear left side

MICHELIN7mm

Rear right side

MICHELIN7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes ☐ No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			O/S FRONT DOOR			Repair	0	0	0	0	0	Deny
☐		2	1			O/S FRONT DOOR BLACK STICKER -1 & 2			Serviceable	0	0	0	0	0	Deny
☐		3	1			O/S REAR DOOR			Repair	0	0	0	0	0	Deny
☐		4	1			O/S REAR DOOR BLACK STICKER - 1			Serviceable	0	0	0	0	0	Deny

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
☐		1		TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS	380	0	0	Reviewing		
☐		2		TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	600	0	0	Reviewing		
☐		3		TO REMOVE DOOR'S FITTINGS	0	0	0	Deny		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 4 DAYS	Reviewing			
☐		2	O/S REAR SPORT RIM (ORIGINAL) - 14"	Reviewing	300	DAMAGED	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--	--------------------------	--	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$980.00

Claim Amount

\$980.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$980.00	\$980.00
Miscellaneous	\$300.00	\$300.00
Excess	-\$300.00	-\$300.00

Submit for Review