

22/03/2002

ASS. REQ. BY:

REF: CS/CTI18002937/R1/d3/n2 Special Instruction:

Surveyor: Meinmen ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 13/2/18 @ 4:51pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKU 291K Insured: SJG 7964S

at Workshop m/s Boneo Motors Tel: 98476171

of 2 pandan Crescent / Level 4

Policy No: DMP CS N3093221701 Claim No: SNM18D00825C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 10/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 26.02.2018 @ 10am - 12pm H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 8:58am @ 14/2/18 Person Contacted: Thomas Pang Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 291K - X
	SJG 7964S - X
	Part by Part \$3579.821- (Red: 1028 122%)

Repair

REF: CTI

30093

ASSIGNMENT

Date 26/2/18

SKU 291K 2015 Jun

Estimated Cost:

QD TP WS TP RES / OD RES / EVA / INV / MV

To inspect vehicle No: SKU 291K

By Workorder No: Burned Motors

of: 2panden Crescent / level 4

Insured:

Policy No:

Claim No:


Sum Insured: Excess

Diagnosis Record: 10am - 12pm

Make of Van: Thomas 98476171

(Policy Condition)

Remarks: The van had commenced its repair at the time of inspection.



Salvage / Market Value:

ICAO Accident Report: Consistent? Yes or No

QIA / RR Seen: Consistent? Yes or No

Est. Repair: days Res: Yes or No

Lim. Sum: % Sval: Yes or No

CA / REV / REP. / 24 HRS up

Date Person Contacted Vehicle IN / OUT

Make: TOYOTA CAROLLA ALTIS 1.6 1598

Colour: GREY

St. No: 35038

Engine:

IC No: MA053REH1045 35611

Gen. Cond: Good (C) Poor: Burnt

Steering: (C) Jammed Leaked Burnt

Brake: (C) Jammed Leaked Burnt

Mod: Nil (C) STD A/Rum or

Tyre Size: 205/55R16

BS: DUNLOP EXNOVA BY FS LIZA MIC OHTSU PR SLM

TOYO / YOKO

Front: 6 Rear: 6

DOB: 10/02/18 DOB: 26/02/19

Sunday red at: BURNED MOTOR

Dist. of Damage: FR Rear OS NS UC Roof: 10/5 REAR

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 19 APR 2018

Date Time File Ref of:  Prel. Report

19/4 Typist  Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Repair Partner: TP

Lim. Sum: 3579.82

Add Fee:	Site visit	6
	Hourly	6
	Test	6
	Resurvey	6

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

220



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18002937/R1td3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 13-02-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJG 7964S	Veh. Inspected	SKU 291K
Policy No.	DMPCSN3093221701	Coverage (\$)	0.00
Claim No.	SNM18D00825C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	13/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	10/02/2018	Inspection Date	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING					Adj Submitted	Ins Auth'd	Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt			<b>New Assignment</b> <a href="#">Cancel Case</a>
Main	13 Feb 2018		13 Feb 2018 16:51 <a href="#">Assign</a>				

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

[Created by insurer]

<b>CLAIM SUBFOLDER DETAILS</b>	
Insured:	LAKSHMANAN SUBRAMANIAN, ID: S7664557D
Main Claimant:	KONG HOCK MIN, ID: S1853009J
Vehicle Reg. No.:	SKU291K
Claim Type:	TP / SNM18D00825C02
Vehicle Reg. No. (Insured):	SJG7964S
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/02/2018]
Driver/Custodian (Insured):	LAKSHMANAN SUBRAMANIAN (42 / Male), NRIC: S7664557D
Adj Asg. Remarks:	EST \$4930.37 , CASE WITH SJE.

**ASSOCIATED MAIL RECEIVED**

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

**ALL ASSOCIATED TASKS**

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Lucas Lee

**From:** Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>  
**Sent:** Monday, 12 February, 2018 3:47 PM  
**To:** Claims Dept of CTI  
**Subject:** Direct Settlement (TP) - Accident Involving SKU291K & SJG7964S DOA 10.02.2018  
**Attachments:** SKU291K\_FULL GIA RPT.pdf; SKU291K\_Est Inv.pdf; SKU291K\_Rear\_Video - Accident.AVI

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Scene Photos, Accident Video Footage, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SJG7964S thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental @ \$100 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, Thomas Pang @ 9847 6171 / 6631 1860 located at 2 Pandan Crescent / Level 4 for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you very much in advance!

Warmest Regards,  
SURAIDAH

TPR TEAM, CLAIMS DEPT

: 6631 1887 | : 6872 7260 | : [suraidahb.saidi@inchcape.com.sg](mailto:suraidahb.saidi@inchcape.com.sg)


Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

[www.borneomotors.com.sg](http://www.borneomotors.com.sg) | [www.lexus.com.sg](http://www.lexus.com.sg) | [www.toyotasingapore.com.sg](http://www.toyotasingapore.com.sg) | [www.hino.com.sg](http://www.hino.com.sg)





This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/02/2018 13:44
Date Of Accident	10/02/2018 16:20
Exact Location Of Accident	PIE TWD CHANGI AIRPORT AFTER LORONG6 TOA PAYOH EXI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU291K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KONG HOCK MIN
NRIC No	S1853009J
Email Address	HOCKMIN@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96857865
Alternative Phone No	OFFICE-92293295
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100419483
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAI SHI PING
NRIC No	S7929153F
Date Of Birth	01/10/1979
Occupation	INDOOR
Date Of Driving Pass	09/01/2002
Driving Experience	16 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97632649
Fax Number	
Contact Number	
EMail Address	KEITH.TAI@GMAIL.COM

Address BLK 8 TAO CHING ROAD #14-16  
 Postcode 618724  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - SON-IN-LAW  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 6

Passenger 1 NAME: : KONG HOCK MIN  
 GENDER: : MALE  
 Passenger 2 NAME: : TOH KOOI WAH  
 GENDER: : FEMALE  
 Passenger 3 NAME: : KONG PEI ZHEN(PAULINE)  
 GENDER: : FEMALE  
 Passenger 4 NAME: : TAI YI EN(EAN)  
 GENDER: : MALE  
 Passenger 5 NAME: : TAI YI XUAN(ELISE)  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJG7964S  
 Vehicle Make/Model/Colour

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 12/9/2018

Policyholder's Signature / Date & Time 10 25 AM

 Driver's Signature (if driver is not the policyholder) / Date & Time

 Witnessed by Reporting Centre Personnel

### Sketch Plan



↑ ↑ ↑ ↑  
DIB (change)



Utk

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyotasingsapore.com.sg

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

### ESTIMATE

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	
	Document No	
	Document Date	
	0	Mr Kong Hock Min 135 Teck Whye Lane #03-295 Singapore 680135 Mobile: 96857865
	12/02/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	29/06/2015	SKU0291K	0	29621 SKU0291K
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104535611	1ZR520643	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: SJG7964S DATE OF ACC : 10.02.2018			nee	50 <del>100.00</del>
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (NETT)				154.00
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NETT)				104.72
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				462.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				924 <del>1232.00</del>
6	B	BP-RES RESPRAY ACC AFFECTED AREAS				1012 <del>1518.00</del>
7	1	S52159-02904 COVER, RR BUMPER	1.00	539.90		539.90
8	2	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70		105.70
9	3	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30		58.30
10	4	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70		105.70
11	5	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30		58.30
12	6	S52161-OK040 PIECE, RR BUMPER	10.00	3.90		39.00
13	7	S52592-02301 SEAL, RR BUMPER	1.00	53.30		53.30
14	8	T90189-06013 GROMMET,	5.00	1.80		9.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle.	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3620217

TO SECURITY GUARD

3620217

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/02/2018  
TIME 10:58

VEHICLE NO  
SKU0291K  
CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**



Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

### ESTIMATE

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1188

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Kong Hock Min 135 Teck Whye Lane #03-295 Singapore 680135  Mobile: 96857865	
		Document No		
		0		
		Document Date		
		12/02/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ S2	ZRE171R	29/06/2015	SKU0291K	0	29621	SKU0291K
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MRO53REH104535611    1ZR520643    60    Thomas Pang W T    --/--/-- 0.00    --/--/-- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	9	T90467-05170    CLIP	5.00	2.00		net/ 10.00 ✓
16	0	S81920-02110    REFLECTOR ASSY, REFL	1.00	57.90		sea/ 57.90 ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*Rafael*  
*4p 90010068*  
*5 days*  
*26/02/18 @ 1030*  
*Resurvey by part*

*[Signature]*  
*11/3/18*

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of <b>Borneo Motors</b>	Customer's Signature	Change Summary	Total	4,607.82
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	322.55
		Labour	Less	0.00
		Materials		
		Lubrication/Fluid		
		Others	Amount Due	4,930.37

PLEASE TEAR ALONG PERFORATED LINE

3620218

TO SECURITY GUARD

3620218

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/02/2018  
TIME 10:58

VEHICLE NO  
**SKU0291K**

CUSTOMER

SIGNATURE  
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyotasingapore.com.sg

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

**ESTIMATE**

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6631 1168

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	
		Document No	
		Document Date	
		0	Mr Kong Hock Min 135 Teck Whye Lane #03-295 Singapore 680135 Mobile: 96857865
		01/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	29/06/2015	SKU0291K	30968	29621 SKU0291K
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104535611	1ZR520643	60	Thomas Pang W T	26/02/2018	8.00	01/03/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: SJG7964S DATE OF ACC : 10.02.2018 BY:LKK-RASUL @ 26.02.2018 05 WORKING DAYS				50.00
2	B	BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR (N + ETT)				154.00
3	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET + T)				104.72
4	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT) 18				462.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS *				924.00
6	B	AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS *				1012.00
7	1	BP-RES RESPRAY ACC AFFECTED AREAS	1.00	539.90		539.90
8	2	S52159-02904 COVER, RR BUMPER	1.00	105.70		105.70
9	3	S52576-02140 RETAINER, RR BUMPER L	1.00	58.30		58.30
10	4	S52563-02250 RETAINER, RR BUMPER L	10.00	3.90		39.00
11	5	S52161-0K040 PIECE, RR BUMPER	1.00	53.30		53.30
12	6	S52592-02301 SEAL, RR BUMPER LH	5.00	1.80		9.00
		T90189-06013 GROMMET				

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3620944

3620944

01/03/2018  
10:47

SKU0291K

WORKSHOP



Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :  
www.toyotasingapore.com.sg

Co Reg No : 196700086Z  
GST Reg No : MR-8500000-9

**ESTIMATE**

Toyota Bodycare Centre  
No. 2 Pandan Crescent  
Singapore 128462  
Tel no.: 6531 1188

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Kong Hock Min 135 Teck Whye Lane #03-295 Singapore 680135 Mobile: 96857865
		Document No	
		0	
		Document Date	
		01/03/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	29/06/2015	SKU0291K	30968	29621 SKU0291K
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104535611	12RX520643	60	Thomas Pang W T	26/02/2018	8.00	01/03/2018	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	7	T90467-05170 CLIP	5.00	2.00		10.00
14	8	S81920-02110 REFLECTOR ASSY, LH	1.00	57.90		57.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	3,579.82
	Please acknowledge receipt of vehicle	Parts 873.10	GST 7.00%	250.59
		Labour 2,706.72	Less	0.00
		Materials 0.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	3,830.41

3620945

3620945

01/03/2018  
10:47

SKU0291K

WORKSHOP



**Borneo Moto**

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18002937/R1TD3N2

Date: 20/04/2018

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3093221701
Claimant Vehicle No :	SKU291K	Insured Vehicle No :	SJG7964S
Date of Loss:	10/02/2018	Nature of Claim:	TP
		Claim No:	SNM18D00825C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU291K	Engine No:	1ZR520643
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104535611
Reg. Date:	29/06/2015 (Man. Year: 2015)	Odometer:	35038 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,137.10	923.10	214.00	18.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.72	2,656.72	814.00	23.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,607.82</b>	<b>3,579.82</b>	<b>1,028.00</b>	<b>22.31</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>322.55</b>	<b>250.59</b>	<b>71.96</b>	<b>22.31</b>
<b>Nett Amount (S\$)</b>	<b>4,930.37</b>	<b>3,830.41</b>	<b>1,099.96</b>	<b>22.31</b>

#### INSPECTION

Date of Assignment:	13/02/2018	
Date Inspected:	26/02/2018	Inspected At:
		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	5.0 days	

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Apr 2018)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKU291K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,RR BUMPER	Scratched	539.90 FS	*539.90 FS
2	1		*RETAINER,RR BUMPER L	Necessary	105.70 FS	*105.70 FS
3	1		*RETAINER,RR BUMPER L	Necessary	58.30 FS	*58.30 FS
4	1		*RETAINER,RR BUMPER R	Serviceable	105.70 FS	*- FS
5	1		*RETAINER,RR BUMPER R	Serviceable	58.30 FS	*- FS
6	10		*PIECE,RR BUMPER	Necessary	39.00 FS	*39.00 FS
7	1		*SEAL,RR BUMPER	Cut	53.30 FS	*53.30 FS
8	5		*GROMMET	Necessary	9.00 FS	*9.00 FS
9	5		*CLIP	Necessary	10.00 FS	*10.00 FS
10	1		*REFLECTOR ASSY,REFL	Scratched	57.90 FS	*57.90 FS
11	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
<b>Total Parts (S\$)</b>					<b>1,137.10</b>	<b>923.10</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	154.00	154.00
2	CHECK WIRING AND CONDUCT WATER TEST	New	104.72	104.72
3	TO RESET ECU AND REPROGRAMME	New	462.00	462.00
4	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	1,232.00	924.00
5	RESPRAY ACC AFFECTED AREAS	New	1,518.00	1,012.00
<b>Gross Labour Cost (S\$)</b>			<b>3,470.72</b>	<b>2,656.72</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >