

ASS. REC. BY:

REF: CS/AWA18002949/Tird3er

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Peggy Chan

of

AWAC

Date/Time

13/2/18 @ 4:25pm

Estimated Cost:

Bill to:

OD / ~~IP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SUU 7674E

Insured:

GBG 2511T

at Workshop m/s

Vermogen Ace

Tel:

of

J. Bkt Bortok Crescent #04-54/55 Wega Plaza

Policy No:

AVCP S B0087511700

Claim No:

GBG 2511T / SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/02/2018

CA / REV / REP. / REV 24 HRS 'wpr'

14/02/2018

Insp: 6 Benoi see

H.O.D. Endorsement:

Date/Time:

4:28pm @ 13/2/18

Person Contacted:

Eze

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction

☒

Estimate

SUU 7674E - x

GBG 2511T - x

Confirm

L/S

\$1350 @ 3 day

Red. \$4261.39, 76%.

SYNOPSIS

Tariff

REF:

AWAC

ASSIGNMENT

From: Date: 14/02/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJU 7674E

at Workshop / Mile: Vermogen Ace

of: 6 Benoit seefor

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Ver:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Bel. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

CIA / PR Seen: Consistent? : Yes or No

Est. Receipts: days: Res: Yes or No

Lim Sum: %: 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted:

Vehicle IN / OUT

Date / Time: Action / Instruction:

RECEIVED 18 MAY 2018

Date/Time File Pass to:

☐

: Prelim. Report

Days Of Repair: 3

by: *byast*☒

: Final Report

Resurvey No. of Trip: 1

Date/Time File Return to:

Survey Fee:

200

Transportation:

Add Fee:

☐

Steered: \$

☐

Tire: \$

☐

Tire: \$

☐

Tire: \$

☐

Tire: \$

Report Format:

TP

Lim Sum: 1200

B30

200

Ver No: SJU 7674E Page: 2009 Dec.

Type: ☒ Micro Cycle Bus / Van / Long / Taxi / Prime Mover

Truck / Trailer or:

Make: Nissan Sylphy 1498

Colour: Silver. 40 Insured Std N/A

So. Reading: 168841 T. Paid Insured Std N/A

Eng No:

Ch No:

JN13AAG112 0110074

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Incident / Jammed / Leaked / Burnt or

Brake: Incident / Jammed / Leaked / Burnt or

Mod: Nil / STD AIR / or

Tyre Size: R 185/60R15

BS / DUN / EXNOVA / GY / FS LIZA / MIO / OHTSU / PIR / SUMI

TOYO / YOKO or

Front:

Rear:

R.Bal: 6 -- R.Bal: 6 --

L.Bal: 6 -- L.Bal: 6 --

D.O.A: D.O.A: 14/2/18

Surveyed at: Vermogen Benoit

Des. of Damages: Frt / Rear / OS NS / UIC / Roofed or

The UIC / Chassis frame / Body Structure affected due to collision

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	01 Feb 2018		01 Feb 2018 15:34			
						New Assignment
						Cancel Case

Main		Reference	Claim Details	Documents	Show All
------	--	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS										
Insured:	EFICAZ PEST MANAGEMENT PTE LTD, Co. Reg. No.: 201717718D									
Main Claimant:	RASEL HASAN ABDUL HALIM GAZI, ID: G8378497R									
Vehicle Reg. No.:	GBD2043T	Date of Loss:	30/01/2018 15:00 - :59							
Claim Type:	TP / SNM18D00583C02	Policy/Cover Note No.:	DMCVSN3060421700							
Vehicle Reg. No. (Insured):	G8G3644L	Policy No. (Claimant):		Excess:	\$50.00					
Repairer:	V.z Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #02-02, 417883 Kaki Bukit - Tel:									
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/02/2018]									
Adj Asg. Remarks:	NO EST, CASE W/O SJE									
ASSOCIATED MAIL RECEIVED										
There are no mail for this case.										
View All										
Compose Case Mail										
ALL ASSOCIATED TASKS										
View All										
Search Tasks										
Create New Task										
Complete										
Due Date										
Priority										
Type										
Task Group										
Subject										
Handler										
Assigned By										
Completed On										
Created On										
Done?										
No results.										

Nivitha (LKK Auto)

From: Chan, Peggy <Peggy.Chan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Tuesday, 13 February 2018 4:25 PM
To: assignments@lkkauto.com
Cc: SUR; 'ezelvermogenace@gmail.com'
Subject: TP Survey assignment for SJU 7674E - DOA: 12/02/2018 Our ref: GBG 2511T/SG

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Mohamad Taufikh** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SJU 7674 E
Insured Vehicle	:	GBG 2511 T (Accident not Reported)
Policy Number	:	AVCPSB0087511700
Name of Workshop	:	Vermogen Ace Pte Ltd
Contact Number	:	6358 3031
Person to Contact	:	Ezel Tejano
Estimated Cost of repairs	:	\$ NA

Regards,
Claims Division

Copy to Vermogen Ace Pte Ltd via Email

Note -


1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments

hereto, are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA18002949/T1rd3		
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 13-02-2018		
		Code : AWA		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 2511T	Veh. Inspected	SJU 7674E	
Policy No.	AVCP5B0087511700	Coverage (\$)	0.00	
Claim No.	GBG 2511T/SG	Excess (\$)	0.00	
Assign From	PEGGY CHAN	Assign Date	13/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/02/2018	Inspection Date		
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2018 16:30
Date Of Accident	12/02/2018 13:40
Exact Location Of Accident	KIM TIAN RD (BETWEEN BLK 120 & 121A)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU7674E
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995109
Cover Note Number	

Driver

Name of Driver	KWEK JUAN HOCK
NRIC No	S6808660D
Date Of Birth	19/02/1968
Occupation	OUTDOOR
Date Of Driving Pass	11/05/1987
Driving Experience	30 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI ROAD BLOCK B (ENTRANCE 6 BENOI SECTOR)
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS AND VIDEO. THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG2511T
Vehicle Make/Model/Colour	
Details Of Properties	VEH B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

NIKO

SKETCH PLAN

Car A: SJU7674E

Car B: GBG2511T



Location:

Kim Tian Rd
C Between Blk
120 & 121A)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/02/18 at 13.40pm, my vehicle A was stationary in my parking lot. As my vehicle A was stationary, suddenly vehicle B which is moving off from his stationary position on my right has collided onto my vehicle A. I wish to state that I have in-car camera in my vehicle A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: NIKO



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S6808660D**

Name: **KWEK JUAN HOCK**

Birth Date: **19 Feb 1968**

Issue Date: **02 Jun 2003**

000535023J

VMG USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S6808660D**

Name: **KWEK JUAN HOCK**

Race: **CHINESE**

Date of Birth: **19-02-1968**

Sex: **M**

Country of Birth: **SINGAPORE**

郭远福

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **11 May 1987**

NP 428A

Licence No: **S6808660D**

VMG USE ONLY

0021

NRIC No. **S6808660D**

Blood Group: **O+**

Date of Issue: **21-05-1991**

APT BLK 3390 KANG CHING ROAD #19-352
SINGAPORE 614339

NRIC No: **S6808660D**

Date: **18/10/2010**

No: **6634877**

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





SJU7674E

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AWAC

OWN INSURER : AIG

CLAIM TYPE : TP

Date of Accident : 2/12/2018

Vehicle Reg. No. : SJU7674E

Vehicle Reg. Date: 28-Dec-2009

Make / Model : N. SYLPHY 1.5L 4AT ABS

Engine No. : HR15155881B

Chassis No. : JN1BAAG11Z0110074

COST OF CLAIMS

Parts Cost / List Items :	\$	<u>2,125.60</u>
Plus/Less <u>30%</u>	\$	<u>637.68</u>
Total Cost / List :	\$	<u>1,487.92</u>
Nett Items :	\$	<u>1,278.30</u>
Less <u>10%</u>	\$	<u>127.83</u>
Total Nett :	\$	<u>1,150.47</u>
Special Nett Items :	\$	<u>623.00</u>
Total Parts Amount :	\$	<u>3,261.39</u>
Total Labour Amount :	\$	<u>2,350.00</u>
Gross Total :	\$	<u>5,611.39</u>
GST % : <u>7%</u>	\$	<u>392.80</u>
Nett Amount :	\$	<u>6,004.19</u>

Surveyor Name and Company :

Tanpin 97495749

Date of survey : 14/2/18 @ 11am

Part by Part / Lump Sum : 3 days

Resurvey Before Paint / After Paint B

Authorize/Not Authorize/Without Prejudice B

Email : sur@lkkauto.com

Fax No : _____

HP No : _____

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[Signature]
19/2/18

ACKNOWLEDGMENTS

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SJU7674E
 Vehicle Reg. Date: 12/28/2009
 Make / Model : N. SYLPHY 1.5L 4AT ABS D/AB 2V
 Engine No. : HR15155881B
 Chassis No. : JN1BAAG11Z0110074

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	NETT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER	de✓	\$ 595.10	✓		
2	1set	FRONT BUMPER CLIPS	neu✓		\$ 35.00	✓	
3	1/2	FRONT BUMPER RETAINER LH/RH	neu✓	\$ 44.20	22.10		
4	1	FRONT BUMPER SPONGE	x	\$ 244.60	x n n		
5	1	FRONT BUMPER REINFORCEMENT	x	\$ 618.10	x n n		
6	1	FRONT BUMPER LOWER SKIRT	x			\$ 578.00	x n n.
7	1	FRONT FENDER LH	x p	\$ 623.60	x n n.		
8	1	FRONT FENDER SPLASH SHIELD LH	x		\$ 77.10	x n n	
9	1set	FRONT FENDER SPLASH SHIELD CLIPS	x		\$ 30.00	x n n	
10	1/2	HEADLAMP LH/RH	cut✓		\$ 1,136.20	568.10	
11	1	FRONT NUMBER PLATE WITH FRAME	x			\$ 45.00	x n n.
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	2	0					

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SJU7674E
Vehicle Reg. Date:	12/28/2009
Make / Model :	N. SYLPHY 1.5L 4AT ABS D/AB 2V
Engine No. :	HR15155881B
Chassis No. :	JN1BAAG11Z0110074

Estimates on Labour

[illegible]



Janice Lee (LKKAUTO)

From: Baldoz Juan Paulo Bongon <paulo.b@vermogen-group.com>
Sent: Saturday, April 21, 2018 10:38 AM
To: Asher Sng (LKKAUTO); Vic (LKKAUTO); Guo Qiang (LKKAUTO); Ai Phing (LKKAUTO); Shiao Chan (LKKAUTO); Taufikh (LKKAUTO); Rasul (LKKAUTO)
Cc: Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Minoko Chan; Edmond Lim; Quantum Risk; Lina Rosli; Luis Tan; Paul Tan
Subject: SJU7674E DOA: 12/02/2018 TO FINALISE (AWAC TP)
Attachments: 9af5f7a4-cf5c-4d28-bdf8-611baff17cfb.jpg; 51d59de8-c986-42b6-a321-a4a387835fa9.jpg; 77f53b05-b41c-4af7-b5d5-473b8132c504.jpg; 538ed082-9111-46f3-af5e-4d7fc7f455fe.jpg; 55188855-48b3-4353-94ba-79ec0a32fa70.jpg; b4ffc5ef-420f-461f-9c76-6a7cd8ddf0ce.jpg; c2096408-d29b-4e13-90a4-6274913d41c9.jpg; dc0bcbdb-aff3-4266-8baf-910b057e1484.jpg; fa11e520-b771-4c0a-9ea4-221fb83aa64c.jpg; faa8d236-a996-47f5-94dc-1885962d21fc.jpg; SJU7674E FINALISE.pdf

Hi Taufikh,

Please check and confirm finalise COR @ **\$1,350** bef gst (lump sum) 3 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,



Paulo Baldoz
Vermogen Ace Pte Ltd
6358 3031



883 North Bridge Road
#10-05 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5938
(UEN No. 53201417X)

Our Ref : CY.5740.12.SK.DT
Your Ref : Your insured vehicle **SGX7467G**

26 December 2012

Motor Claims Department
M/s Chartis Singapore Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Fax 6835 7416 Only

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES
ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SCN 6755G & SGX 7467G AT
TAMPINES ROAD TOWARDS HOUGANG AVENUE 3 ON 24/12/2012**

We act for Ng Cheng Sim who has appointed the under-mentioned workshop to repair his motor vehicle no. SCN 6755G.

A copy of our client's accident report is enclosed herewith for your attention.

Please be informed that the said vehicle can be inspected at:


Name of workshop : Soon Kiang Motor
Address : Blk 13 Defu Lane 10 #01-430 Singapore 539194
Contact person : Mr Lai
Tel : 9877 8805
Fax no. : 6487 4559

26-12-2012
Arrange tomorrow
morning- AFTER 10.


We hereby give you 2 clear days' notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours. Please call Mr Lai to confirm the date and time of your inspection.

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days (excluding any intervening Saturday, Sunday and/or Public Holiday) you will be deemed to have waived your rights to a pre-repair inspection. The above-mentioned workshop will commence repairs thereafter without further notice to you. They will also be entitled to claim for the additional loss of use/rental arising as a consequence of this notification.

Yours faithfully,


C YOGARAJAH

cc: LKK Auto Consultants Pte Ltd (By Fax 6256 4315 Only)
client (by fax only)



SJU7674E

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AWAC
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 2/12/2018

Vehicle Reg. No. : SJU7674E
Vehicle Reg. Date: 28-Dec-2009
Make / Model : N. SYLPHY 1.5L 4AT ABS
Engine No. : HR15155881B
Chassis No. : JN1BAAG11Z0110074

COST OF CLAIMS

Parts Cost / List Items : \$ 2,125.60
Plus/Less 30% \$ 637.68
Total Cost / List : \$ 1,487.92
Nett Items : \$ 1,278.30
Less 10% \$ 127.83
Total Nett : \$ 1,150.47
Special Nett Items : \$ 623.00
Total Parts Amount : \$ 3,261.39
Total Labour Amount : \$ 2,350.00
Gross Total : \$ 5,611.39
GST % : 7% \$ 392.80
Nett Amount : \$ 6,004.19

Surveyor Name and Company :

Tan Jun 97443749
Date of survey : 14/2/18 @ 11am
Part by Part / Lump Sum : 3 days
Resurvey Before Paint / After Paint After Paint
Authorize/Not Authorize/Without Prejudice Without Prejudice
Email : sur@khant.com
Fax No : _____
HP No : _____

This claim is handled by : EZEL


$$\begin{aligned} P &= 607.20 \\ &- 30\% \\ &= 482.04 \\ N &= 603.10 \\ &- 15\% \\ &= 542.79 \\ TP &= 974.83 \\ L &= 750 \\ &1724.83 \\ &- 20\% \\ &1379.86 \\ \boxed{LC} &= \boxed{1350} \end{aligned}$$

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan





Describe Circumstances of the Accident

please refer to statement.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

24/12/2012 15:15HRS

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SJU7674E
 Vehicle Reg. Date: 12/28/2009
 Make / Model : N. SYLPHY 1.5L 4AT ABS D/AB 2V
 Engine No. : HR15155881B
 Chassis No. : JN1BAAG11Z0110074

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	NETT	S/N	ADJUSTED AMOUNT
1	1	FRONT BUMPER	de✓	\$ 595.10			
2	1set	FRONT BUMPER CLIPS	neu✓		\$ 35.00		
3	1/2	FRONT BUMPER RETAINER LH(RH)	neu✓	\$ 44.20	22.10		
4	1	FRONT BUMPER SPONGE	X	\$ 244.60			
5	1	FRONT BUMPER REINFORCEMENT	X	\$ 618.10			
6	1	FRONT BUMPER LOWER SKIRT	X			\$ 578.00	
7	1	FRONT FENDER LH	frp	\$ 623.60			
8	1	FRONT FENDER SPLASH SHIELD LH	X		\$ 77.10		
9	1set	FRONT FENDER SPLASH SHIELD CLIPS	X		\$ 30.00		
10	1/2	HEADLAMP LH(RH)	cut✓		\$ 1,136.20	568.10	
11	1	FRONT NUMBER PLATE WITH FRAME	X			\$ 45.00	
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	2	0					

P= 617.20
 N= 603.10

MNA112188512 / National Assessment Centre Services - Ltd
ENTRY DATE & TIME: 24/12/2012 15:07

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/12/2012 15:07
Date Of Accident 24/12/2012 07:50
Exact Location Of Accident SLIP ROAD TAMPINES RD FILTERING INTO HOUGANG AVE 3

DETAILS OF OWN VEHICLE

Vehicle Registration Number SCN8755G
Name Of Registered Owner NG CHENG SIM
NRIC No S1425772A

Manufacturer NISSAN
Model MARCH 1.0 M
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? No
If No, Please state action to be taken Third Party
Vehicle Category Private Car

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type Of Coverage Third Party Fire and/or Theft
Fleet Policy No
Policy Number 5055614728
Cover Note Number

Name of Driver NG CHENG SIM
NRIC No S1425772A
Date Of Birth 18/04/1958
Occupation Indoor
Date Of Driving Pass 17/01/1979
Driving Experience 33 Years And 11 Months
Gender Male
Mobile Number (Local) +65-92708738
Fax Number
Contact Number
EMail Address NOEMAIL
Address BLK 46 BEDOK SOUTH AVENUE 3 #08-292
Postcode 460046
Was driver an employee of the Insured's Company No
If No, Relationship of the Driver with the Insured Owner

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]
$$L = 750$$

Condition (CON)

(01) Bent (2) Denied (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (P)
(4) Not Consistent (NC)

Vehicle No: SCN 6755 G

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate	CUT	✓	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp LH	BR	✓	
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket LH	BT	✓	
1148	993068	Rear Bumper Side Retainer LH	BR	✓	
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	DD	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector	DD	✓	
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	DD	R	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	DD	✓	
1182	991328	Tailgate Emblem	NEC	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor		?	
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	NEC	✓	
1196	994607	Tailgate Glass Sealant	NEC	✓	
1197	994629	Tailgate Lock	DM	✓	
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	DIS	✓	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker	NEC	✓	

No of Items: _____

Assessor: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18002949/T1rd3e2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

MAPLETREE ANSON

SINGAPORE 079914

Date : 23-05-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 2511T	Veh. Inspected	SJU 7674E
Policy No.	AVCPSPB0087511700	Coverage (\$)	0.00
Claim No.	GBG 2511T/SG	Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1BAAG11Z0110074	Colour	SILVER
Odometer	168841	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/02/2018	Inspection Date	14/02/2018
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 7674E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	595.10	595.10
2	FRONT BUMPER RETAINER LH/RH	O/S NECESSARY / O/S NOT NECESSARY	44.20	22.10
1	FRONT BUMPER SPONGE	NOT NECESSARY	244.60	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	618.10	-
1	FRONT FENDER LH	NOT NECESSARY	623.60	-
	LESS 30% DISCOUNT		-637.68	-185.16
			1,487.92	432.04
<u>NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	35.00	35.00
1	FRONT FENDER SPLASH SHIELD LH (N)	NOT NECESSARY	77.10	-
1	SET FRONT FENDER SPLASH SHIELD CLIPS (N)	NOT NECESSARY	30.00	-
2	HEADLAMP LH/RH (N)	O/S CUT / N/S NOT NECESSARY	1,136.20	568.10
	LESS 10% DISCOUNT		-127.83	-60.31
			1,150.47	542.79
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER LOWER SKIRT (SN)	NOT NECESSARY	578.00	-
1	FRONT NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	45.00	-
			623.00	-
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREAS.FRONT PORTION.BONNET,FRT BUMPER,FRT BUMPER SKIRT,FRT BUMPER REINFORCEMENT,FRT FENDER LH.		1,000.00	300.00
	TO PUTTY,RESPRAY PAINTING AND POLISH REAR AFFECTED AREAS.FRONT PORTION.BONNET,FRT BUMPER,FRT BUMPER SKIRT,FRT BUMPER REINFORCEMENT,FRT FENDER LH.		1,000.00	400.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		100.00	30.00
	TO RUST PROOF AFFECTED AREAS.		100.00	20.00
	TO REMOVE AND REFIT NECESSARY PARTS TO ASSIST REPAIR.	NOT NECESSARY	150.00	-
			2,350.00	750.00

Report Ref No. CS/AWA18002949/T1rd3e2



GRAND TOTAL		5,611.39	1,724.83
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,350.00

Report Ref No. CS/AWA18002949/T1rd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

