15/5/2410	Navbrah	CC 6 / AIG1800	2955, 4	LKK DAC:	
Surveyor	FASUL	DOI: ASSIGN	7/8	Date / Time :	18
Pre-assign / CCU	FTE CA	19396		Registered in Merimen: ————————————————————————————————————	1 + 1 to
Insured Vehicle No		11/1	Claim No.	1	
Name of Insured	JOHN WIN	v XIM XI	Policy No.	. H. Wach.	_ bx
Insured Tel No.	1	HP: 1 1	Make / Model	. MUAN MARCH	
Excess Sec II :S\$		D.O.A: 11 2/18	Place of Accide	nt: PAYA UBBAR 120 7	PIE
Is driver the owner	? (YES / NO )	Nature of Accident :		***************************************	
If NO, Driver Nar	Fra PIAN	WFNP	OI GIA REPOR	T: YES / NO ; TP GIA REPORT: Y	ES/NO
Driver Tel	10100	(V/L: YES)/ NO.)	Insured Liabilit		
SJF 24)	3€				
INSRS: WSP: Tel: Liability: RMKS:	INSRS WSP: Tel: Liabili RMKS	ry:	INSRS: WSP: Tel: Liability: RMKS:	INSRS: WSP: Tel: Liability: RMKS:	
Date/Time					
- 7V/V	57 FM 736 7 1	MARI 1875 283/16	II. DAA. 1.1.1.0	Non-Reporting ltr (1st):	ATE / PIC
N/M	1000 100 01. 1N	White on the ste	4,007,017/8	Non-Reporting ltr (2nd):	
	2001112010 500	Element and or of or	FART, MODE WILLIAM	Non-Reporting ltr (Final): Notification ltr (if non-pickup):	
12 9				0.11.01	W. W.
13 4 18	Speck to OD	he confirmed acci	dent details.	After call ltr to OI: 16/9	15 d.
	Informed of cla	im and he agree	to settle.	Documentation Check List: Handler	Typist
				Notification ltr (if non-pickup)  After call ltr to OI:	7 1
				Authorisation To Act:	
				Release Voucher:	
				Final Repair Bill:	
				Car Rental Invoice:	4
				Towing Invoice  LTA / GIA :	
	DEAG			Medical Bill:	
	RECEIV	ED 0 0 JUN 2018		PIR:	
				Mandate/Reject Instruction:	
				LOD Payment Breakdown Form:	
PRELIMINARY ADVICE	Date/Time:	Sent By:		Post-Repair Photos:	
I REELINING THE FICE	22000 2 2000	- January -		Others:	
FINALIZATION	Date/Time:	Confirm with:		Confirm by:	
Repair Cost:	SS (	days) Reduction:	%	Email Cal	1
FINAL SETTLEMENT	Date/Time: 5/6/18	Confirm with Soon Sa		Email Call	
Final Liability:	% (300.00 Agree)	/ Assessed) BOLA S/N No. : 2	4	If NO or B 28, Ass. Lia:	177
Repair Cost: Loss of Rental (LOR):	S\$ 1100.00 (	II days) x 100	14	000/1350	4
Loss of Use (LOU):	Total Inc.	c days)		6618	
Loss of Income (LOI):		days)		0101	
LOR only LOU only		LOR + LOI [Tick only of	one]		
GIA/LTA Search Medical:	S\$ S\$			1) Claim status: Normal/Reject/Priv	ate Settle
Disbursement:	SS	(e.g. Tow/ Indepen	dent )	2) Report Format:	
Legal Cost	SS			3) Survey fee:	
Total:	ss 1400.00	Global Sum SS:		P2	
FINAL PAYMENT	Date/Time:	Confirm with:	1 no 0 0 0 0	Email Call	
Payee 1:	ss 7400.00	Name 1: SOON SA Name 2:	IN MOTOR	KHUING	1841
Payee 2: (Strike if N.A.) Payee 3: (Strike if N.A.)	S\$	Name 3:			
7-7-1-1					

66766



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

(Ale		Affiliated to Federation Inter	nationale Des Experts En Autom	obile	
AIG /	ASIA PACIFIC INS	URANCE PTE LTD	Ref : CC6/AIG18002	955/R1ua3	
CHA	HENTON WAY #08 RTIS BUILDING GAPORE 079120	3-16	Date: 13-02-2018  Code: AIG		
1.		Policy Particu	lars :- THIRD PARTY CLAI	M	
	Insured Veh.	SJQ 1939C	Veh. Inspected	SJF 2473E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	13/02/2018	
2.		Vehicle F	Particulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
Odometer -		Steering			
	Brakes Modification				
	General				
3.		Co	enditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Desc	cription of Damages		
5.		Ge	eneral Information		
J.	Accident Date	11/02/2018	Inspection Date	12/02/2018	
	Survey held at	5.150 CT 10.150			
	Survey neid at	BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716			
5a.			Remarks		
	A)THE INSPECTION	ON WAS CONDUCTED ON CE TO YOUR INSTRUCTIO	A"WITHOUT PREJUDICE" BA NS, WE HAVE NOT AUTHORI	SIS. ISED REPAIRS.	

## SOON SAN MOTOR TRADING

BIK.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILING

S,pore 079120

Accident date:11/02/18

Date:12/02/18

Estimate cost to repair vel: SJF 2473E (Honda Airwave) claims under vel: SJQ 1939C.

1pce tail gate	\$ 1,200.00
1pce tail gate top lock	129.40 %/
1pce tail gate lower lock	30.70 %/
1pce tail gate lower lock cover and pure cover	130.00
1pce tail gate airwave plate	35.10 Am /
1pce tail gate emblem	38.00 per/
2pcs tail gate reflectors@\$255.30	510.60 SCA
1pce tail gate centre garnish cover	321.20 (14/
1pce tail gate trim cover	345.90 CP4 /
1pce tail gate handed	21.10 × pus/
2pcs tail gate dampers@\$198	396.00 × 900
2pcs rear fender trim cover@\$158.20 LH-は	316.40 RHX 200 , UL
2pcs tail lamps@\$278	556.00 LH-X/RH-*X
1pce rear windscreen top rubber	42.20 New -
1pce rear windscreen lower rubber	38.50 14-
2pcs rear windscreen side rubber@\$28.10	56.20 /
1pce rear windscreen inner sealant	148:00 60 me/ 5/N./
1pce rear windscreen sunx sticker	350.00   ✓
1pce tail gate rubber	178.40 he
1pce rear bumper	985.00 TVE /
1set rear bumper reverse sensors	450.00 × 8rc
10pcs rear bumper inner clips@\$5	50.00 ne/
4pcs rear bumper top side clips#@\$10	40.00 No -
2pcs rear bumper side holders@\$68	136.00
1pce rear panel	485.00 84
1pce rear spare tyer panel	850.10 page 1

## SOON SAN MOTOR TRADING

BIk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept	"KARNE
AIG ASIA PACIFIC PTE LTD	Hp 90010068
78, Shenton Way #09-16	10 days
AIG BUILING	45
S,pore 079120	12/02/18 @ 1010
Accident date:11/02/18	
Date:12/02/18	Racy after repri

Estimate cost to repair vel: SJF 2473E (Honda Airwave) claims under vel: SJQ 1939C.

1set spare tyer panel paddling	\$ 285.20 /4 /
1pce spare tyer top cover	198.20 ×m 6066.80
	\$ 8,315.20 20%
	1,663.04 4853.44
	\$ 6,652.16
1pce rear number plate with cover	100,00 35 M - S/W - 5/N95
To rustproof	150.00 100
To check wiring	50.00 30
To remove/refit rear windscreen	140:00 120
To dismantle/renew tail gate	150.00 80
To remove/refit rear interior to effect repair	100.00 60
To remove/refit rear petrol tank to effect repa	ir 150.00 ×M 29/0
To dismantle/renew reverse sensors	190:00 (0)
To remove/refit top spoiler	100.00 60
To dismantle/renew accident portion	1,890.00 /200
To spray paint	1,500.00 /200
Total:	\$10,992.16
IDE Tailgate outer Lock	215-10 7 X50
2 pcs Taitlamp ciner panel 3#215.	20 430.40 R
Iple von vertse Courea	SN4350.00 X 50C
	11.856.56
LKK Auto Consultants hence notify	
the Repairer of the following:	
To resurvey before/after spray painting	
To display damaged part(s) during resurvey	110+21111 9
Parts prices are subject to confirmation     Third party survey is on a "Without Prejudice" basis	4853,44 - 7
No illegal modification(s) is allowed.	95.00 - 8/6
Supplementary item(s) must be resurveyed and	
is subject to final approval from Insurance Company	2910.00
Acknowledged by Repairer	12.44
Signature:	7858.44
Date:	10 20% - L

10 Sin Ming Drive Singapore 575701 Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

15 Mar 2018

Our ref 1503180901N036056738

WEE KAH MAY APT BLK 753 PASIR RIS STREET 71 #02-110 SINGAPORE 510753

Dear MS WEE KAH MAY

# RENEWAL OF CERTIFICATE OF ENTITLEMENT (COE) FOR VEHICLE NO. SJF2473E

We refer to your application on 15 Mar 2018 to renew COE for the above vehicle.

- You may be pleased to know that the COE for this vehicle has been renewed until 31 Mar 2023.
   Further COE renewal is not allowed. The vehicle will be deregistered when the COE expires on 31 Mar 2023.
- 3. The road tax for this vehicle will expire/has expired on 22 May 2018. Please renew the road tax promptly as it is an offence to use or keep a vehicle without valid road tax and insurance. Late renews fee will be imposed if road tax is renewed after its expiry.
- 4. Please visit http://www.onemotoring.com.sg for more vehicle-related information and services contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have an questions.

ours sincerely

IG LAY CHOO (MS)
DEPUTY DIRECTOR, VRL SERVICE OPERATIONS
TEHICLE SERVICES GROUP
AND TRANSPORT AUTHORITY

This is a computer-generated notice that requires no signature.)

som 15 February 2017, you do not need to display road tax disc on the windscreen of your vehicle. It is stopped issuing physical road tax discs as part of our efforts to streamline our processes. Place that your original motor insurance certificate is readily available in your vehicle at all times. If the driving into Malaysia, you are advised to carry printed proof of the validity of your road tax in hicle.



port Authority Drive 75701

ation No.: M4-0006529-2

Print Date/Time: 15 Mar 2018 / 12:10:26

Receipt Date/Time: 15 Mar 2018 / 12:10:26

## Tax Invoice/Receipt


LTACT-MTX-180315-000175

eipt No. :

Description/		<b>在</b> 基本的一种研究		
ess Transaction Reference		Amount Before	GST Amount	Amount After GST
OE - SJF2473E		GST (S\$)	(S\$)	(\$\$)
ta Premium ( 01 Apr 2018 - 31 5120928326109	Mar 2023 )	19,637.00	0.00	19,637.00
	Sub-Total	19,637.00	0.00	19,637.00
	Total Before Rounding	19,637.00	0.00	19,637.00
	Rounding Difference			0.00
	Total Amount Payable			19,637.00
	Paid By			
		Cash		20,000.00
	Total			20,000.00
·	Cash Change			363.00
	Tendered Amount			19,637.00
	Excess Refundable Amount			0.00

### THANK YOU AND HAVE A NICE DAY!

that all payments to the Authority are good and promptly settled by the payment service ancial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Transport Authority Ming Drive Sore 575705

Ingistration No. 384-0006526-2

Print Date/filme

15 Mar 2018 / 12.10.26

Receipt Date/Time

15 Mar 2018 / 12 10:26

## Tax Invoice/Receipt

No. LTACT-MYX-180315-500175

s Receipt No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
GST (S\$)		
		STATE OF THE PARTY
19,637.00	0.00	19,637.00
19,637,00	0.00	19,637.00
19,637.00	0.00	19,637.00
		0.00
		19,637 00
Cash		20,000.00
		20,000.00
		363.00
		19,637.00
		0.00
THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN	19,637,00 19,637.00	19,637,00 0.00 19,637.00 0.00

#### THANK YOU AND HAVE A NICE DAY!

ensure that all payments to the Authority are good and promptly settled by the payment service er / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply. WEE KAH MAY APT BLK 753 PASIR RIS STREET 71 907-110 SINGAPORE 510753

DOMENTS WITE KARNIAY

## RENEWAL OF CERTIFICATE OF ENTITLEMENT (COE) FOR VEHICLE NO. SJF1473E

We refer to your application on 13 Mar 2018 to renew COE for the above websiele.

You may be pleased to know that the COE for this vehicle has been renewed until 31 Mar 21 Further COE renewal is not allowed. The vehicle will be deregistered when the COE expires on Mar 2023

The road tax for this vehicle will expire has expired on 22 May 2018. Please senew the source to use or keep a vehicle without valid road tax and insurance. Late remove will be imposed if road tax is renewed after its expiry.

Please visit http://www.onemotoring.com.sg for more vehicle-related information and service ontact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have uestions

ours sincerely

G LAY CHOO (MS)
EPUTY DIRECTOR, VRL SERVICE OPERATIONS
EHICLE SERVICES GROUP
AND TRANSPORT AUTHORITY

ars is a computer-generated notice that requires no signature.)

stopped issuing physical road tax discs as part of our efforts to streamline our processes are that your original motor insurance certificate is readily available in your vehicle at all times driving into Malaysia, you are advised to carry printed proof of the validity of your road tax cle

## Road Tax Payment Notice

15 Mar 2018

Our ref: 1503180704N067241979

WEE KAH MAY APT BLK 753 PASIR RIS STREET 71 #02-110 SINGAPORE 510753

### Vehicle No.: SJF2473E

Dear WEE KAH MAY

The road tax (i.e. vehicle licence) for your vehicle SJF2473E will expire on 22 May 2018.

Please follow the steps listed on the right to pay your road tax by 22 May 2018.

Thank you for paying your road tax on time.

Yours sincerely

Ng Lay Choo (Ms) for Registrar of Vehicles

# Be On Time!

## Avoid Late Payment Fees

ate Payment Fees Payable From: \$

23 May 2018	20
23 Jun 2018	70
06 Aug 2018	90
23 Aug 2018	240

### For your attention:

- · From 15 February 2017
  - LTA has stopped issuing road tax discs
  - There is no need for Singapore-registered vehicles to display the discs
- Road tax is still payable
- Keep your vehicle's original certificate of insurance in your vehicle at all times

# What you need to do: Decide on payment period

Payment Period	6 Months	12 Monti
Road Tax	376	751

Payable \$376 \$751

Complete the following:

 Ensure your motor insurance coverage is va up to 22 Nov 2018 (for 6 month renewal) or May 2019 (for 12 month renewal)

- Pay your road tax at AXS Station Station (mobile) / e-Station (interne www.onemotoring.com.sg
- Onfirm that your road tax has successfully paid



port Authority Drive 75701

ation No.: M4-0006529-2

Print Date/Time:

15 Mar 2018 / 12:10:26

Receipt Date/Time: 15 Mar 2018 / 12:10:26

## Tax Invoice/Receipt

LTACT-MTX-180315-000175

eipt No. :

Description/				
ess Transaction Referen	ce	Amount	GST	Amount
		Before	Amount	After GST
OE - SJF2473E		GST (S\$)	(S\$)	(\$\$)
ta Premium ( 01 Apr 2018 - 5120928326109	31 Mar 2023 )	19,637.00	0.00	19,637.00
	Sub-Total	19,637.00	0.00	19,637.00
	Total Before Rounding	19,637.00	0.00	19,637.00
	Rounding Difference			0.00
	Total Amount Payable			19,637.00
	Paid By			
September 1987		Cash		20,000.00
	Total			20,000.00
	Cash Change			363.00
	Tendered Amount			19,637.00
	Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

that all payments to the Authority are good and promptly settled by the payment service ancial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## **SOON SAN MOTOR TRADING**

BIK.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILING

S,pore 079120

Accident date:11/02/18

Date:12/02/18

Estimate cost to repair vel: SJF 2473E (Honda Airwave) claims under vel: SJQ 1939C.

1pce tail gate	\$ 1,200.00 324
1pce tail gate top lock	129.40 <i>M</i> /
1pce tail gate lower lock	30.70 %/
1pce tail gate lower lock cover and pure corn	130.00
1pce tail gate airwave plate	35.10 Am /
1pce tail gate emblem	38.00
2pcs tail gate reflectors@\$255.30	510.60 50
1pce tail gate centre garnish cover	321.20 CM/
1pce tail gate trim cover	345.90 (14/
1pce tail gate handed	21.10 × pus/
2pcs tail gate dampers@\$198	396.00 ×
2pcs rear fender trim cover@\$158.20 LH-CH/	316.40 RH X
2pcs tail lamps@\$278	556.00 LH-X/RH-?
1pce rear windscreen top rubber	42.20 New /
1pce rear windscreen lower rubber	38.50
2pcs rear windscreen side rubber@\$28.10	56.20
1pce rear windscreen inner sealant	130.00 60 Ne / 5/N
1pce rear windscreen sunx sticker	350.00
1pce tail gate rubber	178.40
1pce rear bumper	985.00 ₩
1set rear bumper reverse sensors	450.00
10pcs rear bumper inner clips@\$5	50.00 ne/
4pcs rear bumper top side clips#@\$10	40.00
2pcs rear bumper side holders@\$68	136.00
1pce rear panel	485.00 84
1pce rear spare tyer panel	850.10 page 1

## **SOON SAN MOTOR TRADING**

BIK.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILING

S,pore 079120

Accident date:11/02/18

Date:12/02/18

RAFIL

HP 90010068

10 days

45

12/02/18 & 1010

Recy after repair

Estimate cost to repair vel: SJF 2473E (Honda Airwave) claims under vel: SJQ 1939C.

1set spare tyer panel paddling	\$ 285.20 /4 /
1pce spare tyer top cover	198.20 🗶
	\$ 8,315.20
	1,663.04
	\$ 6,652.16
1pce rear number plate with cover	100.00 35 M - S/W
To rustproof	150.00 /00
To check wiring	50.00 30
To remove/refit rear windscreen	149.00 120
To dismantle/renew tail gate	150.00 80
To remove/refit rear interior to effect repair	100.00 60
To remove/refit rear petrol tank to effect repair	150.00
To dismantle/renew reverse sensors	100.00 60
To remove/refit top spoiler	100.00 60
To dismantle/renew accident portion	1,890.00 1200
To spray paint	1,500.00 /200
Total:	\$10,992.16
100 Tailcate outer Lock	245-10 7
1 pe Tailgate outer Lock 2 pes Taillamp cinor panel 9#215.20 1 pe ver rerse course	430.40 R
106 ver revise Course	3350.00 ×
A	
LKK Auto Consultants hence notify	
the Repairer of the following:	
To resurvey before/after spray painting     To display damaged part(s) during resurvey	
Parts prices are subject to confirmation	The state of the s

- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

AC	0	DEN'	тет	- 7	<b>E 6.6</b>	EN	т
AL	u	DEN	0	м	į	-	u

12/02/2018 15:02 Date Of Report 11/02/2018 14:30 Date Of Accident

PAYA LEBAR ROAD TWDS PIE Exact Location Of Accident

SINGAPORE Country/State of Loss

#### **DETAILS OF OWN VEHICLE**

SJF2473E Vehicle Registration Number

Insured/Policyholder

NICODEMUS NIKKI WEE, KAH MAY Name Of Registered Owner

S7046676G NRIC No. NOEMAIL **Email Address** 

(LOCAL) +65-93833628 Mobile Phone No OTHERS-93833628 Atternative Phone No.

Vehicle Particulars

HONDA Manufacturer

AIRWAVE 1.5M A Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No. Please state action to be taken Vehicle Category

PRIVATE CAR

**Insurance Company** 

DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

MT/00123933/04 Policy Number

Cover Note Number

#### Driver

NICODEMUS NIKKI WEE, KAH MAY Name of Driver

S7046676G NRIC No 20/12/1970 Date Of Birth OUTDOOR Occupation 24/01/2000 Date Of Driving Pass

18 YEARS AND 0 MONTHS **Driving Experience** 

FEMALE Gender

(LOCAL) +65-93833628 Mobile Number

Fax Number

OTHERS-93833628 Contact Number

NOEMAIL **EMail Address** 

Address

BLK 753 PASIR RIS STREET 71

#02-110

Postcode

510753

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

TRAFFIC POLICE DIVISION HQ

Police Station Name Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20180212/2113

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJQ1939C

Vehicle Make/Model/Colour

**Details Of Properties** 

PRIVATE CAR

Vehicle Category Name of Driver

YEO TIAN MENG

NRIC/Passport Number

Contact Number

97830790

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 20

### No. Of Passenger (Including Driver)

#### **DETAILS OF INJURED PERSON 1**

Name

NICODEMUS NIKKI WEE, KAH MAY

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address

Postcode

SERIOUS

SJF2473E

YES

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Pers

Name:

NRIC/FIN No.:

Policyholder's Signature Date & Time:

(If driver is not the policyholder)

Date & Time:

Name:

NRIC/FIN No.:



T/20180212/2113

1 of 3

Report No. T/20180212/2113

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

A TRAFFIC	ACCIDENT	Line Bound No.	Station Diary No.:	
		Vide Report No		
's Particu	lars			
formant.		Address: APT BLK 753 PASIR RI	IS ST 71 #02-110 SINGAPORE 510753	
D No.:		Contact No.: Home/Office:	Mobile: 93833628	
/: /:	00	Email:		
Age:	Date of Birth:	Type of Informant: Driver  Language:  Driving Licence Information: Class: 3  Date of Expiry:		
47	20/12/10/0			
on:				
	Report May 14:33  S Particular formant: IUS NIKKI D No.: // S704667	respective of Birth: 20/12/1970	Report Made: 3 14:33  S Particulars  Informant: IUS NIKKI WEE KAH MAY  D No.: // S7046676G  Age: Age: 47  Date of Birth: 20/12/1970  Driving Licence Information: Class: 3	

eneral Infor	nation of the Accid	lent	Date/Time of	Type of Location	
Type of Accident:	Injury Others	Drink Drive: No	Accident: 11/02/2018 14:30		
Location: Along Road PAYA LEBAI PAN ISLANI	R ROAD EXPRESSWAY			Coand Limit	
Meather		Road Surface: Dry		Road Speed Limit:  Traffic Volume:  Moderate	
	Clear		162		
Clear		Traffic Control:	N	/loderate	
		Traffic Control:	F	Moderate Anyone conveyed by ambulance:	

Details of Vo	ehicle Invo	lved	10. 11	Color	Condition	No of Passenge
Vehicle No.	Туре	Make	Model		Seriously	
SJF2473E		HONDA	1.5M A	Silver	Damaged	
331 24102	5,600	1.5M A	1.5W A		Slightly	1
SJQ1939C	Car			1	Damaged	

Details of V	ehicle Insurance	Insurance No	The state of the s	Expiry Date
Vahiola No	Insurance Company	MT/00123933/04	23/05/2013	22/05/2018
SJF2473E	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.			





T/20180212/2113

2 of 3

Report No. T/20180212/2113

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

#### CONTINUATION OF REPORT

Details of Person	n Involved			Red Sale	EL STABLES	The state of the s	
Any Pedestrian Ir	volved: No						
No. of Pedestrian			Use of Pe	destrian	Cross	ing: NA	
Driver						070400700	
Name	NICODEMUS NIKKI	WEE KAH	MAY	ID No.	8	S7046676G	
Related Vehicle	SJF2473E (Car)			Conta	ct No.	93833628	
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		_	Class of Driving Licence & Expiry Date		Class: 3 Date of Expiry: NIL	
Date Treatment	11/02/2018		Date Disc	harge	11/02	2/2018	
	ted Medical Leave	05	Degree of	f Injury	Serio	us	
Driver		2010			San Oran		
Name	YEO TIAN MENG			ID No		NIL	
Related Vehicle	NIL			Contact No.		97830790	
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL	
Date Treatment	NIL		Date Disc	charge	NIL		
	ted Medical Leave	NIL	Degree o	f Injury	NIL		

#### Brief Details.

AT THE ABOVE MENTIONED DATE, TIME AND LOCATION, I WANTED TO TRAVEL FROM PAYA LEBAR ROAD TO PIE, HENCE I WAS AT THE SLIP ROAD WAITING TO ENTER PIE, WHEN A CAR HIT ME FROM BEHIND. WE THEN GOT OUT OF OUR CAR AND EXCHANGED PARTICULARS. THATS ALL.





3 of 3

Report No. T/20180212/2113

Police Station Of Origin: Traffic Police Division HQ 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

n

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature:

Signature Of Officer Recording The Report: TP / S SIVAVIKNESH	Signature
Signature Of Interpreter: Not applicable	Date/Tim 12/02/20
Officer In Charge Of Case: TP / AEIT /	Classifica
Sgt 2 YEO KIA HUAT Contact No.: 65476325	

Signature Of Inform	nant:	
Date/Time: 12/02/2018 14:33		
Classification Of C	SINGAP	

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

C 16	lotified	Est Submitted	Adj Assigned	Adj Rpt		Adi Subr	nitted	Ins Auth'ed	Status				
	3 Feb 2018 Edit Reg	Est Submitted	12 Feb 2018 00:00 Edit Adj Rpt	S\$6,300.00 Edit Estimates		S\$6,300.00		<b>S\$6,300.00</b> View Rpt			Pending Report  Cancel Ca	•	rey
М	ain	F	eference		Claim C	Details	$\prod$	Docume	nts	S	how All		
CLAIM SUB	FOLDER DE	TAILS					[Create	ed by adjuster]					
Insured:	Wing Xi Y	i Joan, ID: S8	636293G, Tel: +	6597526256									
Main Claimant:	NICODEM	NICODEMUS NIKKI WEE, KAH MAY, ID: S7046676G											
Vehicle Reg. No.:	SJF2473E				of Loss:	11/02/2 [ <b>116</b> Mc	018 14:00 - :59 onths and <b>19</b> Day	s From LTA Re	eg Date (	(Man Yr)			
Claim Type:	<b>TP</b> / 592	25370853SG				y/Cover No.:	210049	0490921 (Comprehensive)					
Vehicle Reg. No. (Insured):	SJQ1939	с				y No. mant):	MT/00123933/04						
(11.001.00)					Exce								
Repairer:	Soon San	Motor Trading	(HQ) BLK 3006 I	JBI ROAD 1	#01-39	0, 40870	0 Ubi - Te	1: 68414445					
Handling Insurer:		Pacific Insurar dNoor@aig.com	nce Pte. Ltd. (Ex	press) - Tel:	65-64	19-3000 .	[Handle	ed by <b>MdNoor, N</b>	lorsiah]				
Claimant's Insurer:			Singapore) Pte L							102/20	1101		
Adjuster:	LKK Auto	Consultants P	te Ltd (HQ) - Tel	6256-3561	[Har	ndled by I	MOHD R	ASUL] [Final	Rpt due 23	5/02/20	119]		
Driver/Custo dian (Insured):		MENG (), NRI	C: S8826427D										
ASSOCIAT	ED MAIL RI	ECEIVED							View All	Compose	Case Ma		
AIG_SG (	14/02/2018)	: Request To U	pload TP GIA Re	port									
ALL ASSO	CIATED TA	sks⊟					View /	All   Search Tasks	Create Ne	w Task	Comple		
Due Date	Priority	Type Tas	sk Group Sub	ject Han	dler	Assign	ned By	Completed	On Crea	ted On	Don		

### **Claim Documents**

\*SJF2473E (5925370853SG)

[SJQ1939C]

TP

NICODEMUS NIKKI WEE, KAH MAY

Feb 11 2018 2:00PM

[Wing Xi Yi Joan]

Soon San Motor Trading

Lett	ers/Corresponden	ces	1 per page ▼		
0901	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Vo.	(Draft)	Third Party Express Settlement – Payment Breakdown	0	Edit	
			1 per	page ¥	•
	essment Reports	The state of the s	T per	Thumbnail	-
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)  Accident Statement	0	Load HTM	7.7.11
1	14/02/18 11:34	From: OD - Reg. No: SJQ1939C, Claimant: JOAN WING XIN YI		Load Hills	
Pho	tos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	07/06/18 10:19	General View	0	Load JPG	1
2	07/06/18 10:19	General View	0	Load JPG	•
3	07/06/18 10:19	General View	0	Load JPG	•
4	07/06/18 10:19	General View	0	Load JPG	•
5	07/06/18 10:19	General View	0	Load JPG	•
6	07/06/18 10:19	General View	0	Load JPG	•
7	07/06/18 10:19	General View	0	Load JPG	1
8	07/06/18 10:19	General View	0	Load JPG	~
9	07/06/18 10:19	General View	0	Load JPG	2
10	07/06/18 10:19	General View	0	Load JPG	~
11	07/06/18 10:19	General View	0	Load JPG	~
12	07/06/18 10:19	General View	0	Load JPG	•
13	07/06/18 10:19	General View	0	Load JPG	•
14	07/06/18 10:19	General View	0	Load JPG	~
15	07/06/18 10:19	General View	0	Load JPG	•
16	07/06/18 10:19	General View	0	Load JPG	1
17	07/06/18 10:19	General View	0	Load JPG	2
18	07/06/18 10:19	General View	0	Load JPG	~
19	07/06/18 10:19	General View	0	Load JPG	~
20	07/06/18 10:19	General View	0	Load JPG	
21	07/06/18 10:19	General View	0	Load JPG	1
22	07/06/18 10:19	General View	0	Load JPG	
23	07/06/18 10:19	General View	0	Load JPG	
24	07/06/18 10:19	General View	0	Load JPG	
25		General View	0	Load JPG	
26		General View	0	Load JPG	9
27		General View	0	Load JPG	
28		General View	0	Load JPG	9

Letters/Correspondences		1 per page ▼		•	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
29	07/06/18 10:19	General View	0	Load JPG	₹
30	07/06/18 10:19	General View	0	Load JPG	•
31	07/06/18 10:19	General View	0	Load JPG	✓
32	07/06/18 10:19	General View	0	Load JPG	•
33	07/06/18 10:19	General View	0	Load JPG	•
34	07/06/18 10:19	General View	0	Load JPG	•
35	07/06/18 10:19	General View	0	Load JPG	•
36	07/06/18 10:19	General View	0	Load JPG	•
37	07/06/18 10:19	General View	0	Load JPG	•
38	07/06/18 10:19	General View	0	Load JPG	
39	07/06/18 10:19	General View	0	Load JPG	•
40	07/06/18 10:19	General View	0	Load JPG	•
15,000	07/06/18 10:19	General View	0	Load JPG	•
41		General View	0	Load JPG	•
42	07/06/18 10:19	General View	0	Load JPG	•
43	07/06/18 10:19	DATASE AND VIOLENCE D	0	Load JPG	•
44	07/06/18 10:19	General View	0	Load JPG	•
45	07/06/18 10:19	General View	o	Load JPG	•
46	07/06/18 10:19	General View	0	Load JPG	•
47	07/06/18 10:19	General View	0	Load JPG	•
48	07/06/18 10:19	General View			<b>S</b>
49	07/06/18 10:19	General View	0	Load JPG	100000
50	07/06/18 10:19	General View	0	Load JPG	•
Do	cumentation		1 pe	r page ▼	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnai	Prin
1	20/02/18 19:30	TP ESTIMATE - MARKED	0	Load PDF	
2	07/06/18 10:27	AUTHORISATION TO ACT	•	Load PDF	
3	07/06/18 10:27	LETTER TO OI	0		
4	07/06/18 10:27	RELEASE VOUCHER	0		
5	07/06/18 10:27	RENTAL RECEIPT	0		
6	07/06/18 10:27	WORKSHOP INVOICE	0	Load PDF	

### **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

LKK Auto Consultants Pte Ltd

TEA	M	

## THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

			h)	Model:	lu.	ONDA AIRWAVE 1.5 M (A)
		SJF2473E (TP veh)				
Date	of Accident:	11/02/2018				
				***		
Cloba	l Sum Settleme	nt I I I V	'es	[X] No	1	
75.05	r Estimate	14 1 1 1	: \$	11,858.5	5	
	Repair Cost		:\$	6,300.00	4	
	of Use		:\$	0,000.00		days at \$0.00 per day
	il (if any)		: \$	1,100.00	11	days
	GIA Search Fee		: \$	11133133	1	27.7 <b>4</b> 200
77.02.32.5		3	: \$			
Other	S:		: \$		+	
			: \$	7,400.00	1	
	Settlement Sur					//Cir.dl., in disease below)
	VOLUME OF STREET	shop GIA Registered	? []	YES [X]	NO	(Kindly indicate below)
-		egistered Workshop:		Agreed Liability		
- CO		ered Workshop:				BOLA Scenario No:
		(%)		Assessed Liabilit		
3	* Assessed Liab	pility to be filled only for	chain collisi	ions and for cases v	vhere BO	LA does not apply.
Rema	arks					
	49					
Payn	nent Instruction	n: Payee's Breakdowi	n			
1)	Soon San Moto	or Trading		: \$		7,400.0
2)				: \$		
-/						

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

2018 Date

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG18002955/R1UA3S2

Date:

07/06/2018

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100490921

Claimant Vehicle No .

SJF2473E

Insured Vehicle No:

SJQ1939C

Date of Loss:

11/02/2018

Nature of Claim:

Claim No: 5925370853SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Make & Model:

**SJF2473E** 

HONDA AIRWAVE, 1.5 M (A)

23/05/2008 (Man. Year: 2008)

Chassis No: Odometer:

Engine No:

L15A5158987 GJ11207604

180451 km

Reg. Date: Colour:

Grey 1496 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Engine Capacity:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Fair Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

195/55R15

Rear Tyre Size:

195/55R15

Front Left Side:

COST OF CLAIMS

Miscellaneous Items

Paintwork Labour

Parts

Labour

Towing

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm Bridgestone 6 mm

Front Right Side:

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
	7,618.56	4,948.44	2,670.12	35.05
	0.00	0.00	0.00	
	4,240.00	2,910.00	1,330.00	31.37
	0.00	0.00	0.00	
	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,858.56	7,858.44	4,000.12	33.73
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	11,858.56	6,300.00	5,558.56	46.87
+ Car Rental (11.0 x S\$	100.00/day) (S\$)	1,100.00		
N	ett Liability (S\$)	7,400.00		

INSPECTION

Date of Assignment:

12/02/2018

Date Inspected:

12/02/2018

Estimated Period of Repair:

10.0 days

Soon San Motor Trading (HQ) BLK 3006 UBI ROAD 1 #01-390

Singapore 408700

Adjuster:

MOHD RASUL

Manager:

THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_printrpt&caseid=684120&extid=264593&CFID=35061669&CFTOKEN=4

Inspected At:

any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

10,00		mended Parts Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAIL GATE	Buckled	1,200.00 FL	*1,200.00 FL
2	1	*TAIL GATE TOP LOCK	Bent	129.40 FL	*129.40 FL
3	1	*TAIL GATE LOWER LOCK	Bent	30.70 FL	*30.70 FL
4	1	*TAIL GATE LOWER LOCK COVER END PANEL COV	ER Deformed	130.00 FL	*130.00 FL
5	1	*TAIL GATE AIRWAVE PLATE	Necessary	35.10 FL	*35.10 FL
6	1	*TAIL GATE EMBLEM	Necessary	38.00 FL	*38.00 FL
7	2	*TAIL GATE REFLECTORS	Scratched	510.60 FL	*510.60 FL
8	1	*TAIL GATE CENTRE GARNISH COVER	Cracked	321.20 FL	*321.20 FL
9	1	*TAIL GATE TRIM COVER	Cracked	345.90 FL	*345.90 FL
10	1	*TAIL GATE HANDED	Distorted	21.10 FL	*21.10 FL
11	2	*TAIL GATE DAMPERS	Serviceable	396.00 FL	*-FL
12	1	*REAR FENDER TRIM COVER	N/s Cut / O/s Serviceable	316.40 FL	*158.20 FL
13	2	*TAIL LAMPS	Serviceable	556.00 FL	*- FL
14	1	*REAR WINDSCREEN TOP RUBBER	Necessary	42.20 FL	*42.20 FL
15	1	*REAR WINDSCREEN LOWER RUBBER	Necessary	38.50 FL	*38.50 FL
16	2	*REAR WINDSCREEN SIDE RUBBER	Necessary	56.20 FL	*56.20 FL
17	1	*REAR WINDSCREEN SUNX STICKER	Not Necessary	350.00 FL	*- FL
18	1	*TAIL GATE RUBBER	Necessary	178.40 FL	*178,40 FL
19	1	*REAR BUMPER	Deformed	985.00 FL	*985.00 FL
20	1	*SET REAR BUMPER REVERSE SENSOR	Serviceable	450.00 FL	*- FL
21	10	*REAR BUMPER INNER CLIPS	Necessary	50.00 FL	*50.00 FL
22	4	*REAR BUMPER TOP SIDE CLIPS	Necessary	40.00 FL	*40.00 FL
23	2	*REAR BUMPER SIDE HOLDERS	Necessary	136.00 FL	*136.00 FL
24	1	*REAR PANEL	Bent	485.00 FL	*485.00 FL
25	1	*REAR SPARE TYRE PANEL	Buckled	850.10 FL	*850.10 FL
26	1	*SET SPARE TYRE PANEL PADDING	Necessary	285.20 FL	*285.20 FL
27	1	*SPARE TYRE TOP COVER	Serviceable	198.20 FL	*- FL
28	1	*REAR WINDSCREEN INNER SEALANT	Necessary	112.00 FS	
29	1	*REAR NUMBER PLATE WITH COVER	Bent	100.00 FS	*35.00 FS
30	1	*TAILGATE OUTER LOCK	Serviceable	215.10 FL	*-FL
31	2	*TAILLAMP INNER PANEL	Repair	430.40 FL	*-FL
32	1	*REAR REVERSE CAMERA	Serviceable	350.00 FS	*-F8
	ranchise	part, S=SpcNett, L=ListItemDisc,			
			Sub Total (S\$	N - 5.70 M.	6,161.80
		- List Item Discour	t on L Items 20.00/20.00% (S\$	1,764.14	1,213.36
			Total Parts (S\$	7,618.56	4,948.44

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recon	nmen	heh	l ah	OUR
	HILLGIN	100		, Ou

OOF. VIRING.  / REFIT REAR WINDSCREEN.  **LE / RENEW TAIL GATE.  / REFIT REAR INTERIOR TO EFFECT REPAIR.  / REFIT REAR PETROL TANK TO EFFECT REPAIR.	New New New New	150.00 50.00 140.00 150.00	30.00 120.00 80.00
VIRING.  / REFIT REAR WINDSCREEN.  LE / RENEW TAIL GATE.  / REFIT REAR INTERIOR TO EFFECT REPAIR.	New New New	50.00 140.00 150.00	120.00 80.00
/ REFIT REAR WINDSCREEN. 'LE / RENEW TAIL GATE. / REFIT REAR INTERIOR TO EFFECT REPAIR.	New New	140.00 150.00	80.00
LE / RENEW TAIL GATE. / REFIT REAR INTERIOR TO EFFECT REPAIR.	New	150.00	
/ REFIT REAR INTERIOR TO EFFECT REPAIR.	, , , , , , , , , , , , , , , , , , ,	DOWN STATE	80.00 60.00
	New	100.00	60.00
/ REFIT REAR PETROL TANK TO EFFECT REPAIR.			00.00
	New	150.00	0.00
LE / RENEW REVERSE SENSOR.	New	100.00	60.00
/ REFIT TOP SPOILER.	New	100.00	60.00
LE / RENEW ACCIDENT PORTION.	New	1,800.00	1,200.00
AINT.	New	1,500.00	1,200.00
Gross La	abour Cost (S\$)	4,240.00	2,910.00
E	E / REFIT TOP SPOILER. ITLE / RENEW ACCIDENT PORTION. PAINT. Gross La	E / REFIT TOP SPOILER.  ITLE / RENEW ACCIDENT PORTION.  PAINT.  Gross Labour Cost (S\$)	E / REFIT TOP SPOILER. New 100.00 ITLE / RENEW ACCIDENT PORTION. New 1,800.00 PAINT. New 1,500.00

< END OF ESTIMATES >