

(A)

INS. CASE OWNER: Shawn | CC 3 / AIG180 02965 / Kloss | LKK: | IDAC:

Surveyor: 1/ALVIN | DOI: 12/2/18 | Date / Time: 12/02/18
Registered in Meritum: 13/02/18

Pre-assign / CCU / FTE

Insured Vehicle No.: SJY 5929B | Claim No.: 0627999563SG
 Name of Insured: LIM GAH KOON | Policy No.: 2100484513
 Insured Tel No.: _____ | HP: 93822954 | Make / Model: 1-VIOS
 Excess Sec II :SS _____ | D.O.A.: 07/02/18 | Place of Accident: _____
 Is driver the owner? (YES / NO) _____ | Nature of Accident: _____
 If NO: Driver Name / Age: _____ | OIGIA REPORT: YES / NO : TP GIA REPORT: YES / NO
 Driver Tel No.: _____ | (VI- YES / NO) _____ | Insured Liability: % Final ? Yes / No

SH 7652A

INSRS: WSP: 068 (Lump) | Tel: _____ | Liability: _____ | RMKS: _____
 INSRS: WSP: _____ | Tel: _____ | Liability: _____ | RMKS: _____
 INSRS: WSP: _____ | Tel: _____ | Liability: _____ | RMKS: _____
 INSRS: WSP: _____ | Tel: _____ | Liability: _____ | RMKS: _____

Date/Time	STAGE	DATE / PIC
<u>14/02/18 (Chw)</u>	Non-Reporting Itr (1st): <u>14/2/18</u> Non-Reporting Itr (2nd): <u>9/3/18</u> . 1ST AC.. Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call OI: <u>NUMBER 4410</u> After call Itr to OI:	
<u>8/3/18</u>	AM inform Non-Reporting.	
<u>9/3/18</u> <u>17/3/18</u>	SEM OUT 1ST AC FOR NON-REPORTING. 1ST AC → 42-57	
<u>21/3/18</u> 11:30	CALLED ON CONFIRMED ACCIDENT. ON MYM-00 HE ADVISED NO SLIGHTY TOUCH TP VEN. INDM TO LHM ADDED TO SERE AND AMBE FROM NCD FILE.	
RECEIVED 19 APR 2018		
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: - Sent By: -

FINALIZATION Date/Time: 21/3/18 Confirm with: CHUNG Confirm by: ASK

Repair Cost: 45 \$5 200 (2 days) Reduction: 77 % Email Call

FINAL SETTLEMENT Date/Time: 9/4/18 Confirm with: Chw/VA Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 23 | If NO or B 28, Ass. Lia: _____
 Repair Cost: 40/09 \$5 204.00 | ON REVERSED HN TP.
 Loss of Rental (LOR): \$5 298.20 (2.5 days) x \$119.28
 Loss of Use (LOU): \$5 - (5 x days)
 Loss of Income (LOI): \$5 125.00 (550 x 2.5 days)
 LOR only LOU only LOR + LOU LOR + LO (Tick only one)
 GIA/LTA Search: \$5 7.99
 Medical: \$5 -
 Disbursement: \$5 - (e.g. Tow/Independent)
 Legal Cost: \$5 -
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: → 300 + 420

Total: \$5 644.59 Global Sum SS: 640

FINAL PAYMENT Date/Time: 9/4/18 Confirm with: Chw/VA Email Call

Payee 1: \$5 640.00/ Name 1: COMPTON DELTA ENGINEERING PTE LTD

Payee 2: (Strike if N.A.) \$5 Name 2: _____

Payee 3: (Strike if N.A.) \$5 Name 3: _____

A24

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.02.2018

Time: 15:52:08

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305116146
REGN NO : SH 7654A
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.04.2014
DATE/TIME IN : 12.02.2018 11:15
ACCIDENT DATE : 07.02.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0578-G I40V2 COVER-FR BUMPER# 1 562.30 20.00 449.84 *X Repair*

0002 04-01-0103-0654-G I40V2 COVER-FR FOG BLANKI 1 40.30 20.00 32.24 *- 4*

SUB-TOTAL : 482.08

JOB NATURE

0000 L PANEL BEATING ~~240.00~~ *100*

0001 23-502 SPRAYPAINT ON AFFECTED AREA ~~160.00~~ *150*

SUB-TOTAL : 400.00

TOTAL : 882.08

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Katrin (UKK)
12/2/18 160.00
2 Days
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary Part(s) must be Resurveyed and is subject to final approval from Insured
Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18002965/K1es3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 13-02-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 3929B	Veh. Inspected	SH 7654A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/02/2018	Inspection Date	12/02/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.305116146

CUSTOMER MS CUSTOMER NO ADDRESS (R) (F) COUNT CARD NO.	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO: SH 7654A	MILEAGE
		MAKE: HYUNDAI	FUEL E.....1/2.....F
		MODEL: I-40	DATE/TIME IN 12.02.2018 11:15
		YR OF MANU 08.04.2014	TARGET DATE
		CHASSIS CODE KMHLB41UMEU052453	COMPLETION DATE/TIME

AKK

JOB DESCRIPTION

Accident Date: 07.02.2018
 NATURE: 3P 07.02.2018

3/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

RECEIVED & PASSED OUT BY: _____

 SERVICE ADVISOR

 CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SH 7654A** **CHIANG**

Vehicle No.: **SH 7654A**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

A26

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.02.2018

REPAIR ESTIMATE

Time: 15:52:08

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305116146
REGN NO : SH 7654A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.04.2014
DATE/TIME IN : 12.02.2018 11:15
ACCIDENT DATE : 07.02.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0578-G I40V2 COVER-FR BUMPER# 1 562.30 20.00 449.84 *X repair*

0002 04-01-0103-0654-G I40V2 COVER-FR FOG BLANKI 1 40.30 20.00 32.24 *-*

SUB-TOTAL : 482.08

JOB NATURE

0000 L PANEL BEATING ~~240.00~~ *100*

0001 23-502 SPRAYPAINT ON AFFECTED AREA ~~160.00~~ *150*

SUB-TOTAL : 400.00

TOTAL : 882.08

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalin (LKK)
12/2/18 1600L
2 Days
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party liability is the responsibility of the repairer
• No illegal modification allowed
• Supplementary work must be approved and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18002965/K1es3

14th February 2018

Lim Siah Koon

343

Ubi Ave 1

#03-1123

Singapore 400343

Dear Sirs,

**ACCIDENT INVOLVING SJY 3929B AND SH 7654A ON 07/02/2018 ALONG / AT
BLOCK 139 TAMPINES ST 11**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Asher Sng

Claims

Tel : 6841 6051

Fax: 6741 4108

Email : AsherSng@lkkauto.com

*c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18002965/K1es3

09 MAR 2018

By Registered Mail

LIM SIAH KOON
343 UBI AVE 1
#03-1123
SINGAPORE 400343

Dear Sir/Madam,

**ACCIDENT INVOLVING SJY 3929B AND SH 7654A ON 07/02/2018 ALONG BLK 139
TAMPINES ST 11 @ 10:15 HOURS**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **AIG Asia Pacific Insurance Pte Ltd** to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of AIG reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from our office dated 14/02/2018.

To enable us to look into the matter immediately, please let us hear from you within **fourteen (14)** days from date of this letter (by 23/03/2018).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **AIG Asia Pacific Insurance Pte Ltd** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

ASHER SNG
Case Handler
DID: 6841 6051
Fax: 6741 4108
Email: ashersng@lkkauto.com

c.c. Claims Manager
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Our Ref : T 0218 / SH 7654A /CL(st)
 Your Ref: _____
 Date : 26-Feb-18

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road Singapore 579701

CDGE Taxi Claims Dept
 59 Loyang Drive 4th Floor
 Singapore 508969

Mainline +65 6383 6280
 Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 19898049W

Workshops

Braddell
 205 Braddell Road
 Singapore 579701

Loyang
 59 Loyang Drive
 Singapore 508969

Sin Ming
 383 Sin Ming Drive
 Singapore 575717

Pandan
 45 Pandan Road
 Singapore 609286

Ubi
 320 Ubi Road 3
 Singapore 408649

Senoko
 24 Senoko Loop
 Singapore 758156

Sungei Kadut
 7 Sungei Kadut Way
 Singapore 728791

Yishun
 501 Yishun Industrial Park A
 Singapore 768732

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Buliding
 78 Shenton Way
 #07-16
 Singapore 079120

Attn : Motor Claims Department WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 7654A YOUR INSURED SJY3929B
 AND OTHER _____ ON 07.02.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SH 7654A** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SJY3929B** we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	214.00
2	<u>3</u> days Loss of Rental @ \$ 119.28 per day	\$	357.84
3	Survey Report Fees (<i>Surveyed by M/s LKK</i>)	\$	-
4	GIA / LTA Search Fees	\$	7.49
5	GIA / Police Report Fees	\$	-
6	Towing / Medical / Transportation	\$	-
Sub Total :		\$	579.33

HIRER'S CLAIM

7	<u>3</u> days Loss of Income @ \$ 80.00 per days	\$	240.00
Total Claims :		\$	819.33

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 4 pcs.
- b) LTA search slip/s of : SJY3929B
- c) GIA / Police report/s of : SH 7654A
- d) Letter of authority from owner / hirer / operator
 - (X) Photograph/s of Accident Scene () Certificate of Insurance
 - () Witness statement/s (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecillalee@sparkcarcare.com

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC3/AIG18002965/K1ea3

04 APRIL 2018

LIM SIAH KOON
343 UBI AVE 1
#03-1123
SINGAPORE 400343

Dear Sir/Madam,

ACCIDENT INVOLVING SJY 3929B AND SH 7654A ON 07/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher Sng
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING i 40 SH7654A , SJY3929B
ALONG BLK 139 TAMPINES ST 11**ON 07-Feb-18 10:15**I / We **CELINE CHONG MEI YIN** (Hirer) NRIC No.: **S7538830F**

and/or (Relief) NRIC No.:

Taxi Number **SH7654A**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **07-Feb-2018**Name of Hirer **CELINE CHONG MEI YIN**
Hirer NRIC **S7538830F**

Signature :

Address **113 HOUGANG AVENUE 1 #05-1228**
530113Contact No. **96806400**

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, COMFORTDELGRO ENGINEERING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$640.00 (Global Sum) for vehicle no. SH 7654A that was damaged pursuant to the accident which occurred on 07/02/2018 (date) along BLK 139 TAMPINES ST 11 (location) involving vehicle no/s SJY 3929B.

This is pursuant to the inspection conducted on 12/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORT TRANSPORTATION PTE LTD ("the third party claimant") of vehicle no. SH 7654A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SH 7654A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this _____ (day) of 18 APR 2018 (month) 20____ (year)



AWK

Signed by appointed surveyor

CLAIMS DEPARTMENT
COMFORTDELGRO ENGINEERING PTE LTD
205 BRADDELL ROAD
SINGAPORE 579701

Signed by "the workshop" (with chop)

Please forward your cheque made payable to:
COMFORTDELGRO ENGINEERING PTE LTD

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

TAX INVOICE

8010004
 AIG ASIA PACIFIC INSURANCE PTE LTD
 #08-16 78 SHENTON WAY, CHARLIS BUILD
 SINGAPORE 079120
 CONTACT NO: 64193000 3225094

VEHICLE NO INV. NO/DATE
 SH 7654A 91358299 22.02.2018

MAKE JOB NO.
 HYUNDAI 305116146

MODEL ODOMETER READING
 I-40

DATE OF REG JOB TYPE
 08.04.2014

CHASSIS CODE KMHLB41UMKJ052453

Description : 3P 07.02.2018

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt.	200.00
Add GST @ 7.000 %	14.00
Total Invoice amount.	214.00

Issued by : KATHERINETAN 22.02.2018 14:25:27
 Repair Type : CLSO/57/57
 Payment Type/Term : /Credit 30 days

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO No.

Our Ref: CT18020237

Date: 22 February 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 07/02/2018 @ 10:15 hrs
ALONG BLK 139 TAMPINES ST 11
INVOLVING SJY3929B

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH7654A** (the "Taxi"). The Taxi was hired to **CELINE CHONG MEI YIN IC NO S7538830F** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$119.28** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SJY3929B	07 Feb 2018 / 10:15:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous OK

SJY3929B

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018 Edit Reg		12 Feb 2018 00:00 Edit Adj Rpt	S\$200.00 Edit Estimates	S\$200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Lim Siah Koon , ID: S0672641J								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH7654A	Date of Loss:	07/02/2018 10:00 - :59 [45 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0637899563SG	Policy/Cover Note No.:	2100484513-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJY39298	Policy No. (Claimant):	MCOM0015						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 23/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (14/02/2018): No OI GIA Report AIG_SG (14/02/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SH7654A (0637899563SG)
[SJY3929B]
TP
COMFORT TRANSPORTATION PTE LTD
Feb 7 2018 10:15AM
[Lim Siah Koon]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>		
Letters/Correspondences															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown											Edit				
Assessment Reports															1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail	Print				
1	22/03/18 09:02	Accident Statement <small>From: SC - Reg. No: SJY3929B, Claimant: LIM SIAH KOON</small>											Load HTM				
Photos/Images															3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
2	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
3	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
4	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
5	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
6	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
7	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
8	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
9	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
10	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
11	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
12	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
13	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
14	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
15	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
16	14/02/18 08:35	General View											Load JPG <input checked="" type="checkbox"/>				
17	21/02/18 17:43	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
18	21/02/18 17:43	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
19	21/02/18 17:43	Reinspection Photo											Load JPG <input checked="" type="checkbox"/>				
Documentation															1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	14/02/18 11:48	TP GIA REPORT											Load PDF				
2	14/02/18 11:48	TP ESTIMATE- MARKED											Load PDF				
3	14/02/18 12:10	SJY 3929B - NON REPORTING LETTER											Load PDF				
4	09/03/18 15:07	1ST AR NON REPORTING LETTER											Load PDF				
5	04/04/18 17:24	LETTER TO OI											Load PDF				
6	26/04/18 09:19	WORKSHOP INVOICE											Load PDF				
7	26/04/18 09:19	AUTHORISATION TO ACT FORM											Load PDF				
8	26/04/18 09:19	Release Voucher											Load PDF				
9	26/04/18 09:19	RENTAL RECEIPT											Load PDF				
10	26/04/18 09:19	Registered Mail Fee											Load PDF				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
11	26/04/18 09:19	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJY3929B (Insd veh)	Model:	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A)
	SH7654A (TP veh)		
Date of Accident:	07/02/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	943.83
Final Repair Cost	:	\$	640.00
Loss of Use	:	\$	2.50 days at \$50.00 per day
Rental (if any)	:	\$	2.50 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	640.00
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	:	\$ 640.00
2)		:	\$
3)		:	\$
4)		:	\$
5)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

26 Apr
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18002965/K1EA3Q2
Date: 26/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100484513-01
Claimant Vehicle No : SH7654A **Insured Vehicle No :** SJY3929B
 Date of Loss: 07/02/2018 Nature of Claim: TP Claim No: 0637899563SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH7654A**
 Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4DFDU527901
 Reg. Date: 08/04/2014 (Man. Year: 2014) Chassis No: KMHLB41UMEU052453
 Colour: Blue Odometer: 483449 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Hankook 7 mm Rear Left Side: Hankook 7 mm
 Front Right Side: Hankook 7 mm Rear Right Side: Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	482.08	32.24	449.84	93.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	250.00	150.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	882.08	282.24	599.84	68.00
Approved Total (Overridden) (S\$)		200.00		
(S\$)	882.08	200.00	682.08	77.33
+ GST 7.00/7.00% (S\$)	61.75	14.00	47.75	77.33
Nett Amount (S\$)	943.83	214.00	729.83	77.33
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$119.28/day) (S\$)		298.20		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		644.69		
Global Sum Settlement (S\$)		640.00		

INSPECTION

Date of Assignment: 12/02/2018

Date Inspected: 12/02/2018 Inspected At: ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*COVER -FR BUMPER	Repair	562.30 FL	*- FL	
2	1		*COVER-FR FOG BLANKI	Cut	40.30 FL	*40.30 FL	
					Sub Total (\$\$)	602.60	40.30
					- List Item Discount on L Items 20.00/20.00% (\$\$)	120.52	8.06
					Total Parts (\$\$)	482.08	32.24

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	240.00	100.00
2	SPRAYPAINT ON AFFECTED AREA	New	160.00	150.00
Gross Labour Cost (S\$)			400.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >