

AZG

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.02.2018

Time: 15:52:08

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305116146
REGN NO : SH 7654A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.04.2014
DATE/TIME IN : 12.02.2018 11:15
ACCIDENT DATE : 07.02.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0578-G	I40V2 COVER-FR BUMPER#	1	562.30	20.00	449.84	X repair
0002	04-01-0103-0654-G	I40V2 COVER-FR FOG BLANKI	1	40.30	20.00	32.24	-
							SUB-TOTAL : 482.08

JOB NATURE

0000	L	PANEL BEATING				240.00	100
0001	23-502	SPRAYPAINT ON AFFECTED AREA				160.00	150
							SUB-TOTAL : 400.00
							TOTAL : 882.08

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Kalin (UKK)
12/2/18 1600 L
2 Days
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on an "no win, no fee" basis
- No illegal modification(s) allowed
- Supplementary items must be displayed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: