

ASS. REC. BY:

REF: CS/FCI18002982/4tbn2

Special Instruction:

Surveyor: **CWS**

**Marcus**

ASSIGNMENT (Office)

From (Person):

**Mary Chua**

of

**FCI**

Date/Time:

**14/2/18**

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

**GW8700G**

Insured:

**SHD7020F**

at Workshop m/s

**Vfix Auto**

Tel:

**64552957**

of

**60 Kaki Bkt Ave 6**

Policy No:

Claim No:

**D18001282 MFSH**

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

**08/02/2018**

CA / REV / REP. / REV 24 HRS

**'wp'**

H.O.D. Endorsement:

Date/Time:

**5:30pm 14/2/18**

Person Contacted:

**Irene**

Vehicle:

**D/LOUT**

Date/Time	Action/Instruction (✓) Estimate
	GW8700G - CS/7M11E000144/Hlabn2 D.O.A: 4/1/16
	SHD7020F - 003/LCR17001939/Hlda3g2 D.O.A: 07/03/17

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: GW8700G  
 at Workshop m/s: vifir 9.30  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: 11k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 8 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 10 hrs  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

	
N/S	O/S
	

Veh No: GW8700G Yr Regn: 1203  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or (M)  
 Make: isuzu pick-up c.c. 3059  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 35223 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JAA7FR 69H371008-1  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: NiP / S/Rim / STD A/Rim or  
 Tyre Size: F: 195-14  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or WestHoke  
 Front 6 mm Rear 6 mm  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 14/2/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear & Rf.  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
2/3/18 2/3/18 2/3/18  
CNY 16-17 Feb LTA 4930 body plus nett 6070  
confirmed L/S \$6000 with Ken. (led 8730.70, 592)  
 MV: 11k  
 LTA 4930  
 NV: 6070

RECEIVED 27 MAR 2018

Date/Time, File Pass to?  : Preli. Report  : Final Report  
 Days Of Repair: 8  
 Resurvey No. of Trip: 1  
 Survey Fee: 170 + 60  
 Transportation: 50  
 S + RS: 50  
 Photos: 78  
 Others: 32/3/18  
 Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)  
 Report Format: TP  
 Lump Sum / I.B.I: (\$ 6,000)  
 TOTAL 408

## Survey Department Check List (Case Handler)

Reference No. : CS/FC118002982/4th  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin** ( Catherine ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor** ( Marcus ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: Catherine 27/5/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	12-02-2018	<b>Our Ref No.</b> D18001282MFSH
<b>Accident Date</b>	08-02-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHD7020E	<b>Third Party Vehicle.</b> GW8700G
<b>Survey Location</b>	60 KAKI BUKIT AVE 6 ARK@KB	
<b>Contact Person.</b>	IRENE	
<b>Contact No.</b>	64552957/ 64452368	<b>Fax No.</b> 6452368
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	VFIX AUTO SERVICE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18002982/Utb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-02-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 7020E	Veh. Inspected	GW 8700G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/02/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	08/02/2018	Inspection Date	14/02/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2016W
Vehicle Details	
Vehicle No.:	GW8700G
Vehicle to be Exported:	No
Intended De-registration Date:	14 Feb 2018
Vehicle Make:	ISUZU
Vehicle Model:	TFR69H-09(T)
Primary Colour:	Red
Manufacturing Year:	2003
Engine No.:	4JG2947263
Chassis No.:	JAATFR69H37100851
Maximum Power Output:	-
Open Market Value:	\$15,808.00
Original Registration Date:	01 Dec 2003
First Registration Date:	01 Dec 2003
Transfer Count:	1
Actual ARF Paid:	\$791.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2018
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$34,609.00
COE Rebate Amount:	\$4,930.00
<b>Total Rebate Amount:</b>	<b>\$4,930.00</b>
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 14 Feb 2018

**SELL YOUR CAR BY BIDDING**  
**HIGHEST SELLING PRICE GUARANTEED!**  
**OR GET \$100 CASH!**



**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

CNY Offer! May 2014 Range Rover Evoque SDr \$142,800!



In House Finance Available! 1  
 Owner! Low Mileage 33,000 Km!  
 Sporty SUV. Call Now  
 Speedo Motoring StarAd

**KA-HUP**  
**KA-HUP**  
**VALUE FOR MONEY**  
**VALUE FOR TIME**  
**A PEACE OF MIND**  
**HOTLINE: 6741 9997** [View our cars](#)

Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

nissan pick

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	nissan pick		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Nissan	Double-Cab Pickup (COE till 07/2019)	\$15,800	\$10,840 /yr	23-Aug-2004	2,664 cc	-	Truck	Available
<b>Fuel Type:</b> Diesel Hood To Protect Your Equipment Or Goods From Elements. Conditions Are Good For COE Extension. High Loan Available.									
Posted: 08-Feb-2018 Tags: 2004 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan									
	Nissan	Double-Cab Pickup (COE till 02/2022)	\$28,800	\$7,130 /yr	17-Nov-2000	2,664 cc	-	Truck	Available
<b>Fuel Type:</b> Diesel Rebate Of Minimum \$6236 On Lifespan Expiry. Well Maintained.									
Posted: 04-Feb-2018 Tags: 2000 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan									
	Nissan	Double-Cab Pickup (COE till 03/2020)	\$36,800	\$17,720 /yr	14-Mar-2005	2,664 cc	-	Truck	Available
<b>Fuel Type:</b> Diesel Company Which Do Not Carry Heavy Stuffs. Well Maintained By Owner With No Repair Needed. Hurry Before It's Gone. Best Price For The Best Pick Up. Come For A Test Drive To Believe It! Ready To Go!									
Posted: 26-Jan-2018 Tags: 2005 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan									
	Nissan	Double-Cab Pickup (COE till 04/2022)	\$30,800	\$7,350 /yr	24-Apr-2002	2,664 cc	-	Truck	Available
<b>Fuel Type:</b> Diesel Guarantee COE Rebate Of At Least \$3200 At The End Of 2022. Actual Depreciation Of \$6700/Yr Only! Most Reliable And Durable Double Cab Pickup. Excellent Engine, Interior, Aircon. Well Maintained Leathe...									
Posted: 26-Jan-2018 Tags: 2002 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan									
Car Buying	Car Selling	Car Aftermarket	Buying a pre-owned car, but Unsure of its Condition? Get, STA Car Evaluation						
Car Ownership	On The Move	Lifestyle							
	Nissan	Double-Cab Pickup (New 5-yr COE)	\$37,800	\$7,560 /yr	12-Jan-2004	2,664 cc	-	Truck	Available
<b>Fuel Type:</b> Diesel 1 Owner. Durable Nissan Double Cabin Pickup With Silent Powerful TD27 Engine. New Paintwork And Upholstery Just Done. New 5 Years COE Extended Till March 2023.									
Posted: 09-Jan-2018 Tags: 2004 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan									
	Nissan	Single-Cab Pickup (COE till 01/2021)	\$23,800	\$8,160 /yr	14-Jan-2006	2,664 cc	-	Truck	Available
<b>Fuel Type:</b> Diesel									
Posted: 19-Dec-2017 Tags: 2006 Nissan Single-Cab, Nissan Single-Cab, Nissan, Single-Cab, Used Nissan									
	Nissan	Double-Cab Pickup (COE till 04/2022)	\$32,800	\$7,790 /yr	03-Apr-2003	2,664 cc	395,900 km	Truck	Available
<b>Fuel Type:</b> Diesel Think One Automobile & Trading									
Posted: 18-Dec-2017 Tags: 2003 Nissan Double-Cab, Nissan Double-Cab, Nissan, Double-Cab, Used Nissan									



Vfix Auto Service Pte Ltd  
 50 Kaki Bukit Ave 6  
 Ark@KB Singapore 417892  
 Email: vfixauto@gmail.com  
 Tel: 64489268 Fax: 64452368

M/s First Capital Insurance Ltd  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877  
**Attention: Motor Claim Department**

*not allowed*  
*dkk*  
*h/s*  
*of day*  
*take photo of heavy*  
*14/2/18*

**ESTIMATE**

DATE : 12/02/2018  
 ACC DATE : 08/02/2018  
 REF NO. : VFIX-TP20180428  
 POLICY NO. :

**RE : VEHICLE NO.GW 8700 G ISUZU TER69**

PARTICULAR		AMOUNT S\$	
1	2 FRONT HEADLAMP R+L	450.00	900.00 X
2	2 FRONT FENDER R+L	650.00	1,300.00 X
3	1 RADIATOR GRILLE		420.00
4	1 RADIATOR GRILLE (ISUZU) LOGO		122.00
5	1 BRACE PANEL		85.00 X
6	1 FRONT BUMPER TOP		453.00
7	1 FRONT BUMPER LOWER		229.00
8	1 FRONT BUMPER LAMP RH		110.00 X
9	1 FRONT BUMPER RE-INFORCEMENT		298.00 X
10	1 REAR BUMPER TOP		880.00
11	1 REAR BUMPER LOWER		852.00
12	1 REAR BUMPER RE-INFORCEMENT		256.00
13	1 REAR END PANEL		855.00
14	2 NUMBER PLATE LAMP	25.00	50.00 X
15	1 TAIL LAMP		236.00 X
16	1 TAIL GATE		1,552.00
17	2 REAR SIDE PANEL R+L	1,855.00	3,710.00 L2C
18	2 REAR SIDE PANEL MOULDING R+L	285.00	570.00 L2C
19	1 RUBBER STOPPER		45.00
			\$ 12,923.00
			\$ 1,292.30
			\$ 11,630.70

*Handwritten notes:*  
 366.00  
 89.30  
 650  
 25.32  
 1142.00  
 1622  
 MS DD/SUC  
 MS LMI  
 15%  
 LESS 10%  
 6530.72  
 568.11

DESCRIPTION (SPECAIL NETT)		AMOUNT S\$	
1	1 TAIL GATE (70KM/H) STICKER		25.00 105.00
2	1 FRONT/REAR NUMBER PLATE		75.00 285.00
			\$ 100.00

LABOUR & MISCELLANEOUS:

AMOUNT S\$

1	To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten front support panel, repair/reshape dented panels in accordance with factory specifications, replace new parts refit align into position refit all necessary components/attachments	1200	1,600.00
2	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	1000	1,400.00
			\$ 3,000.00

GRAND TOTAL : \$ 14,730.70

7806.11  
6244

SINGAPORE DOLLARS : FOURTEEN THOUSAND SEVEN HUNDRED THIRTY & CENTS SEVENTY ONLY

*Not Affixed*

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18002982/Utbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7020E	Veh. Inspected	GW 8700G
Policy No.		Coverage (\$)	0.00
Claim No.	D18001282MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	14/02/2018
2. Vehicle Particulars & Condition			
Make & Model	ISUZU PICK-UP (M)	c.c	3059
Engine No.	HIDDEN	Year of Reg.	2003
Chassis No.	JAATFR69H37100851	Colour	RED
Odometer	352231	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R14	WEST LAKE	6 mm
L/H Front Tyre	195 R14	WEST LAKE	6 mm
R/H Rear Tyre	195 R14	WEST LAKE	6 mm
L/H Rear Tyre	195 R14	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/02/2018	Inspection Date	14/02/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 8700G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
2	FRONT HEADLAMP R+L @\$450.00	NOT NECESSARY	900.00	-
2	FRONT FENDER R+L @\$650.00 (DENTED)	NOT CONSISTENT WITH THE IMPACT	1,300.00	-
1	RADIATOR GRILLE	CRACKED	420.00	366.10
1	RADIATOR GRILLE (ISUZU) LOGO	NECESSARY	122.00	89.30
1	BRACE PANEL	TO REPAIR SEE LABOUR	85.00	-
1	FRONT BUMPER TOP	DENTED	453.00	453.00
1	FRONT BUMPER LOWER	BENT	229.00	229.00
1	FRONT BUMPER LAMP RH	NOT NECESSARY	110.00	-
1	FRONT BUMPER RE-INFORCEMENT	NOT NECESSARY	298.00	-
1	REAR BUMPER TOP	DISTORTED	880.00	650.00
1	REAR BUMPER LOWER	DISTORTED	852.00	852.00
1	REAR BUMPER RE-INFORCEMENT	DISTORTED	256.00	256.00
1	REAR END PANEL	BADLY DENTED	855.00	525.32
2	NUMBER PLATE LAMP @\$25.00	NOT NECESSARY	50.00	-
1	TAIL LAMP O/S (BROKEN)	NOT CONSISTENT WITH THE IMPACT	236.00	-
1	TAIL GATE	DENTED / BENT	1,552.00	1,145.00
2	REAR SIDE PANEL R+L @\$1855.00	N/S DENTED / BUCKLED	3,710.00	1,655.00
2	REAR SIDE PANEL MOULDING R+L @\$285.00	N/S TWISTED	570.00	285.00
1	RUBBER STOPPER	TORN	45.00	45.00
	LESS 10% DISCOUNT		-1,292.30	-
	LESS 15% DISCOUNT		-	-982.61
			11,630.70	5,568.11
<b>SPECIAL NETT ITEMS</b>				
1	TAIL GATE (70KM/H) STICKER (SN)	NECESSARY	25.00	10.00
1	FRON/REAR NUMBER PLATE (SN)	BENT	75.00	28.00
			100.00	38.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b> TO REMOVE DAMAGED BODY PANELS WITH ALL NECESSARY COMPONENTS/ATTACH-MENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT SUPPORT PANEL REPAIR/RESHAPE DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS,REPLACE NEW PARTS.REFIT ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS/ATTACHMENTS.INCLUSIVE OF THE REPAIR OF BRACE PANEL.  TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS.		1,600.00	1,200.00
			1,400.00	1,000.00
			3,000.00	2,200.00
	<b>GRAND TOTAL</b>		<b>14,730.70</b>	<b>7,806.11</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>6,000.00</b>

Report Ref No. CS/FCI18002982/Utbn2

MARKET VALUE: \$11,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$4,930.00=NETT VALUE: \$6,070.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.