

INRS:

INS. CASE OWNER:

Jacklyn

CC 4 / AIG18003014 / AH52 JV

LKC:

IDAC:

Surveyor:

ADRIAN

DOI:

13/02/18

Date / Time:

13/02/18

Registered in Merimen:

14/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GSS 531A

Claim No.:

249302969856

Name of Insured:

JOINTTECH ENTERPRISE PTE LTD

Policy No.:

2100215894

Insured Tel No.:

HP:

Make / Model:

KIA 2900L - 2.9 DCM

Excess Sec II :SS

D.O.A.:

05/02/18

Place of Accident:

LOWER DELTA ROAD

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age:

PALANI RAMAIAH

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Driver Tel No.:

8670 9602

(VA) YES / NO

Insured Liability:

% Final ? Yes / No

GR 66860



INSRS:

WSP: Precise Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

21/02/18 (v:c)

GR 66860 - X ; GSS 531A - X

STAGE

DATE / PIC

21/02/18 (v:c)  
2:30 am

Spoke to OI (8670 9602), OI later me spoke to his boss Mr Simon at (9018 4509), spoke to Mr Simon

Non-Reporting hr (1st)

Non-Reporting hr (2nd)

Non-Reporting hr (Final)

Notification hr (if non-pickup)

Call OI

After call hr to OI

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA/GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

VIC-OK  
05/05

2/5/2018

11:40 am

per km

02/05/18

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

per km

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

8,000.00 (6 days) Reduction: 51 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Yes / No

Email

Call

Final Liability:

SS

100 (Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

5300.00

Loss of Rental (LOR):

SS

480.00 (4 days) x \$112.15

Loss of Use (LOU):

SS

(5 x days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow / Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$320

Total:

SS

5850.00

Global Sum SS:

\$800.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

\$800.00

Name 1:

Precise Auto Service

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF:

## ASSIGNMENT

GR6686D

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GR6686D Yr Regn: 2000 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace cc 2986Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 792414 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: LH 1620009300Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 185R14CR: 185R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 96 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 13/02/18Survey held at PreciseDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

LH \$5,000.00

(RBD: \$5,277.27/51%)

MV: 18K.

PV: 53K

Net: 12.7K.

Date/Time. File Pass to?

☐

: Preli. Report

1)

Date/Time. File Return to?

☐

: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

| \$ + RS \$

| Photo

| Other

TOTAL

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Invs \$

☐

Weekend \$

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$) \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18003014/Ahs3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 14-02-2018		
		Code : AIG		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBB 531A	Veh. Inspected	GR 6686D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/02/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	09/02/2018	Inspection Date	13/02/2018	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

30-06-18

Date Of Accident : 09-02-18

Adrian

OUR REF : GR 6686D/T/18

Date in/out : 25/02/18 to 03/03/18

Casserole Catering Services Pte Ltd

Blk 372 Jurong East St 32

17 Chin Bee Crescent

Singapore 619898

TPA 16

1/12

ESTIMATE BILL ON VEH. NO. : GR 6686D

MODEL : TOYOTA HIACE

CHASSIS NO : LH 1620009300

## LIST ITEM

Tail Gate	Dented		1,210.20 ✓
Tail Gate Stopper	new	2pcs @ 53.90	107.80 ✓
Tail Gate Lock	Damaged		281.75 ✓
Tail Gate Lock Striker	Bent		121.10 ✓
Tail Gate Weatherstripe	cut		281.75 ✓
Tail Gate Outer Garnish	crushed		<del>381.85</del> 267.10 ✓
Tail Gate Inner Meter Cover	Bent		262.10 ✓
Tail Gate Side Stopper (Male & Female)	new	2pcs @ 43.90	87.80 ✓
Rear Bumper	deformed		380.75 ✓
Rear Bumper Side Clips (Male & Female)	new	4pcs @ 12.90	<del>51.60</del> 20 ✓
Rear Bumper Center Beam	Bent		281.75 ✓
Rear Bumper Clips	new	8pcs @ 12.90	<del>103.20</del> 30 ✓
Tail Lamp Assy	crushed	2pcs @ 289.10	578.20 ✓
Rear Windscreen Rubber	new		289.75 ✓
Rear End Panel (Outer)	Dented		581.75 ✓
Rear End Panel (Inner)	Repair		561.20 ✓

Rear End Panel Top Metal Plate	HE m	187.55	x
Spare Tyre Bracket	Bent	371.20	✓
Spare Tyre Bracket Adjusting Screw	3 new	131.75	x
Spare Tyre Bracket Adjusting Screw Hook		63.90	x
Exhaust Silencer	HE m	981.20	x
Front RH Seat Belt Buckle	New	281.75	x
		7,579.90	
	25% Less Discount	1,894.98	
		5,684.93	

#### SPECIAL NETT ITEM

70 Km/h Sticker	New	10.	20.00	10.
-----------------	-----	-----	-------	-----

#### LABOUR CHARGE

Towing		80.00	x
To check wiring system		80.00	30
To remove & refix rear windscreen		180.00	120
To remove & transfer tail gate mechanism		220.00	80
To remove & refix exhaust silencer & straighten exhaust center pipe		280.00	x
To tuff coat affected areas		180.00	60
To remove & refix spare tyre bracket		100.00	50
To respray affected areas		1,200.00	1000
To renew damaged parts, straighten & repair rear body mudguard, rear end side panel & aligned all parts		1,200.00	1000
To adjust chassis alignment on car O liner		380.00	x

To remove interior stainless steel metal sheet to facilitate repairs.

200.  
280

TOTAL :	9,604.93
GST 7% :	672.34
AMOUNT DUE :	10,277.27

total 6266.02  
h/s SK  
06 Days.

(SK)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0426E
Vehicle Details	
Vehicle No.:	GR6686D
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DIESEL
Primary Colour:	Blue
Manufacturing Year:	2000
Engine No.:	5L4912693
Chassis No.:	LH1620009300
Maximum Power Output:	-
Open Market Value:	\$24,308.00
Original Registration Date:	02 May 2000
First Registration Date:	02 May 2000
Transfer Count:	2
Actual ARF Paid:	\$1,216.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$23,979.00
COE Rebate Amount:	\$5,308.00
<b>Total Rebate Amount:</b>	<b>\$5,308.00</b>

The information contained herein is correct as at 13 Feb 2018

OK

## FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

CNY Promo! Apr 2018 Audi A5 Sportback At \$129,800!



Hi! I have a brand new Audi A5 Sportback, 2018 model, equipped with "Sport Plus" package. It's a 2.0 TFSI engine, 252hp, 0-100 in 6.1s. Speedo Motoring 2018.



Browse by Category

&lt; Back [ 1 2 ] Next &gt;

Sort by Date Posted

20 results/page

33 vehicles

Hiace

Image	Model	Price	Depreciation	REG CODE	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hiace	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Hiace (COE till 03/2020)	\$18,800	\$8,830 /yr	19-Jun-2000	2,986 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Registered On 19/6/2000, COE Till 31/3/2020, 1 Careful Owner, Low Mileage, Road Tax Till 6/2018, New Paint, Very Good, Regular Servicing, Tip Top Condition, 100% Loan At 4% Interest Rate, Trade In Wel...								
Posted: 30-Jan-2018 Tags: 2000 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota Hiace (COE till 03/2022)	\$22,888	\$5,540 /yr	04-Oct-2000	2,986 cc	-	Van	Available
<b>Fuel Type:</b> Diesel \$0 Driveaway. Don't Need Income Proof. Low Depreciation. Stock Condition. Fast Sale! Call Now For More Detail.								
Posted: 10-Feb-2018 Tags: 2000 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota Hiace (COE till 12/2020)	\$21,800	\$7,640 /yr	22-Dec-2000	2,986 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Season Parking At Multi-storey Carpark \$110. Enter All Multi-storey Carpark Above 1.9m. Call Us Now!								
ABWIN Bus Pte Ltd Posted: 12-Jan-2018 Tags: 2000 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								
	Toyota Hiace Commuter (COE till 03/2021)	\$22,800	\$7,400 /yr	15-Mar-2001	2,986 cc	-	Van	Available
<b>Fuel Type:</b> Diesel Great Unit! This Is A Van With Added Windows For Better Driving Visual. Paintwork In Good Condition And Interior Very Well Maintained, Serviced Regularly Without Fail, Well Maintained, Good Low Deprec...								
Posted: 01-Jan-2018 Tags: 2001 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota								

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Toyota Hiace (COE till 04/2022)

\$25,800

\$6,130 /yr

23-May-2001

2,986 cc

-

Bus

Available

**Fuel Type:** Diesel

Well Kept, HDB Parking, In House Loan Available.

Posted: 09-Jan-2018 Tags: 2001 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota



Toyota Hiace (COE till 05/2021)

\$48,800

\$14,810 /yr

01-Jun-2001

2,986 cc

-

Bus

Available

**Fuel Type:** Diesel

The Best Economical And Reliable Van For Sale! Well Maintained By Fussy Owner, Call Now To Find Out More.

Posted: 19-Jan-2018 Tags: 2001 Toyota Hiace, Toyota Hiace, Toyota, Hiace, Used Toyota

Toyota Hiace (COE till 03/2019)

\$8,700

\$7,720 /yr

19-Jun-2001

2,986 cc

-

Van

Available

**Fuel Type:** Diesel

Good Engine! Reliable Vehicle With Low Cost Of Repair And Maintenance. Vehicle Qualifies For Early Turnover Scheme (ETS). Drive Until COE Expiry.

## Vic (LKKAUTO)

---

**From:** Precise Auto Service <Support@preciseauto.sg>  
**Sent:** Friday, 17 May, 2019 5:29 PM  
**To:** Vic (LKKAUTO)  
**Subject:** ACCIDENT INVOLVING VEHICLE NO. GR 6686D AND GBB 531A ON 09/02/2019  
**Attachments:** 17052019171849.pdf

### Without Prejudice

Your Ref. : GBB 531A  
Vehicle No. : GR 6686D/T/18 (SJE)

**M/s AIG Asia Pacific Insurance Pte Ltd**

Dear Vic

We are the repairer for vehicle no. **GR 6686D** and instructed by the owner, Casserole Catering Services Pte Ltd, on his behalf to submit the claims against your insured's vehicle no. **GBB 531A** that was involved in the above mentioned accident.

The accident was clearly caused by your insured's negligence. In order to save the legal cost, we will process the claim to you directly as follows:

1. Cost of Repair (Survey By Mr. Adrian)	\$ 5,350.00	(Including GST)
2. Car Rental (4 days X \$120.00)	\$ 480.00	(Including GST)
4. LTA / GIA Search	\$ 37.00	
<b>Total :</b>	<b>\$ 5,867.00</b>	

Please let us have your payment in our favour of "**Precise Auto Service**".  
Your prompt reply of the above claims will be much appreciated.

Thank You

Best Regards  
Yan Hong

--

T : 6745 7367 | F : 6841 3390  
E : [support@preciseauto.sg](mailto:support@preciseauto.sg)  
W: [www.preciseauto.sg](http://www.preciseauto.sg)  
A : No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883



*Follow us on social media:*





<https://www.instagram.com/preciseautosvs/>



<https://twitter.com/preciseautosvs>



<https://www.facebook.com/PreciseAutoService/>

---



Virus-free. [www.avg.com](http://www.avg.com)

**Enquire Vehicle & Owner Information ( Vehicle No. GBB531A As At 09 Feb 2018 / 10:00:00 )**

**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: GBB531A.IZ

**Current Owner Details**

Owner ID Type: Company

Owner ID: 200404434W

Owner Name: JOINTECH ENTERPRISE PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 8

Registered Street Name: UBI ROAD 2

Registered Unit No.: # 08 - 02

Registered Building Name: ZERVEX

Registered Postal Code: 408538

**Current Vehicle Details**

Vehicle No.: GBB531A

Make Description/Model: KIA / KIA 2900L 5 M/T

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/AIG18003014/Ahb3**

2<sup>nd</sup> May 2018

**JOINTECH ENTERPRISE PTE LTD**

No.8 Ubi Road 2,  
#08-02 Zervex,  
SINGAPORE 408538.

Attn: Ms Serene

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING GBB 531A AND GR 6686D ON  
09.02.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Chong Poh Kin  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

TO: **PRECISE AUTO SERVICE**  
**NO. 1 KAKI BUKIT AVENUE 6**  
**#02-34/36**  
**SINGAPORE 417883**

**LETTER OF AUTHORITY & INDEMNITY**

**ACCIDENT INVOLVING VEHICLE NO. GR 6686D AND 6BB531A**

I/We, Casserole Catering Services Pte Ltd NRIC No. 201530426 E, owner of vehicle no. GR 6686D, hereby authorise **M/S PRECISE AUTO SERVICE** to commence repairs to my motor vehicle and to forward the claim for damages sustained in the above accident to the third party driver and/or his employer and/or the vehicle owner and/or the insurer concerned. I/We agree that in consideration of you giving up your repairer's lien I agree to assign the whole proceeds of my/our third party claim to you and if applicable, our solicitors (to be appointed by you on my/our behalf) shall accept this as my/our irrevocable authority to pay the amount compensated direct to you after deduction of their costs on a Solicitor & Client basis. I/We undertake to co-operate fully with you and our solicitors to see the claim to a successful conclusion. In the event the proceeds of claim for damages, interest, costs and expenses including legal costs are paid to me directly by the third party insurer, I undertake to indemnify and/or reimburse the said proceeds of claim to you.

If the third party driver and/or his employer and/or the vehicle owner and/or the Insurer reject liability, I will be fully responsible for the repair costs.

I/We also authorise you to sign all discharge vouchers/indemnity forms and all necessary papers in connection with the above claim in my/our absence.

I/We authorise you to appoint such a firm of solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurers' claim.

I/We undertake to inform you and/or the solicitors appointed by you on my/our behalf in the event the third party's insurance company communicates with me/us directly by telephone or in writing and I/we further undertake not to enter into any compromise Settlement Agreement with the third party insurance without your consent as I understand that this may jeopardise a fair recovery of the third party claim.

My vehicle is repaired by the repairer on my own free will without any inducement, threat and/or promise.

In the event of any breach of my undertaking and the repairer is compelled to enforce this undertaking, I agree that I shall pay for the legal costs incurred by the repairer on a solicitor and client's full indemnity basis.

*Casserole Catering Services Pte Ltd*  
17 Chin Bee Crescent  
Singapore 619898  
Tel: (65) 6328 6445 Fax: (65) 6223 5246

**Owner Signature**  
**(Company Stamp, if Applicable)**

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, PRECISE AUTO SERVICE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$5,800.00 (Global Sum) for vehicle no. GR 6686D that was damaged pursuant to the accident which occurred on 09/02/2018 (date) along AYE TWDS CITY (EXIT TO LOWER DELTA RD) involving vehicle no/s GBB 531A.

This is pursuant to the inspection conducted on 13/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CASSEROLE CATERING SERVICES PTE LTD ("the third party claimant") of vehicle no. GR 6686D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GR 6686D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 21 (day) of May (month) 2018 (year)



LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

**VEHICLE DAMAGE DISCHARGE ONLY**

This Discharge Voucher applies only to the claimant's claim for property damage and will not affect the personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.

## PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 09-02-18

OUR REF : GR 6686D/T/18 (SJE)

## TAX INVOICE

Casserole Catering Services Pte Ltd

17 Chin Bee Crescent

Singapore 619898

Invoice No. : TP1904-011

DATE : 28-04-19

FINAL BILL ON VEH. NO. : GR 6686D

VEHICLE MODEL : TOYOTA HIACE

LUMP SUM REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

5,000.00

SUB-TOTAL : 5,000.00

ADD GST 7% : 350.00

TOTAL AMOUNT SGD : 5,350.00


This is a computer generated document and requires no signature.

**TAX INVOICE**

GST REG. NO.: 200106276D

INVOICE TO
PRECISE AUTO SERVICE C/O CASSEROLE CATERING SERVICES PTE LTD 17 CHIN BEE CRESCENT SINGAPORE 619898

DATE	INVOICE NO.
06-Mar-2018	A 37417

DESCRIPTION	VHA NO.	DUE DATE	VEH. NO.
	A 37417	06-Mar-2018	GW 2418 L
DESCRIPTION	NO. OF DAYS	RATE	AMOUNT
RENTAL FROM 26 FEBRUARY 2018 TO 02 MARCH 2018 YOUR REF: GR 6686 D  	4	112.15	448.60
GST @ 7%			\$31.40
<b>TOTAL</b>			<b>\$480.00</b>

All cheques must be made payable to BKW Rent A Car Pte Ltd.  
Please write the vehicle and invoice number on the reserve.

**VEHICLE HIRING AGREEMENT**
**HIRER'S PARTICULARS**

Name (as in IC): CASEROLE CATERING SERVICES PTE LTD

NRIC/Passport No: \_\_\_\_\_ Date of Birth: \_\_\_\_\_

Address: 17, CHIN MEI CRESCENT Age: \_\_\_\_\_

SI: 617818

Work & Address of Employer: \_\_\_\_\_

Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_

Driving Licence No: \_\_\_\_\_ Passed Date: \_\_\_\_\_

DL Type: Local/Int'l/Other: \_\_\_\_\_

HP: 323 6445 (R) \_\_\_\_\_ HP: \_\_\_\_\_

**DRIVER'S PARTICULARS**

Name (as in IC): ENG YU SUI EOWIN

NRIC/Passport No: S8931252C Date of Birth: 4/9/1989

Address: 62, KIOXDAH DS DRIVE 16 Age: \_\_\_\_\_

SI: 35485

Occupation: \_\_\_\_\_ Driving Exp: \_\_\_\_\_ Yrs

Driving Licence No: \_\_\_\_\_ Passed / Expiry Date: 1/4/2013

DL Type: Local/Int'l/Other: \_\_\_\_\_ Contact No: \_\_\_\_\_

Hirer's Own Vehicle No: GR 6686D Replace Veh No: \_\_\_\_\_

Loan Vehicle No: Syl 2419 L VR No: \_\_\_\_\_

Make & Model: old Honda Auto/Manual Group: \_\_\_\_\_

**CHARGES** \$ cts

Daily 4 day @ \$ 120 Per day 1420

Weekly/Monthly week @ \$ \_\_\_\_\_ Per week/Monthly \_\_\_\_\_

Others \_\_\_\_\_

CDW/PAI @ \$ \_\_\_\_\_ Per day/Monthly \_\_\_\_\_

Delivery/Collection Svc \_\_\_\_\_

GST \_\_\_\_\_

QR No: \_\_\_\_\_ (A) SUB-TOTAL 1420

Petrol Level: OUT E 1/4 1/2 3/4 F

Surcharge: IN

First \_\_\_\_\_ km FREE per day GST \_\_\_\_\_

Excess mileage is chargeable at \_\_\_\_\_ cents per km TOTAL CHARGES \_\_\_\_\_

Security Deposit: \$ \_\_\_\_\_ Bank: \_\_\_\_\_

CASH/NETS/VISA/MC/AMEX/CHQ No: \_\_\_\_\_


Expiry Date: \_\_\_\_\_ Card ID No: \_\_\_\_\_

Name as in Card: \_\_\_\_\_

NON WAIVER EXCESS (Subject to GST): \$ 5000
**ACCESSORIES CHECK**

- ☐ Data Cards ☐ Camera Systems ☐ Hub Cap ☐ Radio / CD Cartridge
- ☐ Jack ☐ Tyre Opener ☐ Petrol Cap ☐ Spare Tyre

Hirer's Signature: \_\_\_\_\_ Additional Driver's Signature: \_\_\_\_\_

**SINGAPORE Use Only**


I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have been given by BKW Rent A Car Pte Ltd in connection with this agreement is true.

**IMPORTANT**

- The Hirer and the authorized driver must be over 23 years of age and under 65 years and be holding valid driving licences and have a minimum of 2 years regular and qualified driving experience. Failure to observe stipulation may return all damages costs to be borne by the Hirer/the Authorized Driver.
- All vehicles are supplied with petrol and should returned with petrol level likewise. A service charge of \$5 on top of a petrol surcharge is payable by the hirer should he fail to return the vehicle at the appropriate petrol level.
- No refund for early return of vehicle. The hirer shall be liable for additional charges for any late return at the rate shown per hour per day, inclusive of CDW and/or PAI where applicable. Any returns after our operation hours will be charged as a full day rental.
- Use of the vehicle for illegal purpose (For instance, in connection with theft, drug dealing or trafficking, smuggling), is strictly prohibited.
- Vehicle strictly for Singapore use only and may not be driven out of Singapore without prior written consent of BKW Rent A Car Pte Ltd. The hirer is liable for a penalty fee of \$200 in addition to the appropriate insurance top up in the case of non-disclosure of Malaysia usage.
- The hirer and/or driver shall be responsible for all damages or losses howsoever caused, all traffic violations, fines and penalties imposed on the vehicle for whatsoever reason in respect of or in connection with its use or operation.
- The hirer and/or driver shall be responsible for all claims, damages, losses, increased insurance premiums, non-waiver excess and cost expense (including

- legal costs on a full indemnity basis), whatsoever and howsoever brought against, suffered or incurred by you in respect of the vehicle or the use or the operation of the vehicle. Full excess amount have to be paid immediately in the event of an accident. The owner reserve the right not to replace an replacement vehicle if an accident occurred. Any damage to the car will be repair at BKW authorized workshop.
- Smoke or permit smoking and transport of pets in the vehicle are not allowed. Any offensive smell e.g. cigarette, durian or pet's smell, the hirer and/or driver shall bear the cost of removing the offensive smell or pet's hair between \$200 - \$400.
- The Hirer agrees that a punctured tyre, empty petrol tank, loss of vehicle's key or locked keys inside of vehicle, by itself, does not constitute a breakdown and that in the event the owner's 24-Hours Emergency Service is called upon to respond to such occurrence, the Hirer shall bear the cost of such response at \$50.00 per trip.
- In case of accident, the hirer shall report to rental office immediately. An accident report must be made within 24 hours. Failure to comply, the hirer will have to borne all liability from all parties claim. Full excess amount have to be paid immediately in the event of an accident.
- The hirer/Driver also have the responsibility to ensure that the radiator water level in the car is sufficient and do not drive when the vehicle is stall and does not have sufficient water. Any damage to the engine will be bear by the hirer/Driver.
- All customers' data will be kept strictly confidential and is solely used for the purpose of completing the sales transactions and other relating matters.
- I understand and agree to the personal data collection statement stated on the Terms and Conditions Page.

Date Out	Time Out	Mileage	Check By	Remarks
26/2/12	1pm	58166		

Hirer/Driver Signature: \_\_\_\_\_

Return Of Vehicle: The Hirer Driver is Required to Sign In The Column "Signature Of Hirer Driver Failing Which The Day And Time Inserted Below Shall Be Deemed To Be The Day And Time The Vehicle Is Returned To BKW Rent A Car Pte Ltd And The Same Shall Be Accepted As Conclusive Evidence Of The Same And Shall Not Be Challenged Or Questioned On Any Account Whatsoever. And I had cleared my belonging items from the rental vehicle (cashcard, parking coupons, etc)"

Date In	Time In	Mileage	Check By	Remarks
2/3/12	1355hrs	382179	L. H. 2/3/12	17-1

Hirer/Driver Signature: \_\_\_\_\_



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Feb 2018 <a href="#">Edit Reg</a>		13 Feb 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$5,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>














Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Jointech Enterprise Pte Ltd, Co. Reg. No.: 200404434W								
Main Claimant:	CASSEROLE CATERING SERVICES PTE LTD, Co. Reg. No.: 201530426E								
Vehicle Reg. No.:	GR6686D	Date of Loss:	09/02/2018 10:00 - :59 [213 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2493029698SG	Policy/Cover Note No.:	2100215894 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBB531A	Policy No. (Claimant):	A29031802TMV						
		Excess:							
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/02/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents











\*GR6686D (2493029698SG)  
[GBB531A]  
TP  
CASSEROLE CATERING SERVICES PTE LTD  
Feb 9 2018 10:00AM  
[Jointech Enterprise Pte Ltd]  
Precise Auto Service

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<a href="#">View</a>			<a href="#">View in Browser</a>		
<b>Letters/Correspondences</b>															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown												1	Edit					
<b>Assessment Reports</b>															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	15/02/18 11:15	Accident Statement From: SC - Reg. No: G88531A, Claimant: JOINTech ENTERPRISE PTE LTD												1	Load HTM					
<b>Photos/Images</b>															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
2	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
3	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
4	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
5	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
6	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
7	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
8	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
9	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
10	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
11	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
12	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
13	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
14	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
15	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
16	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
17	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
18	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
19	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
20	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
21	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
22	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
23	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
24	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
25	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
26	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
27	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
28	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
29	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				
30	16/05/19 09:34	General View												1	Load JPG	<input checked="" type="checkbox"/>				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	16/05/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
32	16/05/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
33	16/05/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
34	16/05/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
35	16/05/19 09:34	General View	 Load JPG	<input checked="" type="checkbox"/>
36	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
37	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
38	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
39	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
40	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
41	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
42	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
43	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
44	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
45	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
46	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
47	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
48	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
49	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
50	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
51	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
52	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
53	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
54	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
55	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
56	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
57	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
58	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
59	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
60	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
61	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
62	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
63	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
64	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
65	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
66	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
67	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
68	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
69	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
70	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
71	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
72	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
73	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
74	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
75	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
76	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
77	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
78	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
79	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
80	16/05/19 09:34	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
81	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
82	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
83	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
84	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
85	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
86	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
87	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
88	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
89	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
90	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
91	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
92	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>
93	16/05/19 09:34	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/02/18 16:10	EMAIL FROM AIG DD 14.02.2018		Load PDF	
2	14/02/18 16:10	ACKNOWLEDGEMENT EMAIL TO AIG DD 14.02.2018		Load PDF	
3	14/02/18 16:10	LAWYER FORM		Load PDF	
4	15/02/18 10:44	TP GIA REPORT		Load PDF	
5	03/05/18 15:44	LETTER TO OI		Load PDF	
6	17/05/19 10:58	TP ESTIMATE - MARKED		Load PDF	
7	30/05/19 10:44	WORKSHOP INVOICE		Load PDF	
8	30/05/19 10:44	AUTHORISATION TO ACT FORM		Load PDF	
9	30/05/19 10:44	Release Voucher		Load PDF	
10	30/05/19 10:44	RENTAL RECEIPT		Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBB531A (Insd veh)	Model:	TOYOTA HIACE 3.0 (A)
	GR6686D (TP veh)		
Date of Accident:	09/02/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		10,576.86
Final Repair Cost	:	\$		5,800.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		4 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		5,800.00

**Is Third Party Workshop GIA Registered?**    ☐ YES    ☒ NO    (Kindly indicate below)

**A) For Non GIA Registered Workshop:**    Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:**    BOLA Applicable: Yes/ No    BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%)    Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Precise Auto Service	: \$	5,800.00
2)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

30 May  
2019

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18003014/AHB3Q2

Date: 30/05/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100215894  
**Claimant Vehicle No :** GR6686D **Insured Vehicle No :** GBB531A  
 Date of Loss: 09/02/2018 Nature of Claim: TP Claim No: 2493029698SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GR6686D**  
 Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 5L4912693  
 Reg. Date: 02/05/2000 (Man. Year: 2000) Chassis No: LH1620009300  
 Colour: Blue Odometer: 792414 km  
 Engine Capacity: 2986 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185 R14C Rear Tyre Size: 185 R14C  
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm  
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,704.92	3,726.02	1,978.90	34.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	2,540.00	1,640.00	39.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,884.92</b>	<b>6,266.02</b>	<b>3,618.90</b>	<b>36.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
(S\$)	9,884.92	5,000.00	4,884.92	49.42
<b>+ GST 7.00/7.00% (S\$)</b>	<b>691.94</b>	<b>350.00</b>	<b>341.94</b>	<b>49.42</b>
<b>Nett Amount (S\$)</b>	<b>10,576.86</b>	<b>5,350.00</b>	<b>5,226.86</b>	<b>49.42</b>
<b>+ Car Rental (4.0 x S\$112.15/day + 7.00% GST) (S\$)</b>		<b>480.00</b>		
<b>Nett Liability (S\$)</b>		<b>5,830.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,800.00</b>		

### INSPECTION

Date of Assignment: 13/02/2018  
 Date Inspected: 13/02/2018 Inspected At:

Precise Auto Service (HQ)  
No 1 Kaki Bukit Ave 6, #02-34/36  
Singapore 417883

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,210.20 FL	*1,210.20 FL
2	2		*TAIL GATE STOPPER	Not Necessary	107.80 FL	*- FL
3	1		*TAIL GATE LOCK	Damaged	281.75 FL	*281.75 FL
4	1		*TAIL GATE LOCK STRIKER	Bent	121.10 FL	*121.10 FL
5	1		*TAIL GATE WEATHERSTRIP	Cut	281.75 FL	*281.75 FL
6	1		*TAIL GATE OUTER GARNISH	Cracked	381.85 FL	*264.40 FL
7	1		*TAIL GATE INNER METER COVER	Bent	262.10 FL	*262.10 FL
8	2		*TAIL GATE SIDE STOPPER (MALE & FEMALE)	Not Necessary	87.80 FL	*- FL
9	1		*REAR BUMPER	Deformed	380.75 FL	*380.75 FL
10	4		*REAR BUMPER SIDE CLIPS (MALE & FEMALE)	Necessary	51.60 FL	*20.00 FL
11	1		*REAR BUMPER CENTER BEAM	Bent	281.75 FL	*281.75 FL
12	8		*REAR BUMPER CLIPS	Necessary	103.20 FL	*30.00 FL
13	2		*TAIL LAMP ASSY	Cracked	578.20 FL	*578.20 FL
14	1		*REAR WINDSCREEN RUBBER	Necessary	289.75 FL	*289.75 FL
15	1		*REAR END PANEL (OUTER)	Dented	581.75 FL	*581.75 FL
16	1		*REAR END PANEL (INNER)	Repair	561.20 FL	*- FL
17	1		*REAR END PANEL TOP METAL PLATE	Not Necessary	187.55 FL	*- FL
18	1		*SPARE TYRE BRACKET	Bent	371.20 FL	*371.20 FL
19	1		*SPARE TYRE BRACKET ADJUSTING SCREW	Not Necessary	131.75 FL	*- FL
20	1		*SPARE TYRE BRACKET ADJUSTING SCREW HOOK	Not Necessary	63.90 FL	*- FL
21	1		*EXHAUST SILENCER	Not Necessary	981.20 FL	*- FL
22	1		*FRONT RH SEAT BELT BUCKLE	Not Necessary	281.75 FL	*- FL
23	1		*70KM/H STICKER	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,599.90</b>	<b>4,964.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,894.98</b>	<b>1,238.68</b>
<b>Total Parts (\$\$)</b>	<b>5,704.92</b>	<b>3,726.02</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	80.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	30.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	180.00	120.00
4	TO REMOVE & TRANSFER TAIL GATE MECHANISM	New	220.00	80.00
5	TO REMOVE & REFIX EXHAUST SILENCER & STRAIGHTEN EXHAUST CENTER PIPE	New	280.00	0.00
6	TO TUFF COAT AFFECTED AREAS	New	180.00	60.00
7	TO REMOVE & REFIX SPARE TYRE BRACKET	New	100.00	50.00
8	TO RESPRAY AFFECTED AREAS	New	1,200.00	1,000.00
9	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR REAR BODY MUDGUARD ,REAR END SIDE PANEL & ALIGNED ALL PARTS	New	1,200.00	1,000.00
10	TO ADJUST CHASSIS ALIGNMENT ON CAR O LINER	New	380.00	0.00
11	TO REMOVE INTERIOR STAINLESS STEEL METAL SHEET TO FACILITATE REPAIRS	New	280.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,180.00</b>	<b>2,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >